[redacted]

**ಕರ್ನಾಟಕ ವಿಧಾನ ಪರಿಷತ್ತು**

**143 ನೇ ಅಧಿವೇಶನ 2021**

| | | |
|---|---|---|
| ಚುಕ್ಕೆ ಗುರುತಿಲ್ಲದ ಪ್ರಶ್ನೆ ಸಂಖ್ಯೆ | : | 2043 (1772) |
| ಮಾನ್ಯ ಸದಸ್ಯರ ಹೆಸರು | : | ಶ್ರೀ. ಕೆ.ಎ. ತಿಪ್ಪೇಸ್ವಾಮಿ (ನಾಮನಿರ್ದೇಶನ ಹೊಂದಿದವರು) |
| ಉತ್ತರಿಸುವ ದಿನಾಂಕ | : | 24-03-2021 |
| ಉತ್ತರಿಸುವ ಸಚಿವರು | : | ಮಾನ್ಯ ಉಪ ಮುಖ್ಯಮಂತ್ರಿಗಳು ಹಾಗೂ ಲೋಕೋಪಯೋಗಿ ಸಚಿವರು |

| ಕ್ರ.ಸಂ. | ಪ್ರಶ್ನೆ | ಉತ್ತರ |
|---|---|---|
| ಅ) | ರಾಜ್ಯದಲ್ಲಿ PRAMC ಯೋಜನೆ ಅಡಿಯಲ್ಲಿ ರೂಪಿಸಿರುವ ಕಾರ್ಯಕ್ರಮಗಳು ಯಾವುವು: ಮತ್ತು ಈ ಯೋಜನೆಗಳ ತಯಾರಿ ಅನುಷ್ಟಾನಗೊಳಿಸಲು ಸಂಸ್ಥೆಯಲ್ಲಿರುವ ಅಂಗಗಳು ಯಾವುವು; ಇವುಗಳ ಕಾರ್ಯ ನಿರ್ವಹಣೆ ಮತ್ತು ಆಚರಣೆ ಬಗ್ಗೆ ಸಂಪೂರ್ಣ ಮಾಹಿತಿ ನೀಡುವುದು; | ವಿವರಗಳನ್ನು ಅನುಬಂಧ-1 ರಲ್ಲಿ ನೀಡಲಾಗಿದೆ. |
| ಆ) | ಈ ಸಂಸ್ಥೆಯಲ್ಲಿ ರಸ್ತೆ ಸುರಕ್ಷತೆ ಬಗ್ಗೆ ಹಮ್ಮಿಕೊಂಡಿರುವ ಕಾರ್ಯಕ್ರಮಗಳು ಯಾವುವು; ಈ ಕಾರ್ಯಕ್ರಮಗಳ ರೂಪುರೇಷೆ ಮತ್ತು ಅನುಷ್ಠಾನದ ವಿವರ ನೀಡುವುದು; | ವಿವರಗಳನ್ನು ಅನುಬಂಧ-2 ರಲ್ಲಿ ನೀಡಲಾಗಿದೆ. |
| ಇ) | ರಸ್ತೆ ಸುರಕ್ಷತೆ ಅಡಿಯಲ್ಲಿ ರಾಜ್ಯ ಹೆದ್ದಾರಿ ಮತ್ತು ಜಿಲ್ಲಾ ಮುಖ್ಯ ರಸ್ತೆಗಳಲ್ಲಿರುವ ಕಿರಿದಾದ ಮತ್ತು ಹಳೆಯದಾದ ಸೇತುವೆಗಳ ಪುನಶ್ಚೇತನಗೊಳಿಸಲು ಗುರುತಿಸಲಾಗಿರುವ ಸೇತುವೆಗಳೆಷ್ಟು ಮತ್ತು ಈ ಸೇತುವೆಗಳ ಅಗಲೀಕರಣ ಯೋಜನೆಗಳ ಮತ್ತು ಪುನಶ್ಚೇತನಕ್ಕೆ ತಯಾರಿಸಿರುವ ಗುರಿ, ಸಾಧನೆಗಳೇನು; (ವಿವರ ನೀಡುವುದು) | ರಾಜ್ಯದಲ್ಲಿ ಪ್ರಮುಖ ರಸ್ತೆ ಜಾಲದಲ್ಲಿ ಇದುವರೆಗೂ 3234 ಸೇತುವೆಗಳನ್ನು ಗುರುತಿಸಲಾಗಿದ್ದು (CRN) ಇವುಗಳಲ್ಲಿ 2517 ಸೇತುವೆಗಳನ್ನು ದುರಸ್ತಿ ಮತ್ತು ಪುನಶ್ಚೇತನಗೊಳಿಸುವ, 427 ಸೇತುವೆಗಳನ್ನು ಅಗಲೀಕರಣಗೊಳಿಸುವ ಹಾಗೂ 290 ಸೇತುವೆಗಳನ್ನು ಪುನರ್ ನಿರ್ಮಿಸುವ ಅವಶ್ಯಕತೆ ಇರುವುದು ಕಂಡುಬರುತ್ತದೆ. (ವಿವರಗಳನ್ನು ಅನುಬಂಧ-3 ರಲ್ಲಿ ನೀಡಲಾಗಿದೆ) |
| ಈ) | ರಾಜ್ಯದಲ್ಲಿ ಕಿರಿದಾದ ಮತ್ತು ಹಳೆ ಸೇತುವೆಗಳ ಮೇಲೆ ಭಾರಿ ಗಾತ್ರದ ಮತ್ತು ಬಹುಗಾಲಿಗಳ ವಾಹನಗಳು ಚಲಿಸುತ್ತಿರುವುದರಿಂದ ತೀವ್ರವಾದ ಅಪಘಾತಗಳು ಸಂಭವಿಸುತ್ತಿರುವುದು ಸರ್ಕಾರದ ಗಮನಕ್ಕೆ ಬಂದಿದೆಯೇ: ಹಾಗಿದ್ದಲ್ಲಿ, ಈ ಅಪಘಾತಗಳನ್ನು ನಿವಾರಿಸಲು ಇರುವ ವ್ಯವಸ್ಥೆ ಮತ್ತು ಈ ವ್ಯವಸ್ಥೆಯ ಕಾರ್ಯಾಚರಣೆಗಳು ಯಾವುವು? (ಸಂಪೂರ್ಣ ಮಾಹಿತಿ ನೀಡುವುದು) | ಅಗಲ ಕಿರಿದಾದ ಸೇತುವೆಗಳ ಎರಡು ಬದಿಯಲ್ಲಿ ಕೈಪಿಡಿ ಮಾಡಿ ಸೂಚನಾ ಮತ್ತು ನಾಮಫಲಕಗಳನ್ನು ಅಳವಡಿಸಿ ಸುಗಮ ವಾಹನ ಸಂಚಾರಕ್ಕೆ ತೊಂದರೆಯಾಗದ ರೀತಿಯಲ್ಲಿ ದುರಸ್ಥಿ ಮಾಡಲು ಕ್ರಮ ಕೈಗೊಳ್ಳಲಾಗುತ್ತಿದೆ. ಅನುದಾನದ ಲಭ್ಯತೆಗನುಗುಣವಾಗಿ ತೀವ್ರ ದುಸ್ಥಿತಿಯಲ್ಲಿರುವ ಸೇತುವೆಗಳ ಬದಲಿಗೆ ಹೊಸದಾಗಿ ಸೇತುವೆಗಳನ್ನು ನಿರ್ಮಿಸಲು ಕ್ರಮ ಕೈಗೊಳ್ಳಲಾಗುತ್ತಿದೆ. |

ಸಂಖ್ಯೆ. ಲೋಇ E-119 ಇಎಪಿ 2021

[signature]

(ಗೋವಿಂದ ಎಂ. ಕಾರಜೋಳ)

ಮಾನ್ಯ ಉಪ ಮುಖ್ಯಮಂತ್ರಿಗಳು,

ಲೋಕೋಪಯೋಗಿ ಸಚಿವರು

## ಅನುಬಂಧ-1

ಯೋಜನೆ ಮತ್ತು ರಸ್ತೆಗಳ ಆಸ್ತಿ ನಿರ್ವಹಣಾ ಕೇಂದ್ರವು (PRAMC) ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ವ್ಯಾಪ್ತಿಯಲ್ಲಿನ ಇಡೀ ರಸ್ತೆ ವ್ಯವಸ್ಥೆಯ ವಸ್ತುನಿಷ್ಠ ವಾರ್ಷಿಕ ಕ್ರಿಯಾ ಯೋಜನೆಯನ್ನು, ಆಧುನಿಕ ಯಂತ್ರೋಪಕರಣಗಳಾದ ROMDAS, FWD, GPR ಮತ್ತು ಬೃಹತ್ ಸೇತುವೆಗಳ ತಪಾಸಣಾ ವಾಹನಗಳನ್ನು ಉಪಯೋಗಿಸಿಕೊಂಡು ರಸ್ತೆ ಸ್ಥಿತಿಗತಿಗಳ, ರಫ್‌ನೆಸ್, ರಟ್ಟಿಂಗ್ ಮತ್ತು ಪೇವ್‌ಮೆಂಟ್‌ನ ಬಲ, ಸೇತುವೆಗಳ ಸ್ಥಿತಿಗತಿಗಳ ದತ್ತಾಂಶ, ಹೆಚ್‌ಡಿಎಮ್-4 ನಂತಹ ಆಧುನಿಕ ತಂತ್ರಾಂಶಗಳ ವಿಶ್ಲೇಷಣೆಯನ್ನು ಬಳಸಿಕೊಂಡು ರಸ್ತೆಗಳ ನಿರ್ವಹಣೆ ಮತ್ತು ಅಭಿವೃದ್ಧಿಪಡಿಸಲು ವಾರ್ಷಿಕ ಕ್ರಿಯಾ ಯೋಜನೆಯನ್ನು ತಯಾರಿಸಲು ಉಪಕ್ರಮಗಳನ್ನು ಕೈಗೊಳ್ಳುತ್ತಿದೆ.

ಯೋಜನೆ ಮತ್ತು ರಸ್ತೆಗಳ ಆಸ್ತಿ ನಿರ್ವಹಣಾ ಕೇಂದ್ರವು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ವ್ಯಾಪ್ತಿಯ ರಸ್ತೆಗಳ ಯೋಜನೆ, ಆಯವ್ಯಯ ತಯಾರಿಕೆ ಮತ್ತು ಕಾರ್ಯಕ್ರಮ ರೂಪಿಸಲು ಒಂದು ಸಂಘಟನಾ ಕೇಂದ್ರ ಕಚೇರಿಯಾಗಿ ಕಾರ್ಯ ನಿರ್ವಹಿಸುತ್ತಿದೆ. PRAMC ಯು ನೀತಿಗಳನ್ನು ಅಭಿವೃದ್ಧಿಪಡಿಸುವ, ಅಭಿವೃದ್ಧಿ ಕಾರ್ಯಕ್ರಮಗಳಿಗೆ ಯೋಜನೆ ರೂಪಿಸುವ, ರಸ್ತೆಗಳ ಸ್ವತ್ತು ನಿರ್ವಹಣೆ ಮಾಡುವ ವಲಯದ ಸರ್ವೋಚ್ಛ ಸಂಸ್ಥೆಯಾಗಿ ಕಾರ್ಯ ನಿರ್ವಹಿಸುತ್ತಿದೆ.

ಯೋಜನೆ ಮತ್ತು ರಸ್ತೆಗಳ ಆಸ್ತಿ ನಿರ್ವಹಣಾ ಕೇಂದ್ರವು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ವ್ಯಾಪ್ತಿಯಲ್ಲಿ ಇಂಜಿನಿಯರುಗಳಿಗೆ ತರಬೇತಿ ನೀಡುವ ಕಾರ್ಯಕ್ರಮಗಳನ್ನು ಕೈಗೊಳ್ಳುತ್ತಿದೆ.

ರಾಜ್ಯದ ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ವ್ಯಾಪ್ತಿಯ ರಸ್ತೆಗಳನ್ನು ಮೇಲ್ದರ್ಜೆಗೇರಿಸುವ ಮತ್ತು ಕೆಳದರ್ಜೆಗಿಳಿಸುವ ಪ್ರಸ್ತಾವನೆಗಳನ್ನು ಕ್ರೋಢೀಕರಿಸಿ ಅನುಷ್ಠಾನಗೊಳಿಸಲು ಸರ್ಕಾರಕ್ಕೆ ಸಲ್ಲಿಸಲಾಗುತ್ತದೆ.

Karnataka Road Asset Management System (KRAMS) ಒಂದು ಸಮಗ್ರವಾದ ಮತ್ತು ಏಕೀಕೃತಗೊಂಡ ತಂತ್ರಾಂಶವಾಗಿದ್ದು, (COTS, RIS, PWP&IWTD, HDM-4 and TMT) ರಸ್ತೆಗಳ ನಿರ್ವಹಣೆಯನ್ನು ಹೆಚ್ಚಿಸುವ ಮತ್ತು ಸುವ್ಯವಸ್ಥಿತಗೊಳಿಸಲು PRAMC ಗೆ ಸಹಕರಿಸಲು ವಿನ್ಯಾಸಗೊಳಿಸಲಾಗಿದೆ. KRAMS ತಂತ್ರಾಂಶವು ರಸ್ತೆಗಳನ್ನು ನಿರ್ವಹಿಸುವಲ್ಲಿ ದತ್ತಾಂಶ ಆಧರಿಸಿದ ವೈಜ್ಞಾನಿಕ ಪ್ರಕ್ರಿಯೆಯಾಗಿದ್ದು, ಆಯವ್ಯಯದ ನಿರ್ಬಂಧದಡಿ ಸ್ವತ್ತುಗಳನ್ನು ನಿರ್ವಹಿಸುವ ಮತ್ತು ಉನ್ನತೀಕರಿಸುವ ವ್ಯವಸ್ಥೆಯಾಗಿರುತ್ತದೆ.

ಅಂತರಾಷ್ಟ್ರೀಯ ಗುಣಮಟ್ಟದ ಅತ್ಯಾಧುನಿಕವಾದ ದತ್ತಾಂಶ ಸಂಗ್ರಹಿಸುವ ಉಪಕರಣಗಳು:

1) Laser Based Road Condition Data Collection Vehicle (RCDCV)
2) Falling Weight Deflectometer (FWD)
3) Ground Penetration Radars (GPR)
4) Bridge Inspection Vehicle (BIV)

### Road Measurement Data Acquisition System (ROMDAS)

ರಸ್ತೆ ವಲಯದ ಮೇಲೆ ವ್ಯಯಿಸುವ ಬಂಡವಾಳದ ಆರ್ಥಿಕ ಪರಿಣಾಮಗಳನ್ನು ರೂಪಿಸಲು ರಫ್‌ನೆಸ್ ಒಂದು ನಿರ್ಣಾಯಕ ಅಂಶವಾಗಿರುತ್ತದೆ. ROMDAS ಉಪಕರಣಕ್ಕೆ Laser Profiler ಅಳವಡಿಸಿ ಇಡೀ ಸಿಆರ್‌ಎನ್ ರಸ್ತೆ ಜಾಲದ ರಫ್‌ನೆಸ್ ಸಮೀಕ್ಷೆ ಮಾಡಲಾಗುತ್ತದೆ. ಈ ಉಪಕರಣವನ್ನು ಉಪಯೋಗಿಸಿಕೊಂಡು International Roughness Index (IRI), Rutting, Raveling, Potholing ಇತರೆ ಮಾಹಿತಿಗಳನ್ನು ಸಂಗ್ರಹಿಸಲಾಗುತ್ತಿದೆ.

### Falling Weight Deflectometer (FWD)

ಈ ಉಪಕರಣವನ್ನು ಸಿವಿಲ್ ಇಂಜಿನಿಯರುಗಳು ರಸ್ತೆಯ ಭೌತಿಕ ಗುಣಲಕ್ಷಣಗಳನ್ನು ಸ್ಥಿತಿಸ್ಥಾಪಕತ್ವದ ಅಂಶವನ್ನೂ ಒಳಗೊಂಡಂತೆ ಮೌಲ್ಯಮಾಪನ ಮಾಡಲು, ತಾಳಿಕೆಯ ಸಾಮರ್ಥ್ಯ ತಿಳಿಯಲು, ಮತ್ತು standard axle load ಬಳಸಿದಾಗ ರಸ್ತೆ ಮೇಲ್ಮೈನ ಕುಗ್ಗುವಿಕೆ ಇತ್ಯಾದಿ ಅರಿಯಲು ಬಳಸುತ್ತಿದ್ದಾರೆ. FWD ಡೇಟಾವನ್ನು ಪ್ರಾಥಮಿಕವಾಗಿ ಹಾಲಿ ಇರುವ ರಸ್ತೆಯ ಮೇಲ್ಮೈನ ಬಲಪಡಿಸುವಿಕೆ ಅವಶ್ಯಕತೆಗಳನ್ನು ತಿಳಿಯಲು ಉಪಯೋಗಿಸಲಾಗುತ್ತಿದೆ.

ರಸ್ತೆಯ ಸಾಮರ್ಥ್ಯವು, ವಿನ್ಯಾಸಗೊಳಿಸಿದ ರಸ್ತೆಯ ಜೀವಿತಾವಧಿಯವರೆಗೂ ಸುಸ್ಥಿತಿಯಲ್ಲಿಡಲು ಓವರ್‌ಲೇ ಮಾಡಲು ಹಾಗೂ ರಸ್ತೆಯ ಬಾಕಿ ಜೀವಿತಾವಧಿಯನ್ನು ನಿರ್ಧರಿಸಲು ಸಹಾಯಕವಾಗುತ್ತದೆ.

## Ground Penetrating Radar (GPR)

ಈ GPR ಉಪಕರಣವು ರಾಡಾರ್ ಪಲ್ಸ್‌ಗಳನ್ನು ಉಪಯೋಗಿಸಿಕೊಂಡು ರಸ್ತೆಯ ಕೆಳಮೈ ಗುಣಲಕ್ಷಣಗಳನ್ನು ಅರಿಯಲು ಭೂ-ಭೌತಿಕ ವಿಧಾನವಾಗಿದ್ದು, ರಸ್ತೆಯ ಪದರಗಳ ದಪ್ಪವನ್ನು ತಿಳಿಯಬಹುದಾಗಿರುತ್ತದೆ. ಹಾಗೂ ಈ GPR ಉಪಕರಣವು ಪದರಗಳ ವಿವರಗಳನ್ನು ಅರಿಯಲು ಹಾನಿಕಾರಕವಲ್ಲದ ಹಾಗೂ ಭೂಮಿಯನ್ನು ಬಗೆಯದೇ ತಿಳಿಯಬಹುದಾದ ಉಪಕರಣವಾಗಿರುತ್ತದೆ.

## Bridge Inspection Vehicle (BIV)

ಗಣನೀಯವಾಗಿ ಬಂಡವಾಳ ವ್ಯಯಿಸಿ ನಿರ್ಮಿಸಿರುವ ಸೇತುವೆಗಳನ್ನು, ಸಂಭವನೀಯ ವಿಪತ್ತುಗಳಿಂದ ರಕ್ಷಿಸಲು ಮತ್ತು ಸೇತುವೆಗಳ ಕ್ಷಯಿಸುವಿಕೆಯನ್ನು ತಡೆಗಟ್ಟಲು ಕಾಲಕಾಲಕ್ಕೆ ತಪಾಸಣೆ ಮಾಡಬೇಕಾದ, ನಿರ್ವಹಿಸಬೇಕಾದ ಅವಶ್ಯಕತೆ ಇರುತ್ತದೆ. ಈ BIV ಉಪಕರಣವನ್ನು ಉಪಯೋಗಿಸಿಕೊಂಡು ಸೇತುವೆಯ ತಳಭಾಗದಲ್ಲಿ ಹಾಗೂ ಅಂಚುಗಳಲ್ಲಿ ಗಮನಿಸಲಾಗದೇ ಇರುವ ಕ್ಷಯಿಸುವಿಕೆಯನ್ನು ತಿಳಿಯುವ ಸೌಲಭ್ಯವಿರುತ್ತದೆ. ಈ ಉಪಕರಣದಲ್ಲಿ ಸೇತುವೆಯ ಭೌತಿಕ ಮತ್ತು ಕಾರ್ಯತತ್ಪರತೆಯ ಸ್ಥಿತಿಯನ್ನು ಕರಾರುವಾಕ್ಕಾಗಿ ಅರಿಯಲು ಸೌಲಭ್ಯವಿರುತ್ತದೆ. ಸಾಮಾನ್ಯವಾಗಿ ಕೈಗೊಳ್ಳುವ ತಪಾಸಣೆಯ ಜೊತೆಗೆ ಕೆಲವು ಬಾರಿ ಏಣಿಗಳ ಮೂಲಕ ಸುರಕ್ಷಿತವಾಗಿ ತಲುಪಲು ಸಾಧ್ಯವಿರದಿರುವ ಸೇತುವೆಯ ಕೆಲ ನಿರ್ಣಾಯಕ ಭಾಗಗಳಲ್ಲಿ ಅತ್ಯಂತ ಸನಿಹದಿಂದ ಗಮನಿಸಬೇಕಾದ ಸಂದರ್ಭಗಳಲ್ಲಿ ತಪಾಸಣೆಗಳನ್ನು ಕೈಗೊಳ್ಳಲಾಗುತ್ತಿದೆ. ಈ ಉಪಕರಣವನ್ನು ಸೇತುವೆಯ ರಚನೆಯ ವಿಸ್ತೃತವಾಗಿ ಮೌಲ್ಯಮಾಪನ ಮಾಡಲು ಮತ್ತು ಸೇತುವೆಯ ನಿರ್ಣಾಯಕ ಭಾಗಗಳಲ್ಲಿ ಹಾನಿಕಾರಕವಲ್ಲದ ಟೆಸ್ಟ್ ನಡೆಸಲು (ಸೇತುವೆಯ ಸಾಫಿಟ್ ಗಳಲ್ಲಿ, ಬೇರಿಂಗ್ ಲೊಕೇಶನ್‌ಗಳಲ್ಲಿ) ಬಳಸಬಹುದಾಗಿರುತ್ತದೆ. ಈ ತಪಾಸಣೆಯನ್ನು ವಾಹನ ಸಂಚಾರಕ್ಕೆ ಯಾವುದೇ ಧಕ್ಕೆಯುಂಟಾಗದಂತೆ ಅಥವಾ ವಾಹನ ಸಂಚಾರಕ್ಕೆ ಕನಿಷ್ಟ ತೊಂದರೆಯೊಂದಿಗೆ ನಡೆಸಬಹುದಾಗಿರುತ್ತದೆ.

ಪ್ರಧಾನ ಇಂಜಿನಿಯರ್,
ಯೋಜನೆ ಮತ್ತು ರಸ್ತೆಗಳ ಆಸ್ತಿ ನಿರ್ವಹಣಾ ಕೇಂದ್ರ,
4ನೇ ಮಹಡಿ, ಲೋಕ ಮೂರಕಕಟ್ಟಡ, ಕೆ.ಆರ್.ವೃತ್ತ
ಬೆಂಗಳೂರು-560001.

## ಅನುಬಂಧ-2

ರಸ್ತೆ ಸುರಕ್ಷತಾ ಕಾರ್ಯಕ್ರಮಗಳ ಬಗ್ಗೆ

ಯೋಜನೆ ಮತ್ತು ರಸ್ತೆಗಳ ಆಸ್ತಿ ನಿರ್ವಹಣಾ ಕೇಂದ್ರವು ರಾಜ್ಯದಲ್ಲಿ, ಕರ್ನಾಟಕ ರಾಜ್ಯ ರಸ್ತೆ ಸುರಕ್ಷತಾ ಪ್ರಾಧಿಕಾರದಿಂದ ಗುರುತಿಸಲಾಗಿರುವ ಅಪಘಾತ ಕಪ್ಪು ಸ್ಥಳಗಳನ್ನು ಸರಿಪಡಿಸಿ ಸರ್ವೋಚ್ಚ ನ್ಯಾಯಾಲಯದ ರಸ್ತೆ ಸುರಕ್ಷತಾ ಸಮಿತಿಗೆ ಕಾಲಕಾಲಕ್ಕೆ ಮಾಹಿತಿ ನೀಡುತ್ತಿದೆ.

**ಈ ಕೆಳಕಂಡ ಲೆಕ್ಕ ಶೀರ್ಷಿಕೆಗಳಡಿಯಲ್ಲಿ ರಸ್ತೆ ಸುರಕ್ಷತಾ ಕಾರ್ಯಕ್ರಮಗಳನ್ನು ಅನುಷ್ಠಾನಗೊಳಿಸಲಾಗುತ್ತಿದೆ.**

1) **ಲೆಕ್ಕ ಶೀರ್ಷಿಕೆ 3054-03-337-0-07-200 (ಎಸ್‌ಹೆಚ್)** ರಾಜ್ಯ ಹೆದ್ದಾರಿ ರಸ್ತೆ ಸುರಕ್ಷತಾ ನಿರ್ವಹಣೆ ಅಡಿಯಲ್ಲಿ ರಾಜ್ಯ ಹೆದ್ದಾರಿಗಳ ಮೇಲಿರುವ ಅಪಘಾತ ಕಪ್ಪು ಸ್ಥಳಗಳನ್ನು ಸರಿಪಡಿಸುವುದು ಹಾಗೂ ರಸ್ತೆ ಸುರಕ್ಷತಾ ಕಾಮಗಾರಿಗಳನ್ನು ಕೈಗೊಳ್ಳಲಾಗುತ್ತಿದೆ.
2) **ಲೆಕ್ಕ ಶೀರ್ಷಿಕೆ 3054-04-337-1-13-200 (ಎಂಡಿಆರ್)** ಜಿಲ್ಲಾ ಮುಖ್ಯ ರಸ್ತೆ ಮತ್ತು ಇತರೆ ರಸ್ತೆಗಳು - ರಸ್ತೆ ಸುರಕ್ಷತಾ ನಿರ್ವಹಣೆ ಅಡಿಯಲ್ಲಿ ಜಿಲ್ಲಾ ಮುಖ್ಯ ರಸ್ತೆಗಳ ಮೇಲಿರುವ ಅಪಘಾತ ಕಪ್ಪು ಸ್ಥಳಗಳನ್ನು ಸರಿಪಡಿಸುವುದು ಹಾಗೂ ರಸ್ತೆ ಸುರಕ್ಷತಾ ಕಾಮಗಾರಿಗಳನ್ನು ಕೈಗೊಳ್ಳಲಾಗುತ್ತಿದೆ.
3) **ಲೆಕ್ಕ ಶೀರ್ಷಿಕೆ "5054-05-337-4-02-154 ನಾಲೆಗಳ ಬದಿಯಲ್ಲಿ ರಸ್ತೆ ಸುರಕ್ಷತಾ ಕಾಮಗಾರಿಗಳು ಮತ್ತು ಬ್ಯಾರಿಕೇಡಿಂಗ್ ಸುಧಾರಣೆಗಳು"** ಅಡಿಯಲ್ಲಿ ಕೆರೆ ಏರಿಗಳು / ಜಲಮೂಲಗಳಲ್ಲಿ ಸುರಕ್ಷತೆಗಾಗಿ ಕ್ರಾಶ್ ಬ್ಯಾರಿಯರ್ ಮತ್ತು ಇತರೆ ರಸ್ತೆ ಸುರಕ್ಷತಾ ಕ್ರಮಗಳನ್ನು ಆದ್ಯತೆಯ ಮೇಲೆ ಕೈಗೊಳ್ಳುವುದು ಒಳಗೊಂಡಿರುತ್ತದೆ.

ರಸ್ತೆ ಸುರಕ್ಷತಾ ಕಾರ್ಯಕ್ರಮಗಳನ್ನು ಕೈಗೊಳ್ಳಲು ಸಮಾಲೋಚಕರ ಸೇವೆಯನ್ನು ಪಡೆದು, ಅಂದಾಜು ಪಟ್ಟಿಯನ್ನು ತಯಾರಿಸಿ, ವಿಸ್ತೃತ ಯೋಜನಾ ವರದಿಯನ್ನು ತಯಾರಿಸಿ, ಟೆಂಡರ್ ಪ್ರಕ್ರಿಯೆಗಳನ್ನು ಪೂರ್ಣಗೊಳಿಸಿ ಅನುಷ್ಠಾನಗೊಳಿಸಲು ಸಂಬಂಧಪಟ್ಟ ಲೋಕೋಪಯೋಗಿ ವಿಭಾಗದ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರುಗಳು ಹಾಗೂ Project Monitoring Consultants ಗಳ ಉಸ್ತುವಾರಿಯೊಂದಿಗೆ ಕಾಮಗಾರಿಗಳನ್ನು ನಿರ್ವಹಿಸಲಾಗುತ್ತಿದೆ.

ಪ್ರಧಾನ ಇಂಜಿನಿಯರ್,
ಯೋಜನೆ ಮತ್ತು ರಸ್ತೆಗಳ ಆಸ್ತಿ ನಿರ್ವಹಣಾ ಕೇಂದ್ರ,
4ನೇ ಮಹಡಿ, ಲೋಕ ಪೂರಕಕಟ್ಟಡ, ಕೆ.ಆರ್.ವೃತ್ತ
ಬೆಂಗಳೂರು-560001.

ಅನುಬಂಧ-3



# Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | BR:MDR_AFZ2:AFZ2:7.009 | AFZ2 | MDR_AFZ2 | Gulbarga | Gulbarga | Afzalpur | 7000 | 12.00 | Slab | 18.00 | routine |
| 2 | BR:MDR_AFZ2:AFZ2:15.601 | AFZ2 | MDR_AFZ2 | Gulbarga | Gulbarga | Afzalpur | 15583 | 9.00 | Slab | 36.00 | routine |
| 3 | BR:MDR_AFZ2:AFZ2:24.197 | AFZ2 | MDR_AFZ2 | Gulbarga | Gulbarga | Afzalpur | 24193 | 12.50 | pipe | 9.30 | routine |
| 4 | BR:MDR_ALD8:ALD8:9.166 | ALD8 | MDR_ALD8 | Gulbarga | Gulbarga | Aland | 9076 | 8.50 | Slab | 197.60 | routine |
| 5 | BR:MDR_ANK12:ANK12:6.267 | ANK12 | MDR_ANK12 | Bangalore Urban | Bangalore | Anekal | 6261 | 8.00 | pipe | 12.00 | repair |
| 6 | BR:MDR_ANK4:ANK4:6.851 | ANK4 | MDR_ANK4 | Bangalore Urban | Bangalore | Anekal | 6843 | 15.00 | pipe | 16.50 | routine |
| 7 | BR:MDR_BDM201:BDM201:17.284 | BDM201 | MDR_BDM201 | Bagalkot | Bagalkot | Badami | 17250 | 8.50 | Slab | 64.80 | routine |
| 8 | BR:MDR_BER6:BER6:7.783 | BER6 | MDR_BER6 | Bellary | Bellary | Bellary | 7779 | 8.50 | Slab | 9.00 | repair |
| 9 | BR:MDR_BER6:BER6:9.161 | BER6 | MDR_BER6 | Bellary | Bellary | Bellary | 9156 | 8.50 | Slab | 10.00 | repair |
| 10 | BR:MDR_BER6:BER6:9.71 | BER6 | MDR_BER6 | Bellary | Bellary | Bellary | 9707 | 8.50 | Slab | 7.50 | repair |
| 11 | BR:MDR_BER9:BER9:2.767 | BER9 | MDR_BER9 | Bellary | Bellary | Bellary | 2755 | 12.00 | Slab | 24.00 | routine |
| 12 | BR:MDR_BER9:BER9:3.659 | BER9 | MDR_BER9 | Bellary | Bellary | Bellary | 3654 | 8.50 | Slab | 10.00 | repair |
| 13 | BR:MDR_BER9:BER9:6.804 | BER9 | MDR_BER9 | Bellary | Bellary | Bellary | 6801 | 8.50 | Slab | 7.00 | repair |
| 14 | BR:MDR_BER9:BER9:14.778 | BER9 | MDR_BER9 | Bellary | Bellary | Bellary | 14760 | 8.50 | Slab | 36.00 | repair |
| 15 | BR:MDR_BER9:BER9:18.832 | BER9 | MDR_BER9 | Bellary | Bellary | Bellary | 18820 | 8.50 | Pipe | 25.90 | routine |
| 16 | BR:MDR_BGM14:BGM14:0.906 | BGM14 | MDR_BGM14 | Belgaum | Belgaum | Belgaum | 878 | 9.00 | Slab | 56.50 | routine |
| 17 | BR:MDR_BGM14:BGM14:5.223 | BGM14 | MDR_BGM14 | Belgaum | Belgaum | Belgaum | 5219 | 8.00 | Slab | 9.00 | routine |
| 18 | BR:MDR_BGM16:BGM16:2.129 | BGM16 | MDR_BGM16 | Belgaum | Belgaum | Belgaum | 2125 | 12.00 | Slab | 9.00 | routine |
| 19 | BR:MDR_BGM16:BGM16:5.179 | BGM16 | MDR_BGM16 | Belgaum | Belgaum | Belgaum | 5175 | 8.50 | Slab | 9.00 | routine |
| 20 | BR:MDR_BGM201:BGM201:2.386 | BGM201 | MDR_BGM201 | Belgaum | Belgaum | Belgaum | 2377 | 8.00 | pipe | 19.50 | repair |
| 21 | BR:MDR_BID8:BID8:5.429 | BID8 | MDR_BID8 | Bidar | Bidar | Bidar | 5426 | 8.50 | Slab | 7.00 | routine |
| 22 | BR:MDR_BLG9:BLG9:1.771 | BLG9 | MDR_BLG9 | Bagalkot | Bagalkot | Bilgi | 1757 | 8.00 | pipe | 29.50 | repair |
| 23 | BR:MDR_BLG9:BLG9:6.713 | BLG9 | MDR_BLG9 | Bagalkot | Bagalkot | Bilgi | 6706 | 8.00 | Slab | 14.00 | repair |
| 24 | BR:MDR_BLG9:BLG9:11.753 | BLG9 | MDR_BLG9 | Bagalkot | Bagalkot | Bilgi | 11735 | 8.00 | pipe | 37.00 | repair |
| 25 | BR:MDR_BLG9:BLG9:16.37 | BLG9 | MDR_BLG9 | Bagalkot | Bagalkot | Bilgi | 16349 | 8.00 | Slab | 42.00 | repair |
| 26 | BR:MDR_BNG10:BNG10:10.244 | BNG10 | MDR_BNG10 | Bangalore Urban | Bangalore | Bangalore-North | 10238 | 10.00 | Slab | 12.00 | repair |
| 27 | BR:MDR_BNG10:BNG10:13.005 | BNG10 | MDR_BNG10 | Bangalore Urban | Bangalore | Bangalore-North | 12985 | 8.00 | Slab | 40.00 | repair |
| 28 | BR:MDR_BNG8:BNG8:7.44 | BNG8 | MDR_BNG8 | Bangalore Urban | Bangalore | Bangalore-North | 7422 | 6.00 | Slab | 36.00 | repair |
| 29 | BR:MDR_BNG8:BNG8:7.443 | BNG8 | MDR_BNG8 | Bangalore Urban | Bangalore | Bangalore-North | 7425 | 6.00 | Slab | 36.00 | routine |
| 30 | BR:MDR_BNG8:BNG8:7.996 | BNG8 | MDR_BNG8 | Bangalore Urban | Bangalore | Bangalore-North | 7982 | 9.00 | Slab | 28.00 | repair |
| 31 | BR:MDR_BNS10:BNS10:9.157 | BNS10 | MDR_BNS10 | Bangalore Urban | Bangalore | Bangalore South | 9149 | 12.00 | Slab | 16.00 | routine |
| 32 | BR:MDR_BNS10:BNS10:9.485 | BNS10 | MDR_BNS10 | Bangalore Urban | Bangalore | Bangalore South | 9478 | 12.00 | Slab | 14.00 | routine |
| 33 | BR:MDR_CHL204:CHL204:6.853 | CHL204 | MDR_CHL204 | Chitradurga | Chitradurga | Challakere | 6850 | 8.50 | Slab | 6.50 | routine |
| 34 | BR:MDR_CKD17:CKD17:3.825 | CKD17 | MDR_CKD17 | Belgaum | Chikkodi | Chikkodi | 3821 | 8.00 | Slab | 8.00 | routine |
| 35 | BR:MDR_CKD17:CKD17:4.777 | CKD17 | MDR_CKD17 | Belgaum | Chikkodi | Chikkodi | 4773 | 8.00 | Slab | 8.00 | routine |
| 36 | BR:MDR_CKD7:CKD7:9.978 | CKD7 | MDR_CKD7 | Belgaum | Chikkodi | Chikkodi | 9933 | 8.50 | Girder | 90.00 | repair |
| 37 | BR:MDR_CNH10:CNH10:12.894 | CNH10 | MDR_CNH10 | Tumkur | Tumkur | Chiknayakanahalli | 12891 | 7.50 | pipe | 7.00 | repair |
| 38 | BR:MDR_CNH10:CNH10:17.579 | CNH10 | MDR_CNH10 | Tumkur | Tumkur | Chiknayakanahalli | 17576 | 8.00 | Slab | 6.50 | repair |
| 39 | BR:MDR_CNH10:CNH10:19.296 | CNH10 | MDR_CNH10 | Tumkur | Tumkur | Chiknayakanahalli | 19293 | 12.00 | Slab | 7.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 40 | BR:MDR_CNH10:CNH10:20.898 | CNH10 | MDR_CNH10 | Tumkur | Tumkur | Chiknayakanahalli | 20895 | 10.00 | pipe | 6.30 | routine |
| 41 | BR:MDR_CTR6:CTR6:1.263 | CTR6 | MDR_CTR6 | Gulbarga | Sedam | Chitapur | 1238 | 8.00 | Slab | 50.00 | repair |
| 42 | BR:MDR_CTR6:CTR6:3.694 | CTR6 | MDR_CTR6 | Gulbarga | Sedam | Chitapur | 3689 | 12.00 | Slab | 10.00 | routine |
| 43 | BR:MDR_GBB2:GBB2:11.056 | GBB2 | MDR_GBB2 | Tumkur | Tumkur | Gubbi | 11025 | 12.00 | Slab | 65.25 | routine |
| 44 | BR:MDR_GBB2:GBB2:12.074 | GBB2 | MDR_GBB2 | Tumkur | Tumkur | Gubbi | 12069 | 8.00 | Slab | 11.40 | repair |
| 45 | BR:MDR_GBB2:GBB2:12.282 | GBB2 | MDR_GBB2 | Tumkur | Tumkur | Gubbi | 12273 | 8.00 | Slab | 18.00 | repair |
| 46 | BR:MDR_GBB2:GBB2:14.381 | GBB2 | MDR_GBB2 | Tumkur | Tumkur | Gubbi | 14378 | 8.00 | Slab | 6.50 | repair |
| 47 | BR:MDR_GBB2:GBB2:21.577 | GBB2 | MDR_GBB2 | Tumkur | Tumkur | Gubbi | 21573 | 10.00 | pipe | 8.00 | repair |
| 48 | BR:MDR_GBB2:GBB2:23.266 | GBB2 | MDR_GBB2 | Tumkur | Tumkur | Gubbi | 23260 | 8.00 | Slab | 12.00 | repair |
| 49 | BR:MDR_GBB2:GBB2:28.089 | GBB2 | MDR_GBB2 | Tumkur | Tumkur | Gubbi | 28081 | 7.50 | pipe | 16.50 | repair |
| 50 | BR:MDR_GUL13:GUL13:1.191 | GUL13 | MDR_GUL13 | Gulbarga | Gulbarga | Gulbarga | 1177 | 8.50 | Slab | 28.50 | routine |
| 51 | BR:MDR_GUL13:GUL13:4.686 | GUL13 | MDR_GUL13 | Gulbarga | Gulbarga | Gulbarga | 4683 | 8.50 | Slab | 7.00 | routine |
| 52 | BR:MDR_GUL13:GUL13:6.677 | GUL13 | MDR_GUL13 | Gulbarga | Gulbarga | Gulbarga | 6671 | 12.00 | Slab | 12.00 | routine |
| 53 | BR:MDR_HBL15:HBL15:3.859 | HBL15 | MDR_HBL15 | Dharwad | Dharwad | Hubli | 3827 | 8.50 | Slab | 64.00 | routine |
| 54 | BR:MDR_HBL6:HBL6:7.692 | HBL6 | MDR_HBL6 | Dharwad | Dharwad | Hubli | 7687 | 8.50 | Slab | 10.60 | routine |
| 55 | BR:MDR_HNS13:HNS13:26.718 | HNS13 | MDR_HNS13 | Mysore | Hunsur | Hunsur | 26713 | 12.00 | Slab | 10.00 | routine |
| 56 | BR:MDR_HUD43:HUD43:0.996 | HUD43 | MDR_HUD43 | Bagalkot | Bagalkot | Hungund | 992 | 7.50 | Pipe | 9.30 | repair |
| 57 | BR:MDR_KOL14:KOL14:0.837 | KOL14 | MDR_KOL14 | Kolar | Kolar | Kolar | 828 | 10.00 | Slab | 18.00 | routine |
| 58 | BR:MDR_KOL14:KOL14:4.508 | KOL14 | MDR_KOL14 | Kolar | Kolar | Kolar | 4504 | 12.50 | Pipe | 8.00 | routine |
| 59 | BR:MDR_KOL14:KOL14:7.058 | KOL14 | MDR_KOL14 | Kolar | Kolar | Kolar | 7053 | 10.00 | Pipe | 11.50 | routine |
| 60 | BR:MDR_KOL14:KOL14:8.13 | KOL14 | MDR_KOL14 | Kolar | Kolar | Kolar | 8125 | 10.00 | Slab | 10.00 | routine |
| 61 | BR:MDR_KOP19:KOP19:0.888 | KOP19 | MDR_KOP19 | Koppal | Koppal | Koppal | 882 | 12.50 | pipe | 13.50 | repair |
| 62 | BR:MDR_KOP203:KOP203:4.069 | KOP203 | MDR_KOP203 | Koppal | Koppal | Koppal | 4061 | 12.00 | Slab | 16.00 | routine |
| 63 | BR:MDR_KTG5:KTG5:5.909 | KTG5 | MDR_KTG5 | Tumkur | Madhugiri | Koratagere | 5904 | 10.00 | pipe | 10.70 | repair |
| 64 | BR:MDR_KTG5:KTG5:11.147 | KTG5 | MDR_KTG5 | Tumkur | Madhugiri | Koratagere | 11143 | 7.50 | Slab | 8.80 | repair |
| 65 | BR:MDR_MDG101:MDG101:1.85 | MDG101 | MDR_MDG101 | Tumkur | Madhugiri | Madhugiri | 1846 | 9.00 | Slab | 9.00 | routine |
| 66 | BR:MDR_MDG101:MDG101:10.873 | MDG101 | MDR_MDG101 | Tumkur | Madhugiri | Madhugiri | 10828 | 6.20 | Girder | 100.00 | repair |
| 67 | BR:MDR_MDG4:MDG4:8.818 | MDG4 | MDR_MDG4 | Tumkur | Madhugiri | Madhugiri | 8812 | 8.00 | Slab | 12.00 | repair |
| 68 | BR:MDR_MDG4:MDG4:9.682 | MDG4 | MDR_MDG4 | Tumkur | Madhugiri | Madhugiri | 9677 | 12.00 | Slab | 10.00 | repair |
| 69 | BR:MDR_MDG4:MDG4:10.587 | MDG4 | MDR_MDG4 | Tumkur | Madhugiri | Madhugiri | 10584 | 8.00 | Slab | 7.20 | routine |
| 70 | BR:MDR_MDL7:MDL7:31.232 | MDL7 | MDR_MDL7 | Bagalkot | Bagalkot | Mudhol | 31216 | 8.00 | Slab | 32.50 | repair |
| 71 | BR:MDR_MDR12:MDR12:1.351 | MDR12 | MDR_MDR12 | Mandya | Mandya | Maddur | 1347 | 7.00 | pipe | 8.00 | repair |
| 72 | BR:MDR_MDR12:MDR12:2.848 | MDR12 | MDR_MDR12 | Mandya | Mandya | Maddur | 2839 | 8.00 | Slab | 18.00 | repair |
| 73 | BR:MDR_MDR12:MDR12:3.594 | MDR12 | MDR_MDR12 | Mandya | Mandya | Maddur | 3590 | 6.50 | Slab | 9.00 | repair |
| 74 | BR:MDR_MDR12:MDR12:7.796 | MDR12 | MDR_MDR12 | Mandya | Mandya | Maddur | 7791 | 10.00 | pipe | 10.00 | repair |
| 75 | BR:MDR_MDR12:MDR12:12.116 | MDR12 | MDR_MDR12 | Mandya | Mandya | Maddur | 12110 | 6.50 | Slab | 12.00 | repair |
| 76 | BR:MDR_MDR12:MDR12:15.463 | MDR12 | MDR_MDR12 | Mandya | Mandya | Maddur | 15460 | 7.50 | pipe | 6.30 | repair |
| 77 | BR:MDR_MDR12:MDR12:17.415 | MDR12 | MDR_MDR12 | Mandya | Mandya | Maddur | 17411 | 7.50 | pipe | 8.00 | repair |
| 78 | BR:MDR_MDR16:MDR16:17.569 | MDR16 | MDR_MDR16 | Mandya | Mandya | Maddur | 17555 | 8.00 | Girder | 28.00 | repair |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl.No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len. (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 79 | BR:MDR_MDR9:MDR9:8.601 | MDR9 | MDR_MDR9 | Mandya | Mandya | Maddur | 8597 | 8.50 | Slab | 8.00 | routine |
| 80 | BR:MDR_MDR9:MDR9:8.82 | MDR9 | MDR_MDR9 | Mandya | Mandya | Maddur | 8814 | 7.50 | Slab | 12.00 | repair |
| 81 | BR:MDR_MDR9:MDR9:14.291 | MDR9 | MDR_MDR9 | Mandya | Mandya | Maddur | 14280 | 9.00 | Girder | 23.00 | routine |
| 82 | BR:MDR_MDR9:MDR9:20.025 | MDR9 | MDR_MDR9 | Mandya | Mandya | Maddur | 20017 | 9.00 | Slab | 16.00 | routine |
| 83 | BR:MDR_MDR9:MDR9:20.56 | MDR9 | MDR_MDR9 | Mandya | Mandya | Maddur | 20555 | 8.50 | Slab | 10.00 | routine |
| 84 | BR:MDR_MDR9:MDR9:22.464 | MDR9 | MDR_MDR9 | Mandya | Mandya | Maddur | 22459 | 8.50 | Slab | 10.00 | routine |
| 85 | BR:MDR_MDR9:MDR9:23.825 | MDR9 | MDR_MDR9 | Mandya | Mandya | Maddur | 23820 | 8.50 | Slab | 10.00 | routine |
| 86 | BR:MDR_MGD18:MGD18:3.78 | MGD18 | MDR_MGD18 | Ramanagara | Ramanagara | Magadi | 3777 | 10.00 | Slab | 7.00 | routine |
| 87 | BR:MDR_MGD18:MGD18:9.098 | MGD18 | MDR_MGD18 | Ramanagara | Ramanagara | Magadi | 9093 | 7.00 | Slab | 10.00 | repair |
| 88 | BR:MDR_MLR1:MLR1:13.832 | MLR1 | MDR_MLR1 | Kolar | Kolar | Malur | 13828 | 9.00 | Slab | 8.00 | routine |
| 89 | BR:MDR_MLR1:MLR1:24.041 | MLR1 | MDR_MLR1 | Kolar | Kolar | Malur | 24036 | 8.00 | Slab | 10.00 | routine |
| 90 | BR:MDR_MLR1:MLR1:26.272 | MLR1 | MDR_MLR1 | Kolar | Kolar | Malur | 26266 | 8.00 | Slab | 12.00 | routine |
| 91 | BR:MDR_MLR1:MLR1:33.33 | MLR1 | MDR_MLR1 | Kolar | Kolar | Malur | 33312 | 10.00 | Slab | 36.00 | routine |
| 92 | BR:MDR_MLR2:MLR2:1.22 | MLR2 | MDR_MLR2 | Kolar | Kolar | Malur | 1216 | 8.00 | Slab | 8.00 | repair |
| 93 | BR:MDR_MLR2:MLR2:4.017 | MLR2 | MDR_MLR2 | Kolar | Kolar | Malur | 4010 | 10.00 | Pipe | 14.50 | repair |
| 94 | BR:MDR_MLR2:MLR2:13.701 | MLR2 | MDR_MLR2 | Kolar | Kolar | Malur | 13693 | 10.00 | Pipe | 17.50 | routine |
| 95 | BR:MDR_MLV5:MLV5:44.513 | MLV5 | MDR_MLV5 | Mandya | Mandya | Malavalli | 44506 | 7.00 | pipe | 14.50 | repair |
| 96 | BR:MDR_MLV5:MLV5:47.059 | MLV5 | MDR_MLV5 | Mandya | Mandya | Malavalli | 47055 | 7.00 | pipe | 9.50 | repair |
| 97 | BR:MDR_MLV5:MLV5:52.766 | MLV5 | MDR_MLV5 | Mandya | Mandya | Malavalli | 52761 | 8.50 | Slab | 10.00 | routine |
| 98 | BR:MDR_MLV5:MLV5:58.704 | MLV5 | MDR_MLV5 | Mandya | Mandya | Malavalli | 58700 | 12.00 | Slab | 9.00 | routine |
| 99 | BR:MDR_MND18:MND18:3.055 | MND18 | MDR_MND18 | Mandya | Mandya | Mandya | 3042 | 8.50 | Slab | 27.00 | routine |
| 100 | BR:MDR_MND18:MND18:3.265 | MND18 | MDR_MND18 | Mandya | Mandya | Mandya | 3261 | 7.50 | pipe | 8.60 | repair |
| 101 | BR:MDR_MND18:MND18:5.633 | MND18 | MDR_MND18 | Mandya | Mandya | Mandya | 5629 | 7.00 | Slab | 9.00 | repair |
| 102 | BR:MDR_MND2:MND2:6.914 | MND2 | MDR_MND2 | Mandya | Mandya | Mandya | 6910 | 8.00 | Slab | 9.00 | repair |
| 103 | BR:MDR_MND2:MND2:7.846 | MND2 | MDR_MND2 | Mandya | Mandya | Mandya | 7843 | 8.00 | Slab | 7.00 | routine |
| 104 | BR:MDR_MND2:MND2:9.848 | MND2 | MDR_MND2 | Mandya | Mandya | Mandya | 9844 | 8.00 | Slab | 9.00 | repair |
| 105 | BR:MDR_MND2:MND2:14.022 | MND2 | MDR_MND2 | Mandya | Mandya | Mandya | 14015 | 8.00 | pipe | 14.50 | repair |
| 106 | BR:MDR_MUL6:MUL6:1.133 | MUL6 | MDR_MUL6 | Kolar | Kolar | Mulbagal | 1107 | 8.00 | Pipe | 53.90 | routine |
| 107 | BR:MDR_MUL6:MUL6:1.72 | MUL6 | MDR_MUL6 | Kolar | Kolar | Mulbagal | 1716 | 12.00 | Slab | 8.00 | routine |
| 108 | BR:MDR_MUL6:MUL6:16.259 | MUL6 | MDR_MUL6 | Kolar | Kolar | Mulbagal | 16253 | 8.00 | Pipe | 13.00 | repair |
| 109 | BR:MDR_MUL6:MUL6:16.621 | MUL6 | MDR_MUL6 | Kolar | Kolar | Mulbagal | 16615 | 12.00 | Slab | 12.00 | routine |
| 110 | BR:MDR_MYS10:MYS10:1.278 | MYS10 | MDR_MYS10 | Mysore | Mysore | Mysore | 1273 | 12.50 | pipe | 10.00 | repair |
| 111 | BR:MDR_MYS10:MYS10:7.267 | MYS10 | MDR_MYS10 | Mysore | Mysore | Mysore | 7263 | 9.00 | Slab | 8.00 | repair |
| 112 | BR:MDR_MYS8:MYS8:3.073 | MYS8 | MDR_MYS8 | Mysore | Mysore | Mysore | 3069 | 18.50 | Slab | 8.00 | routine |
| 113 | BR:MDR_RMN3:RMN3:5.548 | RMN3 | MDR_RMN3 | Ramanagara | Ramanagara | Ramnagaram | 5518 | 7.50 | Girder | 60.00 | repair |
| 114 | BR:MDR_RMN3:RMN3:12.772 | RMN3 | MDR_RMN3 | Ramanagara | Ramanagara | Ramnagaram | 12752 | 12.00 | Slab | 40.00 | repair |
| 115 | BR:MDR_RMN9:RMN9:18.638 | RMN9 | MDR_RMN9 | Ramanagara | Ramanagara | Ramnagaram | 18634 | 12.00 | Slab | 9.00 | routine |
| 116 | BR:MDR_RMN9:RMN9:19.168 | RMN9 | MDR_RMN9 | Ramanagara | Ramanagara | Ramnagaram | 19164 | 12.00 | Slab | 9.00 | routine |
| 117 | BR:MDR_RMN9:RMN9:22.469 | RMN9 | MDR_RMN9 | Ramanagara | Ramanagara | Ramnagaram | 22461 | 8.00 | pipe | 17.70 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl No | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 118 | BR:MDR_RMN9:RMN9:25.059 | RMN9 | MDR_RMN9 | Ramanagara | Ramanagara | Ramnagaram | 25039 | 8.00 | pipe | 41.50 | repair |
| 119 | BR:MDR_RON10:RON10:19.922 | RON10 | MDR_RON10 | Gadag | Gadag | Ron | 19918 | 8.00 | Pipe | 8.50 | repair |
| 120 | BR:MDR_RON10:RON10:24.3 | RON10 | MDR_RON10 | Gadag | Gadag | Ron | 24297 | 8.00 | Slab | 7.00 | routine |
| 121 | BR:MDR_SNR20:SNR20:3.091 | SNR20 | MDR_SNR20 | Bellary | Bellary | Sandur | 3075 | 12.00 | Slab | 33.00 | routine |
| 122 | BR:MDR_SNR31:SNR31:18.122 | SNR31 | MDR_SNR31 | Bellary | Bellary | Sandur | 18115 | 8.00 | Pipe | 14.50 | repair |
| 123 | BR:MDR_SNR6:SNR6:0.159 | SNR6 | MDR_SNR6 | Bellary | Bellary | Sandur | 124 | 8.50 | Girder | 66.00 | repair |
| 124 | BR:MDR_SNR6:SNR6:7.313 | SNR6 | MDR_SNR6 | Bellary | Bellary | Sandur | 7308 | 8.00 | Slab | 10.00 | repair |
| 125 | BR:MDR_TMK10:TMK10:6.878 | TMK10 | MDR_TMK10 | Tumkur | Madhugiri | Sira | 6874 | 8.00 | Slab | 8.00 | repair |
| 126 | BR:MDR_TMK10:TMK10:10.571 | TMK10 | MDR_TMK10 | Tumkur | Tumkur | Tumkur | 10562 | 8.00 | Slab | 19.80 | repair |
| 127 | BR:MDR_TMK5:TMK5:3.678 | TMK5 | MDR_TMK5 | Tumkur | Madhugiri | Madhugiri | 3669 | 9.00 | Slab | 19.20 | repair |
| 128 | BR:MDR_TMK5:TMK5:6.944 | TMK5 | MDR_TMK5 | Tumkur | Tumkur | Tumkur | 6941 | 9.00 | Slab | 7.00 | routine |
| 129 | BR:MDR_TMK5:TMK5:7.086 | TMK5 | MDR_TMK5 | Tumkur | Tumkur | Tumkur | 7080 | 9.00 | Girder | 12.00 | repair |
| 130 | BR:MDR_TMK5:TMK5:11.756 | TMK5 | MDR_TMK5 | Tumkur | Tumkur | Tumkur | 11752 | 10.00 | pipe | 9.30 | routine |
| 131 | BR:MDR_TMK5:TMK5:18.011 | TMK5 | MDR_TMK5 | Tumkur | Tumkur | Tumkur | 18005 | 9.00 | Girder | 12.00 | repair |
| 132 | BR:MDR_TMK5:TMK5:22.41 | TMK5 | MDR_TMK5 | Tumkur | Tumkur | Tumkur | 22404 | 9.00 | Slab | 12.00 | routine |
| 133 | BR:MDR_TMK7:TMK7:23.849 | TMK7 | MDR_TMK7 | Tumkur | Tumkur | Tumkur | 23841 | 12.50 | pipe | 16.50 | routine |
| 134 | BR:MDR_TPT8:TPT8:39.009 | TPT8 | MDR_TPT8 | Tumkur | Tumkur | Tiptur | 39003 | 11.00 | Slab | 13.20 | repair |
| 135 | BR:MDR_TPT8:TPT8:41.263 | TPT8 | MDR_TPT8 | Tumkur | Tumkur | Tiptur | 41248 | 8.00 | Girder | 30.00 | repair |
| 136 | BR:MDR_TPT8:TPT8:43.901 | TPT8 | MDR_TPT8 | Tumkur | Tumkur | Tiptur | 43889 | 8.00 | Slab | 24.00 | repair |
| 137 | BR:MDR_TPT8:TPT8:47.378 | TPT8 | MDR_TPT8 | Tumkur | Tumkur | Tiptur | 47373 | 10.00 | pipe | 11.40 | repair |
| 138 | BR:MDR_TPT8:TPT8:49.975 | TPT8 | MDR_TPT8 | Tumkur | Tumkur | Tiptur | 49971 | 8.00 | Slab | 9.20 | repair |
| 139 | BR:MDR_TPT8:TPT8:50.224 | TPT8 | MDR_TPT8 | Tumkur | Tumkur | Tumkur | 50216 | 8.00 | Girder | 16.00 | repair |
| 140 | BR:MDR_TVK6:TVK6:0.891 | TVK6 | MDR_TVK6 | Tumkur | Tumkur | Turuvekere | 882 | 8.00 | Slab | 19.80 | routine |
| 141 | BR:MDR_TVK6:TVK6:5.299 | TVK6 | MDR_TVK6 | Tumkur | Tumkur | Turuvekere | 5295 | 8.00 | Slab | 9.00 | routine |
| 142 | BR:SH1:UDP203:3.47 | UDP203 | SH1 | Udupi | Udupi | Udupi | 3452 | 8.00 | Slab | 36.00 | repair |
| 143 | BR:SH1:UDP203:4.925 | UDP203 | SH1 | Udupi | Udupi | Udupi | 4917 | 8.00 | Girder | 16.00 | repair |
| 144 | BR:SH1:KRK40:41.164 | KRK40 | SH1 | Udupi | Udupi | Karkala | 41114 | 12.00 | Girder | 100.00 | routine |
| 145 | BR:SH1:KRK40:47.491 | KRK40 | SH1 | Udupi | Udupi | Karkala | 47482 | 8.50 | Girder | 18.00 | repair |
| 146 | BR:SH1:KRK40:49.916 | KRK40 | SH1 | Udupi | Udupi | Karkala | 49897 | 8.00 | Girder | 39.60 | repair |
| 147 | BR:SH1:KRK40:53.291 | KRK40 | SH1 | Udupi | Udupi | Karkala | 53267 | 8.00 | Girder | 48.00 | repair |
| 148 | BR:SH1:KRK40:56.686 | KRK40 | SH1 | Udupi | Udupi | Karkala | 56670 | 8.00 | Girder | 33.00 | repair |
| 149 | BR:SH1:KRK40:60.051 | KRK40 | SH1 | Udupi | Udupi | Karkala | 60029 | 8.00 | Girder | 45.00 | repair |
| 150 | BR:SH1:KRK40:62.496 | KRK40 | SH1 | Udupi | Udupi | Karkala | 62475 | 8.00 | Girder | 43.50 | repair |
| 151 | BR:SH1:TRT3:115.461 | TRT3 | SH1 | Shimoga | Shimoga_special | Tirthahalli | 115451 | 12.00 | Slab | 20.00 | routine |
| 152 | BR:SH1:SGR88:178.367 | SGR88 | SH1 | Shimoga | Shimoga | Sagar | 178362 | 9.00 | Girder | 10.00 | repair |
| 153 | BR:SH1:SGR88:183.229 | SGR88 | SH1 | Shimoga | Shimoga | Sagar | 183225 | 8.00 | Girder | 9.00 | repair |
| 154 | BR:SH1:SGR88:183.514 | SGR88 | SH1 | Shimoga | Shimoga | Sagar | 183508 | 12.00 | Slab | 12.00 | routine |
| 155 | BR:SH1:SKR2:188.604 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 188600 | 7.00 | Slab | 8.00 | repair |
| 156 | BR:SH1:SKR2:192.389 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 192383 | 12.00 | Slab | 12.00 | routine |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 157 | BR:SH1:SKR2:197.354 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 197327 | 8.50 | Girder | 54.00 | repair |
| 158 | BR:SH1:SKR2:204.044 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 204008 | 12.00 | Slab | 72.00 | routine |
| 159 | BR:SH1:SKR2:204.724 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 204718 | 12.50 | Pipe | 13.10 | repair |
| 160 | BR:SH1:SKR2:205.674 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 205670 | 8.50 | Slab | 9.00 | routine |
| 161 | BR:SH1:SKR2:205.679 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 205675 | 6.00 | Arch | 9.00 | routine |
| 162 | BR:SH1:SKR2:222.264 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 222257 | 8.50 | Slab | 14.00 | routine |
| 163 | BR:SH1:SKR2:224.754 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 224747 | 12.00 | Slab | 15.00 | routine |
| 164 | BR:SH1:SKR2:226.204 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 226198 | 8.50 | Slab | 12.00 | repair |
| 165 | BR:SH1:SKR2:231.504 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 231499 | 12.00 | Slab | 10.00 | routine |
| 166 | BR:SH1:SKR2:231.914 | SKR2 | SH1 | Shimoga | Shimoga | Shikaripur | 231909 | 12.00 | Slab | 10.00 | routine |
| 167 | BR:SH1:HNL1:254.027 | HNL1 | SH1 | Haveri | Haveri | Hangal | 253952 | 8.50 | Girder | 149.00 | routine |
| 168 | BR:SH1:HNL1:269.713 | HNL1 | SH1 | Haveri | Haveri | Hangal | 269703 | 8.50 | Slab | 20.00 | routine |
| 169 | BR:SH1:HNL1:270.323 | HNL1 | SH1 | Haveri | Haveri | Hangal | 270298 | 12.00 | Slab | 50.40 | routine |
| 170 | BR:SH1:HNL1:276.021 | HNL1 | SH1 | Haveri | Haveri | Hangal | 276005 | 12.00 | Girder | 32.00 | routine |
| 171 | BR:SH1:KLG201:321.892 | KLG201 | SH1 | Dharwad | Dharwad | Kalaghatgi | 321889 | 10.00 | Pipe | 7.00 | repair |
| 172 | BR:SH1:KLG201:331.672 | KLG201 | SH1 | Dharwad | Dharwad | Kalaghatgi | 331644 | 12.00 | Slab | 56.00 | routine |
| 173 | BR:SH1:KLG201:331.677 | KLG201 | SH1 | Dharwad | Dharwad | Kalaghatgi | 331652 | 12.00 | Slab | 50.00 | routine |
| 174 | BR:SH1:DRD19:378.95 | DRD19 | SH1 | Dharwad | Dharwad | Dharwad | 378935 | 10.00 | Slab | 30.00 | routine |
| 175 | BR:SH1:DRD19:384.945 | DRD19 | SH1 | Dharwad | Dharwad | Dharwad | 384942 | 8.00 | Slab | 6.50 | repair |
| 176 | BR:SH1:DRD19:386.695 | DRD19 | SH1 | Dharwad | Dharwad | Dharwad | 386663 | 8.00 | Slab | 64.00 | repair |
| 177 | BR:SH1:DRD19:386.715 | DRD19 | SH1 | Dharwad | Dharwad | Dharwad | 386683 | 8.00 | Slab | 64.00 | repair |
| 178 | BR:SH1:DRD19:388.25 | DRD19 | SH1 | Dharwad | Dharwad | Dharwad | 388247 | 10.00 | Pipe | 7.30 | repair |
| 179 | BR:SH1:DRD19:390.865 | DRD19 | SH1 | Dharwad | Dharwad | Dharwad | 390861 | 10.00 | Pipe | 9.90 | repair |
| 180 | BR:SH1:BAI201_A:403.74 | BAI201_A | SH1 | Belgaum | Belgaum | Bailhongal | 403733 | 7.50 | pipe | 14.80 | routine |
| 181 | BR:SH1:BAI201_A:405.655 | BAI201_A | SH1 | Belgaum | Belgaum | Bailhongal | 405652 | 12.00 | Slab | 7.00 | routine |
| 182 | BR:SH1:BAI201_A:409.787 | BAI201_A | SH1 | Belgaum | Belgaum | Bailhongal | 409609 | 8.20 | Girder | 355.30 | repair |
| 183 | BR:SH1:SAU205:425.378 | SAU205 | SH1 | Belgaum | Belgaum | Saundatti | 425372 | 15.00 | pipe | 12.10 | routine |
| 184 | BR:SH1:BAI201_B:432.263 | BAI201_B | SH1 | Belgaum | Belgaum | Bailhongal | 432241 | 9.00 | Slab | 45.00 | repair |
| 185 | BR:SH1:GOK201_A:447.272 | GOK201_A | SH1 | Belgaum | Chikkodi | Gokak | 447269 | 10.00 | pipe | 7.90 | routine |
| 186 | BR:SH1:GOK201_A:448.137 | GOK201_A | SH1 | Belgaum | Chikkodi | Gokak | 448133 | 10.00 | pipe | 9.30 | routine |
| 187 | BR:SH1:HUK204:477.971 | HUK204 | SH1 | Belgaum | Chikkodi | Hukkeri | 477873 | 8.00 | Girder | 195.20 | repair |
| 188 | BR:SH1:HUK204:489.021 | HUK204 | SH1 | Belgaum | Chikkodi | Hukkeri | 489018 | 10.00 | pipe | 7.90 | repair |
| 189 | BR:SH10:ALD1:1.44 | ALD1 | SH10 | Gulbarga | Gulbarga | Aland | 1433 | 12.00 | Slab | 14.00 | routine |
| 190 | BR:SH10:ALD1:18.325 | ALD1 | SH10 | Gulbarga | Gulbarga | Aland | 18280 | 8.20 | Arch | 90.00 | routine |
| 191 | BR:SH10:ALD1:21.805 | ALD1 | SH10 | Gulbarga | Gulbarga | Aland | 21801 | 12.00 | Slab | 9.00 | routine |
| 192 | BR:SH10:ALD1:24.14 | ALD1 | SH10 | Gulbarga | Gulbarga | Aland | 24130 | 12.00 | Slab | 21.00 | routine |
| 193 | BR:SH10:ALD1:28.325 | ALD1 | SH10 | Gulbarga | Gulbarga | Aland | 28322 | 12.00 | Slab | 7.00 | routine |
| 194 | BR:SH10:ALD1:31.3 | ALD1 | SH10 | Gulbarga | Gulbarga | Aland | 31280 | 8.00 | Slab | 40.00 | routine |
| 195 | BR:SH10:ALD1:31.31 | ALD1 | SH10 | Gulbarga | Gulbarga | Aland | 31293 | 8.00 | Slab | 35.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 196 | BR:SH10:ALD1:38.93 | ALD1 | SH10 | Gulbarga | Gulbarga | Aland | 38927 | 12.00 | Slab | 7.50 | routine |
| 197 | BR:SH10:ALD1:39.835 | ALD1 | SH10 | Gulbarga | Gulbarga | Aland | 39831 | 12.00 | Slab | 8.00 | routine |
| 198 | BR:SH10:GUL2:42.795 | GUL2 | SH10 | Gulbarga | Gulbarga | Gulbarga | 42792 | 12.00 | Slab | 7.50 | routine |
| 199 | BR:SH10:GUL2:64.958 | GUL2 | SH10 | Gulbarga | Gulbarga | Gulbarga | 64951 | 9.00 | Slab | 15.00 | repair |
| 200 | BR:SH10:GUL2:69.963 | GUL2 | SH10 | Gulbarga | Gulbarga | Gulbarga | 69960 | 12.00 | Slab | 7.00 | routine |
| 201 | BR:SH10:GUL2:72.898 | GUL2 | SH10 | Gulbarga | Gulbarga | Gulbarga | 72888 | 12.00 | Slab | 21.00 | routine |
| 202 | BR:SH10:GUL2:74.883 | GUL2 | SH10 | Gulbarga | Gulbarga | Gulbarga | 74879 | 12.00 | Slab | 9.00 | routine |
| 203 | BR:SH10:GUL2:78.323 | GUL2 | SH10 | Gulbarga | Gulbarga | Gulbarga | 78317 | 12.00 | Slab | 12.00 | routine |
| 204 | BR:SH10:GUL2:78.993 | GUL2 | SH10 | Gulbarga | Gulbarga | Gulbarga | 78990 | 12.00 | Slab | 6.40 | routine |
| 205 | BR:SH10:GUL2:80.243 | GUL2 | SH10 | Gulbarga | Gulbarga | Gulbarga | 80234 | 12.00 | Slab | 18.00 | routine |
| 206 | BR:SH10:CTR70:83.023 | CTR70 | SH10 | Gulbarga | Sedam | Chitapur | 83020 | 12.00 | Slab | 6.40 | routine |
| 207 | BR:SH10:CTR70:83.643 | CTR70 | SH10 | Gulbarga | Sedam | Chitapur | 83640 | 12.00 | Slab | 6.40 | routine |
| 208 | BR:SH10:CTR70:84.788 | CTR70 | SH10 | Gulbarga | Sedam | Chitapur | 84781 | 12.00 | Slab | 14.00 | routine |
| 209 | BR:SH10:CTR70:85.808 | CTR70 | SH10 | Gulbarga | Sedam | Chitapur | 85805 | 12.00 | Slab | 6.40 | routine |
| 210 | BR:SH10:CTR70:86.763 | CTR70 | SH10 | Gulbarga | Sedam | Chitapur | 86760 | 12.00 | Slab | 7.00 | routine |
| 211 | BR:SH10:CTR70:86.958 | CTR70 | SH10 | Gulbarga | Sedam | Chitapur | 86953 | 12.00 | Slab | 10.00 | routine |
| 212 | BR:SH10:CTR70:90.382 | CTR70 | SH10 | Gulbarga | Sedam | Chitapur | 90356 | 8.50 | Slab | 52.50 | routine |
| 213 | BR:SH10:CTR70:91.977 | CTR70 | SH10 | Gulbarga | Sedam | Chitapur | 91973 | 12.00 | Slab | 9.00 | routine |
| 214 | BR:SH10:CTR70:93.502 | CTR70 | SH10 | Gulbarga | Sedam | Chitapur | 93498 | 10.00 | Slab | 8.00 | routine |
| 215 | BR:SH10:SED1:100.747 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 100627 | 7.30 | Girder | 210.00 | repair |
| 216 | BR:SH10:SED1:108.287 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 108283 | 12.00 | Slab | 9.00 | routine |
| 217 | BR:SH10:SED1:108.552 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 108532 | 8.50 | Slab | 40.00 | routine |
| 218 | BR:SH10:SED1:113.112 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 113105 | 12.00 | Slab | 14.00 | routine |
| 219 | BR:SH10:SED1:113.497 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 113483 | 12.00 | Slab | 28.00 | routine |
| 220 | BR:SH10:SED1:117.477 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 117461 | 12.00 | Slab | 32.00 | routine |
| 221 | BR:SH10:SED1:118.457 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 118414 | 8.50 | Girder | 87.15 | routine |
| 222 | BR:SH10:SED1:131.842 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 131830 | 12.00 | Slab | 24.00 | routine |
| 223 | BR:SH10:SED1:135.587 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 135579 | 12.00 | Slab | 16.00 | routine |
| 224 | BR:SH10:SED1:136.017 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 136013 | 12.00 | Slab | 8.00 | routine |
| 225 | BR:SH10:SED1:137.877 | SED1 | SH10 | Gulbarga | Sedam | Sedam | 137873 | 12.00 | Slab | 8.00 | routine |
| 226 | BR:SH101:MNG18:29.41 | MNG18 | SH101 | Dakshina Kannada | Mangalore | Mangalore | 29315 | 9.00 | Girder | 189.00 | repair |
| 227 | BR:SH101:BNT201:69.018 | BNT201 | SH101 | Dakshina Kannada | Mangalore | Bantwal | 69004 | 8.00 | Slab | 28.80 | routine |
| 228 | BR:SH101:BNT201:71.758 | BNT201 | SH101 | Dakshina Kannada | Mangalore | Bantwal | 71751 | 8.00 | Girder | 15.00 | repair |
| 229 | BR:SH102:ARS201:29.455 | ARS201 | SH102 | Hassan | Hassan | Arsikere | 29452 | 8.50 | Slab | 7.00 | repair |
| 230 | BR:SH102:ARS201:46.27 | ARS201 | SH102 | Hassan | Hassan | Arsikere | 46262 | 10.00 | Pipe | 16.50 | repair |
| 231 | BR:SH102:ARS201:50.305 | ARS201 | SH102 | Hassan | Hassan | Arsikere | 50302 | 10.00 | Pipe | 6.30 | repair |
| 232 | BR:SH102:ARS201:57.53 | ARS201 | SH102 | Hassan | Hassan | Arsikere | 57522 | 8.50 | Slab | 16.60 | repair |
| 233 | BR:SH102:HSS240:79.595 | HSS240 | SH102 | Hassan | Hassan | Hassan | 79587 | 12.00 | Slab | 16.00 | routine |
| 234 | BR:SH102:HSS240:84.875 | HSS240 | SH102 | Hassan | Hassan | Hassan | 84866 | 12.50 | Pipe | 19.90 | routine |

Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 235 | BR:SH103:GOK15:5.41 | GOK15 | SH103 | Belgaum | Chikkodi | Gokak | 5404 | 10.00 | Slab | 12.00 | routine |
| 236 | BR:SH103:SAU203:16.615 | SAU203 | SH103 | Belgaum | Belgaum | Saundatti | 16604 | 8.00 | pipe | 22.50 | repair |
| 237 | BR:SH103:SAU203:17.875 | SAU203 | SH103 | Belgaum | Belgaum | Saundatti | 17868 | 8.50 | Girder | 14.00 | routine |
| 238 | BR:SH104:DVN3:28.375 | DVN3 | SH104 | Bangalore Rural | Bangalore | Devanahalli | 28371 | 10.00 | pipe | 8.00 | repair |
| 239 | BR:SH104:DVN3:33.695 | DVN3 | SH104 | Bangalore Rural | Bangalore | Devanahalli | 33687 | 10.00 | pipe | 16.50 | routine |
| 240 | BR:SH104:DVN3:49.1 | DVN3 | SH104 | Bangalore Rural | Bangalore | Devanahalli | 49097 | 11.20 | Slab | 7.65 | routine |
| 241 | BR:SH104:DVN3:50.82 | DVN3 | SH104 | Bangalore Rural | Bangalore | Devanahalli | 50815 | 12.00 | Slab | 11.60 | routine |
| 242 | BR:SH104:DVN3:51.855 | DVN3 | SH104 | Bangalore Rural | Bangalore | Devanahalli | 51851 | 12.00 | Slab | 9.90 | routine |
| 243 | BR:SH11:ALD2:61.485 | ALD2 | SH11 | Gulbarga | Gulbarga | Aland | 61435 | 8.50 | Girder | 99.20 | routine |
| 244 | BR:SH110:BLR301:1.105 | BLR301 | SH110 | Hassan | Hassan | Belur | 1089 | 9.00 | Slab | 33.00 | repair |
| 245 | BR:SH110:BLR301:13.635 | BLR301 | SH110 | Hassan | Hassan | Belur | 13604 | 8.00 | Slab | 63.60 | routine |
| 246 | BR:SH110:BLR301:17.855 | BLR301 | SH110 | Hassan | Hassan | Belur | 17836 | 7.50 | pipe | 39.50 | repair |
| 247 | BR:SH110:BLR301:18.125 | BLR301 | SH110 | Hassan | Hassan | Belur | 18122 | 8.00 | Slab | 6.80 | repair |
| 248 | BR:SH110:ALR204:31.99 | ALR204 | SH110 | Hassan | Hassan | Alur | 31983 | 10.80 | Girder | 15.20 | routine |
| 249 | BR:SH110:ALR204:44.836 | ALR204 | SH110 | Hassan | Hassan | Alur | 44815 | 8.50 | Girder | 43.50 | repair |
| 250 | BR:SH110:ALR204:54.366 | ALR204 | SH110 | Hassan | Hassan | Alur | 54363 | 8.50 | Slab | 6.60 | repair |
| 251 | BR:SH110:ALR204:61.926 | ALR204 | SH110 | Hassan | Hassan | Alur | 61916 | 8.50 | Girder | 21.50 | repair |
| 252 | BR:SH110:SLP249:66.751 | SLP249 | SH110 | Hassan | Hassan_Special | Sakleshpur | 66696 | 8.50 | Girder | 110.00 | repair |
| 253 | BR:SH112:SLP201:12.82 | SLP201 | SH112 | Hassan | Hassan_Special | Sakleshpur | 12807 | 8.50 | Slab | 27.60 | routine |
| 254 | BR:SH112:SLP201:24.4 | SLP201 | SH112 | Hassan | Hassan_Special | Sakleshpur | 24393 | 8.50 | Girder | 14.00 | repair |
| 255 | BR:SH112:SLP201:41.865 | SLP201 | SH112 | Hassan | Hassan_Special | Sakleshpur | 41859 | 8.50 | Slab | 12.00 | repair |
| 256 | BR:SH112:SVP79:89.011 | SVP79 | SH112 | Kodagu | Kodagu | Somvarpet | 89001 | 8.00 | Girder | 20.00 | repair |
| 257 | BR:SH112:SVP79:91.026 | SVP79 | SH112 | Kodagu | Kodagu | Somvarpet | 91020 | 10.00 | Slab | 12.00 | repair |
| 258 | BR:SH115:BRV64:12.865 | BRV64 | SH115 | Shimoga | Shimoga_special | Bhadravathi | 12862 | 12.00 | Slab | 6.50 | repair |
| 259 | BR:SH115:BRV64:17.51 | BRV64 | SH115 | Shimoga | Shimoga_special | Bhadravathi | 17499 | 8.50 | Girder | 22.00 | repair |
| 260 | BR:SH115:HNN14:26.32 | HNN14 | SH115 | Davanagere | Davanagere | Honnali | 26308 | 7.00 | Slab | 24.00 | routine |
| 261 | BR:SH115:HNN14:35.89 | HNN14 | SH115 | Davanagere | Davanagere | Honnali | 35884 | 12.00 | Slab | 12.00 | routine |
| 262 | BR:SH12:BJP4:10.925 | BJP4 | SH12 | Bijapur | Bijapur | Bijapur | 10921 | 12.00 | Slab | 9.00 | routine |
| 263 | BR:SH12:BJP4:13.54 | BJP4 | SH12 | Bijapur | Bijapur | Bijapur | 13534 | 12.00 | pipe | 13.50 | routine |
| 264 | BR:SH12:BJP4:16.925 | BJP4 | SH12 | Bijapur | Bijapur | Bijapur | 16875 | 12.00 | Girder | 106.50 | routine |
| 265 | BR:SH12:BJP4:20.24 | BJP4 | SH12 | Bijapur | Bijapur | Bijapur | 20237 | 9.00 | Slab | 7.20 | repair |
| 266 | BR:SH12:BJP4:31.365 | BJP4 | SH12 | Bijapur | Bijapur | Bijapur | 31307 | 8.20 | Girder | 117.00 | repair |
| 267 | BR:SH12:BJP4:34.675 | BJP4 | SH12 | Bijapur | Bijapur | Bijapur | 34668 | 8.00 | Slab | 15.00 | repair |
| 268 | BR:SH12:ATN2:60.6 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 60555 | 8.40 | Slab | 89.05 | repair |
| 269 | BR:SH12:ATN2:62.22 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 62208 | 8.00 | Slab | 24.00 | repair |
| 270 | BR:SH12:ATN2:63.525 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 63521 | 10.00 | pipe | 8.50 | repair |
| 271 | BR:SH12:ATN2:65.93 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 65927 | 12.00 | Slab | 6.50 | routine |
| 272 | BR:SH12:ATN2:70.31 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 70306 | 12.00 | Slab | 8.00 | routine |
| 273 | BR:SH12:ATN2:73.93 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 73925 | 12.00 | Slab | 10.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 274 | BR:SH12:ATN2:76.005 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 75998 | 8.50 | Slab | 15.00 | repair |
| 275 | BR:SH12:ATN2:80.005 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 79995 | 7.50 | pipe | 20.20 | repair |
| 276 | BR:SH12:ATN2:85.875 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 85819 | 8.50 | Girder | 111.15 | routine |
| 277 | BR:SH12:ATN2:90.32 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 90317 | 12.00 | Slab | 7.00 | routine |
| 278 | BR:SH12:ATN2:95.59 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 95579 | 8.00 | pipe | 22.50 | repair |
| 279 | BR:SH12:ATN2:102.812 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 102796 | 8.00 | pipe | 32.50 | repair |
| 280 | BR:SH12:ATN2:105.132 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 105128 | 12.00 | Slab | 8.00 | routine |
| 281 | BR:SH12:ATN2:108.287 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 108272 | 8.00 | Slab | 30.00 | repair |
| 282 | BR:SH12:ATN2:119.372 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 119369 | 10.00 | pipe | 7.00 | repair |
| 283 | BR:SH12:ATN2:123.772 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 123769 | 10.00 | pipe | 7.00 | repair |
| 284 | BR:SH12:ATN2:124.402 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 124399 | 10.00 | pipe | 7.00 | repair |
| 285 | BR:SH12:CKD2:128.937 | CKD2 | SH12 | Belgaum | Chikkodi | Chikkodi | 128897 | 8.50 | Girder | 117.00 | repair |
| 286 | BR:SH12:CKD2:133.257 | CKD2 | SH12 | Belgaum | Chikkodi | Chikkodi | 133023 | 9.00 | Girder | 505.40 | routine |
| 287 | BR:SH12:CKD2:151.61 | CKD2 | SH12 | Belgaum | Chikkodi | Chikkodi | 151598 | 8.00 | Slab | 24.00 | repair |
| 288 | BR:SH12:CKD2:158.075 | CKD2 | SH12 | Belgaum | Chikkodi | Chikkodi | 158069 | 8.00 | Slab | 12.00 | repair |
| 289 | BR:SH12:CKD2:158.81 | CKD2 | SH12 | Belgaum | Chikkodi | Chikkodi | 158807 | 10.00 | pipe | 6.70 | repair |
| 290 | BR:SH12:CKD2:160.265 | CKD2 | SH12 | Belgaum | Chikkodi | Chikkodi | 160262 | 10.00 | pipe | 7.00 | repair |
| 291 | BR:SH12:HUK205:165.85 | HUK205 | SH12 | Belgaum | Chikkodi | Hukkeri | 165847 | 10.00 | Slab | 7.00 | routine |
| 292 | BR:SH12:HUK205:172.11 | HUK205 | SH12 | Belgaum | Chikkodi | Hukkeri | 172102 | 8.00 | pipe | 17.90 | repair |
| 293 | BR:SH122:AUR20:15.01 | AUR20 | SH122 | Bidar | Bidar | Aurad | 15005 | 10.00 | pipe | 10.00 | repair |
| 294 | BR:SH122:AUR20:16.07 | AUR20 | SH122 | Bidar | Bidar | Aurad | 16065 | 10.00 | pipe | 11.50 | repair |
| 295 | BR:SH122:AUR20:18.62 | AUR20 | SH122 | Bidar | Bidar | Aurad | 18614 | 8.00 | Slab | 12.00 | repair |
| 296 | BR:SH122:AUR20:19.995 | AUR20 | SH122 | Bidar | Bidar | Aurad | 19991 | 8.00 | Slab | 9.00 | repair |
| 297 | BR:SH122:AUR20:23.645 | AUR20 | SH122 | Bidar | Bidar | Aurad | 23641 | 12.00 | Slab | 8.00 | routine |
| 298 | BR:SH122:AUR20:39.585 | AUR20 | SH122 | Bidar | Bidar | Aurad | 39573 | 12.00 | Slab | 24.00 | routine |
| 299 | BR:SH122:AUR20:44.295 | AUR20 | SH122 | Bidar | Bidar | Aurad | 44281 | 10.00 | Slab | 28.00 | routine |
| 300 | BR:SH122:AUR20:60.535 | AUR20 | SH122 | Bidar | Bidar | Aurad | 60245 | 9.00 | Girder | 581.90 | routine |
| 301 | BR:SH122:BID51:90.625 | BID51 | SH122 | Bidar | Bidar | Bidar | 90621 | 8.00 | pipe | 9.50 | repair |
| 302 | BR:SH122:BID51:90.745 | BID51 | SH122 | Bidar | Bidar | Bidar | 90730 | 8.50 | Slab | 30.00 | routine |
| 303 | BR:SH122:BID51:103.41 | BID51 | SH122 | Bidar | Bidar | Bidar | 103402 | 9.50 | Slab | 16.00 | routine |
| 304 | BR:SH122:BID51:106.13 | BID51 | SH122 | Bidar | Bidar | Bidar | 106116 | 8.00 | pipe | 29.50 | repair |
| 305 | BR:SH124:ALD201_A:14.81 | ALD201_A | SH124 | Gulbarga | Gulbarga | Aland | 14803 | 12.00 | Slab | 14.00 | routine |
| 306 | BR:SH124:ALD201_A:17.16 | ALD201_A | SH124 | Gulbarga | Gulbarga | Aland | 17143 | 8.00 | Slab | 35.00 | repair |
| 307 | BR:SH124:ALD201_A:21.7 | ALD201_A | SH124 | Gulbarga | Gulbarga | Aland | 21696 | 9.00 | Slab | 8.00 | repair |
| 308 | BR:SH124:ALD201_A:40.262 | ALD201_A | SH124 | Gulbarga | Gulbarga | Aland | 40259 | 10.00 | pipe | 7.00 | routine |
| 309 | BR:SH124:AFZ62:91.085 | AFZ62 | SH124 | Gulbarga | Gulbarga | Afzalpur | 91078 | 9.00 | Slab | 14.00 | routine |
| 310 | BR:SH124:AFZ62:111.345 | AFZ62 | SH124 | Gulbarga | Gulbarga | Afzalpur | 111339 | 10.00 | Slab | 12.00 | repair |
| 311 | BR:SH124:AFZ62:111.81 | AFZ62 | SH124 | Gulbarga | Gulbarga | Afzalpur | 111645 | 8.00 | Slab | 330.00 | routine |
| 312 | BR:SH124:MDD202:231.769 | MDD202 | SH124 | Bijapur | Bijapur | Muddebihal | 231764 | 7.50 | pipe | 11.50 | routine |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width,m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 313 | BR:SH124:BBV8:244.953 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 244948 | 7.50 | pipe | 11.50 | routine |
| 314 | BR:SH124:BBV8:247.573 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 247566 | 8.00 | Slab | 15.00 | repair |
| 315 | BR:SH124:BBV8:265.575 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 265571 | 12.00 | Slab | 9.00 | routine |
| 316 | BR:SH124:BBV8:265.695 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 265691 | 12.00 | Slab | 9.00 | routine |
| 317 | BR:SH124:BBV8:267.07 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 267060 | 12.00 | Slab | 21.00 | routine |
| 318 | BR:SH124:BBV8:283.13 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 283112 | 8.00 | pipe | 37.00 | repair |
| 319 | BR:SH124:BBV8:283.395 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 283391 | 8.00 | Slab | 9.00 | repair |
| 320 | BR:SH124:BBV8:284.59 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 284586 | 8.00 | Slab | 9.00 | repair |
| 321 | BR:SH124:BLG204:309.426 | BLG204 | SH124 | Bagalkot | Bagalkot | Bilgi | 309404 | 12.00 | Slab | 44.00 | routine |
| 322 | BR:SH124:BLG204:313.426 | BLG204 | SH124 | Bagalkot | Bagalkot | Bilgi | 313421 | 8.00 | pipe | 11.50 | repair |
| 323 | BR:SH124:BLG204:319.726 | BLG204 | SH124 | Bagalkot | Bagalkot | Bilgi | 319716 | 8.00 | pipe | 21.50 | repair |
| 324 | BR:SH125:CTR75:8.06 | CTR75 | SH125 | Gulbarga | Sedam | Chitapur | 8051 | 8.50 | Slab | 19.50 | routine |
| 325 | BR:SH125:CTR75:19.895 | CTR75 | SH125 | Gulbarga | Sedam | Chitapur | 19890 | 8.00 | Slab | 10.00 | repair |
| 326 | BR:SH125:CTR75:43.065 | CTR75 | SH125 | Gulbarga | Sedam | Chitapur | 43036 | 8.00 | pipe | 59.50 | repair |
| 327 | BR:SH125:CTR75:50.295 | CTR75 | SH125 | Gulbarga | Sedam | Chitapur | 50247 | 8.00 | Girder | 144.00 | repair |
| 328 | BR:SH125:CNL202:63.52 | CNL202 | SH125 | Gulbarga | Sedam | Chincholi | 63515 | 8.00 | Slab | 10.00 | repair |
| 329 | BR:SH125:CNL202:74.715 | CNL202 | SH125 | Gulbarga | Sedam | Chincholi | 74711 | 8.00 | Slab | 8.00 | repair |
| 330 | BR:SH125:CNL202:76.91 | CNL202 | SH125 | Gulbarga | Sedam | Chincholi | 76903 | 8.00 | Slab | 14.00 | repair |
| 331 | BR:SH125:CNL202:79.495 | CNL202 | SH125 | Gulbarga | Sedam | Chincholi | 79490 | 8.00 | Slab | 10.00 | repair |
| 332 | BR:SH125:GUL202:92.92 | GUL202 | SH125 | Gulbarga | Gulbarga | Gulbarga | 92915 | 8.00 | Slab | 10.00 | repair |
| 333 | BR:SH125:GUL202:102.625 | GUL202 | SH125 | Gulbarga | Gulbarga | Gulbarga | 102610 | 9.00 | Slab | 30.00 | routine |
| 334 | BR:SH127:SED202:5.27 | SED202 | SH127 | Gulbarga | Sedam | Sedam | 5261 | 9.00 | Slab | 18.00 | repair |
| 335 | BR:SH127:SED202:19.18 | SED202 | SH127 | Gulbarga | Sedam | Sedam | 19166 | 8.50 | Slab | 28.00 | routine |
| 336 | BR:SH127:YDG204:43.83 | YDG204 | SH127 | Yadgir | Yadgir | Yadgir | 43822 | 10.00 | Others | 17.50 | repair |
| 337 | BR:SH127:YDG204:47.33 | YDG204 | SH127 | Yadgir | Yadgir | Yadgir | 47316 | 8.50 | Slab | 28.00 | routine |
| 338 | BR:SH127:YDG204:47.95 | YDG204 | SH127 | Yadgir | Yadgir | Yadgir | 47940 | 8.50 | Slab | 21.00 | routine |
| 339 | BR:SH127:YDG204:58.531 | YDG204 | SH127 | Yadgir | Yadgir | Yadgir | 58464 | 7.00 | Pipe | 167.50 | repair |
| 340 | BR:SH127:SHA203:90.08 | SHA203 | SH127 | Yadgir | Yadgir | Shahpur | 89818 | 8.50 | Slab | 528.00 | routine |
| 341 | BR:SH127:SHA203:101.205 | SHA203 | SH127 | Yadgir | Yadgir | Shahpur | 101187 | 9.00 | Girder | 36.00 | routine |
| 342 | BR:SH127:SHA203:101.675 | SHA203 | SH127 | Yadgir | Yadgir | Shahpur | 101325 | 9.50 | Slab | 800.00 | routine |
| 343 | BR:SH127:DEV203:106.315 | DEV203 | SH127 | Raichur | Raichur | Devadurga | 106293 | 8.50 | Slab | 45.00 | routine |
| 344 | BR:SH127:DEV203:124.644 | DEV203 | SH127 | Raichur | Raichur | Devadurga | 124634 | 9.00 | Slab | 21.00 | routine |
| 345 | BR:SH127:DEV203:135.022 | DEV203 | SH127 | Raichur | Raichur | Devadurga | 135014 | 8.00 | Slab | 16.00 | routine |
| 346 | BR:SH127:MAN203:160.254 | MAN203 | SH127 | Raichur | Raichur | Manvi | 160251 | 10.00 | pipe | 7.00 | repair |
| 347 | BR:SH127:MAN203:176.844 | MAN203 | SH127 | Raichur | Raichur | Manvi | 176841 | 10.00 | Slab | 7.50 | routine |
| 348 | BR:SH127:MAN203:177.239 | MAN203 | SH127 | Raichur | Raichur | Manvi | 177236 | 10.00 | Slab | 7.00 | routine |
| 349 | BR:SH127:MAN203:178.354 | MAN203 | SH127 | Raichur | Raichur | Manvi | 178336 | 7.50 | pipe | 37.00 | repair |
| 350 | BR:SH127:RAI202:191.524 | RAI202 | SH127 | Raichur | Raichur | Raichur | 191521 | 10.00 | Slab | 7.00 | routine |
| 351 | BR:SH127:RAI202:195.729 | RAI202 | SH127 | Raichur | Raichur | Raichur | 195688 | 7.50 | Pipe | 76.50 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 352 | BR:SH127:RAI202:200.704 | RAI202 | SH127 | Raichur | Raichur | Raichur | 200666 | 8.50 | Slab | 73.50 | routine |
| 353 | BR:SH127:RAI202:208.069 | RAI202 | SH127 | Raichur | Raichur | Raichur | 208063 | 9.00 | Arch | 12.00 | repair |
| 354 | BR:SH127:RAI202:208.794 | RAI202 | SH127 | Raichur | Raichur | Raichur | 208786 | 8.00 | Slab | 17.50 | repair |
| 355 | BR:SH127:RAI202:209.139 | RAI202 | SH127 | Raichur | Raichur | Raichur | 209111 | 7.80 | Slab | 57.00 | repair |
| 356 | BR:SH127:RAI202:211.569 | RAI202 | SH127 | Raichur | Raichur | Raichur | 211562 | 8.00 | Arch | 15.00 | repair |
| 357 | BR:SH127:RAI202:213.774 | RAI202 | SH127 | Raichur | Raichur | Raichur | 213769 | 8.00 | Arch | 10.00 | repair |
| 358 | BR:SH127:RAI202:214.734 | RAI202 | SH127 | Raichur | Raichur | Raichur | 214727 | 8.00 | Arch | 15.00 | repair |
| 359 | BR:SH128:SRG47:182.39 | SRG47 | SH128 | Bellary | Bellary | Siruguppa | 182387 | 8.00 | Slab | 7.50 | repair |
| 360 | BR:SH128:BER10:191.79 | BER10 | SH128 | Bellary | Bellary | Bellary | 191774 | 7.50 | Pipe | 32.50 | repair |
| 361 | BR:SH128:BER10:192.335 | BER10 | SH128 | Bellary | Bellary | Bellary | 192326 | 4.50 | Steel Structure | 18.00 | routine |
| 362 | BR:SH128:BER10:203.29 | BER10 | SH128 | Bellary | Bellary | Bellary | 203280 | 8.50 | Slab | 21.00 | routine |
| 363 | BR:SH128:BER10:204.81 | BER10 | SH128 | Bellary | Bellary | Bellary | 204807 | 8.00 | Slab | 6.50 | routine |
| 364 | BR:SH128:BER10:209.555 | BER10 | SH128 | Bellary | Bellary | Bellary | 209549 | 8.00 | Slab | 12.00 | repair |
| 365 | BR:SH128:BER10:222.435 | BER10 | SH128 | Bellary | Bellary | Bellary | 222424 | 7.50 | Pipe | 23.50 | repair |
| 366 | BR:SH128:BER10:224.665 | BER10 | SH128 | Bellary | Bellary | Bellary | 224656 | 8.00 | Slab | 18.00 | repair |
| 367 | BR:SH128:BER10:227.97 | BER10 | SH128 | Bellary | Bellary | Bellary | 227964 | 10.00 | Slab | 12.00 | routine |
| 368 | BR:SH128:BER10:228.43 | BER10 | SH128 | Bellary | Bellary | Bellary | 228209 | 12.00 | Girder | 425.00 | routine |
| 369 | BR:SH128:BER10:231.245 | BER10 | SH128 | Bellary | Bellary | Bellary | 231223 | 10.00 | Slab | 44.00 | routine |
| 370 | BR:SH128:BER10:232.83 | BER10 | SH128 | Bellary. | Bellary | Bellary | 232825 | 7.50 | Pipe | 10.30 | routine |
| 371 | BR:SH128:BER10:233.02 | BER10 | SH128 | Bellary | Bellary | Bellary | 233010 | 12.00 | Slab | 20.00 | routine |
| 372 | BR:SH129:LIN36:20.715 | LIN36 | SH129 | Raichur | Raichur | Lingsugur | 20709 | 12.00 | Slab | 12.00 | routine |
| 373 | BR:SH129:LIN36:41.73 | LIN36 | SH129 | Raichur | Raichur | Lingsugur | 41717 | 8.00 | pipe | 27.10 | repair |
| 374 | BR:SH129:LIN36:49.595 | LIN36 | SH129 | Raichur | Raichur | Lingsugur | 49583 | 12.00 | Slab | 24.00 | routine |
| 375 | BR:SH129:LIN36:52.165 | LIN36 | SH129 | Raichur | Raichur | Lingsugur | 52128 | 8.00 | Pipe | 89.40 | repair |
| 376 | BR:SH129:KST209:64.485 | KST209 | SH129 | Koppal | Koppal | Kushtagi | 64463 | 8.50 | Slab | 44.00 | routine |
| 377 | BR:SH129:KST209:79.1 | KST209 | SH129 | Koppal | Koppal | Kushtagi | 79097 | 9.00 | Slab | 7.50 | repair |
| 378 | BR:SH129:MUI210:189.405 | MUI210 | SH129 | Gadag | Gadag | Mundargi | 189400 | 10.00 | Pipe | 10.70 | repair |
| 379 | BR:SH130:GAN95:55.375 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 55337 | 7.00 | Pipe | 74.90 | repair |
| 380 | BR:SH130:GAN95:60.46 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 60432 | 7.50 | pipe | 56.50 | repair |
| 381 | BR:SH130:GAN95:64.425 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 64397 | 8.50 | Slab | 56.00 | routine |
| 382 | BR:SH130:GAN95:67.19 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 67187 | 12.00 | Slab | 7.00 | routine |
| 383 | BR:SH130:GAN95:68.235 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 68199 | 8.50 | Slab | 78.30 | routine |
| 384 | BR:SH130:GAN95:74.865 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 74852 | 12.00 | Slab | 27.00 | routine |
| 385 | BR:SH130:GAN95:78.135 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 78131 | 12.00 | Slab | 8.00 | routine |
| 386 | BR:SH130:GAN95:94.35 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 94345 | 12.00 | Slab | 10.00 | routine |
| 387 | BR:SH130:KOP9:97.295 | KOP9 | SH130 | Koppal | Koppal | Koppal | 97289 | 8.00 | Slab | 13.20 | repair |
| 388 | BR:SH130:KOP9:99.195 | KOP9 | SH130 | Koppal | Koppal | Koppal | 99177 | 12.00 | Slab | 36.00 | routine |
| 389 | BR:SH130:KOP9:102.13 | KOP9 | SH130 | Koppal | Koppal | Koppal | 102120 | 12.00 | Slab | 21.00 | routine |
| 390 | BR:SH130:KOP9:106.405 | KOP9 | SH130 | Koppal | Koppal | Koppal | 106392 | 12.00 | Slab | 27.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width.m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 391 | BR:SH131:HSP202:5.6 | HSP202 | SH131 | Bellary | Bellary | Hospet | 5595 | 4.50 | Slab | 10.00 | routine |
| 392 | BR:SH131:HSP202:8.29 | HSP202 | SH131 | Bellary | Bellary | Hospet | 8278 | 4.50 | Slab | 24.00 | routine |
| 393 | BR:SH131:HSP202:16.5 | HSP202 | SH131 | Bellary | Bellary | Hospet | 16483 | 7.50 | Pipe | 35.50 | repair |
| 394 | BR:SH131:HSP202:21.115 | HSP202 | SH131 | Bellary | Bellary | Hospet | 21112 | 7.50 | Pipe | 7.00 | repair |
| 395 | BR:SH131:SNR35:33.335 | SNR35 | SH131 | Bellary | Bellary | Sandur | 33330 | 7.50 | Pipe | 10.70 | repair |
| 396 | BR:SH131:SNR35:45.695 | SNR35 | SH131 | Bellary | Bellary | Sandur | 45688 | 8.00 | Slab | 14.00 | repair |
| 397 | BR:SH131:SNR35:56.085 | SNR35 | SH131 | Bellary | Bellary | Sandur | 56071 | 8.00 | Slab | 28.00 | repair |
| 398 | BR:SH131:MOL201:80.01 | MOL201 | SH131 | Chitradurga | Chitradurga | Molakalmuru | 80007 | 7.50 | Slab | 7.50 | repair |
| 399 | BR:SH131:MOL201:93.26 | MOL201 | SH131 | Chitradurga | Chitradurga | Molakalmuru | 93257 | 8.50 | Slab | 6.50 | repair |
| 400 | BR:SH131:MOL201:93.94 | MOL201 | SH131 | Chitradurga | Chitradurga | Molakalmuru | 93936 | 8.00 | Slab | 8.00 | repair |
| 401 | BR:SH131:KDL44:104.37 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 104366 | 9.00 | Slab | 9.00 | repair |
| 402 | BR:SH131:KDL44:162.1 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 162087 | 7.50 | Pipe | 26.50 | routine |
| 403 | BR:SH131:KDL44:175.78 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 175765 | 10.00 | Slab | 30.00 | routine |
| 404 | BR:SH131:HGB61:190.055 | HGB61 | SH131 | Bellary | Hadagalli | Hagaribommanahalli | 190029 | 7.50 | Pipe | 52.70 | repair |
| 405 | BR:SH132:HSP18:4.345 | HSP18 | SH132 | Bellary | Bellary | Hospet | 4341 | 8.00 | Slab | 9.00 | repair |
| 406 | BR:SH132:BER19:7.47 | BER19 | SH132 | Bellary | Bellary | Bellary | 7442 | 8.50 | Girder | 56.00 | routine |
| 407 | BR:SH132:BER19:10.702 | BER19 | SH132 | Bellary | Bellary | Bellary | 10674 | 8.50 | Girder | 56.00 | routine |
| 408 | BR:SH132:BER19:42.337 | BER19 | SH132 | Bellary | Bellary | Bellary | 42325 | 7.00 | Slab | 24.00 | routine |
| 409 | BR:SH132:BER19:77.66 | BER19 | SH132 | Bellary | Bellary | Bellary | 77657 | 22.00 | Slab | 6.50 | routine |
| 410 | BR:SH132:BER19:78.105 | BER19 | SH132 | Bellary | Bellary | Bellary | 78101 | 22.00 | Slab | 8.00 | routine |
| 411 | BR:SH132:BER19:86.71 | BER19 | SH132 | Bellary | Bellary | Bellary | 86698 | 12.00 | Girder | 24.00 | routine |
| 412 | BR:SH132:BER19:87.147 | BER19 | SH132 | Bellary | Bellary | Bellary | 87141 | 10.00 | Slab | 12.00 | routine |
| 413 | BR:SH132:BER19:96.522 | BER19 | SH132 | Bellary | Bellary | Bellary | 96510 | 12.00 | Girder | 528.00 | routine |
| 414 | BR:SH132:BER19:96.812 | BER19 | SH132 | Bellary | Bellary | Bellary | 96764 | 12.00 | Girder | 96.00 | routine |
| 415 | BR:SH132:BER19:97.057 | BER19 | SH132 | Bellary | Bellary | Bellary | 97033 | 12.00 | Girder | 48.00 | routine |
| 416 | BR:SH132:BER19:97.407 | BER19 | SH132 | Bellary | Bellary | Bellary | 97395 | 12.00 | Girder | 24.00 | routine |
| 417 | BR:SH132:BER19:98.352 | BER19 | SH132 | Bellary | Bellary | Bellary | 98340 | 12.00 | Girder | 24.00 | routine |
| 418 | BR:SH132:BER19:99.897 | BER19 | SH132 | Bellary | Bellary | Bellary | 99894 | 12.00 | Slab | 7.00 | routine |
| 419 | BR:SH133:RMG203:1.955 | RMG203 | SH133 | Belgaum | Belgaum | Ramdurg | 1903 | 8.30 | Pipe | 132.50 | repair |
| 420 | BR:SH133:BDM206:19.22 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 19192 | 8.00 | pipe | 56.50 | repair |
| 421 | BR:SH133:BDM206:34.859 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 34853 | 7.50 | pipe | 13.00 | routine |
| 422 | BR:SH133:BDM206:36.314 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 36305 | 8.50 | Slab | 18.00 | routine |
| 423 | BR:SH133:BDM206:49.989 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 49976 | 8.00 | Slab | 27.00 | routine |
| 424 | BR:SH133:HUD209:87.283 | HUD209 | SH133 | Bagalkot | Bagalkot | Hungund | 87250 | 7.80 | Slab | 81.00 | repair |
| 425 | BR:SH133:HUD209:90.143 | HUD209 | SH133 | Bagalkot | Bagalkot | Hungund | 90112 | 8.00 | Pipe | 77.90 | repair |
| 426 | BR:SH134:RMG205:69.654 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 69651 | 8.00 | Slab | 6.50 | routine |
| 427 | BR:SH134:RMG205:70.084 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 70079 | 8.50 | Slab | 10.00 | routine |
| 428 | BR:SH134:GOK17:98.029 | GOK17 | SH134 | Belgaum | Chikkodi | Gokak | 98026 | 12.00 | Slab | 7.00 | routine |
| 429 | BR:SH134:GOK17:102.619 | GOK17 | SH134 | Belgaum | Chikkodi | Gokak | 102601 | 7.50 | pipe | 37.30 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len. (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 430 | BR:SH134:GOK17:106.679 | GOK17 | SH134 | Belgaum | Chikkodi | Gokak | 106661 | 7.50 | pipe | 37.30 | repair |
| 431 | BR:SH134:GOK17:107.059 | GOK17 | SH134 | Belgaum | Chikkodi | Gokak | 107042 | 7.50 | pipe | 34.60 | repair |
| 432 | BR:SH134:GOK17:116.834 | GOK17 | SH134 | Belgaum | Chikkodi | Gokak | 116809 | 8.00 | Girder | 50.00 | repair |
| 433 | BR:SH135:BDM207:22.305 | BDM207 | SH135 | Bagalkot | Bagalkot | Badami | 22272 | 12.00 | Slab | 64.80 | routine |
| 434 | BR:SH135:BGL201:59.889 | BGL201 | SH135 | Bagalkot | Bagalkot | Bagalkot | 59884 | 12.00 | Slab | 11.00 | routine |
| 435 | BR:SH136:RON78:18.13 | RON78 | SH136 | Gadag | Gadag | Ron | 18121 | 12.00 | Slab | 18.00 | routine |
| 436 | BR:SH136:RON78:24.545 | RON78 | SH136 | Gadag | Gadag | Ron | 24501 | 8.50 | Pipe | 95.50 | repair |
| 437 | BR:SH136:RON78:35.39 | RON78 | SH136 | Gadag | Gadag | Ron | 35326 | 8.50 | Girder | 127.70 | routine |
| 438 | BR:SH136:RON78:59.969 | RON78 | SH136 | Gadag | Gadag | Ron | 59965 | 10.00 | Pipe | 8.00 | repair |
| 439 | BR:SH136:RON78:65.539 | RON78 | SH136 | Gadag | Gadag | Ron | 65534 | 8.50 | Slab | 10.00 | repair |
| 440 | BR:SH136:GDG203:89.534 | GDG203 | SH136 | Gadag | Gadag | Gadag | 89508 | 8.00 | Pipe | 53.50 | repair |
| 441 | BR:SH136:GDG203:105.742 | GDG203 | SH136 | Gadag | Gadag | Gadag | 105735 | 8.00 | Pipe | 14.50 | repair |
| 442 | BR:SH136:GDG203:115.997 | GDG203 | SH136 | Gadag | Gadag | Gadag | 115989 | 12.00 | Slab | 16.00 | routine |
| 443 | BR:SH136:GDG203:116.737 | GDG203 | SH136 | Gadag | Gadag | Gadag | 116727 | 12.00 | Slab | 20.00 | routine |
| 444 | BR:SH136:GDG203:120.657 | GDG203 | SH136 | Gadag | Gadag | Gadag | 120649 | 12.00 | Slab | 17.60 | routine |
| 445 | BR:SH136:GDG203:121.677 | GDG203 | SH136 | Gadag | Gadag | Gadag | 121667 | 12.00 | Slab | 20.00 | routine |
| 446 | BR:SH136:SRT215:151.096 | SRT215 | SH136 | Gadag | Gadag | Shirahatti | 151092 | 8.00 | Pipe | 8.50 | repair |
| 447 | BR:SH136:MUI211:177.649 | MUI211 | SH136 | Gadag | Gadag | Mundargi | 177633 | 12.00 | Slab | 32.70 | routine |
| 448 | BR:SH136:MUI211:180.384 | MUI211 | SH136 | Gadag | Gadag | Mundargi | 180368 | 8.50 | Slab | 33.00 | routine |
| 449 | BR:SH136:SRT200:188.089 | SRT200 | SH136 | Gadag | Gadag | Shirahatti | 188071 | 12.00 | Slab | 37.80 | routine |
| 450 | BR:SH136:HVR219:212.516 | HVR219 | SH136 | Haveri | Haveri | Haveri | 212512 | 8.50 | Slab | 9.00 | routine |
| 451 | BR:SH136:HVR219:217.076 | HVR219 | SH136 | Haveri | Haveri | Haveri | 216986 | 8.50 | Girder | 180.00 | repair |
| 452 | BR:SH136:HVR219:223.686 | HVR219 | SH136 | Haveri | Haveri | Haveri | 223680 | 12.00 | Girder | 12.50 | routine |
| 453 | BR:SH136:HVR219:227.781 | HVR219 | SH136 | Haveri | Haveri | Haveri | 227770 | 8.50 | Girder | 23.50 | routine |
| 454 | BR:SH136:HVR219:233.086 | HVR219 | SH136 | Haveri | Haveri | Haveri | 233077 | 8.50 | Slab | 19.50 | repair |
| 455 | BR:SH136:BYD2:241.844 | BYD2 | SH136 | Haveri | Haveri | Byadagi | 241841 | 8.50 | Slab | 7.50 | repair |
| 456 | BR:SH136:BYD2:256.019 | BYD2 | SH136 | Haveri | Haveri | Byadagi | 256015 | 12.00 | Slab | 9.00 | routine |
| 457 | BR:SH137:NVG203:5.655 | NVG203 | SH137 | Dharwad | Dharwad | Navalgund | 5643 | 7.50 | Pipe | 24.80 | repair |
| 458 | BR:SH137:NVG203:6.905 | NVG203 | SH137 | Dharwad | Dharwad | Navalgund | 6901 | 8.00 | Slab | 9.00 | repair |
| 459 | BR:SH137:HBL201:40.541 | HBL201 | SH137 | Dharwad | Dharwad | Hubli | 40538 | 8.00 | Slab | 7.00 | repair |
| 460 | BR:SH137:HBL201:41.626 | HBL201 | SH137 | Dharwad | Dharwad | Hubli | 41606 | 8.50 | Slab | 40.00 | routine |
| 461 | BR:SH137:KNG202:68.945 | KNG202 | SH137 | Dharwad | Dharwad | Kundgol | 68932 | 7.50 | Pipe | 26.50 | repair |
| 462 | BR:SH137:SVN4:89.355 | SVN4 | SH137 | Haveri | Haveri | Savanur | 89348 | 8.00 | Pipe | 14.50 | repair |
| 463 | BR:SH137:HNL4:115.563 | HNL4 | SH137 | Haveri | Haveri | Hangal | 115559 | 8.00 | Pipe | 8.50 | repair |
| 464 | BR:SH137:SRS93:156.4 | SRS93 | SH137 | Uttara Kannada | Sirsi | Sirsi | 156392 | 8.50 | Slab | 16.00 | repair |
| 465 | BR:SH137:SRS93:166.77 | SRS93 | SH137 | Uttara Kannada | Sirsi | Sirsi | 166766 | 8.00 | Slab | 8.00 | repair |
| 466 | BR:SH137:SRS93:171.315 | SRS93 | SH137 | Uttara Kannada | Sirsi | Sirsi | 171295 | 8.50 | Slab | 40.00 | repair |
| 467 | BR:SH139:RMG204:7.525 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 7500 | 10.00 | Slab | 50.00 | routine |
| 468 | BR:SH139:RMG204:9.39 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 9380 | 8.50 | Slab | 20.00 | routine |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 469 | BR:SH139:RMG204:16.315 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 16310 | 8.00 | Slab | 10.00 | repair |
| 470 | BR:SH139:RMG204:27.905 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 27863 | 8.30 | Girder | 82.25 | repair |
| 471 | BR:SH139:RMG204:35.84 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 35831 | 12.00 | Slab | 18.00 | routine |
| 472 | BR:SH139:RMG204:37.445 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 37437 | 8.50 | Slab | 16.00 | routine |
| 473 | BR:SH139:RMG204:55.01 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 54987 | 7.50 | pipe | 47.80 | repair |
| 474 | BR:SH139:MDL203:79.735 | MDL203 | SH139 | Bagalkot | Bagalkot | Mudhol | 79730 | 10.00 | pipe | 10.70 | repair |
| 475 | BR:SH14:BDM2:31.78 | BDM2 | SH14 | Bagalkot | Bagalkot | Badami | 31767 | 8.00 | Slab | 27.00 | routine |
| 476 | BR:SH14:BDM2:34.28 | BDM2 | SH14 | Bagalkot | Bagalkot | Badami | 34274 | 8.00 | Slab | 12.00 | routine |
| 477 | BR:SH14:BDM2:35.565 | BDM2 | SH14 | Bagalkot | Bagalkot | Badami | 35558 | 8.00 | pipe | 15.50 | routine |
| 478 | BR:SH14:BDM2:36.985 | BDM2 | SH14 | Bagalkot | Bagalkot | Badami | 36978 | 8.00 | pipe | 14.50 | routine |
| 479 | BR:SH14:BDM2:41.621 | BDM2 | SH14 | Bagalkot | Bagalkot | Badami | 41614 | 8.00 | pipe | 15.50 | routine |
| 480 | BR:SH14:BDM2:59.908 | BDM2 | SH14 | Bagalkot | Bagalkot | Badami | 59905 | 8.00 | Slab | 7.00 | routine |
| 481 | BR:SH14:BDM2:63.107 | BDM2 | SH14 | Bagalkot | Bagalkot | Badami | 63103 | 8.00 | pipe | 9.50 | routine |
| 482 | BR:SH14:BDM2:63.287 | BDM2 | SH14 | Bagalkot | Bagalkot | Badami | 63224 | 8.20 | Girder | 124.20 | repair |
| 483 | BR:SH14:BDM2:67.692 | BDM2 | SH14 | Bagalkot | Bagalkot | Badami | 67643 | 8.00 | Slab | 104.50 | repair |
| 484 | BR:SH14:HUD3_B:110.602 | HUD3_B | SH14 | Bagalkot | Bagalkot | Hungund | 110558 | 8.50 | Girder | 98.80 | routine |
| 485 | BR:SH14:HUD3_B:111.707 | HUD3_B | SH14 | Bagalkot | Bagalkot | Hungund | 111704 | 12.00 | Slab | 7.00 | routine |
| 486 | BR:SH14:HUD3_B:116.212 | HUD3_B | SH14 | Bagalkot | Bagalkot | Hungund | 116157 | 8.00 | Slab | 102.00 | repair |
| 487 | BR:SH14:HUD3_B:118.112 | HUD3_B | SH14 | Bagalkot | Bagalkot | Hungund | 118096 | 8.00 | pipe | 32.00 | repair |
| 488 | BR:SH14:HUD3_B:127.22 | HUD3_B | SH14 | Bagalkot | Bagalkot | Hungund | 127185 | 8.00 | Pipe | 84.70 | repair |
| 489 | BR:SH14:LIN201:139.725 | LIN201 | SH14 | Raichur | Raichur | Lingsugur | 139714 | 12.00 | Slab | 22.00 | routine |
| 490 | BR:SH14:LIN201:151.482 | LIN201 | SH14 | Raichur | Raichur | Lingsugur | 151466 | 12.00 | Slab | 32.50 | routine |
| 491 | BR:SH14:LIN201:158.296 | LIN201 | SH14 | Raichur | Raichur | Lingsugur | 158278 | 7.50 | pipe | 37.00 | repair |
| 492 | BR:SH14:LIN201:168.006 | LIN201 | SH14 | Raichur | Raichur | Lingsugur | 167996 | 12.00 | Slab | 20.00 | routine |
| 493 | BR:SH14:MAN201:235.814 | MAN201 | SH14 | Raichur | Raichur | Manvi | 235804 | 8.50 | Slab | 21.00 | routine |
| 494 | BR:SH14:MAN201:239.154 | MAN201 | SH14 | Raichur | Raichur | Manvi | 239130 | 12.00 | Slab | 48.00 | routine |
| 495 | BR:SH148:TRT202_B:31 | TRT202_B | SH148 | Shimoga | Shimoga_special | Tirthahalli | 30995 | 12.00 | Slab | 10.00 | routine |
| 496 | BR:SH148:TRT202_B:32.265 | TRT202_B | SH148 | Shimoga | Shimoga_special | Tirthahalli | 32255 | 12.00 | Slab | 21.00 | routine |
| 497 | BR:SH148:TRT202_B:37.215 | TRT202_B | SH148 | Shimoga | Shimoga_special | Tirthahalli | 37203 | 12.00 | Slab | 24.00 | routine |
| 498 | BR:SH148:TRT202_B:47.8 | TRT202_B | SH148 | Shimoga | Shimoga_special | Tirthahalli | 47797 | 12.00 | Slab | 6.50 | routine |
| 499 | BR:SH148:SKR204:83.258 | SKR204 | SH148 | Shimoga | Shimoga | Shikaripur | 83255 | 7.50 | Pipe | 7.90 | repair |
| 500 | BR:SH148:SKR204:90.104 | SKR204 | SH148 | Shimoga | Shimoga | Shikaripur | 90100 | 10.00 | Slab | 8.00 | routine |
| 501 | BR:SH148:SKR204:91.004 | SKR204 | SH148 | Shimoga | Shimoga | Shikaripur | 90994 | 12.00 | Slab | 21.00 | routine |
| 502 | BR:SH148:SKR204:93.675 | SKR204 | SH148 | Shimoga | Shimoga | Shikaripur | 93648 | 12.00 | Girder | 54.00 | routine |
| 503 | BR:SH148:SKR204:106.75 | SKR204 | SH148 | Shimoga | Shimoga | Shikaripur | 106740 | 8.50 | Pipe | 20.50 | repair |
| 504 | BR:SH148:SKR204:117.875 | SKR204 | SH148 | Shimoga | Shimoga | Shikaripur | 117863 | 12.00 | Slab | 24.00 | routine |
| 505 | BR:SH149:SHA210:2.465 | SHA210 | SH149 | Yadgir | Yadgir | Shahpur | 2452 | 8.50 | Girder | 27.00 | routine |
| 506 | BR:SH149:SHA210:4.37 | SHA210 | SH149 | Yadgir | Yadgir | Shahpur | 4365 | 9.00 | Slab | 10.50 | repair |
| 507 | BR:SH149:SHA210:16.165 | SHA210 | SH149 | Yadgir | Yadgir | Shahpur | 16143 | 8.00 | Slab | 45.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 508 | BR:SH149:SHA210:19.3 | SHA210 | SH149 | Yadgir | Yadgir | Shahpur | 19287 | 8.50 | Girder | 26.00 | routine |
| 509 | BR:SH149:CTR202_A:19.745 | CTR202_A | SH149 | Gulbarga | Sedam | Chitapur | 19394 | 8.50 | Slab | 657.00 | routine |
| 510 | BR:SH149:CTR202_A:26.81 | CTR202_A | SH149 | Gulbarga | Sedam | Chitapur | 26786 | 8.00 | Slab | 48.00 | repair |
| 511 | BR:SH149:CTR202_A:27.7 | CTR202_A | SH149 | Gulbarga | Sedam | Chitapur | 27673 | 8.50 | Slab | 54.00 | routine |
| 512 | BR:SH149:GUL32:99.18 | GUL32 | SH149 | Gulbarga | Gulbarga | Gulbarga | 99172 | 10.00 | pipe | 16.30 | repair |
| 513 | BR:SH149:GUL32:107.31 | GUL32 | SH149 | Gulbarga | Gulbarga | Gulbarga | 107306 | 8.50 | Slab | 9.00 | routine |
| 514 | BR:SH149:GUL32:107.385 | GUL32 | SH149 | Gulbarga | Gulbarga | Gulbarga | 107381 | 8.50 | Slab | 9.00 | routine |
| 515 | BR:SH149:GUL32:110.56 | GUL32 | SH149 | Gulbarga | Gulbarga | Gulbarga | 110540 | 12.00 | Slab | 40.00 | routine |
| 516 | BR:SH149:CNL3:191.15 | CNL3 | SH149 | Gulbarga | Sedam | Chincholi | 191143 | 8.00 | Slab | 15.00 | repair |
| 517 | BR:SH149:CNL3:192.275 | CNL3 | SH149 | Gulbarga | Sedam | Chincholi | 192271 | 8.50 | Slab | 8.00 | repair |
| 518 | BR:SH15:AUR1:2.57 | AUR1 | SH15 | Bidar | Bidar | Aurad | 2565 | 12.50 | pipe | 10.00 | routine |
| 519 | BR:SH15:AUR1:4.05 | AUR1 | SH15 | Bidar | Bidar | Aurad | 4030 | 12.00 | Slab | 40.00 | routine |
| 520 | BR:SH15:AUR1:10.395 | AUR1 | SH15 | Bidar | Bidar | Aurad | 10382 | 12.00 | Slab | 27.00 | routine |
| 521 | BR:SH15:AUR1:15.54 | AUR1 | SH15 | Bidar | Bidar | Aurad | 15536 | 10.00 | Slab | 8.00 | routine |
| 522 | BR:SH15:AUR1:18.435 | AUR1 | SH15 | Bidar | Bidar | Aurad | 18431 | 8.00 | pipe | 9.50 | repair |
| 523 | BR:SH15:AUR1:29.805 | AUR1 | SH15 | Bidar | Bidar | Aurad | 29800 | 8.00 | Slab | 10.50 | repair |
| 524 | BR:SH15:BID2:32.845 | BID2 | SH15 | Bidar | Bidar | Bidar | 32683 | 8.50 | Girder | 323.00 | repair |
| 525 | BR:SH15:BID2:40.805 | BID2 | SH15 | Bidar | Bidar | Bidar | 40792 | 8.00 | Slab | 27.00 | repair |
| 526 | BR:SH15:BID2:42.91 | BID2 | SH15 | Bidar | Bidar | Bidar | 42905 | 8.00 | Slab | 10.00 | repair |
| 527 | BR:SH15:BID2:45.305 | BID2 | SH15 | Bidar | Bidar | Bidar | 45297 | 8.00 | pipe | 16.50 | repair |
| 528 | BR:SH15:BID2:58.382 | BID2 | SH15 | Bidar | Bidar | Bidar | 58369 | 12.00 | Slab | 27.00 | routine |
| 529 | BR:SH15:BID2:63.077 | BID2 | SH15 | Bidar | Bidar | Bidar | 63053 | 8.50 | Girder | 48.00 | routine |
| 530 | BR:SH15:BID2:74.092 | BID2 | SH15 | Bidar | Bidar | Bidar | 74003 | 8.50 | Girder | 177.45 | routine |
| 531 | BR:SH15:HUM3:79.932 | HUM3 | SH15 | Bidar | Bidar | Homnabad | 79926 | 10.00 | pipe | 13.50 | repair |
| 532 | BR:SH15:HUM3:80.607 | HUM3 | SH15 | Bidar | Bidar | Homnabad | 80604 | 10.00 | pipe | 7.00 | repair |
| 533 | BR:SH15:HUM3:81.487 | HUM3 | SH15 | Bidar | Bidar | Homnabad | 81481 | 8.00 | Slab | 12.00 | repair |
| 534 | BR:SH15:CNL1:98.472 | CNL1 | SH15 | Gulbarga | Sedam | Chincholi | 98450 | 9.00 | Slab | 45.00 | repair |
| 535 | BR:SH15:CNL1:105.039 | CNL1 | SH15 | Gulbarga | Sedam | Chincholi | 104973 | 8.10 | Slab | 124.20 | repair |
| 536 | BR:SH15:CNL1:110.609 | CNL1 | SH15 | Gulbarga | Sedam | Chincholi | 110510 | 8.00 | Girder | 197.20 | repair |
| 537 | BR:SH15:CNL1:128.818 | CNL1 | SH15 | Gulbarga | Sedam | Chincholi | 128806 | 8.00 | Slab | 24.00 | repair |
| 538 | BR:SH15:CNL1:130.273 | CNL1 | SH15 | Gulbarga | Sedam | Chincholi | 130266 | 8.00 | Slab | 15.00 | repair |
| 539 | BR:SH15:CNL1:137.113 | CNL1 | SH15 | Gulbarga | Sedam | Chincholi | 137106 | 8.00 | Slab | 15.00 | repair |
| 540 | BR:SH15:SED2:145.413 | SED2 | SH15 | Gulbarga | Sedam | Sedam | 145293 | 8.00 | Girder | 222.30 | repair |
| 541 | BR:SH15:SED2:149.978 | SED2 | SH15 | Gulbarga | Sedam | Sedam | 149942 | 8.10 | Slab | 69.00 | repair |
| 542 | BR:SH15:SED2:174.018 | SED2 | SH15 | Gulbarga | Sedam | Sedam | 174011 | 12.00 | Slab | 15.00 | routine |
| 543 | BR:SH15:YDG1:188.398 | YDG1 | SH15 | Yadgir | Yadgir | Yadgir | 188389 | 12.00 | Slab | 18.00 | routine |
| 544 | BR:SH15:YDG1:195.293 | YDG1 | SH15 | Yadgir | Yadgir | Yadgir | 195275 | 12.00 | Slab | 36.00 | routine |
| 545 | BR:SH15:YDG1:196.533 | YDG1 | SH15 | Yadgir | Yadgir | Yadgir | 196528 | 12.00 | Slab | 10.50 | routine |
| 546 | BR:SH15:YDG1:202.338 | YDG1 | SH15 | Yadgir | Yadgir | Yadgir | 202332 | 12.00 | Slab | 12.50 | routine |

Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl.No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width,m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 547 | BR:SH15:YDG1:206.818 | YDG1 | SH15 | Yadgir | Yadgir | Yadgir | 206814 | 12.00 | Slab | 8.00 | routine |
| 548 | BR:SH15:YDG1:207.108 | YDG1 | SH15 | Yadgir | Yadgir | Yadgir | 207073 | 8.50 | Girder | 62.50 | routine |
| 549 | BR:SH15:SHA206:217.93 | SHA206 | SH15 | Yadgir | Yadgir | Shahpur | 217927 | 12.00 | Slab | 6.50 | routine |
| 550 | BR:SH15:SHA206:220.67 | SHA206 | SH15 | Yadgir | Yadgir | Shahpur | 220666 | 12.00 | Slab | 9.00 | routine |
| 551 | BR:SH15:SHA206:222.3 | SHA206 | SH15 | Yadgir | Yadgir | Shahpur | 222296 | 12.00 | Slab | 8.00 | routine |
| 552 | BR:SH15:SHA206:224.265 | SHA206 | SH15 | Yadgir | Yadgir | Shahpur | 224251 | 8.50 | Slab | 28.00 | routine |
| 553 | BR:SH15:SHA206:259.515 | SHA206 | SH15 | Yadgir | Yadgir | Shahpur | 259245 | 8.20 | Girder | 540.00 | repair |
| 554 | BR:SH15:DEV1:262.73 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 262726 | 12.00 | Slab | 9.00 | routine |
| 555 | BR:SH15:DEV1:270.855 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 270851 | 12.00 | Slab | 8.00 | routine |
| 556 | BR:SH15:DEV1:273.835 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 273811 | 8.50 | pipe | 49.50 | routine |
| 557 | BR:SH15:DEV1:275.835 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 275830 | 12.00 | Slab | 11.00 | routine |
| 558 | BR:SH15:DEV1:278.125 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 278115 | 12.00 | Slab | 20.00 | routine |
| 559 | BR:SH15:DEV1:279.44 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 279428 | 12.00 | Slab | 24.00 | routine |
| 560 | BR:SH15:DEV1:281.245 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 281239 | 12.00 | Slab | 12.00 | routine |
| 561 | BR:SH15:DEV1:281.785 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 281781 | 12.00 | Slab | 8.00 | routine |
| 562 | BR:SH15:DEV1:282.34 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 282337 | 12.00 | Slab | 6.50 | routine |
| 563 | BR:SH15:DEV1:284.13 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 284121 | 12.00 | Slab | 18.00 | routine |
| 564 | BR:SH15:DEV1:286.58 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 286577 | 12.00 | Slab | 7.40 | routine |
| 565 | BR:SH15:DEV1:288.645 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 288633 | 12.00 | Slab | 25.00 | routine |
| 566 | BR:SH15:DEV1:289.935 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 289905 | 8.50 | Girder | 61.50 | routine |
| 567 | BR:SH15:DEV1:290.65 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 290647 | 12.00 | Slab | 7.40 | routine |
| 568 | BR:SH15:DEV1:292.015 | DEV1 | SH15 | Raichur | Raichur | Devadurga | 291995 | 12.00 | Girder | 40.00 | routine |
| 569 | BR:SH15:RAI3:301.05 | RAI3 | SH15 | Raichur | Raichur | Raichur | 301035 | 12.00 | Girder | 30.00 | routine |
| 570 | BR:SH15:RAI3:303.67 | RAI3 | SH15 | Raichur | Raichur | Raichur | 303662 | 12.00 | Slab | 16.00 | routine |
| 571 | BR:SH15:RAI3:306.66 | RAI3 | SH15 | Raichur | Raichur | Raichur | 306652 | 8.00 | Girder | 17.00 | routine |
| 572 | BR:SH154:SPT2:129.1 | SPT2 | SH154 | Mandya | Mandya | Srirangapattana | 129093 | 8.50 | Slab | 15.00 | repair |
| 573 | BR:SH154:SPT2:131.395 | SPT2 | SH154 | Mandya | Mandya | Srirangapattana | 131392 | 8.00 | Slab | 7.00 | repair |
| 574 | BR:SH154:SPT2:136.245 | SPT2 | SH154 | Mandya | Mandya | Srirangapattana | 136242 | 8.00 | Slab | 7.30 | repair |
| 575 | BR:SH154:SPT2:138.385 | SPT2 | SH154 | Mandya | Mandya | Srirangapattana | 138381 | 10.00 | Slab | 8.00 | repair |
| 576 | BR:SH154:SPT2:138.585 | SPT2 | SH154 | Mandya | Mandya | Srirangapattana | 138579 | 12.00 | Slab | 12.00 | repair |
| 577 | BR:SH16:SND2:8.57 | SND2 | SH16 | Bijapur | Bijapur | Sindgi | 8556 | 12.00 | Girder | 29.00 | routine |
| 578 | BR:SH16:SND2:13.28 | SND2 | SH16 | Bijapur | Bijapur | Sindgi | 13252 | 8.00 | Slab | 56.00 | routine |
| 579 | BR:SH16:SND2:13.895 | SND2 | SH16 | Bijapur | Bijapur | Sindgi | 13850 | 8.50 | Slab | 91.00 | repair |
| 580 | BR:SH16:SND2:23.17 | SND2 | SH16 | Bijapur | Bijapur | Sindgi | 23146 | 8.00 | Slab | 48.00 | repair |
| 581 | BR:SH16:SRP3:44.66 | SRP3 | SH16 | Yadgir | Yadgir | Shorapur | 44606 | 8.00 | Others | 105.30 | repair |
| 582 | BR:SH16:SRP3:52.205 | SRP3 | SH16 | Yadgir | Yadgir | Shorapur | 52196 | 8.50 | Slab | 18.00 | routine |
| 583 | BR:SH16:SHA205_B:62.035 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 62018 | 8.00 | Slab | 34.00 | routine |
| 584 | BR:SH16:SHA205_B:71.345 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 71337 | 8.00 | Slab | 16.00 | routine |
| 585 | BR:SH16:SHA205_B:78.475 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 78459 | 8.00 | Slab | 33.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 586 | BR:SH16:SHA205_B:84.035 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 84028 | 8.00 | Slab | 14.00 | routine |
| 587 | BR:SH16:SHA205_B:86.345 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 86342 | 12.00 | Slab | 7.00 | routine |
| 588 | BR:SH16:SHA205_B:88.075 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 88072 | 12.00 | Slab | 7.00 | routine |
| 589 | BR:SH16:SHA205_B:92.68 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 92677 | 12.00 | Slab | 7.00 | routine |
| 590 | BR:SH16:SHA205_B:93.775 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 93772 | 12.00 | Slab | 7.00 | routine |
| 591 | BR:SH16:SHA205_B:94.865 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 94854 | 12.00 | Slab | 22.50 | routine |
| 592 | BR:SH16:YDG202:126.625 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 126621 | 12.00 | Slab | 8.00 | routine |
| 593 | BR:SH16:YDG202:129.915 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 129911 | 12.00 | Slab | 8.00 | routine |
| 594 | BR:SH16:YDG202:130.52 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 130513 | 12.00 | Slab | 14.00 | routine |
| 595 | BR:SH16:YDG202:132.9 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 132882 | 12.00 | Slab | 36.00 | routine |
| 596 | BR:SH16:YDG202:138.385 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 138381 | 12.00 | Slab | 9.00 | routine |
| 597 | BR:SH16:YDG202:141.05 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 141043 | 12.00 | Slab | 14.00 | routine |
| 598 | BR:SH16:YDG202:141.925 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 141918 | 12.00 | Slab | 14.00 | routine |
| 599 | BR:SH16:YDG202:142.795 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 142777 | 12.00 | Slab | 36.00 | routine |
| 600 | BR:SH16:YDG202:151.39 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 151386 | 12.00 | Slab | 8.00 | routine |
| 601 | BR:SH16:YDG202:152.065 | YDG202 | SH16 | Yadgir | Yadgir | Yadgir | 152061 | 8.50 | Slab | 9.50 | routine |
| 602 | BR:SH18:MDL1:0.16 | MDL1 | SH18 | Bagalkot | Bagalkot | Mudhol | 153 | 6.50 | Slab | 14.00 | routine |
| 603 | BR:SH18:MDL1:3.055 | MDL1 | SH18 | Bagalkot | Bagalkot | Mudhol | 3031 | 7.50 | Slab | 48.00 | routine |
| 604 | BR:SH18:MDL1:5.16 | MDL1 | SH18 | Bagalkot | Bagalkot | Mudhol | 5145 | 6.50 | Arch | 30.00 | routine |
| 605 | BR:SH18:MDL1:8.48 | MDL1 | SH18 | Bagalkot | Bagalkot | Mudhol | 8465 | 6.50 | Arch | 30.00 | routine |
| 606 | BR:SH18:MDL1:15.06 | MDL1 | SH18 | Bagalkot | Bagalkot | Mudhol | 15051 | 6.50 | Arch | 18.00 | routine |
| 607 | BR:SH18:MDL1:23.115 | MDL1 | SH18 | Bagalkot | Bagalkot | Mudhol | 23106 | 6.50 | Arch | 18.00 | routine |
| 608 | BR:SH18:MDL1:27.01 | MDL1 | SH18 | Bagalkot | Bagalkot | Mudhol | 27006 | 6.50 | Arch | 9.00 | routine |
| 609 | BR:SH18:GOK202:31.95 | GOK202 | SH18 | Belgaum | Chikkodi | Gokak | 31940 | 7.50 | pipe | 21.90 | routine |
| 610 | BR:SH18:GOK202:32.945 | GOK202 | SH18 | Belgaum | Chikkodi | Gokak | 32939 | 6.50 | Steel Structure | 12.00 | routine |
| 611 | BR:SH18:GOK202:33.25 | GOK202 | SH18 | Belgaum | Chikkodi | Gokak | 33235 | 6.50 | Steel Structure | 30.00 | routine |
| 612 | BR:SH18:GOK202:37.33 | GOK202 | SH18 | Belgaum | Chikkodi | Gokak | 37324 | 6.50 | Arch | 12.00 | routine |
| 613 | BR:SH18:GOK202:37.46 | GOK202 | SH18 | Belgaum | Chikkodi | Gokak | 37440 | 6.50 | Arch | 40.00 | routine |
| 614 | BR:SH18:RBG1:43.305 | RBG1 | SH18 | Belgaum | Chikkodi | Raibag | 43298 | 6.50 | Arch | 14.00 | routine |
| 615 | BR:SH18:RBG1:45.52 | RBG1 | SH18 | Belgaum | Chikkodi | Raibag | 45513 | 6.50 | Arch | 14.00 | routine |
| 616 | BR:SH18:RBG1:46.5 | RBG1 | SH18 | Belgaum | Chikkodi | Raibag | 46493 | 6.50 | Arch | 14.00 | routine |
| 617 | BR:SH18:RBG1:48.275 | RBG1 | SH18 | Belgaum | Chikkodi | Raibag | 48266 | 6.50 | Slab | 18.00 | routine |
| 618 | BR:SH18:RBG1:49.655 | RBG1 | SH18 | Belgaum | Chikkodi | Raibag | 49637 | 6.50 | Arch | 36.00 | routine |
| 619 | BR:SH18:CKD3:57.595 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 57585 | 6.50 | Arch | 20.00 | routine |
| 620 | BR:SH18:CKD3:61.265 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 61245 | 6.50 | Arch | 40.00 | routine |
| 621 | BR:SH18:CKD3:63.062 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 63042 | 6.50 | Arch | 40.00 | routine |
| 622 | BR:SH18:CKD3:63.852 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 63849 | 6.50 | Slab | 7.00 | routine |
| 623 | BR:SH18:CKD3:79.777 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 79771 | 6.50 | Arch | 12.00 | routine |
| 624 | BR:SH18:CKD3:80.172 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 80166 | 6.50 | Arch | 12.00 | routine |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 625 | BR:SH18:CKD3:80.784 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 80769 | 20.00 | Slab | 30.00 | routine |
| 626 | BR:SH18:CKD3:83.419 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 83415 | 6.50 | Arch | 8.00 | routine |
| 627 | BR:SH18:CKD3:84.649 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 84643 | 6.50 | Arch | 12.00 | routine |
| 628 | BR:SH18:CKD3:86.014 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 86008 | 6.50 | Arch | 12.00 | routine |
| 629 | BR:SH18:CKD3:86.869 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 86865 | 6.50 | Arch | 8.00 | routine |
| 630 | BR:SH18:CKD3:87.004 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 86999 | 6.50 | Arch | 10.00 | routine |
| 631 | BR:SH18:CKD3:89.069 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 89063 | 6.50 | Arch | 12.00 | routine |
| 632 | BR:SH18:CKD3:89.614 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 89607 | 6.50 | Arch | 15.00 | routine |
| 633 | BR:SH18:CKD3:90.309 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 90300 | 6.50 | Arch | 18.00 | routine |
| 634 | BR:SH18:CKD3:91.369 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 91362 | 6.50 | Arch | 14.00 | routine |
| 635 | BR:SH18:CKD3:92.84 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 92831 | 6.50 | Arch | 18.00 | routine |
| 636 | BR:SH18:CKD3:97.77 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 97763 | 6.50 | Arch | 14.00 | routine |
| 637 | BR:SH18:CKD3:98.9 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 98890 | 12.00 | Slab | 20.00 | routine |
| 638 | BR:SH18:CKD3:102.675 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 102669 | 6.50 | Arch | 12.00 | routine |
| 639 | BR:SH18:CKD3:103.01 | CKD3 | SH18 | Belgaum | Chikkodi | Chikkodi | 103003 | 6.50 | Arch | 14.00 | routine |
| 640 | BR:SH2:SRS3:3.325 | SRS3 | SH2 | Uttara Kannada | Sirsi | Sirsi | 3317 | 8.00 | Slab | 16.00 | repair |
| 641 | BR:SH2:HNL2:43.87 | HNL2 | SH2 | Haveri | Haveri | Hangal | 43802 | 12.00 | Girder | 136.00 | routine |
| 642 | BR:SH2:HVR2:63.015 | HVR2 | SH2 | Haveri | Haveri | Haveri | 63011 | 8.00 | Slab | 8.00 | repair |
| 643 | BR:SH2:HVR2:63.685 | HVR2 | SH2 | Haveri | Haveri | Haveri | 63679 | 8.00 | Girder | 12.00 | repair |
| 644 | BR:SH2:HVR2:70.085 | HVR2 | SH2 | Haveri | Haveri | Haveri | 70078 | 7.50 | Slab | 15.00 | repair |
| 645 | BR:SH2:HVR2:79.4 | HVR2 | SH2 | Haveri | Haveri | Haveri | 79395 | 12.00 | Slab | 10.00 | routine |
| 646 | BR:SH2:HVR2:84.105 | HVR2 | SH2 | Haveri | Haveri | Haveri | 84102 | 12.00 | Slab | 6.60 | routine |
| 647 | BR:SH2:HDG204:88.235 | HDG204 | SH2 | Bellary | Hadagalli | Hadagalli | 88390 | 8.20 | Girder | 396.00 | repair |
| 648 | BR:SH2:HRP1:104.688 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 104680 | 8.50 | Pipe | 17.50 | repair |
| 649 | BR:SH2:HRP1:108.328 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 108317 | 12.00 | Slab | 22.50 | routine |
| 650 | BR:SH2:HRP1:114.593 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 114573 | 8.00 | Others | 40.00 | routine |
| 651 | BR:SH2:HRP1:121.903 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 121898 | 10.00 | Arch | 10.50 | repair |
| 652 | BR:SH2:HRP1:123.808 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 123805 | 10.00 | Slab | 6.80 | repair |
| 653 | BR:SH2:HRP1:124.268 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 124264 | 12.00 | Slab | 8.00 | routine |
| 654 | BR:SH2:HRP1:137.014 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 137007 | 10.00 | Pipe | 14.50 | repair |
| 655 | BR:SH2:HRP1:138.319 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 138314 | 10.00 | Pipe | 10.00 | repair |
| 656 | BR:SH2:HRP1:144.294 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 144289 | 11.00 | Slab | 10.00 | repair |
| 657 | BR:SH2:HRP1:146.249 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 146227 | 8.00 | Girder | 44.00 | repair |
| 658 | BR:SH2:KDL41:150.779 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 150737 | 8.00 | Girder | 95.20 | repair |
| 659 | BR:SH2:KDL41:152.859 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 152834 | 9.00 | Girder | 50.00 | repair |
| 660 | BR:SH2:KDL41:153.124 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 153120 | 10.00 | Slab | 8.00 | repair |
| 661 | BR:SH2:KDL41:153.229 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 153226 | 12.00 | Slab | 6.80 | repair |
| 662 | BR:SH2:KDL41:153.519 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 153516 | 12.50 | Pipe | 6.30 | repair |
| 663 | BR:SH2:KDL41:156.357 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 156354 | 8.00 | Slab | 6.60 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width in | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 664 | BR:SH2:KDL41:161.012 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 161004 | 12.00 | Slab | 16.00 | routine |
| 665 | BR:SH2:KDL41:170.772 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 170769 | 10.00 | Slab | 6.60 | repair |
| 666 | BR:SH2:KDL41:170.887 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 170878 | 10.00 | Slab | 18.00 | repair |
| 667 | BR:SH2:KDL41:175.712 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 175708 | 10.00 | Slab | 9.00 | repair |
| 668 | BR:SH2:KDL41:177.347 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 177342 | 12.50 | Pipe | 10.00 | repair |
| 669 | BR:SH2:KDL41:184.76 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 184755 | 10.00 | Pipe | 11.50 | repair |
| 670 | BR:SH2:KDL41:204.09 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 204081 | 8.50 | Pipe | 19.50 | repair |
| 671 | BR:SH2:KDL41:206.62 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 206608 | 10.00 | Slab | 24.00 | routine |
| 672 | BR:SH2:KDL41:209.595 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 209587 | 10.00 | Slab | 16.00 | repair |
| 673 | BR:SH2:KDL41:214.965 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 214948 | 7.50 | Pipe | 35.90 | repair |
| 674 | BR:SH2:MOL2:218.11 | MOL2 | SH2 | Chitradurga | Chitradurga | Molakalmuru | 218074 | 8.50 | Pipe | 73.00 | repair |
| 675 | BR:SH2:MOL2:222.68 | MOL2 | SH2 | Chitradurga | Chitradurga | Molakalmuru | 222674 | 10.00 | Slab | 12.00 | repair |
| 676 | BR:SH2:MOL2:224.825 | MOL2 | SH2 | Chitradurga | Chitradurga | Molakalmuru | 224821 | 12.50 | Pipe | 8.00 | routine |
| 676 | BR:SH20:RAI2:5.92 | RAI2 | SH20 | Raichur | Raichur | Raichur | 5912 | 12.00 | Slab | 16.00 | routine |
| 677 | BR:SH20:RAI2:6.85 | RAI2 | SH20 | Raichur | Raichur | Raichur | 6847 | 12.00 | Slab | 6.50 | routine |
| 678 | BR:SH20:RAI2:10.25 | RAI2 | SH20 | Raichur | Raichur | Raichur | 10241 | 9.00 | Girder | 18.00 | repair |
| 679 | BR:SH20:RAI2:13.71 | RAI2 | SH20 | Raichur | Raichur | Raichur | 13706 | 12.00 | Slab | 8.00 | routine |
| 680 | BR:SH20:RAI2:14.765 | RAI2 | SH20 | Raichur | Raichur | Raichur | 14761 | 12.00 | Slab | 9.00 | routine |
| 681 | BR:SH20:RAI2:15.27 | RAI2 | SH20 | Raichur | Raichur | Raichur | 15261 | 12.00 | Slab | 18.00 | routine |
| 682 | BR:SH20:RAI2:17.745 | RAI2 | SH20 | Raichur | Raichur | Raichur | 17741 | 10.00 | pipe | 8.00 | repair |
| 683 | BR:SH20:RAI2:19.835 | RAI2 | SH20 | Raichur | Raichur | Raichur | 19831 | 12.00 | Slab | 8.00 | routine |
| 684 | BR:SH20:MAN1_A:22.395 | MAN1_A | SH20 | Raichur | Raichur | Manvi | 22387 | 12.00 | Slab | 16.00 | routine |
| 685 | BR:SH20:MAN1_A:25.33 | MAN1_A | SH20 | Raichur | Raichur | Manvi | 25322 | 12.00 | Slab | 16.00 | routine |
| 686 | BR:SH20:MAN1_A:27.86 | MAN1_A | SH20 | Raichur | Raichur | Manvi | 27844 | 12.00 | Slab | 32.00 | routine |
| 687 | BR:SH20:MAN1_B:30.87 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 30849 | 12.00 | Girder | 43.50 | routine |
| 688 | BR:SH20:MAN1_B:31.73 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 31726 | 12.00 | Slab | 9.00 | routine |
| 689 | BR:SH20:MAN1_B:37.208 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 37198 | 10.00 | Slab | 20.00 | routine |
| 690 | BR:SH20:MAN1_B:41.598 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 41586 | 10.00 | Slab | 24.00 | routine |
| 691 | BR:SH20:MAN1_B:43.233 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 43224 | 12.00 | Slab | 18.00 | routine |
| 692 | BR:SH20:MAN1_B:46.677 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 46637 | 8.50 | Slab | 80.32 | routine |
| 693 | BR:SH20:MAN1_B:49.842 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 49834 | 12.00 | Slab | 16.00 | routine |
| 694 | BR:SH20:MAN1_B:54.357 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 54345 | 10.00 | Slab | 25.00 | routine |
| 695 | BR:SH20:MAN1_B:58.142 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 58133 | 12.00 | Slab | 18.00 | routine |
| 696 | BR:SH20:MAN1_B:58.962 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 58952 | 10.00 | Slab | 20.00 | routine |
| 697 | BR:SH20:MAN1_B:63.727 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 63723 | 12.00 | Slab | 9.00 | routine |
| 698 | BR:SH20:MAN1_B:64.392 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 64388 | 9.00 | Arch | 8.00 | repair |
| 699 | BR:SH20:MAN1_B:67.967 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 67958 | 10.00 | Slab | 18.00 | routine |
| 700 | BR:SH20:MAN1_B:69.132 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 69123 | 10.00 | Slab | 18.00 | routine |
| 701 | BR:SH20:MAN1_B:74.597 | MAN1_B | SH20 | Raichur | Raichur | Manvi | 74584 | 12.00 | Slab | 27.00 | routine |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width(m) | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 702 | BR:SH20:LIN2:84.857 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 84853 | 11.00 | Slab | 9.00 | routine |
| 703 | BR:SH20:LIN2:85.777 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 85752 | 9.00 | Slab | 50.00 | routine |
| 704 | BR:SH20:LIN2:86.332 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 86329 | 11.00 | Slab | 7.50 | routine |
| 705 | BR:SH20:LIN2:90.497 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 90494 | 11.00 | Slab | 7.50 | routine |
| 706 | BR:SH20:LIN2:97.877 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 97873 | 10.00 | Slab | 9.00 | routine |
| 707 | BR:SH20:LIN2:103.947 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 103933 | 8.00 | pipe | 29.50 | repair |
| 708 | BR:SH20:LIN2:109.062 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 109054 | 8.00 | pipe | 17.50 | repair |
| 709 | BR:SH20:LIN2:121.382 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 121377 | 9.00 | Slab | 10.00 | repair |
| 710 | BR:SH20:LIN2:124.512 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 124505 | 12.00 | Slab | 14.00 | repair |
| 711 | BR:SH20:HUD2:127.597 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 127588 | 12.00 | Slab | 18.00 | repair |
| 712 | BR:SH20:HUD2:129.692 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 129671 | 8.50 | Girder | 42.00 | repair |
| 713 | BR:SH20:HUD2:140.402 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 140353 | 8.50 | Girder | 94.15 | routine |
| 714 | BR:SH20:HUD2:145.946 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 145850 | 8.50 | Slab | 182.00 | repair |
| 715 | BR:SH20:HUD2:163.506 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 163499 | 12.00 | Slab | 14.00 | routine |
| 716 | BR:SH20:HUD2:166.216 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 166170 | 8.00 | Slab | 72.00 | repair |
| 717 | BR:SH20:HUD2:166.951 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 166947 | 12.00 | Slab | 9.00 | routine |
| 718 | BR:SH20:HUD2:179.071 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 178926 | 8.00 | Girder | 225.00 | repair |
| 719 | BR:SH20:BGL2:184.499 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 184496 | 12.00 | Slab | 7.00 | routine |
| 720 | BR:SH20:BGL2:190.784 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 190777 | 12.00 | Slab | 14.00 | routine |
| 721 | BR:SH20:BGL2:193.439 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 193421 | 12.00 | Slab | 36.00 | routine |
| 722 | BR:SH20:BGL2:195.479 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 195475 | 12.00 | Slab | 9.00 | routine |
| 723 | BR:SH20:BGL2:199.534 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 199437 | 12.00 | Girder | 195.00 | routine |
| 724 | BR:SH20:BGL2:214.615 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 214608 | 12.00 | Girder | 15.00 | routine |
| 725 | BR:SH20:BGL2:215.765 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 215761 | 12.00 | Slab | 9.00 | routine |
| 726 | BR:SH20:BGL2:218.14 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 218131 | 12.00 | Slab | 18.00 | routine |
| 727 | BR:SH20:BGL2:223.115 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 223111 | 12.00 | Slab | 9.00 | routine |
| 728 | BR:SH20:BGL2:223.305 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 223290 | 12.00 | Girder | 31.00 | routine |
| 729 | BR:SH20:BGL2:223.94 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 223928 | 12.00 | Girder | 25.00 | routine |
| 730 | BR:SH20:BGL2:225.65 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 225641 | 12.00 | Slab | 18.00 | routine |
| 731 | BR:SH20:BGL2:229.265 | BGL2 | SH20 | Bagalkot | Bagalkot | Bagalkot | 229258 | 12.00 | Slab | 14.00 | routine |
| 732 | BR:SH20:MDL3:231.165 | MDL3 | SH20 | Bagalkot | Bagalkot | Mudhol | 231132 | 8.00 | Pipe | 95.35 | repair |
| 733 | BR:SH20:MDL3:234.03 | MDL3 | SH20 | Bagalkot | Bagalkot | Mudhol | 234026 | 12.00 | Slab | 9.00 | routine |
| 734 | BR:SH20:MDL3:234.12 | MDL3 | SH20 | Bagalkot | Bagalkot | Mudhol | 234114 | 12.50 | pipe | 13.10 | routine |
| 735 | BR:SH20:MDL3:236.11 | MDL3 | SH20 | Bagalkot | Bagalkot | Mudhol | 236106 | 12.00 | Slab | 9.00 | routine |
| 736 | BR:SH20:MDL3:239.545 | MDL3 | SH20 | Bagalkot | Bagalkot | Mudhol | 239520 | 12.00 | Girder | 50.00 | routine |
| 737 | BR:SH20:MDL3:240.57 | MDL3 | SH20 | Bagalkot | Bagalkot | Mudhol | 240566 | 12.00 | Slab | 8.00 | routine |
| 738 | BR:SH20:MDL3:241.665 | MDL3 | SH20 | Bagalkot | Bagalkot | Mudhol | 241661 | 12.50 | pipe | 8.00 | routine |
| 739 | BR:SH20:MDL3:242.26 | MDL3 | SH20 | Bagalkot | Bagalkot | Mudhol | 242256 | 12.00 | Slab | 9.00 | routine |
| 740 | BR:SH20:MDL3:244.62 | MDL3 | SH20 | Bagalkot | Bagalkot | Mudhol | 244607 | 12.00 | Slab | 27.00 | routine |

Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 741 | BR:SH20:RMG2:253.035 | RMG2 | SH20 | Belgaum | Belgaum | Ramdurg | 253031 | 12.00 | Slab | 9.00 | routine |
| 742 | BR:SH20:RMG2:263.97 | RMG2 | SH20 | Belgaum | Belgaum | Ramdurg | 263966 | 12.00 | Slab | 9.00 | routine |
| 743 | BR:SH20:RMG2:266.565 | RMG2 | SH20 | Belgaum | Belgaum | Ramdurg | 266556 | 12.00 | Slab | 18.00 | routine |
| 744 | BR:SH20:RMG2:269.015 | RMG2 | SH20 | Belgaum | Belgaum | Ramdurg | 269008 | 12.00 | Girder | 15.00 | routine |
| 745 | BR:SH20:SAU2:275.05 | SAU2 | SH20 | Belgaum | Belgaum | Saundatti | 275022 | 12.00 | Slab | 56.00 | routine |
| 746 | BR:SH20:SAU2:275.555 | SAU2 | SH20 | Belgaum | Belgaum | Saundatti | 275540 | 12.00 | Girder | 30.00 | routine |
| 747 | BR:SH20:SAU2:278.31 | SAU2 | SH20 | Belgaum | Belgaum | Saundatti | 278304 | 12.00 | Girder | 12.00 | routine |
| 748 | BR:SH20:SAU2:290.985 | SAU2 | SH20 | Belgaum | Belgaum | Saundatti | 290981 | 12.00 | Slab | 9.00 | routine |
| 749 | BR:SH20:SAU2:292.345 | SAU2 | SH20 | Belgaum | Belgaum | Saundatti | 292341 | 12.00 | Slab | 9.00 | routine |
| 750 | BR:SH20:BAI2:306.314 | BAI2 | SH20 | Belgaum | Belgaum | Bailhongal | 306307 | 12.00 | Girder | 15.00 | routine |
| 751 | BR:SH20:BAI2:307.809 | BAI2 | SH20 | Belgaum | Belgaum | Bailhongal | 307803 | 12.00 | Girder | 12.00 | routine |
| 752 | BR:SH20:BAI2:308.864 | BAI2 | SH20 | Belgaum | Belgaum | Bailhongal | 308852 | 12.00 | Girder | 24.00 | routine |
| 753 | BR:SH20:BAI2:313.244 | BAI2 | SH20 | Belgaum | Belgaum | Bailhongal | 313238 | 12.00 | Slab | 12.00 | routine |
| 754 | BR:SH20:BAI2:317.799 | BAI2 | SH20 | Belgaum | Belgaum | Bailhongal | 317781 | 12.00 | Girder | 36.00 | routine |
| 755 | BR:SH20:BGM3:326.154 | BGM3 | SH20 | Belgaum | Belgaum | Belgaum | 326146 | 12.00 | Slab | 16.00 | routine |
| 756 | BR:SH20:BGM3:329.424 | BGM3 | SH20 | Belgaum | Belgaum | Belgaum | 329409 | 12.00 | Girder | 30.00 | routine |
| 757 | BR:SH20:BGM3:332.274 | BGM3 | SH20 | Belgaum | Belgaum | Belgaum | 332259 | 12.00 | Girder | 30.00 | routine |
| 758 | BR:SH20:BGM3:337.959 | BGM3 | SH20 | Belgaum | Belgaum | Belgaum | 337941 | 12.00 | Slab | 36.00 | routine |
| 759 | BR:SH20:BGM3:348.791 | BGM3 | SH20 | Belgaum | Belgaum | Belgaum | 348780 | 8.00 | Slab | 22.00 | repair |
| 760 | BR:SH20:BGM3:351.941 | BGM3 | SH20 | Belgaum | Belgaum | Belgaum | 351925 | 8.00 | Girder | 32.00 | repair |
| 761 | BR:SH21:BLR4:6.16 | BLR4 | SH21 | Hassan | Hassan | Belur | 6156 | 12.00 | Slab | 8.50 | routine |
| 762 | BR:SH21:BLR4:12.445 | BLR4 | SH21 | Hassan | Hassan | Belur | 12441 | 12.00 | Slab | 8.00 | routine |
| 763 | BR:SH21:HSS2:24.503 | HSS2 | SH21 | Hassan | Hassan | Hassan | 24498 | 8.00 | Slab | 10.00 | repair |
| 764 | BR:SH21:HSS2:30.778 | HSS2 | SH21 | Hassan | Hassan | Hassan | 30770 | 25.00 | Slab | 17.00 | routine |
| 765 | BR:SH21:HSS2:31.113 | HSS2 | SH21 | Hassan | Hassan | Hassan | 31109 | 26.00 | Slab | 8.00 | routine |
| 766 | BR:SH21:HSS2:47.063 | HSS2 | SH21 | Hassan | Hassan | Hassan | 47060 | 12.00 | Slab | 6.50 | routine |
| 767 | BR:SH21:HSS2:47.238 | HSS2 | SH21 | Hassan | Hassan | Hassan | 47235 | 12.00 | Slab | 6.50 | routine |
| 768 | BR:SH21:HSS2:53.803 | HSS2 | SH21 | Hassan | Hassan | Hassan | 53792 | 8.50 | Girder | 22.50 | repair |
| 769 | BR:SH21:ARK1:56.373 | ARK1 | SH21 | Hassan | Hassan_Special | Arkalgud | 56369 | 8.50 | Slab | 9.00 | repair |
| 770 | BR:SH21:ARK1:65.743 | ARK1 | SH21 | Hassan | Hassan_Special | Arkalgud | 65740 | 12.00 | Slab | 6.50 | repair |
| 771 | BR:SH21:ARK1:71.623 | ARK1 | SH21 | Hassan | Hassan_Special | Arkalgud | 71617 | 9.00 | Slab | 12.00 | repair |
| 772 | BR:SH21:ARK1:76.273 | ARK1 | SH21 | Hassan | Hassan_Special | Arkalgud | 76268 | 8.50 | Slab | 11.00 | repair |
| 773 | BR:SH21:ARK1:76.803 | ARK1 | SH21 | Hassan | Hassan_Special | Arkalgud | 76799 | 12.00 | Slab | 8.20 | repair |
| 774 | BR:SH21:ARK1:81.018 | ARK1 | SH21 | Hassan | Hassan_Special | Arkalgud | 81013 | 8.50 | Slab | 10.00 | repair |
| 775 | BR:SH21:ARK1:85.248 | ARK1 | SH21 | Hassan | Hassan_Special | Arkalgud | 85244 | 8.50 | Slab | 8.00 | routine |
| 776 | BR:SH21:PRP2:90.413 | PRP2 | SH21 | Mysore | Hunsur | Piriyapatna | 90408 | 12.00 | Slab | 10.00 | routine |
| 777 | BR:SH21:PRP2:104.63 | PRP2 | SH21 | Mysore | Hunsur | Piriyapatna | 104627 | 8.50 | pipe | 7.00 | repair |
| 778 | BR:SH21:PRP2:112.115 | PRP2 | SH21 | Mysore | Hunsur | Piriyapatna | 112104 | 12.00 | Slab | 22.00 | routine |
| 779 | BR:SH22:AFZ1:56.453 | AFZ1 | SH22 | Gulbarga | Gulbarga | Afzalpur | 56433 | 12.00 | Girder | 40.00 | routine |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 780 | BR:SH22:AFZ1:59.833 | AFZ1 | SH22 | Gulbarga | Gulbarga | Afzalpur | 59828 | 12.00 | Slab | 11.00 | routine |
| 781 | BR:SH22:AFZ1:64.268 | AFZ1 | SH22 | Gulbarga | Gulbarga | Afzalpur | 64264 | 12.00 | Slab | 9.00 | routine |
| 782 | BR:SH22:AFZ1:65.128 | AFZ1 | SH22 | Gulbarga | Gulbarga | Afzalpur | 65067 | 12.00 | Girder | 122.50 | routine |
| 783 | BR:SH23:MAN2:5.93 | MAN2 | SH23 | Raichur | Raichur | Manvi | 5917 | 12.00 | Slab | 27.00 | routine |
| 784 | BR:SH23:MAN2:8.125 | MAN2 | SH23 | Raichur | Raichur | Manvi | 8107 | 12.00 | Slab | 36.00 | routine |
| 785 | BR:SH23:MAN2:11.355 | MAN2 | SH23 | Raichur | Raichur | Manvi | 11346 | 12.00 | Slab | 18.00 | routine |
| 786 | BR:SH23:MAN2:18.35 | MAN2 | SH23 | Raichur | Raichur | Manvi | 18320 | 12.00 | Girder | 62.40 | routine |
| 787 | BR:SH23:MAN2:22.555 | MAN2 | SH23 | Raichur | Raichur | Manvi | 22525 | 12.00 | Girder | 62.40 | routine |
| 788 | BR:SH23:MAN2:31.73 | MAN2 | SH23 | Raichur | Raichur | Manvi | 31703 | 9.00 | Slab | 55.00 | repair |
| 789 | BR:SH23:MAN2:33.44 | MAN2 | SH23 | Raichur | Raichur | Manvi | 33431 | 12.00 | Slab | 18.00 | routine |
| 790 | BR:SH23:MAN2:41.262 | MAN2 | SH23 | Raichur | Raichur | Manvi | 41244 | 12.00 | Slab | 36.00 | routine |
| 791 | BR:SH23:MAN2:42.267 | MAN2 | SH23 | Raichur | Raichur | Manvi | 42215 | 12.00 | Girder | 109.20 | routine |
| 792 | BR:SH23:MAN2:48.777 | MAN2 | SH23 | Raichur | Raichur | Manvi | 48767 | 12.00 | Slab | 21.00 | routine |
| 793 | BR:SH23:MAN2:52.247 | MAN2 | SH23 | Raichur | Raichur | Manvi | 52219 | 12.00 | Slab | 56.00 | routine |
| 794 | BR:SH23:MAN2:55.517 | MAN2 | SH23 | Raichur | Raichur | Manvi | 55508 | 12.00 | Slab | 18.00 | routine |
| 795 | BR:SH23:MAN2:56.487 | MAN2 | SH23 | Raichur | Raichur | Manvi | 56403 | 12.00 | Girder | 218.40 | routine |
| 796 | BR:SH23:SIN1:60.207 | SIN1 | SH23 | Raichur | Raichur | Sindhnur | 60183 | 12.00 | Girder | 48.00 | routine |
| 797 | BR:SH23:SIN1:73.012 | SIN1 | SH23 | Raichur | Raichur | Sindhnur | 72996 | 12.00 | Slab | 32.00 | routine |
| 798 | BR:SH23:SIN1:89.532 | SIN1 | SH23 | Raichur | Raichur | Sindhnur | 89504 | 12.00 | Girder | 56.00 | routine |
| 799 | BR:SH23:SIN1:90.012 | SIN1 | SH23 | Raichur | Raichur | Sindhnur | 90008 | 12.00 | Slab | 8.00 | routine |
| 800 | BR:SH23:SIN1:90.537 | SIN1 | SH23 | Raichur | Raichur | Sindhnur | 90533 | 12.00 | Slab | 8.00 | routine |
| 801 | BR:SH23:SIN1:95.942 | SIN1 | SH23 | Raichur | Raichur | Sindhnur | 95928 | 12.00 | Slab | 28.00 | routine |
| 802 | BR:SH23:GAN92:99.212 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 99205 | 12.00 | Slab | 14.00 | routine |
| 803 | BR:SH23:GAN92:103.577 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 103573 | 12.00 | Slab | 9.00 | routine |
| 804 | BR:SH23:GAN92:104.397 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 104388 | 12.00 | Slab | 18.00 | routine |
| 805 | BR:SH23:GAN92:108.062 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 108055 | 12.00 | Slab | 14.00 | routine |
| 806 | BR:SH23:GAN92:110.477 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 110470 | 12.00 | Slab | 14.00 | routine |
| 807 | BR:SH23:GAN92:110.922 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 110919 | 12.00 | pipe | 7.90 | routine |
| 808 | BR:SH23:GAN92:111.542 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 111452 | 12.00 | Girder | 187.20 | routine |
| 809 | BR:SH23:GAN92:112.897 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 112879 | 12.00 | Slab | 36.00 | routine |
| 810 | BR:SH23:GAN92:121.867 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 121811 | 12.00 | Girder | 117.95 | routine |
| 811 | BR:SH23:GAN92:134.806 | GAN92 | SH23 | Koppal | Koppal | Gangawati | 134793 | 8.00 | Girder | 27.00 | repair |
| 812 | BR:SH23:KOP3:154.542 | KOP3 | SH23 | Koppal | Koppal | Koppal | 154524 | 12.00 | Slab | 36.00 | routine |
| 813 | BR:SH23:KOP3:157.172 | KOP3 | SH23 | Koppal | Koppal | Koppal | 157167 | 12.00 | Slab | 11.00 | routine |
| 814 | BR:SH23:KOP3:159.892 | KOP3 | SH23 | Koppal | Koppal | Koppal | 159887 | 12.00 | Slab | 11.00 | routine |
| 815 | BR:SH23:KOP3:161.762 | KOP3 | SH23 | Koppal | Koppal | Koppal | 161757 | 12.00 | Slab | 11.00 | routine |
| 816 | BR:SH23:KOP3:168.222 | KOP3 | SH23 | Koppal | Koppal | Koppal | 168216 | 8.00 | Slab | 12.00 | repair |
| 817 | BR:SH23:KOP3:182.393 | KOP3 | SH23 | Koppal | Koppal | Koppal | 182348 | 12.00 | Girder | 100.20 | routine |
| 818 | BR:SH23:KOP3:182.833 | KOP3 | SH23 | Koppal | Koppal | Koppal | 182817 | 12.00 | Slab | 32.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 819 | BR:SH23:KOP3:184.813 | KOP3 | SH23 | Koppal | Koppal | Koppal | 184808 | 10.00 | pipe | 10.00 | repair |
| 820 | BR:SH23:KOP3:190.893 | KOP3 | SH23 | Koppal | Koppal | Koppal | 190885 | 8.00 | pipe | 16.50 | repair |
| 821 | BR:SH23:KOP3:197.203 | KOP3 | SH23 | Koppal | Koppal | Koppal | 197181 | 8.00 | pipe | 44.30 | repair |
| 822 | BR:SH23:KOP3:197.848 | KOP3 | SH23 | Koppal | Koppal | Koppal | 197792 | 8.00 | Pipe | 161.10 | repair |
| 823 | BR:SH23:KOP3:201.248 | KOP3 | SH23 | Koppal | Koppal | Koppal | 201217 | 8.00 | Pipe | 67.60 | repair |
| 824 | BR:SH23:MUI208:212.623 | MUI208 | SH23 | Gadag | Gadag | Mundargi | 212609 | 7.50 | Pipe | 29.50 | repair |
| 825 | BR:SH23:MUI208:217.223 | MUI208 | SH23 | Gadag | Gadag | Mundargi | 217211 | 12.00 | Slab | 25.00 | routine |
| 826 | BR:SH23:MUI208:228.153 | MUI208 | SH23 | Gadag | Gadag | Mundargi | 228136 | 7.50 | Pipe | 34.50 | repair |
| 827 | BR:SH23:SRT202:236.448 | SRT202 | SH23 | Gadag | Gadag | Shirahatti | 236444 | 8.00 | Slab | 8.00 | repair |
| 828 | BR:SH23:SRT202:248.633 | SRT202 | SH23 | Gadag | Gadag | Shirahatti | 248609 | 7.50 | Pipe | 49.50 | repair |
| 829 | BR:SH23:SRT202:255.283 | SRT202 | SH23 | Gadag | Gadag | Shirahatti | 255280 | 10.00 | Pipe | 7.00 | repair |
| 830 | BR:SH23:KNG201:280.294 | KNG201 | SH23 | Dharwad | Dharwad | Kundgol | 280288 | 10.00 | Pipe | 13.10 | routine |
| 831 | BR:SH23:SIG206_B:299.979 | SIG206_B | SH23 | Haveri | Haveri | Shiggaon | 299954 | 12.00 | Slab | 50.40 | routine |
| 832 | BR:SH23:SIG206_B:300.624 | SIG206_B | SH23 | Haveri | Haveri | Shiggaon | 300617 | 7.50 | Pipe | 14.50 | repair |
| 833 | BR:SH24:TRK3:0.815 | TRK3 | SH24 | Chikmagalur | Chikmagalur | Tarikere | 811 | 9.00 | Slab | 8.00 | repair |
| 834 | BR:SH24:TRK3:2.855 | TRK3 | SH24 | Chikmagalur | Chikmagalur | Tarikere | 2847 | 8.00 | Slab | 16.00 | repair |
| 835 | BR:SH24:TRK3:12.92 | TRK3 | SH24 | Chikmagalur | Chikmagalur | Tarikere | 12912 | 8.50 | pipe | 17.50 | repair |
| 836 | BR:SH24:TRK3:25.789 | TRK3 | SH24 | Chikmagalur | Chikmagalur | Tarikere | 25771 | 8.50 | Girder | 37.50 | routine |
| 837 | BR:SH24:TRK3:27.334 | TRK3 | SH24 | Chikmagalur | Chikmagalur | Tarikere | 27327 | 9.00 | Slab | 15.00 | repair |
| 838 | BR:SH24:TRK3:27.674 | TRK3 | SH24 | Chikmagalur | Chikmagalur | Tarikere | 27669 | 12.00 | Slab | 11.00 | routine |
| 839 | BR:SH24:TRK3:31.083 | TRK3 | SH24 | Chikmagalur | Chikmagalur | Tarikere | 31079 | 10.00 | Pipe | 9.70 | repair |
| 840 | BR:SH24:HSD2:35.693 | HSD2 | SH24 | Chitradurga | Chitradurga | Hosdurga | 35689 | 12.50 | Pipe | 9.70 | routine |
| 841 | BR:SH24:HSD2:40.358 | HSD2 | SH24 | Chitradurga | Chitradurga | Hosdurga | 40341 | 10.00 | Pipe | 35.20 | repair |
| 842 | BR:SH24:HSD2:41.788 | HSD2 | SH24 | Chitradurga | Chitradurga | Hosdurga | 41784 | 8.50 | Pipe | 9.70 | repair |
| 843 | BR:SH24:HSD2:46.563 | HSD2 | SH24 | Chitradurga | Chitradurga | Hosdurga | 46558 | 12.50 | Pipe | 11.40 | routine |
| 844 | BR:SH24:HSD2:50.341 | HSD2 | SH24 | Chitradurga | Chitradurga | Hosdurga | 50337 | 8.50 | Slab | 9.60 | repair |
| 845 | BR:SH24:HSD2:55.591 | HSD2 | SH24 | Chitradurga | Chitradurga | Hosdurga | 55587 | 9.00 | Slab | 9.00 | repair |
| 846 | BR:SH24:HSD2:59.026 | HSD2 | SH24 | Chitradurga | Chitradurga | Hosdurga | 59009 | 8.50 | Pipe | 34.50 | repair |
| 847 | BR:SH24:HSD2:66.82 | HSD2 | SH24 | Chitradurga | Chitradurga | Hosdurga | 66803 | 8.50 | Pipe | 34.50 | repair |
| 848 | BR:SH24:HRY3:94.793 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 94787 | 12.00 | Slab | 12.00 | routine |
| 849 | BR:SH24:HRY3:97.338 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 97313 | 12.00 | Slab | 50.00 | routine |
| 850 | BR:SH24:HRY3:115.328 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 115274 | 7.00 | Girder | 144.00 | repair |
| 851 | BR:SH24:HRY3:122.858 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 122849 | 12.00 | Slab | 18.00 | routine |
| 852 | BR:SH24:HRY3:125.683 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 125679 | 10.00 | Pipe | 9.70 | repair |
| 853 | BR:SH24:HRY3:131.053 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 131048 | 12.00 | Slab | 10.20 | routine |
| 854 | BR:SH24:HRY3:132.763 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 132746 | 12.00 | Girder | 34.80 | routine |
| 855 | BR:SH25:HSP3:0.195 | HSP3 | SH25 | Bellary | Bellary | Hospet | 178 | 8.00 | Girder | 35.00 | repair |
| 856 | BR:SH25:HDG1:56.043 | HDG1 | SH25 | Bellary | Hadagalli | Hadagalli | 56016 | 8.00 | Girder | 55.20 | repair |
| 857 | BR:SH25:HRP2:64.808 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 64804 | 12.00 | Slab | 8.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 858 | BR:SH25:HRP2:69.263 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 69260 | 12.00 | Slab | 6.50 | routine |
| 859 | BR:SH25:HRP2:71.499 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 71492 | 11.00 | Slab | 14.00 | repair |
| 860 | BR:SH25:HRP2:71.714 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 71710 | 12.00 | Slab | 8.00 | repair |
| 861 | BR:SH25:HRP2:72.174 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 72170 | 12.00 | Slab | 8.00 | routine |
| 862 | BR:SH25:HRP2:92.189 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 92185 | 8.00 | Slab | 9.00 | repair |
| 863 | BR:SH25:HRP2:96.414 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 96408 | 8.00 | Girder | 12.00 | repair |
| 864 | BR:SH25:HRP2:99.114 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 99100 | 8.00 | Slab | 28.80 | repair |
| 865 | BR:SH25:HRP2:101.039 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 101035 | 12.00 | Slab | 8.00 | routine |
| 866 | BR:SH25:HRP2:105.099 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 105087 | 12.00 | Slab | 24.00 | routine |
| 867 | BR:SH25:HRR3:111.624 | HRR3 | SH25 | Davanagere | Davanagere | Harihar | 111616 | 8.00 | Slab | 16.00 | repair |
| 868 | BR:SH25:HRR3:112.754 | HRR3 | SH25 | Davanagere | Davanagere | Harihar | 112750 | 8.50 | Slab | 9.00 | repair |
| 869 | BR:SH25:HRR3:120.847 | HRR3 | SH25 | Davanagere | Davanagere | Harihar | 120842 | 8.50 | Slab | 10.00 | routine |
| 870 | BR:SH25:HRR3:122.147 | HRR3 | SH25 | Davanagere | Davanagere | Harihar | 122144 | 10.00 | Slab | 6.20 | routine |
| 871 | BR:SH25:HRR3:122.387 | HRR3 | SH25 | Davanagere | Davanagere | Harihar | 122379 | 12.00 | Slab | 16.00 | routine |
| 872 | BR:SH25:HRR3:126.457 | HRR3 | SH25 | Davanagere | Davanagere | Harihar | 126416 | 7.00 | Girder | 72.00 | repair |
| 873 | BR:SH25:HNN1:144.142 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 144135 | 12.00 | Slab | 15.00 | routine |
| 874 | BR:SH25:HNN1:154.217 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 154060 | 6.00 | Arch | 315.00 | routine |
| 875 | BR:SH25:HNN1:160.624 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 160619 | 5.00 | Arch | 11.00 | routine |
| 876 | BR:SH25:HNN1:160.626 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 160621 | 12.00 | Slab | 11.00 | routine |
| 877 | BR:SH25:HNN1:162.311 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 162308 | 8.00 | Girder | 7.00 | repair |
| 878 | BR:SH25:HNN1:163.491 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 163467 | 12.00 | Girder | 48.00 | routine |
| 879 | BR:SH25:HNN1:165.456 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 165448 | 12.00 | Slab | 16.00 | routine |
| 880 | BR:SH25:HNN1:166.826 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 166823 | 8.50 | Slab | 7.00 | routine |
| 881 | BR:SH25:HNN1:167.016 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 167012 | 12.00 | Slab | 8.00 | routine |
| 882 | BR:SH25:HNN1:172.361 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 172355 | 12.00 | Slab | 13.00 | routine |
| 883 | BR:SH25:HNN1:172.951 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 172947 | 8.00 | Slab | 8.00 | repair |
| 884 | BR:SH25:SMG4:176.001 | SMG4 | SH25 | Shimoga | Shimoga_special | Shimoga | 175997 | 12.00 | Slab | 8.00 | routine |
| 885 | BR:SH25:SMG4:176.971 | SMG4 | SH25 | Shimoga | Shimoga_special | Shimoga | 176962 | 12.00 | Slab | 18.00 | routine |
| 886 | BR:SH25:SMG4:192.206 | SMG4 | SH25 | Shimoga | Shimoga_special | Shimoga | 192202 | 12.00 | Slab | 9.00 | routine |
| 887 | BR:SH25:SMG4:192.751 | SMG4 | SH25 | Shimoga | Shimoga_special | Shimoga | 192706 | 12.00 | Steel Structure | 90.00 | routine |
| 888 | BR:SH26:RBN4:6.47 | RBN4 | SH26 | Haveri | Haveri | Ranebennur | 6462 | 7.50 | Pipe | 17.50 | repair |
| 889 | BR:SH26:RBN4:7.43 | RBN4 | SH26 | Haveri | Haveri | Ranebennur | 7408 | 8.50 | Girder | 44.00 | repair |
| 890 | BR:SH26:RBN4:17.175 | RBN4 | SH26 | Haveri | Haveri | Ranebennur | 17168 | 12.00 | Slab | 15.00 | routine |
| 891 | BR:SH26:HKR204:28 | HKR204 | SH26 | Haveri | Haveri | Hirekerur | 27988 | 8.50 | Slab | 24.00 | repair |
| 892 | BR:SH26:HNN2:33.832 | HNN2 | SH26 | Davanagere | Davanagere | Honnali | 33822 | 8.50 | Slab | 21.00 | repair |
| 893 | BR:SH26:HNN2:34.607 | HNN2 | SH26 | Davanagere | Davanagere | Honnali | 34584 | 8.50 | Pipe | 47.50 | repair |
| 894 | BR:SH26:HNN2:43.722 | HNN2 | SH26 | Davanagere | Davanagere | Honnali | 43709 | 8.50 | Slab | 27.00 | routine |
| 895 | BR:SH26:HNN2:50.857 | HNN2 | SH26 | Davanagere | Davanagere | Honnali | 50848 | 8.50 | Slab | 19.00 | repair |
| 896 | BR:SH26:HNN2:55.947 | HNN2 | SH26 | Davanagere | Davanagere | Honnali | 55937 | 8.50 | Slab | 21.00 | repair |

Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width,m | Type of Super Str | Bridge Lgh (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 897 | BR:SH26:HNN2:59.327 | HNN2 | SH26 | Davanagere | Davanagere | Honnali | 59321 | 8.50 | Slab | 12.00 | routine |
| 898 | BR:SH26:HNN2:60.517 | HNN2 | SH26 | Davanagere | Davanagere | Honnali | 60497 | 12.00 | Slab | 40.00 | routine |
| 899 | BR:SH26:SMG5:70.014 | SMG5 | SH26 | Shimoga | Shimoga_special | Shimoga | 70010 | 8.50 | Slab | 9.00 | repair |
| 900 | BR:SH26:SMG5:79.539 | SMG5 | SH26 | Shimoga | Shimoga_special | Shimoga | 79533 | 12.00 | Slab | 12.00 | routine |
| 901 | BR:SH26:HSN2:86.929 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 86919 | 8.00 | Slab | 20.00 | repair |
| 902 | BR:SH26:HSN2:90.354 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 90351 | 8.00 | Slab | 7.00 | repair |
| 903 | BR:SH26:HSN2:97.494 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 97490 | 9.00 | Slab | 8.00 | repair |
| 904 | BR:SH26:HSN2:102.564 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 102546 | 5.50 | Steel Structure | 36.00 | repair |
| 905 | BR:SH26:HSN2:108.384 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 108372 | 12.00 | Girder | 24.00 | routine |
| 906 | BR:SH26:HSN2:114.204 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 114201 | 10.00 | Slab | 6.50 | repair |
| 907 | BR:SH26:HSN2:118.084 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 118072 | 12.00 | Girder | 24.00 | routine |
| 908 | BR:SH26:HSN2:119.359 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 119352 | 8.00 | Slab | 14.00 | repair |
| 909 | BR:SH26:HSN2:126.698 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 126678 | 8.00 | Girder | 40.00 | repair |
| 910 | BR:SH26:HSN2:130.158 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 130138 | 8.00 | Girder | 40.00 | repair |
| 911 | BR:SH26:HSN2:134.263 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 134259 | 8.00 | Girder | 8.00 | repair |
| 912 | BR:SH26:HSN2:137.458 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 137438 | 8.00 | Girder | 40.00 | repair |
| 913 | BR:SH26:HSN2:142.308 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 142302 | 8.00 | Girder | 12.00 | repair |
| 914 | BR:SH26:HSN2:142.923 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 142911 | 12.00 | Slab | 24.00 | routine |
| 915 | BR:SH26:HSN2:150.398 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 150393 | 6.00 | Girder | 10.00 | repair |
| 916 | BR:SH26:HSN2:152.773 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 152768 | 12.00 | Slab | 11.00 | routine |
| 917 | BR:SH26:HSN2:160.144 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 160140 | 8.00 | Slab | 8.00 | repair |
| 918 | BR:SH26:HSN2:168.554 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 168534 | 12.00 | Girder | 40.50 | routine |
| 919 | BR:SH26:HSN2:170.279 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 170276 | 10.00 | Slab | 7.00 | repair |
| 920 | BR:SH26:HSN2:171.644 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 171634 | 12.00 | Slab | 20.00 | repair |
| 921 | BR:SH26:KDP3:185.894 | KDP3 | SH26 | Udupi | Udupi | Kundapura | 185884 | 12.00 | Slab | 20.00 | routine |
| 922 | BR:SH26:KDP3:187.514 | KDP3 | SH26 | Udupi | Udupi | Kundapura | 187505 | 8.00 | Girder | 18.00 | repair |
| 923 | BR:SH26:KDP3:189.299 | KDP3 | SH26 | Udupi | Udupi | Kundapura | 189296 | 8.50 | Slab | 6.50 | repair |
| 924 | BR:SH27:VJP71:4.005 | VJP71 | SH27 | Kodagu | Kodagu | Virajpet | 4001 | 8.50 | Slab | 9.00 | repair |
| 925 | BR:SH27:VJP71:4.28 | VJP71 | SH27 | Kodagu | Kodagu | Virajpet | 4269 | 8.50 | Slab | 22.50 | routine |
| 926 | BR:SH27:VJP71:11.31 | VJP71 | SH27 | Kodagu | Kodagu | Virajpet | 11306 | 9.00 | Slab | 9.00 | repair |
| 927 | BR:SH27:MDK3:19.6 | MDK3 | SH27 | Kodagu | Kodagu | Madikeri | 19588 | 8.50 | Slab | 24.00 | routine |
| 928 | BR:SH27:MDK3:23.46 | MDK3 | SH27 | Kodagu | Kodagu | Madikeri | 23457 | 8.50 | pipe | 7.50 | repair |
| 929 | BR:SH27:MDK3:25.63 | MDK3 | SH27 | Kodagu | Kodagu | Madikeri | 25627 | 8.50 | Slab | 6.00 | repair |
| 930 | BR:SH27:SVP76:46.37 | SVP76 | SH27 | Kodagu | Kodagu | Somvarpet | 46310 | 12.00 | Girder | 120.00 | routine |
| 931 | BR:SH27:SVP76:50.82 | SVP76 | SH27 | Kodagu | Kodagu | Somvarpet | 50780 | 12.00 | Girder | 80.00 | routine |
| 932 | BR:SH27:SVP76:69.535 | SVP76 | SH27 | Kodagu | Kodagu | Somvarpet | 69531 | 8.00 | Slab | 8.00 | routine |
| 933 | BR:SH27:SVP76:74.78 | SVP76 | SH27 | Kodagu | Kodagu | Somvarpet | 74776 | 8.50 | Slab | 8.00 | repair |
| 934 | BR:SH27:SVP76:81.17 | SVP76 | SH27 | Kodagu | Kodagu | Somvarpet | 81166 | 8.00 | Slab | 8.00 | routine |
| 935 | BR:SH27:SVP76:87.305 | SVP76 | SH27 | Kodagu | Kodagu | Somvarpet | 87287 | 8.50 | Girder | 36.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len. (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 936 | BR:SH27:SVP76:93.13 | SVP76 | SH27 | Kodagu | Kodagu | Somvarpet | 93126 | 8.50 | Slab | 8.00 | repair |
| 937 | BR:SH27:SVP76:93.245 | SVP76 | SH27 | Kodagu | Kodagu | Somvarpet | 93240 | 9.50 | Slab | 10.00 | repair |
| 938 | BR:SH27:SLP214:104.045 | SLP214 | SH27 | Hassan | Hassan_Special | Sakleshpur | 104027 | 9.00 | Girder | 36.00 | repair |
| 939 | BR:SH27:SLP214:104.055 | SLP214 | SH27 | Hassan | Hassan_Special | Sakleshpur | 104035 | 8.50 | Girder | 40.00 | repair |
| 940 | BR:SH27:SLP214:109.83 | SLP214 | SH27 | Hassan | Hassan_Special | Sakleshpur | 109810 | 8.50 | Girder | 40.00 | repair |
| 941 | BR:SH27:SLP214:110.93 | SLP214 | SH27 | Hassan | Hassan_Special | Sakleshpur | 110917 | 8.50 | Girder | 27.00 | repair |
| 942 | BR:SH27:SLP214:136.65 | SLP214 | SH27 | Hassan | Hassan_Special | Sakleshpur | 136645 | 12.00 | Slab | 10.00 | repair |
| 943 | BR:SH27:SLP214:140.14 | SLP214 | SH27 | Hassan | Hassan_Special | Sakleshpur | 140131 | 8.50 | Slab | 18.00 | repair |
| 944 | BR:SH27:BLR303:143.86 | BLR303 | SH27 | Hassan | Hassan | Belur | 143855 | 10.00 | Slab | 10.00 | routine |
| 945 | BR:SH27:MDI201:169.005 | MDI201 | SH27 | Chikmagalur | Chikmagalur | Mudigere | 168999 | 8.00 | Slab | 12.00 | repair |
| 946 | BR:SH27:MDI201:172.29 | MDI201 | SH27 | Chikmagalur | Chikmagalur | Mudigere | 172284 | 6.50 | Slab | 12.00 | repair |
| 947 | BR:SH27:MDI201:182.97 | MDI201 | SH27 | Chikmagalur | Chikmagalur | Mudigere | 182961 | 10.00 | Slab | 18.00 | routine |
| 948 | BR:SH27:CHK202:202.595 | CHK202 | SH27 | Chikmagalur | Chikmagalur | Chikmagalur | 202591 | 8.50 | Slab | 8.00 | repair |
| 949 | BR:SH27:CHK202:205.645 | CHK202 | SH27 | Chikmagalur | Chikmagalur | Chikmagalur | 205639 | 12.00 | Girder | 12.00 | repair |
| 950 | BR:SH27:CHK202:212.765 | CHK202 | SH27 | Chikmagalur | Chikmagalur | Chikmagalur | 212761 | 8.50 | Slab | 8.00 | repair |
| 951 | BR:SH27:CHK202:214.335 | CHK202 | SH27 | Chikmagalur | Chikmagalur | Chikmagalur | 214323 | 9.00 | Slab | 24.00 | routine |
| 952 | BR:SH27:CHK202:216.895 | CHK202 | SH27 | Chikmagalur | Chikmagalur | Chikmagalur | 216891 | 8.00 | Slab | 8.50 | repair |
| 953 | BR:SH27:KPA201:246.84 | KPA201 | SH27 | Chikmagalur | Chikmagalur | Koppa | 246829 | 10.00 | Slab | 22.00 | routine |
| 954 | BR:SH27:KPA201:248.655 | KPA201 | SH27 | Chikmagalur | Chikmagalur | Koppa | 248630 | 8.00 | Slab | 50.00 | repair |
| 955 | BR:SH27:SNG203:265.09 | SNG203 | SH27 | Chikmagalur | Chikmagalur | Sringeri | 265038 | 7.50 | Girder | 102.40 | repair |
| 956 | BR:SH27:SNG203:273.725 | SNG203 | SH27 | Chikmagalur | Chikmagalur | Sringeri | 273722 | 12.00 | Slab | 6.00 | routine |
| 957 | BR:SH27:SNG203:278.04 | SNG203 | SH27 | Chikmagalur | Chikmagalur | Sringeri | 278037 | 8.50 | Slab | 6.50 | repair |
| 958 | BR:SH27:KRK41:303.355 | KRK41 | SH27 | Udupi | Udupi | Karkala | 303352 | 8.00 | Girder | 7.50 | repair |
| 959 | BR:SH27:KRK41:304.315 | KRK41 | SH27 | Udupi | Udupi | Karkala | 304305 | 6.00 | Steel Structure | 20.00 | repair |
| 960 | BR:SH27:KDP206:308.545 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 308532 | 5.50 | Steel Structure | 27.00 | repair |
| 961 | BR:SH27:KDP206:330.325 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 330320 | 8.60 | Slab | 11.50 | routine |
| 962 | BR:SH27:KDP206:331.54 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 331467 | 9.00 | Girder | 140.00 | repair |
| 963 | BR:SH27:KDP206:338.025 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 338017 | 8.00 | Girder | 16.00 | repair |
| 964 | BR:SH27:KDP206:340.965 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 340954 | 8.00 | Girder | 22.00 | repair |
| 965 | BR:SH27:KDP206:347.19 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 347169 | 8.00 | Girder | 42.00 | repair |
| 966 | BR:SH27:KDP206:353.61 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 353560 | 8.00 | Girder | 100.00 | repair |
| 967 | BR:SH27:KDP206:359.665 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 359660 | 8.00 | Slab | 10.00 | repair |
| 968 | BR:SH27:KDP206:366.745 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 366726 | 8.00 | Girder | 39.00 | repair |
| 969 | BR:SH27:KDP206:370.185 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 370178 | 8.20 | Girder | 14.00 | repair |
| 970 | BR:SH27:KDP206:374.51 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 374506 | 8.00 | Slab | 8.00 | repair |
| 971 | BR:SH27:KDP206:378.5 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 378496 | 8.00 | Slab | 8.50 | repair |
| 972 | BR:SH27:KDP206:379.68 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 379674 | 9.50 | Slab | 12.00 | repair |
| 973 | BR:SH27:KDP206:380.305 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 380302 | 8.50 | Slab | 6.50 | routine |
| 974 | BR:SH27:KDP206:390.86 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 390856 | 11.00 | Slab | 9.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 975 | BR:SH28:JOD3:2.49 | JOD3 | SH28 | Uttara Kannada | Sirsi | Joida | 2487 | 9.00 | Slab | 7.00 | repair |
| 976 | BR:SH28:HLY2:12.075 | HLY2 | SH28 | Uttara Kannada | Sirsi | Haliyal | 12049 | 8.50 | Girder | 52.00 | repair |
| 977 | BR:SH28:HLY2:22.69 | HLY2 | SH28 | Uttara Kannada | Sirsi | Haliyal | 22671 | 8.50 | Girder | 39.00 | repair |
| 978 | BR:SH28:HLY2:28.15 | HLY2 | SH28 | Uttara Kannada | Sirsi | Haliyal | 28126 | 8.50 | Girder | 48.00 | routine |
| 979 | BR:SH28:HLY2:38.035 | HLY2 | SH28 | Uttara Kannada | Sirsi | Haliyal | 38030 | 9.00 | Slab | 11.50 | routine |
| 980 | BR:SH28:DRD5:40.555 | DRD5 | SH28 | Dharwad | Dharwad | Dharwad | 40550 | 9.50 | Slab | 10.00 | repair |
| 981 | BR:SH28:DRD5:51.2 | DRD5 | SH28 | Dharwad | Dharwad | Dharwad | 51194 | 8.50 | Slab | 13.00 | repair |
| 982 | BR:SH28:DRD5:70.885 | DRD5 | SH28 | Dharwad | Dharwad | Dharwad | 70876 | 8.50 | Girder | 18.00 | routine |
| 983 | BR:SH28:DRD5:76.67 | DRD5 | SH28 | Dharwad | Dharwad | Dharwad | 76661 | 8.50 | Girder | 18.00 | routine |
| 984 | BR:SH28:HBL4_A:87.325 | HBL4_A | SH28 | Dharwad | Dharwad | Hubli | 87310 | 12.00 | Slab | 30.00 | routine |
| 985 | BR:SH28:HBL4_A:90.055 | HBL4_A | SH28 | Dharwad | Dharwad | Hubli | 90046 | 12.00 | Slab | 18.00 | routine |
| 986 | BR:SH28:HBL4_A:91.32 | HBL4_A | SH28 | Dharwad | Dharwad | Hubli | 91316 | 12.00 | Slab | 8.00 | routine |
| 987 | BR:SH28:HBL4_A:92.655 | HBL4_A | SH28 | Dharwad | Dharwad | Hubli | 92647 | 12.00 | Slab | 16.00 | routine |
| 988 | BR:SH28:HBL4_A:93.655 | HBL4_A | SH28 | Dharwad | Dharwad | Hubli | 93652 | 12.50 | Pipe | 7.90 | routine |
| 989 | BR:SH29:KST207:34.76 | KST207 | SH29 | Koppal | Koppal | Kushtagi | 34733 | 8.00 | Slab | 55.00 | routine |
| 990 | BR:SH29:KST207:36.245 | KST207 | SH29 | Koppal | Koppal | Kushtagi | 36241 | 12.00 | Slab | 9.00 | routine |
| 991 | BR:SH29:KST207:37.43 | KST207 | SH29 | Koppal | Koppal | Kushtagi | 37408 | 12.00 | Slab | 45.00 | routine |
| 992 | BR:SH29:GAN2:38.495 | GAN2 | SH29 | Koppal | Koppal | Gangawati | 38487 | 12.00 | Slab | 16.00 | routine |
| 993 | BR:SH29:GAN2:40.69 | GAN2 | SH29 | Koppal | Koppal | Gangawati | 40665 | 12.00 | Girder | 50.00 | routine |
| 994 | BR:SH29:GAN2:52.216 | GAN2 | SH29 | Koppal | Koppal | Gangawati | 52185 | 12.00 | Girder | 63.00 | routine |
| 995 | BR:SH29:GAN2:62.521 | GAN2 | SH29 | Koppal | Koppal | Gangawati | 62509 | 8.00 | Girder | 25.50 | routine |
| 996 | BR:SH29:GAN2:65.071 | GAN2 | SH29 | Koppal | Koppal | Gangawati | 65056 | 8.50 | pipe | 31.80 | routine |
| 997 | BR:SH29:GAN2:65.406 | GAN2 | SH29 | Koppal | Koppal | Gangawati | 65390 | 12.00 | Slab | 32.00 | routine |
| 998 | BR:SH29:GAN2:68.805 | GAN2 | SH29 | Koppal | Koppal | Gangawati | 68785 | 12.00 | Girder | 40.00 | routine |
| 999 | BR:SH29:GAN2:70.02 | GAN2 | SH29 | Koppal | Koppal | Gangawati | 70016 | 12.50 | pipe | 8.00 | routine |
| 1000 | BR:SH29:GAN2:80.821 | GAN2 | SH29 | Koppal | Koppal | Gangawati | 80526 | 7.50 | Slab | 596.70 | repair |
| 1001 | BR:SH29:HSP5:82.456 | HSP5 | SH29 | Bellary | Bellary | Hospet | 82451 | 12.00 | Slab | 11.00 | repair |
| 1002 | BR:SH29:HSP5:83.941 | HSP5 | SH29 | Bellary | Bellary | Hospet | 83938 | 12.00 | Slab | 7.50 | repair |
| 1003 | BR:SH29:HSP5:92.296 | HSP5 | SH29 | Bellary | Bellary | Hospet | 92289 | 12.00 | Slab | 15.00 | routine |
| 1004 | BR:SH29:HSP5:97.991 | HSP5 | SH29 | Bellary | Bellary | Hospet | 97979 | 12.00 | Slab | 25.00 | routine |
| 1005 | BR:SH29:HSP5:99.081 | HSP5 | SH29 | Bellary | Bellary | Hospet | 99072 | 10.00 | Slab | 18.00 | routine |
| 1006 | BR:SH29:SNR32:102.721 | SNR32 | SH29 | Bellary | Bellary | Sandur | 102709 | 12.00 | Slab | 24.00 | routine |
| 1007 | BR:SH29:SNR32:102.866 | SNR32 | SH29 | Bellary | Bellary | Sandur | 102863 | 10.00 | Slab | 7.00 | routine |
| 1008 | BR:SH29:SNR32:102.951 | SNR32 | SH29 | Bellary | Bellary | Sandur | 102945 | 10.00 | Slab | 12.00 | routine |
| 1009 | BR:SH29:SNR32:105.43 | SNR32 | SH29 | Bellary | Bellary | Sandur | 105426 | 10.00 | Slab | 8.00 | repair |
| 1010 | BR:SH29:BER4:108.215 | BER4 | SH29 | Bellary | Bellary | Bellary | 108209 | 10.00 | Slab | 12.00 | routine |
| 1011 | BR:SH29:BER4:110.17 | BER4 | SH29 | Bellary | Bellary | Bellary | 110160 | 10.00 | Slab | 20.00 | routine |
| 1012 | BR:SH29:BER4:112.93 | BER4 | SH29 | Bellary | Bellary | Bellary | 112910 | 8.00 | Slab | 40.00 | repair |
| 1013 | BR:SH3:KNK2:10.71 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 10706 | 7.50 | pipe | 9.70 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1014 | BR:SH3:KNK2:18.045 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 18017 | 8.00 | Girder | 56.50 | repair |
| 1015 | BR:SH3:KNK2:23.135 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 23126 | 8.00 | pipe | 18.20 | repair |
| 1016 | BR:SH3:KNK2:29.265 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 29211 | 8.10 | Girder | 108.80 | repair |
| 1017 | BR:SH3:KNK2:32.212 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 32207 | 8.00 | Slab | 10.40 | repair |
| 1018 | BR:SH3:KNK2:38.112 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 38109 | 10.00 | Slab | 7.20 | repair |
| 1019 | BR:SH3:KNK2:40.162 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 40158 | 8.50 | Slab | 8.00 | repair |
| 1020 | BR:SH3:KNK2:42.127 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 42124 | 12.00 | Slab | 6.00 | routine |
| 1021 | BR:SH3:KNK2:43.267 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 43258 | 12.00 | Girder | 19.40 | routine |
| 1022 | BR:SH3:RMN2:49.197 | RMN2 | SH3 | Ramanagara | Ramanagara | Ramnagaram | 49194 | 8.00 | Slab | 6.60 | repair |
| 1023 | BR:SH3:RMN2:50.937 | RMN2 | SH3 | Ramanagara | Ramanagara | Ramnagaram | 50931 | 8.20 | Slab | 12.40 | repair |
| 1024 | BR:SH3:RMN2:52.132 | RMN2 | SH3 | Ramanagara | Ramanagara | Ramnagaram | 52128 | 8.00 | pipe | 9.70 | repair |
| 1025 | BR:SH3:RMN2:62.185 | RMN2 | SH3 | Ramanagara | Ramanagara | Ramnagaram | 62180 | 12.00 | Slab | 11.00 | repair |
| 1026 | BR:SH3:MGD3:97.124 | MGD3 | SH3 | Ramanagara | Ramanagara | Magadi | 97121 | 6.50 | Slab | 7.00 | routine |
| 1027 | BR:SH3:MGD3:98.644 | MGD3 | SH3 | Ramanagara | Ramanagara | Magadi | 98635 | 8.45 | Slab | 18.20 | routine |
| 1028 | BR:SH3:MGD3:106.844 | MGD3 | SH3 | Ramanagara | Ramanagara | Magadi | 106841 | 9.50 | Others | 7.20 | routine |
| 1029 | BR:SH3:MGD3:108.544 | MGD3 | SH3 | Ramanagara | Ramanagara | Magadi | 108539 | 5.50 | Slab | 11.50 | routine |
| 1030 | BR:SH3:NLM4:125.284 | NLM4 | SH3 | Bangalore Rural | Bangalore | Nelmangala | 125279 | 11.00 | Slab | 10.85 | routine |
| 1031 | BR:SH3:NLM4:129.356 | NLM4 | SH3 | Bangalore Rural | Bangalore | Nelmangala | 129348 | 11.40 | Girder | 17.60 | routine |
| 1032 | BR:SH3:TMK201:139.981 | TMK201 | SH3 | Tumkur | Tumkur | Tumkur | 139972 | 12.00 | Slab | 18.80 | routine |
| 1033 | BR:SH3:KTG1:148.033 | KTG1 | SH3 | Tumkur | Madhugiri | Koratagere | 148030 | 12.50 | pipe | 6.30 | routine |
| 1034 | BR:SH3:KTG1:154.838 | KTG1 | SH3 | Tumkur | Madhugiri | Koratagere | 154829 | 12.00 | Slab | 19.60 | routine |
| 1035 | BR:SH3:KTG1:160.168 | KTG1 | SH3 | Tumkur | Madhugiri | Koratagere | 160164 | 12.50 | pipe | 8.00 | routine |
| 1036 | BR:SH3:KTG1:162.103 | KTG1 | SH3 | Tumkur | Madhugiri | Koratagere | 162079 | 7.50 | Girder | 49.50 | routine |
| 1037 | BR:SH3:KTG1:162.498 | KTG1 | SH3 | Tumkur | Madhugiri | Koratagere | 162494 | 15.00 | Arch | 8.00 | routine |
| 1038 | BR:SH3:KTG1:165.593 | KTG1 | SH3 | Tumkur | Madhugiri | Koratagere | 165587 | 9.00 | Slab | 12.00 | routine |
| 1039 | BR:SH3:KTG1:167.338 | KTG1 | SH3 | Tumkur | Madhugiri | Koratagere | 167333 | 9.50 | Slab | 10.00 | routine |
| 1040 | BR:SH3:KTG1:168.648 | KTG1 | SH3 | Tumkur | Madhugiri | Koratagere | 168632 | 12.00 | Slab | 32.00 | routine |
| 1041 | BR:SH3:KTG1:170.068 | KTG1 | SH3 | Tumkur | Madhugiri | Koratagere | 170062 | 7.50 | pipe | 13.10 | routine |
| 1042 | BR:SH3:MDG2_A:174.063 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 174059 | 9.00 | Slab | 8.10 | routine |
| 1043 | BR:SH3:MDG2_A:175.723 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 175719 | 12.00 | Slab | 9.00 | routine |
| 1044 | BR:SH3:MDG2_A:176.628 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 176624 | 11.00 | Slab | 9.60 | routine |
| 1045 | BR:SH3:MDG2_A:177.088 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 177085 | 12.00 | Slab | 7.00 | routine |
| 1046 | BR:SH3:MDG2_A:177.988 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 177973 | 12.00 | Slab | 30.00 | routine |
| 1047 | BR:SH3:MDG2_A:178.538 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 178535 | 10.00 | Slab | 6.50 | routine |
| 1048 | BR:SH3:MDG2_A:183.583 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 183571 | 8.00 | Slab | 24.00 | routine |
| 1049 | BR:SH3:MDG2_A:185.043 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 185039 | 12.00 | Slab | 8.00 | routine |
| 1050 | BR:SH3:MDG2_A:186.348 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 186343 | 11.50 | Slab | 10.80 | routine |
| 1051 | BR:SH3:MDG2_A:186.608 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 186604 | 9.00 | Arch | 8.40 | routine |
| 1052 | BR:SH3:MDG2_A:187.368 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 187365 | 10.00 | pipe | 6.30 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl.No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m. | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1053 | BR:SH3:MDG2_A:188.528 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 188525 | 10.00 | Slab | 6.00 | routine |
| 1054 | BR:SH3:MDG2_A:190.338 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 190328 | 8.50 | Slab | 21.00 | routine |
| 1055 | BR:SH3:MDG2_A:191.098 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 191090 | 8.50 | Slab | 16.00 | routine |
| 1056 | BR:SH3:MDG2_A:192.053 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 192050 | 13.00 | Others | 7.50 | routine |
| 1057 | BR:SH3:MDG2_A:193.108 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 193103 | 10.00 | Slab | 10.00 | routine |
| 1058 | BR:SH3:MDG2_A:193.308 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 193305 | 10.50 | Slab | 7.00 | routine |
| 1059 | BR:SH3:MDG2_A:194.508 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 194500 | 7.00 | Arch | 16.00 | routine |
| 1060 | BR:SH3:MDG2_A:195.638 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 195632 | 11.00 | Slab | 12.00 | routine |
| 1061 | BR:SH3:MDG2_A:196.523 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 196519 | 10.00 | Slab | 9.00 | routine |
| 1062 | BR:SH3:MDG2_A:197.563 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 197557 | 10.00 | Slab | 12.00 | routine |
| 1063 | BR:SH3:MDG2_A:198.153 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 198149 | 7.00 | Arch | 9.00 | routine |
| 1064 | BR:SH3:MDG2_A:201.613 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 201609 | 11.00 | Slab | 8.00 | routine |
| 1065 | BR:SH3:MDG2_A:203.608 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 203593 | 8.50 | Girder | 30.00 | routine |
| 1066 | BR:SH3:MDG2_A:205.498 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 205495 | 12.00 | Slab | 6.00 | routine |
| 1067 | BR:SH3:MDG2_A:206.823 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 206813 | 10.50 | Others | 20.00 | routine |
| 1068 | BR:SH3:MDG2_A:207.443 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 207440 | 10.50 | Slab | 7.50 | routine |
| 1069 | BR:SH3:MDG2_A:207.538 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 207530 | 10.50 | Others | 17.00 | routine |
| 1070 | BR:SH3:MDG2_A:209.883 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 209879 | 9.50 | Slab | 8.00 | routine |
| 1071 | BR:SH3:MDG2_A:210.508 | MDG2_A | SH3 | Tumkur | Madhugiri | Madhugiri | 210505 | 10.00 | Slab | 7.00 | routine |
| 1072 | BR:SH3:PVG57:226.756 | PVG57 | SH3 | Tumkur | Madhugiri | Pavagada | 226750 | 12.00 | Slab | 12.00 | routine |
| 1073 | BR:SH3:PVG57:240.627 | PVG57 | SH3 | Tumkur | Madhugiri | Pavagada | 240619 | 12.00 | Slab | 16.00 | routine |
| 1074 | BR:SH3:PVG57:242.102 | PVG57 | SH3 | Tumkur | Madhugiri | Pavagada | 242092 | 12.00 | Slab | 20.00 | routine |
| 1075 | BR:SH3:PVG57:248.927 | PVG57 | SH3 | Tumkur | Madhugiri | Pavagada | 248897 | 12.00 | Girder | 50.00 | routine |
| 1076 | BR:SH3:PVG57:254.782 | PVG57 | SH3 | Tumkur | Madhugiri | Pavagada | 254772 | 12.00 | Slab | 20.00 | routine |
| 1077 | BR:SH3:PVG57:257.982 | PVG57 | SH3 | Tumkur | Madhugiri | Pavagada | 257966 | 10.00 | Girder | 32.00 | routine |
| 1078 | BR:SH3:PVG57:258.492 | PVG57 | SH3 | Tumkur | Madhugiri | Pavagada | 258483 | 12.00 | Slab | 18.00 | routine |
| 1079 | BR:SH30:SIN3:19.185 | SIN3 | SH30 | Raichur | Raichur | Sindhnur | 19175 | 8.00 | Girder | 20.00 | repair |
| 1080 | BR:SH30:SIN3:30.655 | SIN3 | SH30 | Raichur | Raichur | Sindhnur | 30645 | 12.00 | Slab | 20.00 | routine |
| 1081 | BR:SH30:KST2:50.01 | KST2 | SH30 | Koppal | Koppal | Kushtagi | 49998 | 12.00 | Slab | 24.00 | routine |
| 1082 | BR:SH30:KST2:54.035 | KST2 | SH30 | Koppal | Koppal | Kushtagi | 54032 | 8.50 | Slab | 6.60 | routine |
| 1083 | BR:SH30:KST2:60.685 | KST2 | SH30 | Koppal | Koppal | Kushtagi | 60673 | 12.00 | Slab | 25.20 | repair |
| 1084 | BR:SH30:KST2:65.425 | KST2 | SH30 | Koppal | Koppal | Kushtagi | 65419 | 10.00 | pipe | 12.10 | repair |
| 1085 | BR:SH30:KST2:68.525 | KST2 | SH30 | Koppal | Koppal | Kushtagi | 68507 | 8.00 | Girder | 36.00 | repair |
| 1086 | BR:SH30:KST2:70.045 | KST2 | SH30 | Koppal | Koppal | Kushtagi | 70021 | 8.00 | Girder | 48.00 | repair |
| 1087 | BR:SH30:YEL231_A:80.09 | YEL231_A | SH30 | Koppal | Koppal | Yelbarga | 80085 | 10.00 | Slab | 11.00 | repair |
| 1088 | BR:SH30:RON69_A:85.245 | RON69_A | SH30 | Gadag | Gadag | Ron | 85236 | 7.50 | Pipe | 19.00 | repair |
| 1089 | BR:SH30:RON69_B:102.795 | RON69_B | SH30 | Gadag | Gadag | Ron | 102783 | 10.00 | Pipe | 24.70 | routine |
| 1090 | BR:SH30:RON69_B:108.685 | RON69_B | SH30 | Gadag | Gadag | Ron | 108661 | 8.00 | Pipe | 52.40 | repair |
| 1091 | BR:SH30:RON69_B:109.545 | RON69_B | SH30 | Gadag | Gadag | Ron | 109542 | 12.00 | Slab | 6.50 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| SlNo | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1092 | BR:SH30:RON69_B:110.47 | RON69_B | SH30 | Gadag | Gadag | Ron | 110467 | 12.00 | Slab | 6.50 | routine |
| 1093 | BR:SH30:RON69_B:111.11 | RON69_B | SH30 | Gadag | Gadag | Ron | 111084 | 7.50 | Pipe | 53.50 | repair |
| 1094 | BR:SH30:RON69_B:117.51 | RON69_B | SH30 | Gadag | Gadag | Ron | 117506 | 10.00 | Slab | 8.00 | repair |
| 1095 | BR:SH30:RON69_B:118.115 | RON69_B | SH30 | Gadag | Gadag | Ron | 118107 | 12.00 | Slab | 16.00 | routine |
| 1096 | BR:SH30:RON69_B:120.73 | RON69_B | SH30 | Gadag | Gadag | Ron | 120726 | 10.00 | Pipe | 8.00 | routine |
| 1097 | BR:SH30:RON69_B:124.065 | RON69_B | SH30 | Gadag | Gadag | Ron | 124061 | 7.00 | Slab | 8.00 | routine |
| 1098 | BR:SH30:RON69_B:125.095 | RON69_B | SH30 | Gadag | Gadag | Ron | 125091 | 10.00 | Pipe | 8.00 | repair |
| 1099 | BR:SH30:RON69_B:125.255 | RON69_B | SH30 | Gadag | Gadag | Ron | 125226 | 8.50 | Pipe | 65.10 | repair |
| 1100 | BR:SH30:RON69_B:128.95 | RON69_B | SH30 | Gadag | Gadag | Ron | 128947 | 8.00 | Slab | 7.00 | repair |
| 1101 | BR:SH30:RON69_B:133.32 | RON69_B | SH30 | Gadag | Gadag | Ron | 133308 | 8.00 | Slab | 24.00 | repair |
| 1102 | BR:SH30:RON69_B:136.629 | RON69_B | SH30 | Gadag | Gadag | Ron | 136609 | 7.50 | Pipe | 41.50 | repair |
| 1103 | BR:SH30:RON69_B:143.109 | RON69_B | SH30 | Gadag | Gadag | Ron | 143080 | 8.00 | Pipe | 81.40 | repair |
| 1104 | BR:SH30:RON69_B:143.314 | RON69_B | SH30 | Gadag | Gadag | Ron | 143306 | 7.50 | Pipe | 17.00 | repair |
| 1105 | BR:SH30:NGD2:151.504 | NGD2 | SH30 | Gadag | Gadag | Nargund | 151494 | 12.00 | Slab | 20.00 | routine |
| 1106 | BR:SH30:NGD2:152.579 | NGD2 | SH30 | Gadag | Gadag | Nargund | 152566 | 12.00 | Slab | 27.00 | routine |
| 1107 | BR:SH30:NGD2:160.344 | NGD2 | SH30 | Gadag | Gadag | Nargund | 160337 | 12.00 | Slab | 14.00 | routine |
| 1108 | BR:SH30:NGD2:162.184 | NGD2 | SH30 | Gadag | Gadag | Nargund | 162181 | 12.00 | Slab | 6.50 | routine |
| 1109 | BR:SH30:NGD2:162.409 | NGD2 | SH30 | Gadag | Gadag | Nargund | 162397 | 12.00 | Slab | 24.00 | routine |
| 1110 | BR:SH30:NGD2:163.509 | NGD2 | SH30 | Gadag | Gadag | Nargund | 163505 | 12.50 | Pipe | 8.50 | routine |
| 1111 | BR:SH30:NGD2:165.249 | NGD2 | SH30 | Gadag | Gadag | Nargund | 165245 | 12.50 | Pipe | 8.50 | routine |
| 1112 | BR:SH30:NGD2:165.959 | NGD2 | SH30 | Gadag | Gadag | Nargund | 165954 | 12.50 | Pipe | 11.50 | routine |
| 1113 | BR:SH30:NGD2:166.409 | NGD2 | SH30 | Gadag | Gadag | Nargund | 166405 | 8.50 | Girder | 8.00 | repair |
| 1114 | BR:SH30:SAU202:205.322 | SAU202 | SH30 | Belgaum | Belgaum | Saundatti | 205319 | 7.50 | pipe | 7.60 | repair |
| 1115 | BR:SH30:BAI202:220.862 | BAI202 | SH30 | Belgaum | Belgaum | Bailhongal | 220852 | 8.00 | pipe | 21.50 | repair |
| 1116 | BR:SH30:BAI202:239.322 | BAI202 | SH30 | Belgaum | Belgaum | Bailhongal | 239319 | 12.00 | Slab | 7.00 | routine |
| 1117 | BR:SH30:BAI202:245.144 | BAI202 | SH30 | Belgaum | Belgaum | Bailhongal | 245140 | 12.00 | Slab | 9.00 | routine |
| 1118 | BR:SH30:BAI202:247.739 | BAI202 | SH30 | Belgaum | Belgaum | Bailhongal | 247735 | 12.00 | Slab | 9.00 | routine |
| 1119 | BR:SH30:BAI202:249.239 | BAI202 | SH30 | Belgaum | Belgaum | Bailhongal | 249234 | 10.00 | Slab | 10.00 | routine |
| 1120 | BR:SH30:BAI202:253.269 | BAI202 | SH30 | Belgaum | Belgaum | Bailhongal | 253252 | 8.00 | Slab | 35.00 | repair |
| 1121 | BR:SH30:KNP204:264.334 | KNP204 | SH30 | Belgaum | Belgaum | Khanapur | 264328 | 8.00 | Girder | 12.00 | repair |
| 1122 | BR:SH30:KNP204:264.974 | KNP204 | SH30 | Belgaum | Belgaum | Khanapur | 264962 | 8.00 | Girder | 24.00 | repair |
| 1123 | BR:SH30:KNP204:287.948 | KNP204 | SH30 | Belgaum | Belgaum | Khanapur | 287934 | 7.50 | pipe | 29.50 | repair |
| 1124 | BR:SH30:KNP204:294.133 | KNP204 | SH30 | Belgaum | Belgaum | Khanapur | 294129 | 10.00 | Slab | 8.00 | routine |
| 1125 | BR:SH30:KNP204:305.138 | KNP204 | SH30 | Belgaum | Belgaum | Khanapur | 305126 | 9.00 | Slab | 24.00 | routine |
| 1126 | BR:SH30:KNP204:305.983 | KNP204 | SH30 | Belgaum | Belgaum | Khanapur | 305975 | 10.00 | Slab | 16.00 | routine |
| 1127 | BR:SH30:JOD201:310.113 | JOD201 | SH30 | Uttara Kannada | Sirsi | Joida | 310103 | 8.00 | Slab | 20.00 | routine |
| 1128 | BR:SH30:JOD201:311.938 | JOD201 | SH30 | Uttara Kannada | Sirsi | Joida | 311923 | 8.00 | Slab | 31.50 | routine |
| 1129 | BR:SH30:JOD201:312.868 | JOD201 | SH30 | Uttara Kannada | Sirsi | Joida | 312847 | 8.00 | Slab | 42.00 | routine |
| 1130 | BR:SH30:JOD201:313.488 | JOD201 | SH30 | Uttara Kannada | Sirsi | Joida | 313475 | 9.00 | Slab | 27.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1131 | BR:SH31:ATN3:9.097 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 9067 | 12.00 | Girder | 60.00 | routine |
| 1132 | BR:SH31:ATN3:36.758 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 36753 | 10.00 | pipe | 11.50 | routine |
| 1133 | BR:SH31:ATN3:41.393 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 41218 | 8.50 | Girder | 260.00 | repair |
| 1134 | BR:SH31:ATN3:45.107 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 45094 | 7.50 | pipe | 27.10 | repair |
| 1135 | BR:SH31:RBG2:67.453 | RBG2 | SH31 | Belgaum | Chikkodi | Raibag | 67449 | 8.00 | Girder | 8.00 | repair |
| 1136 | BR:SH31:RBG2:71.083 | RBG2 | SH31 | Belgaum | Chikkodi | Raibag | 71073 | 8.00 | Slab | 21.00 | repair |
| 1137 | BR:SH31:GOK1:83.832 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 83815 | 8.00 | pipe | 35.50 | repair |
| 1138 | BR:SH31:GOK1:90.012 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 89985 | 8.00 | Slab | 54.00 | repair |
| 1139 | BR:SH31:GOK1:102.237 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 102141 | 7.00 | Arch | 180.00 | repair |
| 1140 | BR:SH31:GOK1:107.032 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 107029 | 12.50 | pipe | 7.00 | routine |
| 1141 | BR:SH31:GOK1:107.227 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 107223 | 12.00 | Slab | 8.00 | routine |
| 1142 | BR:SH31:GOK1:115.679 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 115671 | 8.00 | Slab | 16.50 | routine |
| 1143 | BR:SH31:GOK1:123.293 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 123287 | 8.00 | pipe | 13.10 | repair |
| 1144 | BR:SH31:BAI3:133.028 | BAI3 | SH31 | Belgaum | Belgaum | Bailhongal | 133022 | 12.00 | Slab | 12.00 | routine |
| 1145 | BR:SH31:BAI3:137.038 | BAI3 | SH31 | Belgaum | Belgaum | Bailhongal | 137020 | 12.00 | Slab | 36.00 | routine |
| 1146 | BR:SH31:BAI3:139.623 | BAI3 | SH31 | Belgaum | Belgaum | Bailhongal | 139609 | 12.00 | Slab | 28.80 | routine |
| 1147 | BR:SH31:KNP4:194.875 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 194860 | 8.00 | Slab | 30.00 | repair |
| 1148 | BR:SH31:KNP4:198.445 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 198430 | 8.50 | Girder | 30.00 | routine |
| 1149 | BR:SH31:KNP4:202.62 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 202611 | 12.00 | Slab | 18.00 | routine |
| 1150 | BR:SH31:KNP4:205.409 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 205401 | 8.00 | pipe | 17.90 | repair |
| 1151 | BR:SH31:KNP4:208.596 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 208592 | 8.00 | pipe | 8.70 | repair |
| 1152 | BR:SH31:KNP4:214.466 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 214441 | 8.30 | Girder | 60.00 | repair |
| 1153 | BR:SH31:KNP4:236.036 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 236031 | 12.00 | Slab | 10.00 | routine |
| 1154 | BR:SH31:KNP4:236.606 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 236601 | 12.00 | Slab | 10.00 | routine |
| 1155 | BR:SH31:KNP4:248.651 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 248648 | 12.50 | pipe | 6.50 | routine |
| 1156 | BR:SH31:KNP4:250.081 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 250078 | 12.50 | pipe | 6.50 | routine |
| 1157 | BR:SH31:KNP4:250.291 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 250288 | 12.50 | pipe | 6.50 | routine |
| 1158 | BR:SH32:ALD3:13.925 | ALD3 | SH32 | Gulbarga | Gulbarga | Aland | 13922 | 12.00 | Slab | 7.00 | routine |
| 1159 | BR:SH32:ALD3:16.676 | ALD3 | SH32 | Gulbarga | Gulbarga | Aland | 16666 | 7.50 | Others | 20.00 | routine |
| 1160 | BR:SH32:ALD3:30.336 | ALD3 | SH32 | Gulbarga | Gulbarga | Aland | 30331 | 7.50 | pipe | 10.50 | repair |
| 1161 | BR:SH32:ALD3:37.096 | ALD3 | SH32 | Gulbarga | Gulbarga | Aland | 37061 | 8.50 | Slab | 95.40 | routine |
| 1162 | BR:SH32:ALD3:41.276 | ALD3 | SH32 | Gulbarga | Gulbarga | Aland | 41265 | 12.00 | Slab | 22.50 | routine |
| 1163 | BR:SH32:GUL4:68.301 | GUL4 | SH32 | Gulbarga | Gulbarga | Gulbarga | 68284 | 7.50 | pipe | 35.50 | repair |
| 1164 | BR:SH32:GUL4:76.931 | GUL4 | SH32 | Gulbarga | Gulbarga | Gulbarga | 76928 | 10.00 | Slab | 7.50 | routine |
| 1165 | BR:SH32:GUL4:78.456 | GUL4 | SH32 | Gulbarga | Gulbarga | Gulbarga | 78416 | 8.50 | Slab | 81.00 | routine |
| 1166 | BR:SH32:GUL4:80.386 | GUL4 | SH32 | Gulbarga | Gulbarga | Gulbarga | 80383 | 10.00 | Slab | 7.00 | routine |
| 1167 | BR:SH32:CTR214:86.016 | CTR214 | SH32 | Gulbarga | Sedam | Chitapur | 85998 | 8.00 | Slab | 36.00 | repair |
| 1168 | BR:SH32:CTR214:86.996 | CTR214 | SH32 | Gulbarga | Sedam | Chitapur | 86969 | 8.00 | Slab | 55.00 | repair |
| 1169 | BR:SH32:CNL2:93.276 | CNL2 | SH32 | Gulbarga | Sedam | Chincholi | 93270 | 8.00 | Slab | 12.00 | repair |

Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1170 | BR:SH32:CNL2:94.616 | CNL2 | SH32 | Gulbarga | Sedam | Chincholi | 94604 | 8.00 | Slab | 25.00 | repair |
| 1171 | BR:SH32:CNL2:96.156 | CNL2 | SH32 | Gulbarga | Sedam | Chincholi | 96149 | 8.00 | Slab | 14.00 | repair |
| 1172 | BR:SH32:CNL2:104.313 | CNL2 | SH32 | Gulbarga | Sedam | Chincholi | 104307 | 8.00 | Slab | 12.00 | repair |
| 1173 | BR:SH32:CNL2:106.778 | CNL2 | SH32 | Gulbarga | Sedam | Chincholi | 106772 | 8.00 | Slab | 12.00 | repair |
| 1174 | BR:SH32:CNL2:107.823 | CNL2 | SH32 | Gulbarga | Sedam | Chincholi | 107817 | 8.00 | Slab | 12.00 | repair |
| 1175 | BR:SH32:CNL2:109.913 | CNL2 | SH32 | Gulbarga | Sedam | Chincholi | 109904 | 9.00 | Slab | 18.00 | repair |
| 1176 | BR:SH32:CNL2:115.803 | CNL2 | SH32 | Gulbarga | Sedam | Chincholi | 115796 | 12.00 | Slab | 15.00 | routine |
| 1176 | BR:SH33:KTG2:3.08 | KTG2 | SH33 | Tumkur | Madhugiri | Koratagere | 3070 | 8.50 | Slab | 20.00 | routine |
| 1177 | BR:SH33:KTG2:5.6 | KTG2 | SH33 | Tumkur | Madhugiri | Koratagere | 5596 | 12.50 | pipe | 9.70 | routine |
| 1178 | BR:SH33:TMK3:7.095 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 7080 | 8.50 | Slab | 30.80 | routine |
| 1179 | BR:SH33:TMK3:8.57 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 8561 | 12.50 | pipe | 18.20 | routine |
| 1180 | BR:SH33:TMK3:9.2 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 9191 | 12.00 | Girder | 19.00 | routine |
| 1181 | BR:SH33:TMK3:9.93 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 9922 | 12.00 | Slab | 17.10 | routine |
| 1182 | BR:SH33:TMK3:13.415 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 13411 | 12.50 | pipe | 8.50 | routine |
| 1183 | BR:SH33:TMK3:13.94 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 13933 | 12.00 | Slab | 14.00 | routine |
| 1184 | BR:SH33:TMK3:14.855 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 14849 | 12.00 | Girder | 12.70 | routine |
| 1185 | BR:SH33:TMK3:17.23 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 17226 | 12.50 | pipe | 9.30 | routine |
| 1186 | BR:SH33:TMK3:23.002 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 22993 | 10.00 | Slab | 18.00 | routine |
| 1187 | BR:SH33:TMK3:28.429 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 28426 | 12.00 | Slab | 7.00 | routine |
| 1188 | BR:SH33:TMK3:29.434 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 29423 | 10.00 | pipe | 23.30 | routine |
| 1189 | BR:SH33:TMK3:30.034 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 30027 | 10.00 | pipe | 14.80 | routine |
| 1190 | BR:SH33:TMK3:42.034 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 42029 | 8.50 | Slab | 10.80 | routine |
| 1191 | BR:SH33:TMK3:47.264 | TMK3 | SH33 | Tumkur | Tumkur | Tumkur | 47255 | 10.00 | pipe | 19.90 | routine |
| 1192 | BR:SH33:KNL2:53.935 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 53932 | 8.50 | Slab | 7.20 | routine |
| 1193 | BR:SH33:KNL2:57.17 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 57165 | 12.00 | Slab | 11.00 | routine |
| 1194 | BR:SH33:KNL2:57.505 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 57499 | 10.00 | Slab | 12.00 | routine |
| 1195 | BR:SH33:KNL2:59.045 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 59042 | 12.00 | Slab | 6.50 | routine |
| 1196 | BR:SH33:KNL2:61.5 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 61488 | 8.60 | Girder | 25.00 | routine |
| 1197 | BR:SH33:KNL2:64.499 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 64492 | 8.60 | Girder | 15.10 | routine |
| 1198 | BR:SH33:KNL2:75.45 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 75447 | 8.00 | Slab | 6.30 | routine |
| 1199 | BR:SH33:KNL2:79.335 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 79329 | 12.00 | Slab | 13.00 | routine |
| 1200 | BR:SH33:KNL2:83 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 82992 | 12.00 | Slab | 17.00 | routine |
| 1201 | BR:SH33:KNL2:96.076 | KNL2 | SH33 | Tumkur | Tumkur | Kunigal | 96067 | 8.50 | Slab | 19.80 | routine |
| 1202 | BR:SH33:MDR1:101.741 | MDR1 | SH33 | Mandya | Mandya | Maddur | 101734 | 8.20 | Slab | 15.00 | routine |
| 1203 | BR:SH33:MDR1:107.581 | MDR1 | SH33 | Mandya | Mandya | Maddur | 107561 | 8.50 | Girder | 41.95 | routine |
| 1204 | BR:SH33:MDR1:121.032 | MDR1 | SH33 | Mandya | Mandya | Maddur | 121029 | 8.50 | Slab | 6.00 | routine |
| 1205 | BR:SH33:MDR1:124.072 | MDR1 | SH33 | Mandya | Mandya | Maddur | 124069 | 8.50 | Slab | 6.60 | routine |
| 1206 | BR:SH33:MDR1:124.537 | MDR1 | SH33 | Mandya | Mandya | Maddur | 124516 | 8.50 | Girder | 42.90 | routine |
| 1207 | BR:SH33:MDR1:125.382 | MDR1 | SH33 | Mandya | Mandya | Maddur | 125372 | 8.50 | Girder | 20.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1208 | BR:SH33:MDR1:128.827 | MDR1 | SH33 | Mandya | Mandya | Maddur | 128817 | 8.50 | Girder | 20.00 | routine |
| 1209 | BR:SH33:MLV201:137.635 | MLV201 | SH33 | Mandya | Mandya | Malavalli | 137626 | 7.50 | Girder | 19.20 | routine |
| 1210 | BR:SH33:MLV201:138.875 | MLV201 | SH33 | Mandya | Mandya | Malavalli | 138871 | 12.00 | Slab | 8.60 | routine |
| 1211 | BR:SH33:MLV201:145.952 | MLV201 | SH33 | Mandya | Mandya | Malavalli | 145939 | 8.00 | pipe | 26.50 | repair |
| 1212 | BR:SH33:TNP204:155.651 | TNP204 | SH33 | Mysore | Mysore | Tnarsipur | 155647 | 8.50 | Slab | 9.50 | repair |
| 1213 | BR:SH33:TNP204:159.006 | TNP204 | SH33 | Mysore | Mysore | Tnarsipur | 159002 | 12.00 | Slab | 9.50 | routine |
| 1214 | BR:SH33:TNP204:160.586 | TNP204 | SH33 | Mysore | Mysore | Tnarsipur | 160583 | 12.00 | Slab | 6.30 | repair |
| 1215 | BR:SH33:TNP204:164.616 | TNP204 | SH33 | Mysore | Mysore | Tnarsipur | 164462 | 8.50 | Girder | 250.00 | repair |
| 1216 | BR:SH33:TNP204:165.081 | TNP204 | SH33 | Mysore | Mysore | Tnarsipur | 165077 | 8.00 | Girder | 9.50 | repair |
| 1217 | BR:SH33:MYS232:196.23 | MYS232 | SH33 | Mysore | Mysore | Mysore | 196222 | 8.40 | Slab | 17.40 | routine |
| 1218 | BR:SH33:MYS232:205.235 | MYS232 | SH33 | Mysore | Mysore | Mysore | 205231 | 12.00 | Slab | 9.00 | routine |
| 1219 | BR:SH33:MYS232:210.895 | MYS232 | SH33 | Mysore | Mysore | Mysore | 210888 | 12.00 | Slab | 14.00 | routine |
| 1220 | BR:SH33:HDK201:219.035 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 219031 | 12.00 | Slab | 9.00 | routine |
| 1221 | BR:SH33:HDK201:219.76 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 219753 | 8.50 | Slab | 15.60 | routine |
| 1222 | BR:SH33:HDK201:229.855 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 229834 | 8.50 | Arch | 43.50 | repair |
| 1223 | BR:SH33:HDK201:234.563 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 234559 | 8.00 | Slab | 8.00 | routine |
| 1224 | BR:SH33:HDK201:240.923 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 240919 | 8.00 | Slab | 8.00 | repair |
| 1225 | BR:SH33:HDK201:244.203 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 244198 | 8.00 | Slab | 11.60 | routine |
| 1226 | BR:SH33:HDK201:266.948 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 266935 | 8.50 | Girder | 27.00 | repair |
| 1227 | BR:SH33:HDK201:267.968 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 267964 | 8.50 | Slab | 9.20 | repair |
| 1228 | BR:SH33:HDK201:271.053 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 271047 | 8.50 | Girder | 13.50 | repair |
| 1229 | BR:SH33:HDK201:278.403 | HDK201 | SH33 | Mysore | Hunsur | Heggadadevanakote | 278400 | 8.50 | Slab | 6.00 | repair |
| 1230 | BR:SH34:AUR7:13.2 | AUR7 | SH34 | Bidar | Bidar | Aurad | 13195 | 10.00 | pipe | 10.70 | routine |
| 1231 | BR:SH34:AUR7:20.385 | AUR7 | SH34 | Bidar | Bidar | Aurad | 20381 | 8.00 | pipe | 8.50 | repair |
| 1232 | BR:SH34:AUR7:21.01 | AUR7 | SH34 | Bidar | Bidar | Aurad | 20906 | 12.00 | Girder | 208.00 | routine |
| 1233 | BR:SH34:BHA201:26.555 | BHA201 | SH34 | Bidar | Bidar | Bhalki | 26551 | 10.00 | Slab | 8.00 | repair |
| 1234 | BR:SH34:BHA201:50.68 | BHA201 | SH34 | Bidar | Bidar | Bhalki | 50676 | 12.00 | Slab | 8.00 | routine |
| 1235 | BR:SH34:BHA201:51.08 | BHA201 | SH34 | Bidar | Bidar | Bhalki | 51076 | 10.00 | Slab | 8.00 | repair |
| 1236 | BR:SH34:BHA201:55.24 | BHA201 | SH34 | Bidar | Bidar | Bhalki | 55236 | 9.00 | Slab | 8.00 | repair |
| 1237 | BR:SH34:BHA201:56.515 | BHA201 | SH34 | Bidar | Bidar | Bhalki | 56483 | 8.10 | Girder | 130.90 | repair |
| 1238 | BR:SH34:BHA201:67.79 | BHA201 | SH34 | Bidar | Bidar | Bhalki | 67778 | 8.00 | pipe | 24.50 | repair |
| 1239 | BR:SH34:BAK204_A:73 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 72997 | 12.00 | Slab | 7.50 | routine |
| 1240 | BR:SH34:BAK204_A:78.675 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 78672 | 12.00 | Slab | 7.50 | routine |
| 1241 | BR:SH34:BAK204_A:112.73 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 112726 | 8.50 | Slab | 8.00 | repair |
| 1242 | BR:SH34:BAK204_A:125.735 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 125731 | 10.00 | pipe | 8.50 | repair |
| 1243 | BR:SH34:BAK204_A:128.65 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 128632 | 8.50 | Slab | 36.00 | routine |
| 1244 | BR:SH34:ALD202_A:145.175 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 145171 | 12.00 | Slab | 8.00 | routine |
| 1245 | BR:SH34:ALD202_A:167 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 166997 | 16.00 | Slab | 7.00 | routine |
| 1246 | BR:SH34:ALD202_A:167.1 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 167097 | 16.00 | Slab | 6.50 | routine |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1247 | BR:SH34:ALD202_A:177.595 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 177583 | 8.00 | pipe | 24.50 | repair |
| 1248 | BR:SH34:ALD202_A:190.5 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 190484 | 9.00 | Slab | 33.00 | routine |
| 1249 | BR:SH34:ALD202_A:202.79 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 202776 | 8.00 | pipe | 29.50 | repair |
| 1250 | BR:SH34:AFZ201_A:231.685 | AFZ201_A | SH34 | Gulbarga | Gulbarga | Afzalpur | 231682 | 8.50 | Slab | 6.50 | routine |
| 1251 | BR:SH34:SND201:233.71 | SND201 | SH34 | Bijapur | Bijapur | Sindgi | 233500 | 8.20 | Arch | 432.60 | repair |
| 1252 | BR:SH34:SND201:235.58 | SND201 | SH34 | Bijapur | Bijapur | Sindgi | 235564 | 8.00 | pipe | 33.50 | repair |
| 1253 | BR:SH34:SND201:239.625 | SND201 | SH34 | Bijapur | Bijapur | Sindgi | 239618 | 8.00 | pipe | 15.50 | repair |
| 1254 | BR:SH34:SND201:247.48 | SND201 | SH34 | Bijapur | Bijapur | Sindgi | 247463 | 8.00 | pipe | 34.50 | repair |
| 1255 | BR:SH34:IND12:254.18 | IND12 | SH34 | Bijapur | Bijapur | Indi | 254143 | 8.00 | Slab | 75.00 | repair |
| 1256 | BR:SH34:IND12:262.015 | IND12 | SH34 | Bijapur | Bijapur | Indi | 261950 | 8.50 | Slab | 137.80 | repair |
| 1257 | BR:SH34:IND12:267.12 | IND12 | SH34 | Bijapur | Bijapur | Indi | 267106 | 8.00 | pipe | 28.40 | repair |
| 1258 | BR:SH34:IND12:267.26 | IND12 | SH34 | Bijapur | Bijapur | Indi | 267251 | 8.00 | pipe | 19.50 | repair |
| 1259 | BR:SH34:IND12:277.73 | IND12 | SH34 | Bijapur | Bijapur | Indi | 277722 | 8.50 | Girder | 16.50 | routine |
| 1260 | BR:SH34:IND12:290.7 | IND12 | SH34 | Bijapur | Bijapur | Indi | 290694 | 8.00 | Slab | 13.50 | repair |
| 1261 | BR:SH34:IND12:290.725 | IND12 | SH34 | Bijapur | Bijapur | Indi | 290695 | 8.40 | Slab | 58.00 | repair |
| 1262 | BR:SH34:IND12:300.06 | IND12 | SH34 | Bijapur | Bijapur | Indi | 300054 | 8.00 | Slab | 12.00 | repair |
| 1263 | BR:SH34:IND12:305.305 | IND12 | SH34 | Bijapur | Bijapur | Indi | 305273 | 12.00 | Slab | 78.00 | routine |
| 1264 | BR:SH34:BJP201:312.34 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 312332 | 8.00 | Slab | 16.50 | repair |
| 1265 | BR:SH34:BJP201:319.915 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 319912 | 8.00 | Slab | 7.00 | repair |
| 1266 | BR:SH34:BJP201:337.23 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 337223 | 12.00 | Girder | 14.00 | routine |
| 1267 | BR:SH34:BJP201:349.725 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 349669 | 7.50 | Girder | 111.20 | repair |
| 1268 | BR:SH34:BJP201:350.025 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 350017 | 12.00 | Slab | 16.00 | routine |
| 1269 | BR:SH34:BJP201:352.91 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 352898 | 12.00 | Slab | 24.00 | routine |
| 1270 | BR:SH34:BJP201:357.555 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 357542 | 12.00 | Slab | 27.00 | routine |
| 1271 | BR:SH34:BJP201:358.375 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 358365 | 12.00 | Slab | 21.00 | routine |
| 1272 | BR:SH34:BJP201:359.46 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 359455 | 12.50 | pipe | 10.70 | routine |
| 1273 | BR:SH34:BJP201:365.87 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 365845 | 12.00 | Girder | 50.00 | routine |
| 1274 | BR:SH34:BJP201:369.515 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 369503 | 12.00 | Girder | 25.00 | routine |
| 1275 | BR:SH34:JMK1:378.085 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 378082 | 12.00 | Slab | 7.00 | routine |
| 1276 | BR:SH34:JMK1:380.905 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 380897 | 15.00 | pipe | 16.50 | routine |
| 1277 | BR:SH34:JMK1:383.46 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 383456 | 12.00 | Slab | 8.00 | routine |
| 1278 | BR:SH34:JMK1:391.65 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 391643 | 12.00 | Slab | 14.00 | routine |
| 1279 | BR:SH34:JMK1:392.825 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 392818 | 12.00 | Slab | 14.00 | routine |
| 1280 | BR:SH34:JMK1:395.915 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 395908 | 12.00 | Slab | 14.00 | routine |
| 1281 | BR:SH34:JMK1:397.23 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 397227 | 9.00 | pipe | 7.00 | routine |
| 1282 | BR:SH34:JMK1:402.535 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 402525 | 12.00 | Slab | 21.00 | routine |
| 1283 | BR:SH34:JMK1:402.715 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 402706 | 12.00 | Slab | 18.00 | routine |
| 1284 | BR:SH34:JMK1:406.6 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 406595 | 8.00 | Girder | 10.50 | repair |
| 1285 | BR:SH34:MDL201:409.09 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 409081 | 12.00 | Slab | 18.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1286 | BR:SH34:MDL201:410.4 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 410396 | 12.00 | Slab | 9.00 | routine |
| 1287 | BR:SH34:MDL201:410.61 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 410607 | 12.00 | Slab | 7.00 | routine |
| 1288 | BR:SH34:MDL201:412.84 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 412836 | 12.00 | Slab | 9.00 | routine |
| 1289 | BR:SH34:MDL201:415.57 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 415566 | 12.00 | Slab | 9.00 | routine |
| 1290 | BR:SH34:MDL201:424.99 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 424907 | 8.20 | Girder | 164.40 | repair |
| 1291 | BR:SH34:MDL201:425.58 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 425552 | 8.00 | Girder | 56.00 | repair |
| 1292 | BR:SH34:MDL201:429.855 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 429837 | 12.00 | Girder | 37.80 | routine |
| 1293 | BR:SH34:MDL201:431.03 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 431021 | 12.00 | Slab | 18.00 | routine |
| 1294 | BR:SH34:MDL201:432.995 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 432983 | 12.00 | Girder | 25.20 | routine |
| 1295 | BR:SH34:MDL201:440.345 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 440315 | 8.50 | Girder | 66.00 | routine |
| 1296 | BR:SH34:MDL201:443.77 | MDL201 | SH34 | Bagalkot | Bagalkot | Mudhol | 443757 | 12.00 | Slab | 27.00 | routine |
| 1297 | BR:SH34:RMG206:459.76 | RMG206 | SH34 | Belgaum | Belgaum | Ramdurg | 459740 | 8.00 | Girder | 40.00 | repair |
| 1298 | BR:SH34:RMG206:470.025 | RMG206 | SH34 | Belgaum | Belgaum | Ramdurg | 469947 | 8.20 | Girder | 154.20 | routine |
| 1299 | BR:SH34:RMG206:471.62 | RMG206 | SH34 | Belgaum | Belgaum | Ramdurg | 471611 | 7.50 | Slab | 18.00 | routine |
| 1300 | BR:SH34:RMG206:479.06 | RMG206 | SH34 | Belgaum | Belgaum | Ramdurg | 479056 | 7.50 | pipe | 9.30 | routine |
| 1301 | BR:SH34:SAU201:487.03 | SAU201 | SH34 | Belgaum | Belgaum | Saundatti | 487022 | 8.00 | Slab | 16.00 | routine |
| 1302 | BR:SH34:SAU201:504.185 | SAU201 | SH34 | Belgaum | Belgaum | Saundatti | 504178 | 8.00 | Slab | 14.00 | routine |
| 1303 | BR:SH34:SAU201:504.96 | SAU201 | SH34 | Belgaum | Belgaum | Saundatti | 504957 | 8.00 | Slab | 7.00 | routine |
| 1304 | BR:SH34:SAU201:505.07 | SAU201 | SH34 | Belgaum | Belgaum | Saundatti | 505066 | 12.00 | Slab | 9.00 | routine |
| 1305 | BR:SH34:SAU201:513.09 | SAU201 | SH34 | Belgaum | Belgaum | Saundatti | 513078 | 12.00 | Slab | 24.00 | routine |
| 1306 | BR:SH34:SAU201:524.46 | SAU201 | SH34 | Belgaum | Belgaum | Saundatti | 524447 | 8.50 | Girder | 27.00 | routine |
| 1307 | BR:SH34:DRD2:564.58 | DRD2 | SH34 | Dharwad | Dharwad | Dharwad | 564575 | 12.00 | Slab | 11.00 | routine |
| 1308 | BR:SH34:DRD2:568.495 | DRD2 | SH34 | Dharwad | Dharwad | Dharwad | 568481 | 12.00 | Slab | 28.00 | routine |
| 1309 | BR:SH34:DRD2:576.785 | DRD2 | SH34 | Dharwad | Dharwad | Dharwad | 576770 | 6.00 | Slab | 30.00 | routine |
| 1310 | BR:SH34:KNP203:581.35 | KNP203 | SH34 | Belgaum | Belgaum | Khanapur | 581328 | 12.00 | Girder | 45.00 | routine |
| 1311 | BR:SH34:KNP203:595.725 | KNP203 | SH34 | Belgaum | Belgaum | Khanapur | 595721 | 12.00 | Slab | 9.00 | routine |
| 1312 | BR:SH34:KNP203:602.495 | KNP203 | SH34 | Belgaum | Belgaum | Khanapur | 602491 | 12.00 | Slab | 8.00 | routine |
| 1313 | BR:SH34:KNP203:606 | KNP203 | SH34 | Belgaum | Belgaum | Khanapur | 605996 | 12.00 | Slab | 8.00 | routine |
| 1314 | BR:SH34:JOD208:634.405 | JOD208 | SH34 | Uttara Kannada | Sirsi | Joida | 634323 | 8.50 | Girder | 153.00 | repair |
| 1315 | BR:SH34:JOD208:659.035 | JOD208 | SH34 | Uttara Kannada | Sirsi | Joida | 659032 | 12.00 | Slab | 7.00 | routine |
| 1316 | BR:SH34:JOD208:661 | JOD208 | SH34 | Uttara Kannada | Sirsi | Joida | 660996 | 8.50 | Slab | 8.00 | repair |
| 1317 | BR:SH34:JOD208:669.735 | JOD208 | SH34 | Uttara Kannada | Sirsi | Joida | 669703 | 8.50 | Girder | 64.00 | repair |
| 1318 | BR:SH34:JOD208:683 | JOD208 | SH34 | Uttara Kannada | Sirsi | Joida | 682978 | 8.50 | Girder | 45.00 | repair |
| 1319 | BR:SH34:JOD208:692.465 | JOD208 | SH34 | Uttara Kannada | Sirsi | Joida | 692453 | 10.00 | Slab | 24.00 | repair |
| 1320 | BR:SH34:JOD208:693.025 | JOD208 | SH34 | Uttara Kannada | Sirsi | Joida | 693022 | 9.00 | Slab | 6.50 | repair |
| 1321 | BR:SH34:KRW3:696.77 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 696767 | 10.00 | Slab | 6.50 | repair |
| 1322 | BR:SH34:KRW3:699.805 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 699784 | 8.50 | Girder | 42.00 | repair |
| 1323 | BR:SH34:KRW3:701.095 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 701064 | 8.50 | Girder | 70.00 | repair |
| 1324 | BR:SH34:KRW3:702.695 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 702689 | 9.00 | Slab | 12.00 | repair |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposed |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1325 | BR:SH34:KRW3:703.49 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 703487 | 9.00 | Slab | 6.50 | repair |
| 1326 | BR:SH34:KRW3:704.95 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 704941 | 9.00 | Slab | 19.50 | repair |
| 1327 | BR:SH34:KRW3:708.285 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 708276 | 9.00 | Slab | 18.00 | repair |
| 1328 | BR:SH34:KRW3:710.445 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 710435 | 9.00 | Slab | 21.00 | repair |
| 1329 | BR:SH34:KRW3:711.685 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 711675 | 9.00 | Slab | 21.00 | repair |
| 1330 | BR:SH34:KRW3:717.465 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 717460 | 9.00 | pipe | 11.50 | repair |
| 1331 | BR:SH34:KRW3:719.905 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 719899 | 8.50 | Slab | 12.00 | routine |
| 1332 | BR:SH34:KRW3:720.745 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 720740 | 9.00 | Slab | 11.00 | repair |
| 1333 | BR:SH34:KRW3:722.88 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 722876 | 12.00 | Slab | 8.00 | routine |
| 1334 | BR:SH34:KRW3:723.865 | KRW3 | SH34 | Uttara Kannada | Karwar | Karwar | 723861 | 12.00 | Slab | 8.00 | routine |
| 1335 | BR:SH35:SGA2:5.33 | SGA2 | SH35 | Chikballapur | Chikballapur | Sidlaghatta | 5319 | 11.00 | Slab | 23.20 | routine |
| 1336 | BR:SH35:SGA2:13.9 | SGA2 | SH35 | Chikballapur | Chikballapur | Sidlaghatta | 13896 | 15.00 | pipe | 9.70 | routine |
| 1337 | BR:SH35:HOS4:19.875 | HOS4 | SH35 | Bangalore Rural | Bangalore | Hoskote | 19872 | 8.40 | Slab | 7.70 | routine |
| 1338 | BR:SH35:HOS4:22.16 | HOS4 | SH35 | Bangalore Rural | Bangalore | Hoskote | 22156 | 10.00 | pipe | 9.70 | repair |
| 1339 | BR:SH35:HOS4:24.545 | HOS4 | SH35 | Bangalore Rural | Bangalore | Hoskote | 24542 | 8.50 | Slab | 6.00 | routine |
| 1340 | BR:SH35:HOS4:25.665 | HOS4 | SH35 | Bangalore Rural | Bangalore | Hoskote | 25661 | 10.00 | pipe | 8.50 | repair |
| 1341 | BR:SH35:HOS4:28.705 | HOS4 | SH35 | Bangalore Rural | Bangalore | Hoskote | 28702 | 10.00 | pipe | 6.30 | repair |
| 1342 | BR:SH35:HOS4:29.545 | HOS4 | SH35 | Bangalore Rural | Bangalore | Hoskote | 29541 | 8.40 | Slab | 8.20 | routine |
| 1343 | BR:SH35:HOS4:30.82 | HOS4 | SH35 | Bangalore Rural | Bangalore | Hoskote | 30817 | 12.10 | Slab | 6.40 | routine |
| 1344 | BR:SH35:HOS4:35.44 | HOS4 | SH35 | Bangalore Rural | Bangalore | Hoskote | 35429 | 12.00 | Slab | 23.20 | routine |
| 1345 | BR:SH35:BNE7:42.263 | BNE7 | SH35 | Bangalore Urban | Bangalore | Bangalore-East | 42260 | 18.00 | Slab | 6.00 | routine |
| 1346 | BR:SH35:BNE7:46.743 | BNE7 | SH35 | Bangalore Urban | Bangalore | Bangalore-East | 46729 | 11.60 | Slab | 29.40 | routine |
| 1347 | BR:SH35:BNE7:46.748 | BNE7 | SH35 | Bangalore Urban | Bangalore | Bangalore-East | 46734 | 11.80 | Girder | 29.40 | routine |
| 1348 | BR:SH35:BNE7:54.188 | BNE7 | SH35 | Bangalore Urban | Bangalore | Bangalore-East | 54146 | 10.80 | Girder | 85.00 | routine |
| 1349 | BR:SH35:ANK3:70.651 | ANK3 | SH35 | Bangalore Urban | Bangalore | Anekal | 70648 | 10.60 | pipe | 6.30 | repair |
| 1350 | BR:SH35:ANK3:81.346 | ANK3 | SH35 | Bangalore Urban | Bangalore | Anekal | 81329 | 8.40 | Slab | 34.00 | repair |
| 1351 | BR:SH37:SLY203:1.705 | SLY203 | SH37 | Dakshina Kannada | Mangalore | Sulya | 1656 | 8.00 | Slab | 99.00 | routine |
| 1352 | BR:SH37:PUT3:6.265 | PUT3 | SH37 | Dakshina Kannada | Mangalore | Puttur | 6247 | 8.00 | Slab | 36.00 | repair |
| 1353 | BR:SH37:PUT3:11.015 | PUT3 | SH37 | Dakshina Kannada | Mangalore | Puttur | 10994 | 8.00 | Slab | 42.00 | repair |
| 1354 | BR:SH37:PUT3:11.995 | PUT3 | SH37 | Dakshina Kannada | Mangalore | Puttur | 11985 | 12.00 | Slab | 20.00 | routine |
| 1355 | BR:SH37:PUT3:15.88 | PUT3 | SH37 | Dakshina Kannada | Mangalore | Puttur | 15870 | 12.00 | Slab | 20.00 | routine |
| 1356 | BR:SH37:PUT3:26.8 | PUT3 | SH37 | Dakshina Kannada | Mangalore | Puttur | 26727 | 12.00 | Girder | 147.00 | routine |
| 1357 | BR:SH37:BEL2:35.549 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 35543 | 10.00 | pipe | 13.10 | repair |
| 1358 | BR:SH37:BEL2:40.769 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 40711 | 8.00 | Slab | 117.00 | routine |
| 1359 | BR:SH37:BEL2:48.519 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 48477 | 8.00 | Slab | 85.00 | routine |
| 1360 | BR:SH37:BEL2:50.439 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 50435 | 8.50 | pipe | 8.50 | repair |
| 1361 | BR:SH37:BEL2:55.289 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 55249 | 8.00 | Girder | 80.00 | repair |
| 1362 | BR:SH37:BEL2:75.954 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 75912 | 8.00 | Girder | 84.00 | repair |
| 1363 | BR:SH37:BEL2:79.212 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 79184 | 8.00 | Girder | 56.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1364 | BR:SH37:BEL2:83.337 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 83330 | 8.00 | Girder | 14.00 | repair |
| 1365 | BR:SH37:BEL2:83.707 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 83686 | 8.00 | Girder | 42.00 | repair |
| 1366 | BR:SH37:BEL2:84.917 | BEL2 | SH37 | Dakshina Kannada | Mangalore | Belthangady | 84889 | 9.00 | Girder | 56.00 | repair |
| 1367 | BR:SH37:KRK42:93.572 | KRK42 | SH37 | Udupi | Udupi | Karkala | 93542 | 9.00 | Girder | 60.00 | repair |
| 1368 | BR:SH37:KRK42:94.362 | KRK42 | SH37 | Udupi | Udupi | Karkala | 94355 | 8.00 | Girder | 14.00 | repair |
| 1369 | BR:SH37:KRK42:94.877 | KRK42 | SH37 | Udupi | Udupi | Karkala | 94873 | 8.00 | pipe | 8.50 | repair |
| 1370 | BR:SH37:KRK42:123.967 | KRK42 | SH37 | Udupi | Udupi | Karkala | 123947 | 8.00 | Slab | 40.80 | repair |
| 1371 | BR:SH37:KRK42:129.922 | KRK42 | SH37 | Udupi | Udupi | Karkala | 129907 | 8.00 | Slab | 30.00 | repair |
| 1372 | BR:SH37:UDP3:146.977 | UDP3 | SH37 | Udupi | Udupi | Udupi | 146957 | 8.00 | Girder | 40.00 | repair |
| 1373 | BR:SH37:UDP3:150.057 | UDP3 | SH37 | Udupi | Udupi | Udupi | 150044 | 8.00 | Slab | 27.00 | routine |
| 1374 | BR:SH38:KLL302:6.582 | KLL302 | SH38 | Chamrajnagar | Chamrajnagar | Kollegal | 6576 | 8.50 | Slab | 13.80 | repair |
| 1375 | BR:SH38:KLL302:20.722 | KLL302 | SH38 | Chamrajnagar | Chamrajnagar | Kollegal | 20719 | 8.50 | Slab | 7.50 | repair |
| 1376 | BR:SH38:KLL302:23.492 | KLL302 | SH38 | Chamrajnagar | Chamrajnagar | Kollegal | 23489 | 10.00 | pipe | 7.00 | routine |
| 1377 | BR:SH38:KLL302:28.702 | KLL302 | SH38 | Chamrajnagar | Chamrajnagar | Kollegal | 28699 | 10.00 | pipe | 7.00 | repair |
| 1378 | BR:SH38:KLL302:41.117 | KLL302 | SH38 | Chamrajnagar | Chamrajnagar | Kollegal | 41106 | 7.50 | pipe | 23.30 | routine |
| 1379 | BR:SH39:BNG4:3.805 | BNG4 | SH39 | Bangalore Urban | Bangalore | Bangalore-North | 3802 | 12.00 | Slab | 6.50 | routine |
| 1380 | BR:SH39:BNG4:4.3 | BNG4 | SH39 | Bangalore Urban | Bangalore | Bangalore-North | 4297 | 11.90 | Slab | 7.80 | routine |
| 1381 | BR:SH39:BNG4:7.275 | BNG4 | SH39 | Bangalore Urban | Bangalore | Bangalore-North | 7263 | 12.60 | Slab | 25.20 | routine |
| 1382 | BR:SH39:BNG4:11.27 | BNG4 | SH39 | Bangalore Urban | Bangalore | Bangalore-North | 11267 | 12.40 | Slab | 6.50 | routine |
| 1383 | BR:SH40:HDG201:1.995 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 1987 | 8.00 | Slab | 16.00 | routine |
| 1384 | BR:SH40:HDG201:5.87 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 5867 | 10.00 | Pipe | 6.30 | repair |
| 1385 | BR:SH40:HDG201:6.4 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 6391 | 10.00 | Slab | 18.00 | routine |
| 1386 | BR:SH40:HDG201:14.425 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 14418 | 10.00 | Slab | 15.00 | routine |
| 1387 | BR:SH40:HDG201:15.13 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 15110 | 10.00 | Slab | 40.00 | routine |
| 1388 | BR:SH40:HDG201:17.735 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 17729 | 10.00 | Pipe | 13.10 | repair |
| 1389 | BR:SH40:HDG201:25.89 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 25886 | 10.00 | Pipe | 9.70 | routine |
| 1390 | BR:SH40:HDG201:30.475 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 30471 | 10.00 | Slab | 8.00 | routine |
| 1391 | BR:SH40:HDG201:32.495 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 32477 | 12.00 | Slab | 36.00 | routine |
| 1392 | BR:SH40:HDG201:37.515 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 37497 | 12.00 | Slab | 36.00 | routine |
| 1393 | BR:SH40:HDG201:45.435 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 45430 | 10.00 | Slab | 10.00 | repair |
| 1394 | BR:SH40:HDG201:47.15 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 47146 | 10.00 | Slab | 8.00 | repair |
| 1395 | BR:SH40:HGB59:68.155 | HGB59 | SH40 | Bellary | Hadagalli | Hagaribommanahalli | 68152 | 8.00 | Slab | 6.60 | repair |
| 1396 | BR:SH40:HGB59:82.7 | HGB59 | SH40 | Bellary | Hadagalli | Hagaribommanahalli | 82694 | 10.00 | Slab | 12.00 | routine |
| 1397 | BR:SH40:HGB59:91.435 | HGB59 | SH40 | Bellary | Hadagalli | Hagaribommanahalli | 91432 | 12.00 | Slab | 6.60 | routine |
| 1398 | BR:SH40:HGB59:94.165 | HGB59 | SH40 | Bellary | Hadagalli | Hagaribommanahalli | 94162 | 12.00 | Slab | 6.60 | routine |
| 1399 | BR:SH40:KDL3:100.145 | KDL3 | SH40 | Bellary | Hadagalli | Kudligi | 100133 | 10.00 | Slab | 24.00 | routine |
| 1400 | BR:SH40:KDL3:101.225 | KDL3 | SH40 | Bellary | Hadagalli | Kudligi | 101222 | 10.00 | Pipe | 6.30 | repair |
| 1401 | BR:SH40:KDL3:102.03 | KDL3 | SH40 | Bellary | Hadagalli | Kudligi | 102021 | 10.00 | Pipe | 19.00 | routine |
| 1402 | BR:SH40:KDL3:109.955 | KDL3 | SH40 | Bellary | Hadagalli | Kudligi | 109952 | 12.00 | Slab | 6.50 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1403 | BR:SH40:SNR2:113.08 | SNR2 | SH40 | Bellary | Bellary | Sandur | 113077 | 12.00 | Slab | 7.00 | routine |
| 1404 | BR:SH40:SNR2:113.71 | SNR2 | SH40 | Bellary | Bellary | Sandur | 113707 | 12.00 | Slab | 7.00 | routine |
| 1405 | BR:SH40:SNR2:114.355 | SNR2 | SH40 | Bellary | Bellary | Sandur | 114352 | 12.00 | Slab | 7.00 | routine |
| 1406 | BR:SH40:SNR2:116.885 | SNR2 | SH40 | Bellary | Bellary | Sandur | 116882 | 10.00 | Pipe | 6.70 | routine |
| 1407 | BR:SH40:SNR2:121.025 | SNR2 | SH40 | Bellary | Bellary | Sandur | 121022 | 12.50 | Pipe | 7.00 | routine |
| 1408 | BR:SH40:SNR2:122.985 | SNR2 | SH40 | Bellary | Bellary | Sandur | 122980 | 10.00 | Slab | 10.00 | routine |
| 1409 | BR:SH40:SNR2:128.435 | SNR2 | SH40 | Bellary | Bellary | Sandur | 128401 | 8.00 | Girder | 50.40 | repair |
| 1410 | BR:SH40:SNR2:131.765 | SNR2 | SH40 | Bellary | Bellary | Sandur | 131734 | 12.00 | Girder | 57.45 | routine |
| 1411 | BR:SH40:SNR2:137.965 | SNR2 | SH40 | Bellary | Bellary | Sandur | 137955 | 7.50 | Pipe | 20.50 | routine |
| 1412 | BR:SH40:SNR2:140.05 | SNR2 | SH40 | Bellary | Bellary | Sandur | 140038 | 8.00 | Slab | 24.00 | routine |
| 1413 | BR:SH40:SNR2:145.66 | SNR2 | SH40 | Bellary | Bellary | Sandur | 145657 | 8.00 | Slab | 6.60 | routine |
| 1414 | BR:SH40:SNR2:150.965 | SNR2 | SH40 | Bellary | Bellary | Sandur | 150923 | 12.00 | Girder | 68.40 | routine |
| 1415 | BR:SH40:SNR2:151.79 | SNR2 | SH40 | Bellary | Bellary | Sandur | 151787 | 12.00 | Slab | 6.50 | routine |
| 1416 | BR:SH41:IND2:2.095 | IND2 | SH41 | Bijapur | Bijapur | Indi | 2039 | 8.50 | Girder | 104.00 | repair |
| 1417 | BR:SH41:IND2:12.12 | IND2 | SH41 | Bijapur | Bijapur | Indi | 12029 | 7.80 | Slab | 196.00 | repair |
| 1418 | BR:SH41:IND2:20.05 | IND2 | SH41 | Bijapur | Bijapur | Indi | 20032 | 8.00 | Slab | 36.00 | routine |
| 1419 | BR:SH41:IND2:30.615 | IND2 | SH41 | Bijapur | Bijapur | Indi | 30597 | 8.00 | Slab | 37.50 | routine |
| 1420 | BR:SH41:IND2:31.18 | IND2 | SH41 | Bijapur | Bijapur | Indi | 31153 | 8.00 | Slab | 54.00 | repair |
| 1421 | BR:SH41:IND2:46.371 | IND2 | SH41 | Bijapur | Bijapur | Indi | 46347 | 12.00 | Slab | 48.00 | routine |
| 1422 | BR:SH41:IND2:65.052 | IND2 | SH41 | Bijapur | Bijapur | Indi | 65028 | 8.00 | Slab | 48.00 | repair |
| 1423 | BR:SH41:IND2:68.927 | IND2 | SH41 | Bijapur | Bijapur | Indi | 68849 | 8.50 | Girder | 165.20 | routine |
| 1424 | BR:SH41:IND2:71.692 | IND2 | SH41 | Bijapur | Bijapur | Indi | 71688 | 12.00 | Slab | 9.00 | routine |
| 1425 | BR:SH41:SND3:76.228 | SND3 | SH41 | Bijapur | Bijapur | Sindgi | 76223 | 12.00 | Slab | 10.00 | routine |
| 1426 | BR:SH41:SND3:76.783 | SND3 | SH41 | Bijapur | Bijapur | Sindgi | 76761 | 8.00 | pipe | 45.50 | repair |
| 1427 | BR:SH41:SND3:92.312 | SND3 | SH41 | Bijapur | Bijapur | Sindgi | 92299 | 8.00 | Slab | 26.00 | repair |
| 1428 | BR:SH41:BBV2:101.261 | BBV2 | SH41 | Bijapur | Bijapur | Basavanabagevadi | 101201 | 8.20 | Slab | 104.00 | repair |
| 1429 | BR:SH41:BBV2:110.016 | BBV2 | SH41 | Bijapur | Bijapur | Basavanabagevadi | 110001 | 8.00 | Slab | 30.00 | repair |
| 1430 | BR:SH41:BBV2:114.451 | BBV2 | SH41 | Bijapur | Bijapur | Basavanabagevadi | 114439 | 8.00 | Slab | 24.00 | repair |
| 1431 | BR:SH41:BBV2:126.923 | BBV2 | SH41 | Bijapur | Bijapur | Basavanabagevadi | 126881 | 8.50 | Slab | 72.00 | repair |
| 1432 | BR:SH41:BBV2:129.028 | BBV2 | SH41 | Bijapur | Bijapur | Basavanabagevadi | 129011 | 8.00 | Slab | 35.00 | repair |
| 1433 | BR:SH41:BBV2:131.388 | BBV2 | SH41 | Bijapur | Bijapur | Basavanabagevadi. | 131384 | 8.00 | Slab | 9.00 | repair |
| 1434 | BR:SH41:MDD1:137.023 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 137015 | 10.00 | pipe | 16.30 | repair |
| 1435 | BR:SH41:MDD1:145.818 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 145810 | 12.00 | Slab | 16.00 | routine |
| 1436 | BR:SH41:MDD1:151.478 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 151473 | 12.00 | Slab | 10.00 | routine |
| 1437 | BR:SH41:MDD1:154.088 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 154083 | 12.00 | Slab | 10.00 | routine |
| 1438 | BR:SH41:MDD1:154.448 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 154443 | 12.00 | Slab | 10.00 | routine |
| 1439 | BR:SH41:MDD1:158.378 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 158371 | 8.50 | Slab | 15.00 | repair |
| 1440 | BR:SH41:MDD1:161.468 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 161465 | 10.00 | Slab | 6.60 | repair |
| 1441 | BR:SH41:MDD1:174.498 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 174483 | 8.00 | Slab | 30.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1442 | BR:SH41:MDD1:176.878 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 176863 | 8.00 | Girder | 30.00 | routine |
| 1443 | BR:SH41:MDD1:178.503 | MDD1 | SH41 | Raichur | Raichur | Lingsugur | 177571 | 12.00 | Girder | 1174.95 | routine |
| 1444 | BR:SH41:LIN5:186.611 | LIN5 | SH41 | Raichur | Raichur | Lingsugur | 186578 | 7.30 | Slab | 62.40 | repair |
| 1445 | BR:SH41:LIN5:192.086 | LIN5 | SH41 | Raichur | Raichur | Lingsugur | 192074 | 9.00 | Slab | 24.00 | routine |
| 1446 | BR:SH44:HUK3:3.435 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 3419 | 8.00 | Slab | 32.00 | routine |
| 1447 | BR:SH44:HUK3:4.53 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 4525 | 12.50 | pipe | 10.00 | routine |
| 1448 | BR:SH44:HUK3:5.8 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 5796 | 12.00 | Slab | 9.00 | routine |
| 1449 | BR:SH44:HUK3:11.74 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 11727 | 12.00 | Slab | 27.00 | routine |
| 1450 | BR:SH44:HUK3:13.53 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 13526 | 12.00 | Slab | 9.00 | routine |
| 1451 | BR:SH44:HUK3:18.595 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 18577 | 12.00 | Girder | 37.50 | routine |
| 1452 | BR:SH44:HUK3:21.36 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 21345 | 12.00 | Girder | 30.00 | routine |
| 1453 | BR:SH44:HUK3:21.59 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 21587 | 12.00 | Slab | 6.50 | routine |
| 1454 | BR:SH44:HUK3:22.725 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 22716 | 8.50 | others | 18.00 | routine |
| 1455 | BR:SH44:HUK3:24.615 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 24606 | 12.00 | Slab | 18.00 | routine |
| 1456 | BR:SH44:HUK3:25.42 | HUK3 | SH44 | Belgaum | Chikkodi | Hukkeri | 25416 | 8.50 | others | 9.00 | routine |
| 1457 | BR:SH44:GOK6:31.455 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 31446 | 8.00 | Girder | 18.00 | repair |
| 1458 | BR:SH44:GOK6:34.835 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 34822 | 12.00 | Slab | 27.00 | routine |
| 1459 | BR:SH44:GOK6:35.165 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 35161 | 12.00 | Slab | 9.00 | routine |
| 1460 | BR:SH44:GOK6:52.544 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 52499 | 12.00 | Girder | 90.00 | routine |
| 1461 | BR:SH44:GOK6:57.654 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 57650 | 10.00 | pipe | 9.50 | repair |
| 1462 | BR:SH44:GOK6:69.499 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 69467 | 8.00 | Pipe | 98.30 | repair |
| 1463 | BR:SH44:GOK6:76.759 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 76720 | 8.00 | Pipe | 115.20 | repair |
| 1464 | BR:SH44:MDL202:97.809 | MDL202 | SH44 | Bagalkot | Bagalkot | Mudhol | 97806 | 10.00 | pipe | 7.90 | routine |
| 1465 | BR:SH44:BDM204:113.309 | BDM204 | SH44 | Bagalkot | Bagalkot | Badami | 113299 | 12.00 | Slab | 20.80 | routine |
| 1466 | BR:SH44:BDM204:116.069 | BDM204 | SH44 | Bagalkot | Bagalkot | Badami | 116060 | 12.00 | Slab | 18.00 | routine |
| 1467 | BR:SH44:BDM204:153.302 | BDM204 | SH44 | Bagalkot | Bagalkot | Badami | 153296 | 8.00 | Slab | 13.00 | repair |
| 1468 | BR:SH44:HUD206:178.235 | HUD206 | SH44 | Bagalkot | Bagalkot | Hungund | 178216 | 8.00 | pipe | 39.50 | repair |
| 1469 | BR:SH44:HUD206:183.855 | HUD206 | SH44 | Bagalkot | Bagalkot | Hungund | 183846 | 12.00 | Slab | 18.00 | routine |
| 1470 | BR:SH44:HUD206:187.929 | HUD206 | SH44 | Bagalkot | Bagalkot | Hungund | 187925 | 8.00 | pipe | 9.70 | routine |
| 1471 | BR:SH44:HUD206:190.799 | HUD206 | SH44 | Bagalkot | Bagalkot | Hungund | 190772 | 7.50 | Slab | 54.00 | routine |
| 1472 | BR:SH45:GOK203:4.01 | GOK203 | SH45 | Belgaum | Chikkodi | Gokak | 4001 | 12.00 | Slab | 18.00 | routine |
| 1473 | BR:SH45:GOK203:15.86 | GOK203 | SH45 | Belgaum | Chikkodi | Gokak | 15847 | 8.50 | others | 27.00 | routine |
| 1474 | BR:SH45:GOK203:19.33 | GOK203 | SH45 | Belgaum | Chikkodi | Gokak | 19323 | 12.00 | Slab | 14.00 | routine |
| 1475 | BR:SH45:GOK203:20.91 | GOK203 | SH45 | Belgaum | Chikkodi | Gokak | 20853 | 12.00 | Slab | 73.50 | routine |
| 1476 | BR:SH45:GOK203:22.11 | GOK203 | SH45 | Belgaum | Chikkodi | Gokak | 22101 | 12.00 | Slab | 18.00 | routine |
| 1477 | BR:SH45:GOK203:23.945 | GOK203 | SH45 | Belgaum | Chikkodi | Gokak | 23938 | 12.00 | Slab | 14.00 | routine |
| 1478 | BR:SH45:GOK203:25.95 | GOK203 | SH45 | Belgaum | Chikkodi | Gokak | 25932 | 10.00 | Girder | 36.00 | routine |
| 1479 | BR:SH45:SAU3:26.785 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 26776 | 12.00 | Slab | 18.00 | routine |
| 1480 | BR:SH45:SAU3:30.345 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 30339 | 12.00 | Girder | 12.50 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m. | Type of SuperStr. | Bridge Len (m) | Tentative Improvement Proposals |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1481 | BR:SH45:SAU3:30.645 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 30638 | 12.00 | Slab | 14.00 | routine |
| 1482 | BR:SH45:SAU3:34.751 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 34736 | 12.00 | Girder | 30.00 | routine |
| 1483 | BR:SH45:SAU3:55.246 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 55159 | 12.00 | Girder | 172.20 | routine |
| 1484 | BR:SH45:SAU3:69.776 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 69758 | 12.00 | Slab | 36.00 | routine |
| 1485 | BR:SH45:SAU3:74.386 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 74379 | 12.00 | Slab | 14.00 | routine |
| 1486 | BR:SH45:SAU3:75.996 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 75983 | 12.00 | Slab | 27.00 | routine |
| 1487 | BR:SH45:NGD201:92.887 | NGD201 | SH45 | Gadag | Gadag | Nargund | 92882 | 10.00 | Pipe | 11.50 | repair |
| 1488 | BR:SH45:NGD201:96.692 | NGD201 | SH45 | Gadag | Gadag | Nargund | 96663 | 8.50 | Pipe | 81.50 | repair |
| 1489 | BR:SH45:NVG201:97.112 | NVG201 | SH45 | Dharwad | Dharwad | Navalgund | 97101 | 7.50 | Pipe | 23.50 | repair |
| 1490 | BR:SH45:NVG201:113.292 | NVG201 | SH45 | Dharwad | Dharwad | Navalgund | 113283 | 8.50 | Slab | 18.00 | routine |
| 1491 | BR:SH45:GDG205:121.091 | GDG205 | SH45 | Gadag | Gadag | Gadag | 121084 | 12.00 | Slab | 14.00 | routine |
| 1492 | BR:SH45:GDG205:144.911 | GDG205 | SH45 | Gadag | Gadag | Gadag | 144904 | 12.00 | Slab | 14.00 | routine |
| 1493 | BR:SH45:GDG205:146.426 | GDG205 | SH45 | Gadag | Gadag | Gadag | 146421 | 12.00 | Girder | 10.00 | routine |
| 1494 | BR:SH45:GDG205:147.131 | GDG205 | SH45 | Gadag | Gadag | Gadag | 147119 | 12.00 | Girder | 25.00 | routine |
| 1495 | BR:SH45:MUI209:148.621 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 148606 | 12.00 | Girder | 30.00 | routine |
| 1496 | BR:SH45:MUI209:151.716 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 151707 | 12.00 | Slab | 18.00 | routine |
| 1497 | BR:SH45:MUI209:158.541 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 158529 | 12.00 | Slab | 24.00 | routine |
| 1498 | BR:SH45:MUI209:163.841 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 163810 | 12.00 | Girder | 79.50 | routine |
| 1499 | BR:SH45:MUI209:165.046 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 165038 | 12.00 | Slab | 16.00 | routine |
| 1500 | BR:SH45:MUI209:170.721 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 170701 | 12.00 | Girder | 40.00 | routine |
| 1501 | BR:SH45:MUI209:173.056 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 173048 | 12.00 | Slab | 16.00 | routine |
| 1502 | BR:SH45:MUI209:178.104 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 178082 | 12.00 | Slab | 45.00 | routine |
| 1503 | BR:SH45:MUI209:184.103 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 184091 | 8.00 | Slab | 25.50 | repair |
| 1504 | BR:SH45:MUI209:186.513 | MUI209 | SH45 | Gadag | Gadag | Mundargi | 186313 | 8.50 | Girder | 415.00 | routine |
| 1505 | BR:SH45:HDG202:195.638 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 195635 | 8.00 | Slab | 6.80 | repair |
| 1506 | BR:SH45:HDG202:202.623 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 202613 | 17.50 | Pipe | 20.50 | routine |
| 1507 | BR:SH45:HDG202:203.433 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 203429 | 8.00 | Slab | 8.00 | repair |
| 1508 | BR:SH45:HDG202:204.758 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 204752 | 12.00 | Slab | 12.00 | routine |
| 1509 | BR:SH45:HDG202:206.263 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 206260 | 12.00 | Slab | 6.50 | routine |
| 1510 | BR:SH45:HDG202:209.738 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 209729 | 12.00 | Slab | 19.00 | routine |
| 1511 | BR:SH45:HDG202:210.813 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 210804 | 12.00 | Slab | 18.00 | routine |
| 1512 | BR:SH45:HDG202:217.692 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 217683 | 12.00 | Slab | 18.00 | routine |
| 1513 | BR:SH45:HDG202:220.652 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 220640 | 12.00 | Slab | 24.00 | routine |
| 1514 | BR:SH45:HDG202:221.392 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 221382 | 12.00 | Slab | 20.00 | routine |
| 1515 | BR:SH45:JGL201:282.509 | JGL201 | SH45 | Davanagere | Davanagere | Jagalur | 282505 | 12.50 | Pipe | 8.00 | routine |
| 1516 | BR:SH45:JGL201:285.854 | JGL201 | SH45 | Davanagere | Davanagere | Jagalur | 285849 | 12.00 | Slab | 10.00 | routine |
| 1517 | BR:SH45:JGL201:290.269 | JGL201 | SH45 | Davanagere | Davanagere | Jagalur | 290243 | 12.00 | Girder | 52.00 | routine |
| 1518 | BR:SH45:JGL201:290.564 | JGL201 | SH45 | Davanagere | Davanagere | Jagalur | 290561 | 5.00 | Slab | 6.40 | routine |
| 1519 | BR:SH45:JGL201:291.624 | JGL201 | SH45 | Davanagere | Davanagere | Jagalur | 291617 | 12.50 | Pipe | 14.80 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1520 | BR:SH45:CHL203:308.353 | CHL203 | SH45 | Chitradurga | Chitradurga | Challakere | 308337 | 8.00 | Pipe | 32.80 | repair |
| 1521 | BR:SH45:CHL203:314.903 | CHL203 | SH45 | Chitradurga | Chitradurga | Challakere | 314900 | 12.00 | Slab | 7.50 | routine |
| 1522 | BR:SH45:CHL203:315.848 | CHL203 | SH45 | Chitradurga | Chitradurga | Challakere | 315840 | 10.00 | Slab | 16.00 | routine |
| 1523 | BR:SH45:CHL203:319.528 | CHL203 | SH45 | Chitradurga | Chitradurga | Challakere | 319524 | 10.00 | Pipe | 8.00 | routine |
| 1524 | BR:SH45:CHL203:320.288 | CHL203 | SH45 | Chitradurga | Chitradurga | Challakere | 320284 | 12.50 | Pipe | 8.00 | routine |
| 1525 | BR:SH45:CHL203:322.578 | CHL203 | SH45 | Chitradurga | Chitradurga | Challakere | 322574 | 8.00 | Pipe | 9.70 | routine |
| 1526 | BR:SH45:CHL203:322.713 | CHL203 | SH45 | Chitradurga | Chitradurga | Challakere | 322708 | 9.40 | Slab | 10.80 | repair |
| 1527 | BR:SH46:KLG2:12.336 | KLG2 | SH46 | Dharwad | Dharwad | Kalaghatgi | 12324 | 8.50 | Girder | 24.00 | repair |
| 1528 | BR:SH46:KLG2:20.546 | KLG2 | SH46 | Dharwad | Dharwad | Kalaghatgi | 20535 | 8.00 | Slab | 22.50 | repair |
| 1529 | BR:SH46:KLG2:23.436 | KLG2 | SH46 | Dharwad | Dharwad | Kalaghatgi | 23396 | 8.50 | Girder | 78.40 | repair |
| 1530 | BR:SH46:KLG2:34.901 | KLG2 | SH46 | Dharwad | Dharwad | Kalaghatgi | 34894 | 8.00 | Pipe | 15.70 | repair |
| 1531 | BR:SH46:KLG2:35.916 | KLG2 | SH46 | Dharwad | Dharwad | Kalaghatgi | 35912 | 12.00 | Slab | 9.00 | routine |
| 1532 | BR:SH46:HLY201:39.936 | HLY201 | SH46 | Uttara Kannada | Sirsi | Haliyal | 39930 | 8.00 | Slab | 12.00 | repair |
| 1533 | BR:SH46:HLY201:45.709 | HLY201 | SH46 | Uttara Kannada | Sirsi | Haliyal | 45704 | 9.00 | Slab | 11.00 | repair |
| 1534 | BR:SH46:HLY201:52.109 | HLY201 | SH46 | Uttara Kannada | Sirsi | Haliyal | 52098 | 8.00 | Slab | 23.00 | repair |
| 1535 | BR:SH46:JOD202:108.265 | JOD202 | SH46 | Uttara Kannada | Sirsi | Joida | 108217 | 8.50 | Slab | 96.00 | routine |
| 1536 | BR:SH46:JOD202:130.29 | JOD202 | SH46 | Uttara Kannada | Sirsi | Joida | 130286 | 8.00 | Slab | 8.00 | repair |
| 1537 | BR:SH46:JOD202:132.865 | JOD202 | SH46 | Uttara Kannada | Sirsi | Joida | 132862 | 9.00 | Slab | 6.50 | repair |
| 1538 | BR:SH46:JOD202:133.675 | JOD202 | SH46 | Uttara Kannada | Sirsi | Joida | 133672 | 9.00 | Slab | 6.50 | repair |
| 1539 | BR:SH47:MND6:0.25 | MND6 | SH47 | Mandya | Mandya | Mandya | 245 | 11.00 | Slab | 11.20 | routine |
| 1540 | BR:SH47:MND6:4.79 | MND6 | SH47 | Mandya | Mandya | Mandya | 4778 | 11.00 | Slab | 24.00 | routine |
| 1541 | BR:SH47:MND6:6.165 | MND6 | SH47 | Mandya | Mandya | Mandya | 6162 | 8.00 | pipe | 7.00 | repair |
| 1542 | BR:SH47:MND6:8.02 | MND6 | SH47 | Mandya | Mandya | Mandya | 8017 | 8.00 | pipe | 7.00 | repair |
| 1543 | BR:SH47:MND6:13.286 | MND6 | SH47 | Mandya | Mandya | Mandya | 13280 | 8.50 | Slab | 12.00 | repair |
| 1544 | BR:SH47:MND6:22.735 | MND6 | SH47 | Mandya | Mandya | Mandya | 22719 | 8.50 | Slab | 32.00 | repair |
| 1545 | BR:SH47:PDP212:26.395 | PDP212 | SH47 | Mandya | Mandya | Pandavapura | 26392 | 12.00 | Slab | 6.50 | routine |
| 1546 | BR:SH47:PDP212:29.155 | PDP212 | SH47 | Mandya | Mandya | Pandavapura | 29152 | 12.00 | Slab | 6.50 | routine |
| 1547 | BR:SH47:PDP212:29.385 | PDP212 | SH47 | Mandya | Mandya | Pandavapura | 29378 | 8.00 | Girder | 14.00 | routine |
| 1548 | BR:SH47:KRP248:57.04 | KRP248 | SH47 | Mandya | Mandya | Krishnarajpet | 57019 | 8.50 | Girder | 42.00 | routine |
| 1549 | BR:SH47:KRP248:58.185 | KRP248 | SH47 | Mandya | Mandya | Krishnarajpet | 58175 | 12.50 | Slab | 20.00 | routine |
| 1550 | BR:SH47:CRP201:68.455 | CRP201 | SH47 | Hassan | Hassan | Channarayapattana | 68452 | 10.00 | Pipe | 7.00 | repair |
| 1551 | BR:SH47:CRP201:82.483 | CRP201 | SH47 | Hassan | Hassan | Channarayapattana | 82475 | 8.50 | Pipe | 17.00 | repair |
| 1552 | BR:SH47:CRP201:106.448 | CRP201 | SH47 | Hassan | Hassan | Channarayapattana | 106442 | 10.00 | Pipe | 13.10 | repair |
| 1553 | BR:SH47:TPT213:109.808 | TPT213 | SH47 | Tumkur | Tumkur | Tiptur | 109800 | 8.50 | Slab | 16.00 | repair |
| 1554 | BR:SH47:TPT213:112.668 | TPT213 | SH47 | Tumkur | Tumkur | Tiptur | 112640 | 9.00 | Slab | 56.00 | repair |
| 1555 | BR:SH47:TPT213:113.443 | TPT213 | SH47 | Tumkur | Tumkur | Tiptur | 113435 | 8.00 | Slab | 16.00 | repair |
| 1556 | BR:SH47:TPT213:137.038 | TPT213 | SH47 | Tumkur | Tumkur | Tiptur | 137026 | 12.00 | Slab | 24.00 | routine |
| 1557 | BR:SH47:TPT213:144.688 | TPT213 | SH47 | Tumkur | Tumkur | Tiptur | 144682 | 12.00 | Slab | 12.00 | routine |
| 1558 | BR:SH47:CNH201:145.628 | CNH201 | SH47 | Tumkur | Tumkur | Chiknayakanahalli | 145625 | 9.00 | Slab | 7.00 | repair |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl.No | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1559 | BR:SH47:CNH201:158.283 | CNH201 | SH47 | Tumkur | Tumkur | Chiknayakanahalli | 158279 | 12.00 | Slab | 9.00 | routine |
| 1560 | BR:SH47:CNH201:173.892 | CNH201 | SH47 | Tumkur | Tumkur | Chiknayakanahalli | 173887 | 8.50 | Pipe | 11.40 | repair |
| 1561 | BR:SH47:HSD201:176.077 | HSD201 | SH47 | Chitradurga | Chitradurga | Hosdurga | 176074 | 8.50 | Slab | 7.50 | repair |
| 1562 | BR:SH47:HSD201:177.657 | HSD201 | SH47 | Chitradurga | Chitradurga | Hosdurga | 177654 | 9.50 | Slab | 6.40 | repair |
| 1563 | BR:SH47:HSD201:178.672 | HSD201 | SH47 | Chitradurga | Chitradurga | Hosdurga | 178669 | 9.00 | Slab | 7.00 | repair |
| 1564 | BR:SH47:HSD201:185.877 | HSD201 | SH47 | Chitradurga | Chitradurga | Hosdurga | 185859 | 9.50 | Slab | 36.00 | repair |
| 1565 | BR:SH47:HSD201:189.802 | HSD201 | SH47 | Chitradurga | Chitradurga | Hosdurga | 189793 | 12.00 | Slab | 18.00 | routine |
| 1566 | BR:SH47:HSD201:198.463 | HSD201 | SH47 | Chitradurga | Chitradurga | Hosdurga | 198414 | 7.00 | Steel Structure | 99.00 | repair |
| 1567 | BR:SH47:HSD201:208.783 | HSD201 | SH47 | Chitradurga | Chitradurga | Hosdurga | 208780 | 12.00 | Slab | 6.80 | repair |
| 1568 | BR:SH47:HSD201:214.018 | HSD201 | SH47 | Chitradurga | Chitradurga | Hosdurga | 214012 | 12.00 | Slab | 13.20 | routine |
| 1569 | BR:SH47:HLK203:227.727 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 227718 | 12.00 | Slab | 18.00 | routine |
| 1570 | BR:SH47:HLK203:228.417 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 228413 | 10.00 | Pipe | 9.30 | repair |
| 1571 | BR:SH47:HLK203:231.982 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 231976 | 12.00 | Slab | 12.00 | routine |
| 1572 | BR:SH47:HLK203:235.662 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 235655 | 17.50 | Slab | 15.00 | routine |
| 1573 | BR:SH47:HLK203:238.567 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 238560 | 12.00 | Slab | 14.30 | routine |
| 1574 | BR:SH47:HLK203:242.797 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 242780 | 8.50 | Pipe | 34.50 | repair |
| 1575 | BR:SH47:HLK203:248.632 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 248627 | 14.00 | Slab | 10.00 | repair |
| 1576 | BR:SH47:HLK203:249.982 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 249979 | 12.50 | Pipe | 7.90 | routine |
| 1577 | BR:SH47:HLK203:258.212 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 258197 | 8.00 | Pipe | 31.00 | repair |
| 1578 | BR:SH47:HLK203:259.502 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 259498 | 12.00 | Slab | 8.20 | routine |
| 1579 | BR:SH47:DVG47:266.585 | DVG47 | SH47 | Davanagere | Davanagere | Davanagere | 266581 | 8.50 | Pipe | 9.50 | repair |
| 1580 | BR:SH47:DVG47:275.445 | DVG47 | SH47 | Davanagere | Davanagere | Davanagere | 275429 | 9.00 | Slab | 32.00 | repair |
| 1581 | BR:SH47:HRP201:313.98 | HRP201 | SH47 | Davanagere | Davanagere | Harapanahalli | 313977 | 11.00 | Slab | 6.30 | repair |
| 1582 | BR:SH47:HRP201:341.661 | HRP201 | SH47 | Davanagere | Davanagere | Harapanahalli | 341637 | 8.50 | Slab | 48.00 | repair |
| 1583 | BR:SH47:HRP201:344.156 | HRP201 | SH47 | Davanagere | Davanagere | Harapanahalli | 344151 | 10.00 | Pipe | 11.40 | repair |
| 1584 | BR:SH48:KMT3:1.225 | KMT3 | SH48 | Uttara Kannada | Karwar | Kumta | 1222 | 9.00 | Slab | 7.00 | repair |
| 1585 | BR:SH48:KMT3:12.295 | KMT3 | SH48 | Uttara Kannada | Karwar | Kumta | 12282 | 8.00 | Slab | 27.00 | repair |
| 1586 | BR:SH48:KMT3:18.555 | KMT3 | SH48 | Uttara Kannada | Karwar | Kumta | 18547 | 9.00 | Slab | 16.00 | repair |
| 1587 | BR:SH48:KMT3:21.605 | KMT3 | SH48 | Uttara Kannada | Karwar | Kumta | 21599 | 9.00 | Slab | 12.00 | repair |
| 1588 | BR:SH48:KMT3:24.275 | KMT3 | SH48 | Uttara Kannada | Karwar | Kumta | 24262 | 8.00 | Slab | 27.00 | repair |
| 1589 | BR:SH48:KMT3:25.935 | KMT3 | SH48 | Uttara Kannada | Karwar | Kumta | 25926 | 8.00 | Slab | 18.00 | repair |
| 1590 | BR:SH48:KMT3:28.15 | KMT3 | SH48 | Uttara Kannada | Karwar | Kumta | 28137 | 8.00 | Slab | 27.00 | repair |
| 1591 | BR:SH48:KMT3:35.11 | KMT3 | SH48 | Uttara Kannada | Karwar | Kumta | 35100 | 8.00 | Slab | 20.00 | repair |
| 1592 | BR:SH48:SDP3:53.205 | SDP3 | SH48 | Uttara Kannada | Sirsi | Siddapur | 53185 | 8.00 | Slab | 40.00 | repair |
| 1593 | BR:SH48:SDP3:54.215 | SDP3 | SH48 | Uttara Kannada | Sirsi | Siddapur | 54192 | 8.00 | Slab | 47.50 | repair |
| 1594 | BR:SH48:SDP3:60.25 | SDP3 | SH48 | Uttara Kannada | Sirsi | Siddapur | 60223 | 8.00 | Girder | 54.00 | repair |
| 1595 | BR:SH48:SRB1:85.355 | SRB1 | SH48 | Shimoga | Shimoga | Sorab | 85325 | 8.50 | Girder | 60.00 | repair |
| 1596 | BR:SH48:SRB1:91.145 | SRB1 | SH48 | Shimoga | Shimoga | Sorab | 91132 | 8.50 | Slab | 27.00 | repair |
| 1597 | BR:SH48:SRB1:98.905 | SRB1 | SH48 | Shimoga | Shimoga | Sorab | 98890 | 12.00 | Slab | 30.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1598 | BR:SH48:SKR1:138.365 | SKR1 | SH48 | Shimoga | Shimoga | Shikaripur | 138357 | 10.00 | Pipe | 17.50 | repair |
| 1599 | BR:SH48:SKR1:149.99 | SKR1 | SH48 | Shimoga | Shimoga | Shikaripur | 149984 | 12.00 | Slab | 12.00 | routine |
| 1600 | BR:SH48:SKR1:153.105 | SKR1 | SH48 | Shimoga | Shimoga | Shikaripur | 153101 | 12.00 | Slab | 8.00 | routine |
| 1601 | BR:SH48:SKR1:153.71 | SKR1 | SH48 | Shimoga | Shimoga | Shikaripur | 153706 | 12.00 | Slab | 8.00 | repair |
| 1602 | BR:SH48:SKR1:155.965 | SKR1 | SH48 | Shimoga | Shimoga | Shikaripur | 155962 | 10.00 | Slab | 7.00 | routine |
| 1603 | BR:SH48:HNN3:163.11 | HNN3 | SH48 | Davanagere | Davanagere | Honnali | 163102 | 8.00 | Slab | 16.00 | repair |
| 1604 | BR:SH48:HNN3:164.91 | HNN3 | SH48 | Davanagere | Davanagere | Honnali | 164900 | 8.50 | Slab | 21.00 | repair |
| 1605 | BR:SH48:HNN3:165.33 | HNN3 | SH48 | Davanagere | Davanagere | Honnali | 165326 | 8.00 | Slab | 8.00 | repair |
| 1606 | BR:SH48:HNN3:165.63 | HNN3 | SH48 | Davanagere | Davanagere | Honnali | 165623 | 8.00 | Pipe | 14.50 | repair |
| 1607 | BR:SH48:HNN3:177.04 | HNN3 | SH48 | Davanagere | Davanagere | Honnali | 177027 | 6.00 | Slab | 27.00 | routine |
| 1608 | BR:SH48:HNN3:180.16 | HNN3 | SH48 | Davanagere | Davanagere | Honnali | 180153 | 6.00 | Slab | 15.00 | routine |
| 1609 | BR:SH48:HNN3:183.8 | HNN3 | SH48 | Davanagere | Davanagere | Honnali | 183797 | 12.00 | Slab | 6.50 | routine |
| 1610 | BR:SH48:CNG3:193.8 | CNG3 | SH48 | Davanagere | Davanagere | Channagiri | 193796 | 8.00 | Girder | 9.00 | repair |
| 1611 | BR:SH48:CNG3:195.54 | CNG3 | SH48 | Davanagere | Davanagere | Channagiri | 195536 | 8.00 | Slab | 9.60 | repair |
| 1612 | BR:SH48:CNG3:201.355 | CNG3 | SH48 | Davanagere | Davanagere | Channagiri | 201337 | 12.00 | Slab | 36.00 | routine |
| 1613 | BR:SH48:CNG3:206.13 | CNG3 | SH48 | Davanagere | Davanagere | Channagiri | 206115 | 12.00 | Slab | 30.00 | routine |
| 1614 | BR:SH48:CNG3:210.415 | CNG3 | SH48 | Davanagere | Davanagere | Channagiri | 210411 | 12.00 | Slab | 8.00 | routine |
| 1615 | BR:SH48:HLK3:228.05 | HLK3 | SH48 | Chitradurga | Chitradurga | Holalkere | 228042 | 10.00 | Pipe | 17.00 | repair |
| 1616 | BR:SH48:HLK3:229.115 | HLK3 | SH48 | Chitradurga | Chitradurga | Holalkere | 229109 | 12.00 | Slab | 12.80 | routine |
| 1617 | BR:SH48:HLK3:240.04 | HLK3 | SH48 | Chitradurga | Chitradurga | Holalkere | 240036 | 10.00 | Pipe | 9.70 | routine |
| 1618 | BR:SH48:HLK3:245.17 | HLK3 | SH48 | Chitradurga | Chitradurga | Holalkere | 245164 | 9.00 | Pipe | 12.00 | repair |
| 1619 | BR:SH48:CHD3:247.78 | CHD3 | SH48 | Chitradurga | Chitradurga | Chitradurga | 247772 | 12.00 | Slab | 17.40 | routine |
| 1620 | BR:SH48:CHD3:248.57 | CHD3 | SH48 | Chitradurga | Chitradurga | Chitradurga | 248562 | 8.50 | Pipe | 17.50 | repair |
| 1621 | BR:SH48:CHD3:257.325 | CHD3 | SH48 | Chitradurga | Chitradurga | Chitradurga | 257319 | 9.40 | Girder | 12.00 | repair |
| 1622 | BR:SH48:CHD3:257.495 | CHD3 | SH48 | Chitradurga | Chitradurga | Chitradurga | 257483 | 12.00 | Slab | 24.00 | routine |
| 1623 | BR:SH48:CHD3:261.575 | CHD3 | SH48 | Chitradurga | Chitradurga | Chitradurga | 261572 | 13.00 | Slab | 6.20 | repair |
| 1624 | BR:SH48:CHD3:265.555 | CHD3 | SH48 | Chitradurga | Chitradurga | Chitradurga | 265551 | 12.00 | Slab | 9.20 | routine |
| 1625 | BR:SH48:CHD3:274.075 | CHD3 | SH48 | Chitradurga | Chitradurga | Chitradurga | 274071 | 15.00 | Pipe | 8.50 | routine |
| 1626 | BR:SH48:CHD3:282.81 | CHD3 | SH48 | Chitradurga | Chitradurga | Chitradurga | 282785 | 12.00 | Slab | 50.00 | routine |
| 1627 | BR:SH48:CHD3:284.35 | CHD3 | SH48 | Chitradurga | Chitradurga | Chitradurga | 284347 | 12.50 | Pipe | 6.30 | repair |
| 1628 | BR:SH48:CHL2:291.615 | CHL2 | SH48 | Chitradurga | Chitradurga | Challakere | 291606 | 8.50 | Slab | 18.00 | routine |
| 1629 | BR:SH48:CHL2:307.445 | CHL2 | SH48 | Chitradurga | Chitradurga | Challakere | 307414 | 12.00 | Girder | 63.00 | routine |
| 1630 | BR:SH48:CHL2:315.345 | CHL2 | SH48 | Chitradurga | Chitradurga | Challakere | 315341 | 12.00 | Slab | 8.20 | routine |
| 1631 | BR:SH48:CHL2:316.58 | CHL2 | SH48 | Chitradurga | Chitradurga | Challakere | 316577 | 9.00 | Slab | 6.50 | routine |
| 1632 | BR:SH48:CHL2:316.705 | CHL2 | SH48 | Chitradurga | Chitradurga | Challakere | 316702 | 10.00 | Pipe | 7.00 | repair |
| 1633 | BR:SH48:CHL2:325.615 | CHL2 | SH48 | Chitradurga | Chitradurga | Challakere | 325501 | 7.00 | Steel Structure | 252.00 | repair |
| 1634 | BR:SH48:CHL2:330.3 | CHL2 | SH48 | Chitradurga | Chitradurga | Challakere | 330293 | 12.00 | Slab | 15.00 | routine |
| 1635 | BR:SH48:CHL2:335.095 | CHL2 | SH48 | Chitradurga | Chitradurga | Challakere | 335080 | 8.50 | Pipe | 31.00 | repair |
| 1636 | BR:SH48:PVG58:359.31 | PVG58 | SH48 | Tumkur | Madhugiri | Pavagada | 359307 | 8.00 | Slab | 7.20 | repair |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl.No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of SuperStr | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1637 | BR:SH48:PVG58:360.77 | PVG58 | SH48 | Tumkur | Madhugiri | Pavagada | 360766 | 12.50 | pipe | 9.30 | routine |
| 1638 | BR:SH48:PVG58:361.55 | PVG58 | SH48 | Tumkur | Madhugiri | Pavagada | 361546 | 12.50 | pipe | 8.50 | routine |
| 1639 | BR:SH48:PVG58:367.91 | PVG58 | SH48 | Tumkur | Madhugiri | Pavagada | 367907 | 11.00 | Slab | 6.00 | repair |
| 1640 | BR:SH48:PVG58:373.415 | PVG58 | SH48 | Tumkur | Madhugiri | Pavagada | 373391 | 8.50 | pipe | 49.50 | repair |
| 1641 | BR:SH48:PVG58:387.04 | PVG58 | SH48 | Tumkur | Madhugiri | Pavagada | 387030 | 12.00 | Slab | 20.00 | routine |
| 1642 | BR:SH48:PVG58:390.29 | PVG58 | SH48 | Tumkur | Madhugiri | Pavagada | 390282 | 8.50 | pipe | 17.00 | repair |
| 1643 | BR:SH49:SNR34:1.815 | SNR34 | SH49 | Bellary | Bellary | Sandur | 1808 | 12.00 | Slab | 14.00 | routine |
| 1644 | BR:SH49:SNR34:5.52 | SNR34 | SH49 | Bellary | Bellary | Sandur | 5517 | 12.00 | Slab | 7.00 | routine |
| 1645 | BR:SH49:SNR34:7.2 | SNR34 | SH49 | Bellary | Bellary | Sandur | 7190 | 12.00 | Slab | 20.00 | routine |
| 1646 | BR:SH49:SNR34:7.29 | SNR34 | SH49 | Bellary | Bellary | Sandur | 7281 | 12.00 | Slab | 18.00 | routine |
| 1647 | BR:SH49:SNR34:11.565 | SNR34 | SH49 | Bellary | Bellary | Sandur | 11560 | 12.00 | Slab | 10.00 | routine |
| 1648 | BR:SH49:SNR34:12.4 | SNR34 | SH49 | Bellary | Bellary | Sandur | 12390 | 12.00 | Slab | 20.00 | routine |
| 1649 | BR:SH49:HSP201:20.805 | HSP201 | SH49 | Bellary | Bellary | Hospet | 20800 | 12.00 | Slab | 10.00 | routine |
| 1650 | BR:SH49:HSP201:22.3 | HSP201 | SH49 | Bellary | Bellary | Hospet | 22270 | 11.00 | Slab | 66.00 | repair |
| 1651 | BR:SH49:HSP201:32.135 | HSP201 | SH49 | Bellary | Bellary | Hospet | 32129 | 8.00 | Slab | 12.00 | repair |
| 1652 | BR:SH49:HSP201:37.605 | HSP201 | SH49 | Bellary | Bellary | Hospet | 37590 | 10.00 | Slab | 30.00 | routine |
| 1653 | BR:SH49:HSP201:54.715 | HSP201 | SH49 | Bellary | Bellary | Hospet | 54708 | 8.00 | Slab | 14.00 | repair |
| 1654 | BR:SH49:HSP201:69.44 | HSP201 | SH49 | Bellary | Bellary | Hospet | 69436 | 7.50 | Pipe | 9.10 | repair |
| 1655 | BR:SH49:HSP201:71.115 | HSP201 | SH49 | Bellary | Bellary | Hospet | 71093 | 7.50 | Pipe | 44.50 | repair |
| 1656 | BR:SH49:SRG46:86.26 | SRG46 | SH49 | Bellary | Bellary | Siruguppa | 86248 | 8.00 | Slab | 24.00 | repair |
| 1657 | BR:SH49:SRG46:87.585 | SRG46 | SH49 | Bellary | Bellary | Siruguppa | 87580 | 7.50 | Pipe | 10.30 | repair |
| 1658 | BR:SH49:SRG46:90.56 | SRG46 | SH49 | Bellary | Bellary | Siruguppa | 90555 | 7.50 | Pipe | 10.70 | repair |
| 1659 | BR:SH49:SRG46:94.435 | SRG46 | SH49 | Bellary | Bellary | Siruguppa | 94422 | 7.50 | Pipe | 27.50 | routine |
| 1660 | BR:SH49:SRG46:96.145 | SRG46 | SH49 | Bellary | Bellary | Siruguppa | 96135 | 12.00 | Slab | 21.00 | routine |
| 1661 | BR:SH5:KOL2:11.96 | KOL2 | SH5 | Kolar | Kolar | Kolar | 11957 | 10.80 | Slab | 6.40 | repair |
| 1662 | BR:SH5:KOL2:15.54 | KOL2 | SH5 | Kolar | Kolar | Kolar | 15525 | 8.20 | Pipe | 30.70 | repair |
| 1663 | BR:SH5:KOL2:18.287 | KOL2 | SH5 | Kolar | Kolar | Kolar | 18271 | 10.80 | Slab | 32.00 | repair |
| 1664 | BR:SH5:KOL2:18.752 | KOL2 | SH5 | Kolar | Kolar | Kolar | 18747 | 8.40 | Slab | 11.20 | routine |
| 1665 | BR:SH5:KOL2:29.502 | KOL2 | SH5 | Kolar | Kolar | Kolar | 29480 | 8.50 | Pipe | 45.20 | repair |
| 1666 | BR:SH5:KOL2:37.192 | KOL2 | SH5 | Kolar | Kolar | Kolar | 37188 | 12.50 | pipe | 8.40 | routine |
| 1667 | BR:SH5:CMI3:40.912 | CMI3 | SH5 | Chikballapur | Chikballapur | Chintamani | 40908 | 8.20 | Slab | 8.40 | repair |
| 1668 | BR:SH5:CMI3:44.972 | CMI3 | SH5 | Chikballapur | Chikballapur | Chintamani | 44969 | 10.00 | Slab | 6.90 | repair |
| 1669 | BR:SH5:CMI3:54.015 | CMI3 | SH5 | Chikballapur | Chikballapur | Chintamani | 54008 | 8.60 | Slab | 15.60 | routine |
| 1670 | BR:SH5:CMI3:58.92 | CMI3 | SH5 | Chikballapur | Chikballapur | Chintamani | 58916 | 10.90 | Others | 9.80 | repair |
| 1671 | BR:SH5:CMI3:59.825 | CMI3 | SH5 | Chikballapur | Chikballapur | Chintamani | 59822 | 12.20 | Slab | 6.00 | routine |
| 1672 | BR:SH5:SGA4:66.335 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 66329 | 8.60 | Slab | 13.80 | routine |
| 1673 | BR:SH5:SGA4:73.567 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 73553 | 5.60 | Arch | 24.00 | routine |
| 1674 | BR:SH5:SGA4:73.565 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 73555 | 8.80 | Slab | 21.60 | routine |
| 1675 | BR:SH5:SGA4:75.053 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 75046 | 8.50 | pipe | 14.80 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1676 | BR:SH5:SGA4:76.713 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 76707 | 8.60 | Slab | 12.80 | repair |
| 1677 | BR:SH5:SGA4:78.788 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 78784 | 12.50 | pipe | 8.50 | routine |
| 1678 | BR:SH5:SGA4:79.438 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 79434 | 8.20 | Slab | 8.60 | repair |
| 1679 | BR:SH5:SGA4:81.648 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 81645 | 10.00 | Slab | 6.00 | repair |
| 1680 | BR:SH5:SGA4:81.708 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 81703 | 8.00 | Slab | 10.60 | repair |
| 1681 | BR:SH5:SGA4:88.283 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 88278 | 8.30 | Slab | 11.60 | repair |
| 1682 | BR:SH5:BAG2:96.873 | BAG2 | SH5 | Chikballapur | Chikballapur | Bagepalli | 96870 | 8.30 | Slab | 6.00 | repair |
| 1683 | BR:SH5:BAG2:100.098 | BAG2 | SH5 | Chikballapur | Chikballapur | Bagepalli | 100091 | 8.40 | Slab | 14.40 | routine |
| 1684 | BR:SH5:BAG2:103.518 | BAG2 | SH5 | Chikballapur | Chikballapur | Bagepalli | 103504 | 12.00 | pipe | 28.50 | repair |
| 1685 | BR:SH5:BAG2:106.838 | BAG2 | SH5 | Chikballapur | Chikballapur | Bagepalli | 106819 | 21.00 | Slab | 39.20 | routine |
| 1685 | BR:SH50:BAT45:20.205 | BAT45 | SH50 | Uttara Kannada | Karwar | Bhatkal | 20192 | 7.50 | Girder | 27.00 | repair |
| 1686 | BR:SH50:BAT45:20.915 | BAT45 | SH50 | Uttara Kannada | Karwar | Bhatkal | 20900 | 7.50 | Girder | 30.00 | repair |
| 1687 | BR:SH50:SGR85:57.638 | SGR85 | SH50 | Shimoga | Shimoga | Sagar | 57633 | 8.50 | Slab | 10.00 | repair |
| 1688 | BR:SH50:SGR85:82.623 | SGR85 | SH50 | Shimoga | Shimoga | Sagar | 82618 | 8.00 | Girder | 11.00 | repair |
| 1689 | BR:SH50:SDP201:84.81 | SDP201 | SH50 | Uttara Kannada | Sirsi | Siddapur | 84697 | 8.50 | Girder | 264.00 | repair |
| 1690 | BR:SH51:BAK205:10.3 | BAK205 | SH51 | Bidar | Bidar | Basavakalyan | 10297 | 8.00 | pipe | 7.60 | repair |
| 1691 | BR:SH51:BAK205:23.045 | BAK205 | SH51 | Bidar | Bidar | Basavakalyan | 23030 | 10.00 | Slab | 30.00 | repair |
| 1692 | BR:SH51:BAK205:28.225 | BAK205 | SH51 | Bidar | Bidar | Basavakalyan | 28197 | 8.50 | Slab | 56.00 | repair |
| 1693 | BR:SH51:ALD203:41.65 | ALD203 | SH51 | Gulbarga | Gulbarga | Aland | 41638 | 8.00 | Slab | 24.00 | routine |
| 1694 | BR:SH51:ALD203:45.575 | ALD203 | SH51 | Gulbarga | Gulbarga | Aland | 45550 | 8.00 | Girder | 48.00 | repair |
| 1695 | BR:SH51:GUL5:59.455 | GUL5 | SH51 | Gulbarga | Gulbarga | Gulbarga | 59449 | 8.00 | Slab | 13.00 | repair |
| 1696 | BR:SH51:GUL5:68.705 | GUL5 | SH51 | Gulbarga | Gulbarga | Gulbarga | 68690 | 8.00 | Slab | 31.50 | repair |
| 1697 | BR:SH52:TRT5:8.995 | TRT5 | SH52 | Shimoga | Shimoga_special | Tirthahalli | 8992 | 7.80 | Slab | 6.40 | repair |
| 1698 | BR:SH52:TRT5:13.715 | TRT5 | SH52 | Shimoga | Shimoga_special | Tirthahalli | 13712 | 12.00 | Slab | 6.40 | routine |
| 1699 | BR:SH52:HSN202:34.325 | HSN202 | SH52 | Shimoga | Shimoga | Hosanagara | 34317 | 8.40 | Girder | 17.00 | repair |
| 1700 | BR:SH52:HSN202:38.21 | HSN202 | SH52 | Shimoga | Shimoga | Hosanagara | 38207 | 8.00 | pipe | 7.00 | repair |
| 1701 | BR:SH52:HSN202:38.22 | HSN202 | SH52 | Shimoga | Shimoga | Hosanagara | 38213 | 8.30 | Girder | 15.30 | repair |
| 1702 | BR:SH52:HSN202:41.02 | HSN202 | SH52 | Shimoga | Shimoga | Hosanagara | 41012 | 11.00 | Girder | 16.00 | repair |
| 1703 | BR:SH52:HSN202:42.18 | HSN202 | SH52 | Shimoga | Shimoga | Hosanagara | 42175 | 11.00 | Slab | 10.00 | repair |
| 1704 | BR:SH52:KDP2:60.504 | KDP2 | SH52 | Udupi | Udupi | Kundapura | 60499 | 8.50 | Slab | 10.00 | repair |
| 1705 | BR:SH52:KDP2:68.104 | KDP2 | SH52 | Udupi | Udupi | Kundapura | 68096 | 9.00 | Girder | 17.00 | repair |
| 1706 | BR:SH52:KDP2:79.464 | KDP2 | SH52 | Udupi | Udupi | Kundapura | 79315 | 8.00 | Girder | 300.00 | repair |
| 1707 | BR:SH52:KDP2:84.529 | KDP2 | SH52 | Udupi | Udupi | Kundapura | 84523 | 8.00 | Pipe | 13.50 | repair |
| 1708 | BR:SH52:KDP2:87.039 | KDP2 | SH52 | Udupi | Udupi | Kundapura | 87029 | 8.00 | Pipe | 20.50 | repair |
| 1709 | BR:SH53:RBG8:27 | RBG8 | SH53 | Belgaum | Chikkodi | Raibag | 26992 | 10.00 | pipe | 17.50 | repair |
| 1710 | BR:SH53:RBG8:43.514 | RBG8 | SH53 | Belgaum | Chikkodi | Raibag | 43511 | 10.00 | pipe | 7.20 | repair |
| 1711 | BR:SH53:JMK201:48.459 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 48439 | 8.00 | Slab | 40.00 | repair |
| 1712 | BR:SH53:JMK201:58.574 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 58569 | 8.00 | Slab | 10.00 | routine |
| 1713 | BR:SH53:JMK201:59.204 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 59198 | 8.50 | Slab | 12.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Lgh (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1714 | BR:SH53:JMK201:61.089 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 61078 | 12.00 | Slab | 22.00 | routine |
| 1715 | BR:SH53:JMK201:65.169 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 65152 | 12.00 | Others | 35.00 | routine |
| 1716 | BR:SH53:JMK201:68.389 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 68377 | 12.00 | Others | 25.00 | routine |
| 1717 | BR:SH53:JMK201:74.719 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 74707 | 12.00 | Others | 25.00 | routine |
| 1718 | BR:SH53:JMK201:91.219 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 91209 | 12.00 | Slab | 20.00 | routine |
| 1719 | BR:SH53:JMK201:101.429 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 101423 | 10.00 | pipe | 13.00 | repair |
| 1720 | BR:SH53:BLG206_A:104.584 | BLG206_A | SH53 | Bagalkot | Bagalkot | Bilgi | 104580 | 9.00 | Slab | 8.10 | routine |
| 1721 | BR:SH53:MDL6:107.309 | MDL6 | SH53 | Bagalkot | Bagalkot | Mudhol | 107303 | 10.00 | pipe | 13.50 | repair |
| 1722 | BR:SH53:MDL6:108.409 | MDL6 | SH53 | Bagalkot | Bagalkot | Mudhol | 108404 | 9.00 | Slab | 10.50 | repair |
| 1723 | BR:SH53:BLG206_B:129.319 | BLG206_B | SH53 | Bagalkot | Bagalkot | Bilgi | 129227 | 8.50 | Slab | 179.45 | routine |
| 1724 | BR:SH54:BGM207:10.51 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 10504 | 12.00 | Slab | 12.00 | routine |
| 1725 | BR:SH54:BGM207:13.215 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 13211 | 12.00 | Slab | 9.00 | routine |
| 1726 | BR:SH54:BGM207:14.585 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 14580 | 12.00 | Slab | 10.00 | routine |
| 1727 | BR:SH54:BGM207:15.33 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 15327 | 12.00 | Slab | 7.00 | routine |
| 1728 | BR:SH54:BGM207:18.375 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 18371 | 12.50 | pipe | 8.50 | routine |
| 1729 | BR:SH54:BGM207:34.29 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 34287 | 8.00 | Slab | 6.50 | repair |
| 1730 | BR:SH54:BGM207:36.72 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 36716 | 8.00 | Slab | 9.00 | repair |
| 1731 | BR:SH54:BGM207:37.775 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 37770 | 8.00 | Slab | 10.50 | repair |
| 1732 | BR:SH54:BGM207:39.585 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 39580 | 8.00 | Slab | 10.50 | repair |
| 1733 | BR:SH54:BGM207:40.573 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 40569 | 8.00 | Slab | 8.00 | repair |
| 1734 | BR:SH54:BGM207:44.888 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 44862 | 8.00 | Slab | 52.50 | repair |
| 1735 | BR:SH54:BGM207:50.652 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 50648 | 8.00 | pipe | 9.50 | repair |
| 1736 | BR:SH54:BGM207:52.242 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 52237 | 8.50 | Slab | 10.00 | routine |
| 1737 | BR:SH54:BGM207:53.352 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 53340 | 12.00 | Slab | 24.00 | routine |
| 1738 | BR:SH54:GOK8:75.993 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 75975 | 9.00 | Slab | 36.00 | repair |
| 1739 | BR:SH54:GOK8:76.408 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 76403 | 10.00 | pipe | 10.00 | routine |
| 1740 | BR:SH54:GOK8:89.203 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 89158 | 8.50 | Slab | 93.60 | repair |
| 1741 | BR:SH54:GOK8:96.293 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 96271 | 7.50 | Slab | 44.00 | repair |
| 1742 | BR:SH54:GOK8:110.318 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 110314 | 10.00 | pipe | 9.70 | routine |
| 1743 | BR:SH54:GOK8:113.743 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 113735 | 12.00 | Slab | 16.10 | routine |
| 1744 | BR:SH54:GOK8:117.398 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 117392 | 10.00 | pipe | 13.10 | routine |
| 1745 | BR:SH54:GOK8:120.328 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 120323 | 10.00 | pipe | 11.40 | routine |
| 1746 | BR:SH54:MDL16:123.668 | MDL16 | SH54 | Bagalkot | Bagalkot | Mudhol | 123633 | 6.50 | Slab | 85.00 | repair |
| 1747 | BR:SH54:MDL16:127.423 | MDL16 | SH54 | Bagalkot | Bagalkot | Mudhol | 127409 | 12.00 | Slab | 28.00 | routine |
| 1748 | BR:SH55:RMG6:28.405 | RMG6 | SH55 | Belgaum | Belgaum | Ramdurg | 28391 | 8.00 | Slab | 28.00 | repair |
| 1749 | BR:SH55:GOK204:30.56 | GOK204 | SH55 | Belgaum | Chikkodi | Gokak | 30553 | 9.00 | Slab | 14.00 | routine |
| 1750 | BR:SH55:GOK204:34.01 | GOK204 | SH55 | Belgaum | Chikkodi | Gokak | 33983 | 8.00 | Slab | 54.00 | repair |
| 1751 | BR:SH55:MDL30:50.264 | MDL30 | SH55 | Bagalkot | Bagalkot | Mudhol | 50206 | 8.20 | Girder | 156.00 | repair |
| 1752 | BR:SH55:MDL30:62.379 | MDL30 | SH55 | Bagalkot | Bagalkot | Mudhol | 62372 | 8.00 | Girder | 15.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1753 | BR:SH55:BLG205:76.794 | BLG205 | SH55 | Bagalkot | Bagalkot | Bilgi | 76532 | 8.50 | Girder | 523.60 | repair |
| 1754 | BR:SH55:BJP21:93.427 | BJP21 | SH55 | Bijapur | Bijapur | Bijapur | 93418 | 12.00 | Slab | 18.00 | routine |
| 1755 | BR:SH55:BJP21:99.037 | BJP21 | SH55 | Bijapur | Bijapur | Bijapur | 99025 | 12.00 | Slab | 24.00 | routine |
| 1756 | BR:SH56:KNP8:2.235 | KNP8 | SH56 | Belgaum | Belgaum | Khanapur | 2215 | 8.00 | Slab | 44.00 | routine |
| 1757 | BR:SH56:DRD7:34.71 | DRD7 | SH56 | Dharwad | Dharwad | Dharwad | 34702 | 8.00 | Pipe | 17.50 | repair |
| 1758 | BR:SH56:DRD7:38.435 | DRD7 | SH56 | Dharwad | Dharwad | Dharwad | 38425 | 8.00 | Pipe | 20.50 | repair |
| 1759 | BR:SH56:DRD7:41.915 | DRD7 | SH56 | Dharwad | Dharwad | Dharwad | 41904 | 8.00 | Pipe | 23.50 | repair |
| 1760 | BR:SH56:NVG202:51.79 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 51764 | 12.00 | Slab | 53.00 | routine |
| 1761 | BR:SH56:NVG202:54.08 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 54077 | 8.00 | Slab | 7.00 | routine |
| 1762 | BR:SH56:NVG202:54.105 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 54099 | 8.00 | Slab | 12.00 | routine |
| 1763 | BR:SH56:NVG202:62.165 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 62159 | 7.50 | Pipe | 13.50 | repair |
| 1764 | BR:SH56:NVG202:63.335 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 63330 | 12.00 | Slab | 10.00 | routine |
| 1765 | BR:SH56:NVG202:64.815 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 64811 | 12.00 | Slab | 9.20 | routine |
| 1766 | BR:SH56:NVG202:67.75 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 67745 | 12.00 | Slab | 11.00 | routine |
| 1767 | BR:SH56:NVG202:74.225 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 74194 | 12.00 | Slab | 63.00 | routine |
| 1768 | BR:SH56:NVG202:81.785 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 81776 | 7.50 | Pipe | 19.90 | repair |
| 1769 | BR:SH56:NVG202:83.1 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 83096 | 12.00 | Slab | 8.20 | routine |
| 1770 | BR:SH56:NVG202:92.135 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 92119 | 12.00 | Slab | 32.00 | routine |
| 1771 | BR:SH56:NVG202:93.695 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 93682 | 12.00 | Slab | 26.40 | routine |
| 1772 | BR:SH56:NVG202:97.395 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 97371 | 12.00 | Slab | 48.00 | routine |
| 1773 | BR:SH56:NVG202:102.565 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 102517 | 8.00 | Girder | 96.00 | routine |
| 1774 | BR:SH56:NVG202:105.03 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 105014 | 12.00 | Slab | 32.00 | routine |
| 1775 | BR:SH56:NVG202:105.925 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 105921 | 12.50 | Pipe | 9.70 | routine |
| 1776 | BR:SH56:NVG202:111.855 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 111851 | 12.50 | Pipe | 8.00 | repair |
| 1777 | BR:SH56:NVG202:113.08 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 113076 | 7.50 | Pipe | 8.50 | repair |
| 1778 | BR:SH56:RON71:116.645 | RON71 | SH56 | Gadag | Gadag | Ron | 116623 | 7.50 | Pipe | 44.50 | repair |
| 1779 | BR:SH57:BDM205:47.52 | BDM205 | SH57 | Bagalkot | Bagalkot | Badami | 47490 | 8.50 | Slab | 60.00 | repair |
| 1780 | BR:SH57:RON72:52.425 | RON72 | SH57 | Gadag | Gadag | Ron | 52421 | 8.50 | Slab | 8.00 | repair |
| 1781 | BR:SH57:RON72:54.92 | RON72 | SH57 | Gadag | Gadag | Ron | 54917 | 10.00 | Pipe | 7.90 | repair |
| 1782 | BR:SH57:RON72:57.965 | RON72 | SH57 | Gadag | Gadag | Ron | 57961 | 8.00 | Slab | 8.00 | repair |
| 1783 | BR:SH57:SRT201:160.656 | SRT201 | SH57 | Gadag | Gadag | Shirahatti | 160621 | 7.80 | Slab | 80.00 | repair |
| 1784 | BR:SH57:RBN2:199.81 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 199795 | 12.00 | Slab | 30.00 | routine |
| 1785 | BR:SH57:RBN2:211.686 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 211680 | 10.00 | Slab | 12.00 | routine |
| 1786 | BR:SH57:RBN2:212.301 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 212292 | 8.00 | Slab | 18.00 | repair |
| 1787 | BR:SH57:RBN2:213.201 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 213191 | 8.00 | Slab | 21.00 | repair |
| 1788 | BR:SH57:RBN2:213.991 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 213987 | 12.00 | Slab | 8.50 | routine |
| 1789 | BR:SH57:RBN2:225.22 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 225215 | 10.00 | Slab | 10.50 | routine |
| 1790 | BR:SH57:RBN2:225.48 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 225470 | 8.00 | Slab | 20.00 | repair |
| 1791 | BR:SH57:RBN2:226.265 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 226249 | 8.00 | Slab | 32.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1792 | BR:SH57:HKR203:239.477 | HKR203 | SH57 | Haveri | Haveri | Hirekerur | 239469 | 12.00 | Slab | 17.00 | routine |
| 1793 | BR:SH57:HKR203:243.507 | HKR203 | SH57 | Haveri | Haveri | Hirekerur | 243500 | 8.00 | Slab | 14.00 | repair |
| 1794 | BR:SH57:SKR201:260.522 | SKR201 | SH57 | Shimoga | Shimoga | Shikaripur | 260515 | 12.00 | Slab | 14.00 | routine |
| 1795 | BR:SH57:SKR201:263.972 | SKR201 | SH57 | Shimoga | Shimoga | Shikaripur | 263966 | 12.00 | Slab | 12.00 | routine |
| 1796 | BR:SH57:SKR201:264.237 | SKR201 | SH57 | Shimoga | Shimoga | Shikaripur | 264230 | 12.00 | Slab | 14.00 | routine |
| 1797 | BR:SH57:SKR201:288.673 | SKR201 | SH57 | Shimoga | Shimoga | Shikaripur | 288668 | 12.00 | Slab | 11.00 | routine |
| 1798 | BR:SH57:HNN202:302.367 | HNN202 | SH57 | Davanagere | Davanagere | Honnali | 302346 | 8.50 | Slab | 42.00 | routine |
| 1799 | BR:SH57:SMG201:311.872 | SMG201 | SH57 | Shimoga | Shimoga_special | Shimoga | 311866 | 12.00 | Slab | 12.00 | routine |
| 1800 | BR:SH57:SMG201:317.842 | SMG201 | SH57 | Shimoga | Shimoga_special | Shimoga | 317833 | 16.00 | Slab | 18.00 | routine |
| 1801 | BR:SH57:SMG201:321.702 | SMG201 | SH57 | Shimoga | Shimoga_special | Shimoga | 321696 | 8.00 | Slab | 12.00 | repair |
| 1802 | BR:SH57:SMG201:322.092 | SMG201 | SH57 | Shimoga | Shimoga_special | Shimoga | 322083 | 25.00 | Slab | 18.00 | routine |
| 1803 | BR:SH57:SMG201:322.697 | SMG201 | SH57 | Shimoga | Shimoga_special | Shimoga | 322694 | 18.00 | Slab | 6.80 | routine |
| 1804 | BR:SH57:SMG201:325.599 | SMG201 | SH57 | Shimoga | Shimoga_special | Shimoga | 325455 | 8.00 | Arch | 288.00 | routine |
| 1805 | BR:SH57:SMG201:325.609 | SMG201 | SH57 | Shimoga | Shimoga_special | Shimoga | 325465 | 12.00 | Slab | 288.00 | routine |
| 1806 | BR:SH57:SMG201:329.019 | SMG201 | SH57 | Shimoga | Shimoga_special | Shimoga | 329015 | 27.00 | Slab | 9.00 | routine |
| 1807 | BR:SH57:SMG201:337.304 | SMG201 | SH57 | Shimoga | Shimoga_special | Shimoga | 337300 | 8.50 | Others | 9.00 | repair |
| 1808 | BR:SH57:BRV66:352.01 | BRV66 | SH57 | Shimoga | Shimoga_special | Bhadravathi | 352003 | 12.00 | Slab | 14.00 | routine |
| 1809 | BR:SH57:BRV66:353.215 | BRV66 | SH57 | Shimoga | Shimoga_special | Bhadravathi | 353138 | 6.50 | Girder | 140.00 | repair |
| 1810 | BR:SH57:TRK212:356.86 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 356857 | 8.00 | Slab | 6.50 | repair |
| 1811 | BR:SH57:TRK212:357.26 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 357252 | 6.00 | Steel Structure | 16.00 | repair |
| 1812 | BR:SH57:TRK212:365.3 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 365290 | 6.00 | Steel Structure | 20.00 | repair |
| 1813 | BR:SH57:TRK212:379.689 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 379686 | 8.00 | Slab | 6.00 | repair |
| 1814 | BR:SH57:TRK212:386.014 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 386009 | 7.00 | Slab | 10.50 | repair |
| 1815 | BR:SH57:TRK212:387.049 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 387046 | 8.00 | Slab | 6.00 | repair |
| 1816 | BR:SH57:TRK212:389.289 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 389281 | 8.00 | Slab | 16.00 | repair |
| 1817 | BR:SH57:TRK212:391.704 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 391698 | 8.00 | Slab | 13.50 | repair |
| 1818 | BR:SH57:TRK212:401.739 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 401736 | 8.00 | Slab | 6.00 | routine |
| 1819 | BR:SH57:CHK201:405.684 | CHK201 | SH57 | Chikmagalur | Chikmagalur | Chikmagalur | 405676 | 8.00 | Slab | 16.00 | repair |
| 1820 | BR:SH57:CHK201:412.069 | CHK201 | SH57 | Chikmagalur | Chikmagalur | Chikmagalur | 412063 | 8.00 | Slab | 12.00 | repair |
| 1821 | BR:SH57:CHK201:416.399 | CHK201 | SH57 | Chikmagalur | Chikmagalur | Chikmagalur | 416394 | 8.00 | pipe | 11.50 | repair |
| 1822 | BR:SH57:CHK201:434.584 | CHK201 | SH57 | Chikmagalur | Chikmagalur | Chikmagalur | 434580 | 8.50 | Slab | 8.00 | repair |
| 1823 | BR:SH57:BLR1:452.604 | BLR1 | SH57 | Hassan | Hassan | Belur | 452597 | 8.50 | Slab | 15.00 | repair |
| 1824 | BR:SH57:BLR1:453.604 | BLR1 | SH57 | Hassan | Hassan | Belur | 453601 | 8.50 | Slab | 7.70 | repair |
| 1825 | BR:SH57:BLR1:456.034 | BLR1 | SH57 | Hassan | Hassan | Belur | 456030 | 8.50 | Slab | 9.70 | repair |
| 1826 | BR:SH57:BLR1:458.195 | BLR1 | SH57 | Hassan | Hassan | Belur | 458191 | 12.00 | Slab | 9.00 | routine |
| 1827 | BR:SH57:BLR1:458.63 | BLR1 | SH57 | Hassan | Hassan | Belur | 458626 | 12.00 | Slab | 9.00 | routine |
| 1828 | BR:SH57:HSS4:477.545 | HSS4 | SH57 | Hassan | Hassan | Hassan | 477537 | 15.50 | Slab | 16.00 | routine |
| 1829 | BR:SH57:HSS4:501.52 | HSS4 | SH57 | Hassan | Hassan | Hassan | 501516 | 12.00 | Slab | 8.50 | routine |
| 1830 | BR:SH57:HSS4:507.71 | HSS4 | SH57 | Hassan | Hassan | Hassan | 507699 | 12.00 | Pipe | 22.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1831 | BR:SH57:HSS4:510.355 | HSS4 | SH57 | Hassan | Hassan | Hassan | 510350 | 12.00 | Slab | 10.00 | routine |
| 1832 | BR:SH57:HNP1:513.255 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 513243 | 12.00 | Slab | 24.30 | routine |
| 1833 | BR:SH57:HNP1:517.145 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 517138 | 8.20 | Slab | 15.00 | repair |
| 1834 | BR:SH57:HNP1:517.42 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 517413 | 17.50 | Slab | 15.20 | routine |
| 1835 | BR:SH57:HNP1:517.745 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 517742 | 12.00 | Slab | 7.00 | routine |
| 1836 | BR:SH57:HNP1:519.15 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 519145 | 12.00 | Slab | 10.50 | routine |
| 1837 | BR:SH57:HNP1:523.985 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 523977 | 12.00 | Slab | 16.50 | routine |
| 1838 | BR:SH57:HNP1:524.425 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 524329 | 12.00 | Girder | 193.50 | routine |
| 1839 | BR:SH57:HNP1:528.235 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 528223 | 12.00 | Slab | 24.40 | routine |
| 1840 | BR:SH57:HNP1:532.64 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 532634 | 12.00 | Slab | 13.60 | routine |
| 1841 | BR:SH57:HNP1:537.455 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 537451 | 12.00 | Slab | 9.00 | routine |
| 1842 | BR:SH57:HNP1:543.523 | HNP1 | SH57 | Hassan | Hassan | Holenarsipur | 543520 | 12.00 | Slab | 7.50 | routine |
| 1843 | BR:SH57:KRN1:549.488 | KRN1 | SH57 | Mysore | Hunsur | Krishnarajanagar | 549485 | 12.00 | Slab | 7.00 | routine |
| 1844 | BR:SH57:KRN1:556.533 | KRN1 | SH57 | Mysore | Hunsur | Krishnarajanagar | 556530 | 12.00 | Slab | 7.00 | routine |
| 1845 | BR:SH57:KRN1:557.763 | KRN1 | SH57 | Mysore | Hunsur | Krishnarajanagar | 557760 | 12.00 | Slab | 7.00 | routine |
| 1846 | BR:SH57:KRN1:558.983 | KRN1 | SH57 | Mysore | Hunsur | Krishnarajanagar | 558980 | 12.00 | Slab | 7.00 | routine |
| 1847 | BR:SH57:KRN1:560.213 | KRN1 | SH57 | Mysore | Hunsur | Krishnarajanagar | 560209 | 12.00 | Slab | 9.20 | routine |
| 1848 | BR:SH57:KRN1:566.553 | KRN1 | SH57 | Mysore | Hunsur | Krishnarajanagar | 566459 | 13.80 | Girder | 189.00 | routine |
| 1849 | BR:SH57:KRN1:573.688 | KRN1 | SH57 | Mysore | Hunsur | Krishnarajanagar | 573682 | 12.00 | Slab | 13.60 | routine |
| 1850 | BR:SH57:HNS3:578.903 | HNS3 | SH57 | Mysore | Hunsur | Hunsur | 578840 | 13.80 | Girder | 126.00 | routine |
| 1851 | BR:SH57:MYS242:609.891 | MYS242 | SH57 | Mysore | Mysore | Mysore | 609884 | 8.50 | pipe | 14.80 | repair |
| 1852 | BR:SH57:HDK202_B:620.036 | HDK202_B | SH57 | Mysore | Hunsur | Heggadadevanakote | 619997 | 8.30 | Slab | 142.80 | repair |
| 1853 | BR:SH57:NJG60:624.741 | NJG60 | SH57 | Mysore | Mysore | Nanjangud | 624707 | 8.50 | Girder | 51.00 | repair |
| 1854 | BR:SH57:NJG60:651.334 | NJG60 | SH57 | Mysore | Mysore | Nanjangud | 651329 | 12.00 | Slab | 11.00 | routine |
| 1855 | BR:SH57:NJG60:651.564 | NJG60 | SH57 | Mysore | Mysore | Nanjangud | 651559 | 12.00 | Slab | 10.50 | routine |
| 1856 | BR:SH57:NJG60:670.014 | NJG60 | SH57 | Mysore | Mysore | Nanjangud | 670006 | 12.00 | Slab | 16.00 | routine |
| 1857 | BR:SH57:CRN121:682.467 | CRN121 | SH57 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 682460 | 10.00 | pipe | 14.50 | repair |
| 1858 | BR:SH57:CRN121:682.807 | CRN121 | SH57 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 682798 | 10.00 | pipe | 19.50 | repair |
| 1859 | BR:SH57:CRN121:685.712 | CRN121 | SH57 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 685707 | 9.00 | Slab | 11.00 | routine |
| 1860 | BR:SH57:YLN203:694.322 | YLN203 | SH57 | Chamrajnagar | Chamrajnagar | Yelandur | 694255 | 8.10 | Girder | 135.00 | repair |
| 1861 | BR:SH57:YLN203:699.237 | YLN203 | SH57 | Chamrajnagar | Chamrajnagar | Yelandur | 699231 | 10.00 | Slab | 13.50 | routine |
| 1862 | BR:SH57:YLN203:704.227 | YLN203 | SH57 | Chamrajnagar | Chamrajnagar | Yelandur | 704223 | 8.50 | Slab | 8.00 | repair |
| 1863 | BR:SH59:KST204:7.945 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 7938 | 8.00 | Slab | 15.00 | repair |
| 1864 | BR:SH59:KST204:9.235 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 9230 | 8.00 | Slab | 10.00 | repair |
| 1865 | BR:SH59:KST204:39.36 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 39356 | 8.00 | Slab | 9.60 | repair |
| 1866 | BR:SH59:KST204:40.015 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 40000 | 12.00 | Slab | 31.50 | routine |
| 1867 | BR:SH59:KST204:42.74 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 42736 | 9.00 | Slab | 8.00 | repair |
| 1868 | BR:SH59:KST204:46.345 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 46341 | 8.50 | Slab | 9.00 | repair |
| 1869 | BR:SH6:KRW2:4.245 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 4237 | 8.00 | Slab | 16.50 | repair |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Lnth (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1870 | BR:SH6:KRW2:5.82 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 5815 | 8.50 | Slab | 10.00 | repair |
| 1871 | BR:SH6:KRW2:6.69 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 6685 | 8.00 | Slab | 11.00 | repair |
| 1872 | BR:SH6:KRW2:16.465 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 16460 | 8.20 | Slab | 10.00 | repair |
| 1873 | BR:SH6:KRW2:24.585 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 24576 | 8.80 | Slab | 18.00 | repair |
| 1874 | BR:SH6:KRW2:25.65 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 25637 | 8.40 | Slab | 27.50 | repair |
| 1875 | BR:SH6:KRW2:26.28 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 26261 | 7.50 | pipe | 38.50 | repair |
| 1876 | BR:SH6:KRW2:27.445 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 27434 | 7.50 | pipe | 23.50 | repair |
| 1877 | BR:SH6:KRW2:29.295 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 29283 | 7.50 | pipe | 24.50 | repair |
| 1878 | BR:SH6:KRW2:34.135 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 34131 | 10.00 | Slab | 9.50 | repair |
| 1879 | BR:SH6:KRW2:38.275 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 38271 | 10.00 | Slab | 9.00 | repair |
| 1880 | BR:SH6:KRW2:38.92 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 38916 | 10.00 | Slab | 9.50 | repair |
| 1881 | BR:SH6:KRW2:41.925 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 41919 | 8.00 | Slab | 13.00 | repair |
| 1882 | BR:SH6:KRW2:43.11 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 43106 | 8.00 | Slab | 9.50 | repair |
| 1883 | BR:SH6:KRW2:50.175 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 50159 | 8.00 | Slab | 33.00 | repair |
| 1884 | BR:SH6:KRW2:55.42 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 55401 | 8.00 | Girder | 39.00 | repair |
| 1885 | BR:SH6:KRW2:55.89 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 55871 | 8.00 | Girder | 39.00 | repair |
| 1886 | BR:SH6:KRW2:63.42 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 63417 | 10.00 | Slab | 7.50 | routine |
| 1887 | BR:SH6:KRW2:66.415 | KRW2 | SH6 | Uttara Kannada | Karwar | Karwar | 66407 | 8.00 | Slab | 16.00 | routine |
| 1888 | BR:SH6:YLP3:74.37 | YLP3 | SH6 | Uttara Kannada | Sirsi | Yellapur | 74357 | 8.00 | Slab | 27.00 | repair |
| 1889 | BR:SH6:YLP3:76 | YLP3 | SH6 | Uttara Kannada | Sirsi | Yellapur | 75994 | 8.50 | Slab | 13.00 | routine |
| 1890 | BR:SH6:YLP3:96.14 | YLP3 | SH6 | Uttara Kannada | Sirsi | Yellapur | 96131 | 12.00 | Slab | 18.00 | routine |
| 1891 | BR:SH6:YLP3:108.04 | YLP3 | SH6 | Uttara Kannada | Sirsi | Yellapur | 108035 | 9.00 | Slab | 11.00 | repair |
| 1892 | BR:SH6:YLP3:115.905 | YLP3 | SH6 | Uttara Kannada | Sirsi | Yellapur | 115900 | 12.00 | Slab | 11.00 | routine |
| 1893 | BR:SH6:YLP3:124.86 | YLP3 | SH6 | Uttara Kannada | Sirsi | Yellapur | 124839 | 12.00 | Steel Structure | 43.50 | routine |
| 1894 | BR:SH6:SIG4:174.295 | SIG4 | SH6 | Haveri | Haveri | Shiggaon | 174291 | 8.50 | Slab | 8.00 | routine |
| 1895 | BR:SH6:SVN2:192 | SVN2 | SH6 | Haveri | Haveri | Savanur | 191997 | 12.00 | Slab | 7.00 | routine |
| 1896 | BR:SH6:SVN2:194.7 | SVN2 | SH6 | Haveri | Haveri | Savanur | 194694 | 12.00 | Girder | 12.00 | routine |
| 1897 | BR:SH6:SRT1:200.14 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 200136 | 11.00 | others | 9.00 | routine |
| 1898 | BR:SH6:SRT1:201.905 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 201895 | 8.00 | Slab | 21.00 | repair |
| 1899 | BR:SH6:SRT1:205.23 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 205216 | 8.00 | Slab | 28.00 | repair |
| 1900 | BR:SH6:SRT1:205.935 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 205921 | 8.00 | Slab | 28.00 | repair |
| 1901 | BR:SH6:SRT1:212.47 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 212465 | 12.00 | Slab | 10.00 | routine |
| 1902 | BR:SH6:SRT1:216.095 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 216086 | 8.00 | Slab | 18.00 | repair |
| 1903 | BR:SH6:SRT1:217.065 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 217049 | 8.00 | Slab | 32.00 | repair |
| 1904 | BR:SH6:SRT1:219.82 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 219813 | 12.00 | Slab | 15.00 | routine |
| 1905 | BR:SH6:SRT1:220.62 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 220613 | 8.00 | Slab | 14.00 | repair |
| 1906 | BR:SH6:GDG2:229.2 | GDG2 | SH6 | Gadag | Gadag | Gadag | 229197 | 10.00 | Pipe | 7.00 | repair |
| 1907 | BR:SH6:GDG2:231.185 | GDG2 | SH6 | Gadag | Gadag | Gadag | 231175 | 12.00 | Slab | 20.00 | routine |
| 1908 | BR:SH6:GDG2:234.815 | GDG2 | SH6 | Gadag | Gadag | Gadag | 234805 | 12.00 | Slab | 20.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division Id | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1909 | BR:SH6:GDG2:239.145 | GDG2 | SH6 | Gadag | Gadag | Gadag | 239140 | 12.00 | Slab | 11.00 | routine |
| 1910 | BR:SH6:GDG2:240.33 | GDG2 | SH6 | Gadag | Gadag | Gadag | 240315 | 12.00 | Slab | 30.00 | routine |
| 1911 | BR:SH6:GDG2:253.695 | GDG2 | SH6 | Gadag | Gadag | Gadag | 253688 | 10.00 | Slab | 15.00 | routine |
| 1912 | BR:SH6:GDG2:259.66 | GDG2 | SH6 | Gadag | Gadag | Gadag | 259633 | 7.50 | Pipe | 54.50 | repair |
| 1913 | BR:SH6:GDG2:262.58 | GDG2 | SH6 | Gadag | Gadag | Gadag | 262563 | 7.50 | Pipe | 34.50 | repair |
| 1914 | BR:SH6:GDG2:266.045 | GDG2 | SH6 | Gadag | Gadag | Gadag | 266031 | 7.50 | Pipe | 29.50 | repair |
| 1915 | BR:SH6:GDG2:267.455 | GDG2 | SH6 | Gadag | Gadag | Gadag | 267448 | 7.50 | Pipe | 14.50 | repair |
| 1916 | BR:SH6:GDG2:269.29 | GDG2 | SH6 | Gadag | Gadag | Gadag | 269268 | 7.50 | Pipe | 44.50 | repair |
| 1917 | BR:SH6:RON1_A:282.19 | RON1_A | SH6 | Gadag | Gadag | Ron | 282166 | 7.50 | Pipe | 49.50 | repair |
| 1918 | BR:SH6:RON1_A:283.34 | RON1_A | SH6 | Gadag | Gadag | Ron | 283329 | 12.00 | Slab | 22.00 | routine |
| 1919 | BR:SH6:YEL113:292.74 | YEL113 | SH6 | Koppal | Koppal | Yelbarga | 292729 | 7.50 | Pipe | 23.50 | repair |
| 1920 | BR:SH61:BBV4:12.055 | BBV4 | SH61 | Bijapur | Bijapur | Basavanabagevadi | 12035 | 12.00 | Slab | 40.00 | routine |
| 1921 | BR:SH61:BBV4:16.08 | BBV4 | SH61 | Bijapur | Bijapur | Basavanabagevadi | 16064 | 7.50 | pipe | 32.50 | routine |
| 1922 | BR:SH61:BBV4:22.05 | BBV4 | SH61 | Bijapur | Bijapur | Basavanabagevadi | 22031 | 15.00 | Slab | 38.50 | routine |
| 1923 | BR:SH61:MDD201:58.508 | MDD201 | SH61 | Bijapur | Bijapur | Muddebihal | 58465 | 8.50 | Girder | 85.00 | routine |
| 1924 | BR:SH61:MDD201:58.728 | MDD201 | SH61 | Bijapur | Bijapur | Muddebihal | 58643 | 8.50 | Girder | 170.00 | routine |
| 1925 | BR:SH61:SRP205:77.477 | SRP205 | SH61 | Yadgir | Yadgir | Shorapur | 77457 | 8.00 | Slab | 25.00 | routine |
| 1926 | BR:SH61:DEV201:125.039 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 125029 | 12.00 | Girder | 20.00 | routine |
| 1927 | BR:SH61:DEV201:128.609 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 128597 | 12.00 | Slab | 24.00 | routine |
| 1928 | BR:SH61:DEV201:130.846 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 130836 | 12.00 | Girder | 20.00 | routine |
| 1929 | BR:SH61:DEV201:134.021 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 134012 | 12.00 | Slab | 18.00 | routine |
| 1930 | BR:SH61:DEV201:136.316 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 136312 | 12.00 | Slab | 8.00 | routine |
| 1931 | BR:SH61:DEV201:137.516 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 137512 | 12.00 | Slab | 9.00 | routine |
| 1932 | BR:SH61:DEV201:138.191 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 138179 | 12.00 | Slab | 24.00 | routine |
| 1933 | BR:SH61:DEV201:144.356 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 144349 | 12.00 | Slab | 14.00 | routine |
| 1934 | BR:SH61:DEV201:145.246 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 145166 | 12.00 | Girder | 128.00 | routine |
| 1935 | BR:SH61:DEV201:146.186 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 146177 | 12.00 | Slab | 18.00 | routine |
| 1936 | BR:SH61:DEV201:146.996 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 146992 | 12.00 | Slab | 8.00 | routine |
| 1937 | BR:SH61:DEV201:147.671 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 147666 | 12.00 | Girder | 10.00 | routine |
| 1938 | BR:SH61:DEV201:148.656 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 148638 | 12.00 | Slab | 36.00 | routine |
| 1939 | BR:SH61:DEV201:150.766 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 150762 | 12.00 | Slab | 9.00 | routine |
| 1940 | BR:SH61:DEV201:154.356 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 154351 | 12.00 | Slab | 10.00 | routine |
| 1941 | BR:SH61:DEV201:170.834 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 170825 | 8.00 | Slab | 18.00 | repair |
| 1942 | BR:SH61:DEV201:181.929 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 181908 | 9.00 | Slab | 42.00 | repair |
| 1943 | BR:SH61:DEV201:188.969 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 188959 | 7.00 | Girder | 20.00 | repair |
| 1944 | BR:SH61:MAN202:221.884 | MAN202 | SH61 | Raichur | Raichur | Manvi | 221870 | 10.00 | pipe | 29.50 | routine |
| 1945 | BR:SH61:MAN202:234.494 | MAN202 | SH61 | Raichur | Raichur | Manvi | 234476 | 12.00 | Slab | 36.00 | routine |
| 1946 | BR:SH61:RAI201:240.656 | RAI201 | SH61 | Raichur | Raichur | Raichur | 240648 | 12.00 | Slab | 16.00 | routine |
| 1947 | BR:SH61:RAI201:243.741 | RAI201 | SH61 | Raichur | Raichur | Raichur | 243734 | 12.00 | Slab | 14.00 | routine |

Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id. | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m. | Type of Super Str | Bridge Len (m). | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1948 | BR:SH61:RAI201:245.291 | RAI201 | SH61 | Raichur | Raichur | Raichur | 245284 | 8.00 | Slab | 14.00 | routine |
| 1949 | BR:SH61:RAI201:248.091 | RAI201 | SH61 | Raichur | Raichur | Raichur | 248083 | 8.00 | Slab | 16.00 | routine |
| 1950 | BR:SH61:RAI201:249.606 | RAI201 | SH61 | Raichur | Raichur | Raichur | 249568 | 12.00 | Slab | 73.50 | routine |
| 1951 | BR:SH61:RAI201:251.101 | RAI201 | SH61 | Raichur | Raichur | Raichur | 251097 | 10.00 | pipe | 8.50 | routine |
| 1952 | BR:SH62:HVR5:1.085 | HVR5 | SH62 | Haveri | Haveri | Haveri | 1072 | 12.00 | Slab | 27.00 | routine |
| 1953 | BR:SH62:HVR5:4.405 | HVR5 | SH62 | Haveri | Haveri | Haveri | 4402 | 12.00 | Slab | 7.00 | routine |
| 1954 | BR:SH62:HVR5:9.39 | HVR5 | SH62 | Haveri | Haveri | Haveri | 9387 | 12.00 | Slab | 7.00 | routine |
| 1955 | BR:SH62:BYD6:13.895 | BYD6 | SH62 | Haveri | Haveri | Byadagi | 13892 | 12.00 | Slab | 7.50 | routine |
| 1956 | BR:SH62:SKR202:62.624 | SKR202 | SH62 | Shimoga | Shimoga | Shikaripur | 62621 | 12.00 | Slab | 6.50 | routine |
| 1957 | BR:SH62:SKR202:64.104 | SKR202 | SH62 | Shimoga | Shimoga | Shikaripur | 64101 | 12.00 | Slab | 6.50 | routine |
| 1958 | BR:SH62:SRB5:90.963 | SRB5 | SH62 | Shimoga | Shimoga | Sorab | 90954 | 8.50 | Slab | 18.00 | repair |
| 1959 | BR:SH62:SRB5:98.313 | SRB5 | SH62 | Shimoga | Shimoga | Sorab | 98297 | 8.50 | Girder | 32.00 | routine |
| 1960 | BR:SH62:SGR86:109.098 | SGR86 | SH62 | Shimoga | Shimoga | Sagar | 109083 | 10.00 | Slab | 30.00 | routine |
| 1961 | BR:SH62:SGR86:109.108 | SGR86 | SH62 | Shimoga | Shimoga | Sagar | 109091 | 12.00 | Slab | 35.00 | repair |
| 1962 | BR:SH63:SRG45:1.945 | SRG45 | SH63 | Bellary | Bellary | Siruguppa | 1940 | 10.00 | Pipe | 10.00 | routine |
| 1963 | BR:SH63:SRG45:6.255 | SRG45 | SH63 | Bellary | Bellary | Siruguppa | 6239 | 6.70 | Slab | 35.20 | routine |
| 1964 | BR:SH63:SRG45:8.2 | SRG45 | SH63 | Bellary | Bellary | Siruguppa | 8193 | 12.00 | Slab | 14.00 | routine |
| 1965 | BR:SH63:SRG45:12.585 | SRG45 | SH63 | Bellary | Bellary | Siruguppa | 12582 | 12.00 | Slab | 7.00 | routine |
| 1966 | BR:SH63:SRG45:17.08 | SRG45 | SH63 | Bellary | Bellary | Siruguppa | 17015 | 4.00 | Girder | 134.16 | repair |
| 1967 | BR:SH63:GAN94:68.414 | GAN94 | SH63 | Koppal | Koppal | Gangawati | 68382 | 12.00 | Girder | 66.80 | routine |
| 1968 | BR:SH63:GAN94:80.589 | GAN94 | SH63 | Koppal | Koppal | Gangawati | 80583 | 10.00 | pipe | 13.50 | routine |
| 1969 | BR:SH65:KPA8:72.738 | KPA8 | SH65 | Chikmagalur | Chikmagalur | Koppa | 72731 | 12.00 | Slab | 15.00 | routine |
| 1970 | BR:SH65:KPA8:80.263 | KPA8 | SH65 | Chikmagalur | Chikmagalur | Koppa | 80256 | 8.50 | Girder | 15.00 | repair |
| 1971 | BR:SH65:KPA8:91.862 | KPA8 | SH65 | Chikmagalur | Chikmagalur | Koppa | 91852 | 9.00 | Slab | 21.00 | repair |
| 1972 | BR:SH65:NRP202:102.212 | NRP202 | SH65 | Chikmagalur | Chikmagalur | Narasimharajapura | 102209 | 12.00 | Slab | 6.00 | routine |
| 1973 | BR:SH65:NRP202:107.522 | NRP202 | SH65 | Chikmagalur | Chikmagalur | Narasimharajapura | 107515 | 8.50 | Girder | 15.00 | repair |
| 1974 | BR:SH65:NRP202:115.112 | NRP202 | SH65 | Chikmagalur | Chikmagalur | Narasimharajapura | 115097 | 8.00 | Girder | 30.00 | repair |
| 1975 | BR:SH65:NRP202:129.212 | NRP202 | SH65 | Chikmagalur | Chikmagalur | Narasimharajapura | 129203 | 6.50 | Girder | 18.00 | routine |
| 1976 | BR:SH65:NRP202:134.667 | NRP202 | SH65 | Chikmagalur | Chikmagalur | Narasimharajapura | 134658 | 8.50 | Slab | 18.00 | routine |
| 1977 | BR:SH65:SMG202:137.157 | SMG202 | SH65 | Shimoga | Shimoga_special | Shimoga | 137154 | 10.00 | Slab | 7.50 | routine |
| 1978 | BR:SH65:BRV67:152.654 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 152651 | 8.00 | Others | 7.00 | repair |
| 1979 | BR:SH65:BRV67:155.544 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 155541 | 8.00 | Slab | 6.40 | repair |
| 1980 | BR:SH65:BRV67:155.659 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 155653 | 8.00 | Girder | 12.00 | repair |
| 1981 | BR:SH65:BRV67:167.821 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 167806 | 8.50 | Slab | 30.00 | routine |
| 1982 | BR:SH65:BRV67:167.886 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 167881 | 12.00 | Slab | 10.00 | routine |
| 1983 | BR:SH65:BRV67:175.441 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 175429 | 8.00 | Girder | 24.00 | repair |
| 1984 | BR:SH65:BRV67:177.306 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 177300 | 10.00 | Pipe | 13.10 | repair |
| 1985 | BR:SH65:CNG202:185.501 | CNG202 | SH65 | Davanagere | Davanagere | Channagiri | 185488 | 8.50 | Slab | 27.00 | repair |
| 1986 | BR:SH65:CNG202:204.667 | CNG202 | SH65 | Davanagere | Davanagere | Channagiri | 204656 | 8.50 | Pipe | 22.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1987 | BR:SH65:CNG202:226.957 | CNG202 | SH65 | Davanagere | Davanagere | Channagiri | 226950 | 12.00 | Slab | 15.00 | routine |
| 1988 | BR:SH65:DVG48:229.177 | DVG48 | SH65 | Davanagere | Davanagere | Davanagere | 229165 | 12.00 | Slab | 25.00 | routine |
| 1989 | BR:SH65:DVG48:236.912 | DVG48 | SH65 | Davanagere | Davanagere | Davanagere | 236896 | 8.00 | Girder | 33.00 | repair |
| 1990 | BR:SH65:DVG48:275.628 | DVG48 | SH65 | Davanagere | Davanagere | Davanagere | 275620 | 12.00 | Slab | 16.00 | routine |
| 1991 | BR:SH65:JGL202:281.248 | JGL202 | SH65 | Davanagere | Davanagere | Jagalur | 281220 | 7.50 | Steel Structure | 57.00 | repair |
| 1992 | BR:SH65:JGL202:288.785 | JGL202 | SH65 | Davanagere | Davanagere | Jagalur | 288773 | 8.00 | Slab | 25.90 | routine |
| 1993 | BR:SH65:JGL202:323.105 | JGL202 | SH65 | Davanagere | Davanagere | Jagalur | 323102 | 4.50 | Slab | 6.50 | repair |
| 1994 | BR:SH65:CHL202:341.88 | CHL202 | SH65 | Chitradurga | Chitradurga | Challakere | 341868 | 9.20 | Pipe | 25.00 | routine |
| 1995 | BR:SH65:MOL202:349.75 | MOL202 | SH65 | Chitradurga | Chitradurga | Molakalmuru | 349744 | 8.00 | Slab | 12.00 | repair |
| 1996 | BR:SH65:MOL202:350.465 | MOL202 | SH65 | Chitradurga | Chitradurga | Molakalmuru | 350457 | 8.00 | Slab | 16.00 | repair |
| 1997 | BR:SH65:MOL202:352.275 | MOL202 | SH65 | Chitradurga | Chitradurga | Molakalmuru | 352264 | 10.00 | Pipe | 22.00 | repair |
| 1998 | BR:SH65:MOL202:361.825 | MOL202 | SH65 | Chitradurga | Chitradurga | Molakalmuru | 361822 | 8.00 | Slab | 7.50 | repair |
| 1999 | BR:SH65:MOL202:365.68 | MOL202 | SH65 | Chitradurga | Chitradurga | Molakalmuru | 365676 | 9.50 | Slab | 8.00 | repair |
| 2000 | BR:SH65:MOL202:371.92 | MOL202 | SH65 | Chitradurga | Chitradurga | Molakalmuru | 371911 | 8.50 | Slab | 18.00 | repair |
| 2001 | BR:SH67:MNG6:19.04 | MNG6 | SH67 | Dakshina Kannada | Mangalore | Mangalore | 18944 | 9.00 | Girder | 198.00 | repair |
| 2002 | BR:SH67:MNG6:21.87 | MNG6 | SH67 | Dakshina Kannada | Mangalore | Mangalore | 21865 | 8.00 | Arch | 10.00 | repair |
| 2003 | BR:SH67:MNG6:31.615 | MNG6 | SH67 | Dakshina Kannada | Mangalore | Mangalore | 31598 | 8.00 | Girder | 34.00 | repair |
| 2004 | BR:SH67:MNG6:33.55 | MNG6 | SH67 | Dakshina Kannada | Mangalore | Mangalore | 33524 | 7.50 | Girder | 53.50 | routine |
| 2005 | BR:SH67:KRK44:41.945 | KRK44 | SH67 | Udupi | Udupi | Karkala | 41909 | 8.00 | Slab | 72.00 | repair |
| 2006 | BR:SH67:KRK44:48.36 | KRK44 | SH67 | Udupi | Udupi | Karkala | 48350 | 12.00 | Slab | 20.00 | routine |
| 2007 | BR:SH69:KMT2:17.42 | KMT2 | SH69 | Uttara Kannada | Karwar | Kumta | 17413 | 8.00 | Slab | 14.00 | repair |
| 2008 | BR:SH69:KMT2:18.56 | KMT2 | SH69 | Uttara Kannada | Karwar | Kumta | 18545 | 8.00 | Girder | 30.00 | repair |
| 2009 | BR:SH69:SRS90:32.955 | SRS90 | SH69 | Uttara Kannada | Sirsi | Sirsi | 32952 | 8.50 | Slab | 6.50 | repair |
| 2010 | BR:SH69:SRS90:33.94 | SRS90 | SH69 | Uttara Kannada | Sirsi | Sirsi | 33913 | 7.50 | Girder | 55.00 | repair |
| 2011 | BR:SH69:SRS90:45.71 | SRS90 | SH69 | Uttara Kannada | Sirsi | Sirsi | 45695 | 7.50 | Girder | 30.00 | repair |
| 2012 | BR:SH69:SRS90:55.415 | SRS90 | SH69 | Uttara Kannada | Sirsi | Sirsi | 55412 | 15.00 | Slab | 7.00 | repair |
| 2013 | BR:SH69:MUD1:86.771 | MUD1 | SH69 | Uttara Kannada | Sirsi | Mundgod | 86762 | 8.00 | Slab | 18.00 | repair |
| 2014 | BR:SH69:MUD1:88.206 | MUD1 | SH69 | Uttara Kannada | Sirsi | Mundgod | 88196 | 8.00 | Slab | 21.00 | repair |
| 2015 | BR:SH69:MUD1:103.431 | MUD1 | SH69 | Uttara Kannada | Sirsi | Mundgod | 103428 | 9.50 | Others | 6.50 | repair |
| 2016 | BR:SH69:MUD1:107.111 | MUD1 | SH69 | Uttara Kannada | Sirsi | Mundgod | 107103 | 12.00 | Slab | 16.00 | routine |
| 2017 | BR:SH69:MUD1:115.181 | MUD1 | SH69 | Uttara Kannada | Sirsi | Mundgod | 115169 | 12.00 | Slab | 25.60 | routine |
| 2018 | BR:SH69:MUD1:123.106 | MUD1 | SH69 | Uttara Kannada | Sirsi | Mundgod | 123103 | 14.00 | Others | 7.00 | repair |
| 2019 | BR:SH69:MUD1:125.121 | MUD1 | SH69 | Uttara Kannada | Sirsi | Mundgod | 125117 | 14.00 | Others | 9.00 | routine |
| 2020 | BR:SH7:PDP2_B:11.025 | PDP2_B | SH7 | Mandya | Mandya | Pandavapura | 11011 | 12.00 | Slab | 28.00 | routine |
| 2021 | BR:SH7:PDP2_B:11.335 | PDP2_B | SH7 | Mandya | Mandya | Pandavapura | 11313 | 8.00 | Steel Structure | 44.00 | repair |
| 2022 | BR:SH7:PDP2_B:12.175 | PDP2_B | SH7 | Mandya | Mandya | Pandavapura | 12171 | 12.00 | Slab | 9.50 | routine |
| 2023 | BR:SH7:PDP2_B:12.98 | PDP2_B | SH7 | Mandya | Mandya | Pandavapura | 12976 | 12.00 | Slab | 9.50 | routine |
| 2024 | BR:SH7:PDP2_B:16.945 | PDP2_B | SH7 | Mandya | Mandya | Pandavapura | 16931 | 12.00 | Slab | 28.20 | routine |
| 2025 | BR:SH7:PDP2_B:19.05 | PDP2_B | SH7 | Mandya | Mandya | Pandavapura | 19041 | 12.00 | Slab | 18.80 | routine |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl No | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width(m) | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2026 | BR:SH7:KRP1:28.07 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 28065 | 12.00 | Slab | 10.00 | routine |
| 2027 | BR:SH7:KRP1:32.8 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 32770 | 12.00 | Girder | 60.00 | routine |
| 2028 | BR:SH7:KRP1:35.065 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 35057 | 8.00 | Slab | 17.50 | routine |
| 2029 | BR:SH7:KRP1:46.203 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 46194 | 12.00 | Slab | 18.00 | routine |
| 2030 | BR:SH7:KRP1:47.263 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 47259 | 12.50 | pipe | 8.50 | repair |
| 2031 | BR:SH7:KRP1:48.123 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 48114 | 12.00 | Slab | 18.40 | routine |
| 2032 | BR:SH7:KRP1:49.493 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 49489 | 12.00 | Slab | 8.40 | routine |
| 2033 | BR:SH7:KRP1:57.378 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 57374 | 12.00 | Slab | 9.20 | routine |
| 2034 | BR:SH7:KRP1:59.058 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 59049 | 12.00 | Slab | 18.00 | routine |
| 2035 | BR:SH7:KRP1:60.183 | KRP1 | SH7 | Mandya | Mandya | Krishnarajpet | 60177 | 12.00 | Slab | 12.00 | routine |
| 2036 | BR:SH7:CRP3:60.498 | CRP3 | SH7 | Hassan | Hassan | Channarayapattana | 60473 | 12.00 | Slab | 50.00 | routine |
| 2037 | BR:SH7:CRP3:62.618 | CRP3 | SH7 | Hassan | Hassan | Channarayapattana | 62614 | 11.00 | Slab | 8.00 | repair |
| 2038 | BR:SH7:CRP3:63.378 | CRP3 | SH7 | Hassan | Hassan | Channarayapattana | 63375 | 8.50 | Slab | 6.50 | repair |
| 2039 | BR:SH7:CRP3:64.148 | CRP3 | SH7 | Hassan | Hassan | Channarayapattana | 64138 | 12.00 | Slab | 20.00 | routine |
| 2040 | BR:SH7:CRP3:65.768 | CRP3 | SH7 | Hassan | Hassan | Channarayapattana | 65759 | 8.50 | Slab | 18.00 | routine |
| 2041 | BR:SH7:CRP3:67.733 | CRP3 | SH7 | Hassan | Hassan | Channarayapattana | 67730 | 12.00 | Slab | 7.00 | routine |
| 2042 | BR:SH70:BEL3:15.06 | BEL3 | SH70 | Dakshina Kannada | Mangalore | Belthangady | 15010 | 8.00 | Girder | 100.00 | repair |
| 2043 | BR:SH70:BEL3:17.95 | BEL3 | SH70 | Dakshina Kannada | Mangalore | Belthangady | 17945 | 8.00 | Slab | 11.00 | repair |
| 2044 | BR:SH70:MNG7:23.525 | MNG7 | SH70 | Dakshina Kannada | Mangalore | Mangalore | 25485 | 8.50 | Girder | 78.00 | repair |
| 2045 | BR:SH70:MNG7:42.3 | MNG7 | SH70 | Dakshina Kannada | Mangalore | Mangalore | 42295 | 8.00 | Slab | 10.00 | repair |
| 2046 | BR:SH70:MNG7:44.825 | MNG7 | SH70 | Dakshina Kannada | Mangalore | Mangalore | 44821 | 8.00 | Slab | 9.00 | repair |
| 2047 | BR:SH70:MNG7:59.27 | MNG7 | SH70 | Dakshina Kannada | Mangalore | Mangalore | 59257 | 8.00 | Girder | 27.00 | routine |
| 2048 | BR:SH71:TPT3:4.205 | TPT3 | SH71 | Tumkur | Tumkur | Tiptur | 4201 | 12.00 | Slab | 9.00 | routine |
| 2049 | BR:SH71:TPT3:7.395 | TPT3 | SH71 | Tumkur | Tumkur | Tiptur | 7380 | 9.00 | Girder | 30.00 | repair |
| 2050 | BR:SH71:HSS3:32.576 | HSS3 | SH71 | Hassan | Hassan | Hassan | 32566 | 19.00 | Slab | 20.40 | routine |
| 2051 | BR:SH71:HSS3:37.436 | HSS3 | SH71 | Hassan | Hassan | Hassan | 37424 | 12.00 | Slab | 25.50 | routine |
| 2052 | BR:SH72:CKD201_A:14.551 | CKD201_A | SH72 | Belgaum | Chikkodi | Chikkodi | 14516 | 8.00 | Arch | 71.50 | repair |
| 2053 | BR:SH72:CKD201_A:15.831 | CKD201_A | SH72 | Belgaum | Chikkodi | Chikkodi | 15810 | 8.00 | Slab | 42.00 | repair |
| 2054 | BR:SH72:ATN20_B:100.548 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 100511 | 12.00 | Girder | 82.50 | routine |
| 2055 | BR:SH72:ATN20_B:121.703 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 121699 | 9.00 | Slab | 9.00 | routine |
| 2056 | BR:SH72:ATN20_B:127.903 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 127898 | 8.00 | pipe | 11.50 | repair |
| 2057 | BR:SH72:ATN20_B:132.753 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 132749 | 9.00 | Slab | 8.00 | routine |
| 2058 | BR:SH72:ATN20_B:145.628 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 145598 | 10.00 | Slab | 72.00 | routine |
| 2059 | BR:SH73:ATN6:2.12 | ATN6 | SH73 | Belgaum | Chikkodi | Athni | 2116 | 9.00 | Slab | 8.00 | routine |
| 2060 | BR:SH73:RBG201:29.16 | RBG201 | SH73 | Belgaum | Chikkodi | Raibag | 29157 | 10.00 | pipe | 7.90 | routine |
| 2061 | BR:SH73:RBG201:46.734 | RBG201 | SH73 | Belgaum | Chikkodi | Raibag | 46730 | 12.00 | Slab | 9.00 | routine |
| 2062 | BR:SH73:CKD202:59.244 | CKD202 | SH73 | Belgaum | Chikkodi | Chikkodi | 59220 | 8.00 | Slab | 49.00 | repair |
| 2063 | BR:SH73:GOK205_A:75.624 | GOK205_A | SH73 | Belgaum | Chikkodi | Gokak | 75615 | 8.50 | Slab | 18.00 | repair |
| 2064 | BR:SH73:GOK205_A:77.949 | GOK205_A | SH73 | Belgaum | Chikkodi | Gokak | 77889 | 11.50 | Girder | 116.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2065 | BR:SH73:GOK205_A:78.339 | GOK205_A | SH73 | Belgaum | Chikkodi | Gokak | 78219 | 11.50 | Girder | 240.00 | routine |
| 2066 | BR:SH73:GOK205_A:85.755 | GOK205_A | SH73 | Belgaum | Chikkodi | Gokak | 85750 | 8.00 | Girder | 10.00 | repair |
| 2067 | BR:SH73:GOK205_B:110.02 | GOK205_B | SH73 | Belgaum | Chikkodi | Gokak | 110015 | 10.00 | pipe | 10.70 | routine |
| 2068 | BR:SH73:BAI203:119.48 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 119476 | 8.00 | Slab | 8.00 | repair |
| 2069 | BR:SH73:BAI203:125.18 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 125167 | 8.00 | Slab | 27.00 | repair |
| 2070 | BR:SH73:BAI203:139.367 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 139359 | 8.50 | Slab | 16.00 | routine |
| 2071 | BR:SH73:BAI203:148.907 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 148893 | 7.50 | pipe | 29.50 | repair |
| 2072 | BR:SH73:BAI203:186.802 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 186799 | 12.00 | Slab | 7.00 | routine |
| 2073 | BR:SH73:BAI203:196.102 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 196095 | 8.00 | pipe | 15.60 | repair |
| 2074 | BR:SH73:DRD6:203.922 | DRD6 | SH73 | Dharwad | Dharwad | Dharwad | 203892 | 8.00 | Slab | 60.00 | repair |
| 2075 | BR:SH73:HBL5:234.976 | HBL5 | SH73 | Dharwad | Dharwad | Hubli | 234971 | 8.00 | Slab | 10.00 | repair |
| 2076 | BR:SH73:HBL5:250.631 | HBL5 | SH73 | Dharwad | Dharwad | Hubli | 250627 | 12.00 | Slab | 8.00 | routine |
| 2077 | BR:SH73:HBL5:251.871 | HBL5 | SH73 | Dharwad | Dharwad | Hubli | 251868 | 12.00 | Slab | 7.00 | routine |
| 2078 | BR:SH73:HBL5:252.856 | HBL5 | SH73 | Dharwad | Dharwad | Hubli | 252852 | 12.00 | Slab | 9.00 | routine |
| 2079 | BR:SH73:HBL5:254.531 | HBL5 | SH73 | Dharwad | Dharwad | Hubli | 254525 | 12.00 | Slab | 12.00 | routine |
| 2080 | BR:SH73:HBL5:256.721 | HBL5 | SH73 | Dharwad | Dharwad | Hubli | 256715 | 12.00 | Slab | 12.00 | routine |
| 2081 | BR:SH73:KNG2:258.941 | KNG2 | SH73 | Dharwad | Dharwad | Kundgol | 258938 | 12.00 | Slab | 7.00 | routine |
| 2082 | BR:SH73:KNG2:261.776 | KNG2 | SH73 | Dharwad | Dharwad | Kundgol | 261772 | 12.00 | Slab | 8.00 | routine |
| 2083 | BR:SH73:KNG2:264.748 | KNG2 | SH73 | Dharwad | Dharwad | Kundgol | 264712 | 8.50 | Girder | 72.00 | routine |
| 2084 | BR:SH73:KNG2:267.993 | KNG2 | SH73 | Dharwad | Dharwad | Kundgol | 267973 | 12.00 | Girder | 40.00 | routine |
| 2085 | BR:SH73:KNG2:269.083 | KNG2 | SH73 | Dharwad | Dharwad | Kundgol | 269080 | 12.00 | Slab | 7.50 | routine |
| 2086 | BR:SH73:KNG2:273.678 | KNG2 | SH73 | Dharwad | Dharwad | Kundgol | 273674 | 12.00 | Slab | 8.00 | routine |
| 2087 | BR:SH73:KNG2:275.098 | KNG2 | SH73 | Dharwad | Dharwad | Kundgol | 275094 | 12.00 | Slab | 8.00 | routine |
| 2088 | BR:SH73:KNG2:276.818 | KNG2 | SH73 | Dharwad | Dharwad | Kundgol | 276812 | 12.00 | Slab | 12.00 | routine |
| 2089 | BR:SH73:KNG2:277.293 | KNG2 | SH73 | Dharwad | Dharwad | Kundgol | 277268 | 12.00 | Girder | 50.00 | routine |
| 2090 | BR:SH74:NLM6:4.404 | NLM6 | SH74 | Bangalore Rural | Bangalore | Nelmangala | 4401 | 11.45 | Slab | 6.50 | routine |
| 2091 | BR:SH74:DOD3:18.189 | DOD3 | SH74 | Bangalore Rural | Bangalore | Dod Ballapura | 18161 | 7.40 | Slab | 56.40 | routine |
| 2092 | BR:SH74:DOD3:19.559 | DOD3 | SH74 | Bangalore Rural | Bangalore | Dod Ballapura | 19550 | 7.50 | pipe | 19.90 | routine |
| 2093 | BR:SH74:DOD3:42.519 | DOD3 | SH74 | Bangalore Rural | Bangalore | Dod Ballapura | 42514 | 7.80 | Slab | 11.00 | routine |
| 2094 | BR:SH75:BHA203:7.105 | BHA203 | SH75 | Bidar | Bidar | Bhalki | 7097 | 10.00 | Slab | 16.50 | repair |
| 2095 | BR:SH75:BHA203:10.55 | BHA203 | SH75 | Bidar | Bidar | Bhalki | 10545 | 10.00 | Slab | 10.00 | repair |
| 2096 | BR:SH75:HUM202:15.57 | HUM202 | SH75 | Bidar | Bidar | Homnabad | 15537 | 8.00 | Girder | 72.00 | repair |
| 2097 | BR:SH75:HUM202:44.787 | HUM202 | SH75 | Bidar | Bidar | Homnabad | 44777 | 12.00 | Slab | 21.00 | routine |
| 2098 | BR:SH75:HUM202:51.932 | HUM202 | SH75 | Bidar | Bidar | Homnabad | 51928 | 8.00 | Slab | 8.00 | repair |
| 2099 | BR:SH75:CNL201:56.367 | CNL201 | SH75 | Gulbarga | Sedam | Chincholi | 56363 | 8.00 | Slab | 9.00 | repair |
| 2100 | BR:SH75:CNL201:64.307 | CNL201 | SH75 | Gulbarga | Sedam | Chincholi | 64239 | 7.10 | Girder | 134.40 | repair |
| 2101 | BR:SH75:CNL201:73.712 | CNL201 | SH75 | Gulbarga | Sedam | Chincholi | 73709 | 8.00 | Slab | 6.50 | repair |
| 2102 | BR:SH75:CNL201:74.517 | CNL201 | SH75 | Gulbarga | Sedam | Chincholi | 74504 | 8.00 | Slab | 27.00 | repair |
| 2103 | BR:SH75:CNL201:78.922 | CNL201 | SH75 | Gulbarga | Sedam | Chincholi | 78915 | 8.00 | Slab | 14.00 | repair |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2104 | BR:SH75:CNL201:81.662 | CNL201 | SH75 | Gulbarga | Sedam | Chincholi | 81654 | 8.00 | Slab | 16.00 | repair |
| 2105 | BR:SH75:CNL201:83.812 | CNL201 | SH75 | Gulbarga | Sedam | Chincholi | 83803 | 8.00 | Slab | 18.00 | repair |
| 2106 | BR:SH75:CNL201:84.837 | CNL201 | SH75 | Gulbarga | Sedam | Chincholi | 84834 | 8.00 | Slab | 6.50 | repair |
| 2107 | BR:SH76:KDR210:0.945 | KDR210 | SH76 | Chikmagalur | Chikmagalur | Kadur | 937 | 7.50 | pipe | 17.50 | routine |
| 2108 | BR:SH76:TRK211:15.145 | TRK211 | SH76 | Chikmagalur | Chikmagalur | Tarikere | 15136 | 8.00 | Slab | 18.00 | routine |
| 2109 | BR:SH76:TRK211:24.25 | TRK211 | SH76 | Chikmagalur | Chikmagalur | Tarikere | 24245 | 8.00 | Slab | 11.00 | repair |
| 2110 | BR:SH76:CNG201:66.548 | CNG201 | SH76 | Davanagere | Davanagere | Channagiri | 66530 | 6.00 | Pipe | 37.00 | routine |
| 2111 | BR:SH76:CNG201:75.625 | CNG201 | SH76 | Davanagere | Davanagere | Channagiri | 75618 | 6.50 | Girder | 14.00 | routine |
| 2112 | BR:SH76:CNG201:78.49 | CNG201 | SH76 | Davanagere | Davanagere | Channagiri | 78486 | 12.00 | Slab | 8.00 | routine |
| 2113 | BR:SH76:CNG201:82.445 | CNG201 | SH76 | Davanagere | Davanagere | Channagiri | 82414 | 6.50 | Pipe | 62.50 | routine |
| 2114 | BR:SH76:DVG49:84.84 | DVG49 | SH76 | Davanagere | Davanagere | Davanagere | 84831 | 7.50 | Pipe | 19.10 | routine |
| 2115 | BR:SH76:DVG49:87.88 | DVG49 | SH76 | Davanagere | Davanagere | Davanagere | 87875 | 7.50 | Pipe | 11.50 | routine |
| 2116 | BR:SH76:DVG49:92.29 | DVG49 | SH76 | Davanagere | Davanagere | Davanagere | 92285 | 7.50 | Pipe | 11.50 | routine |
| 2117 | BR:SH76:DVG49:116.5 | DVG49 | SH76 | Davanagere | Davanagere | Davanagere | 116487 | 9.50 | Slab | 26.50 | routine |
| 2118 | BR:SH76:HRR2:122.28 | HRR2 | SH76 | Davanagere | Davanagere | Harihar | 122277 | 12.00 | Slab | 6.50 | routine |
| 2119 | BR:SH76:RBN3:136.277 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 136272 | 8.50 | Slab | 10.00 | routine |
| 2120 | BR:SH76:RBN3:136.607 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 136601 | 12.00 | Slab | 12.00 | routine |
| 2121 | BR:SH76:RBN3:137.072 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 137068 | 8.50 | Slab | 8.00 | routine |
| 2122 | BR:SH76:RBN3:137.962 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 137957 | 8.50 | Slab | 10.00 | routine |
| 2123 | BR:SH76:RBN3:138.932 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 138927 | 8.50 | Slab | 10.00 | routine |
| 2124 | BR:SH76:RBN3:140.942 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 140938 | 8.50 | Slab | 8.00 | routine |
| 2125 | BR:SH76:RBN3:143.582 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 143577 | 8.50 | Slab | 10.00 | routine |
| 2126 | BR:SH76:RBN3:144.407 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 144401 | 8.50 | Slab | 12.00 | routine |
| 2127 | BR:SH76:RBN3:145.427 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 145418 | 8.50 | Slab | 18.00 | routine |
| 2128 | BR:SH76:RBN3:146.147 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 146138 | 8.50 | Slab | 18.00 | routine |
| 2129 | BR:SH76:RBN3:151.997 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 151993 | 12.00 | Slab | 8.00 | routine |
| 2130 | BR:SH76:RBN3:153.327 | RBN3 | SH76 | Haveri | Haveri | Ranebennur | 153318 | 7.50 | Pipe | 19.50 | repair |
| 2131 | BR:SH76:HKR4_A:173.948 | HKR4_A | SH76 | Haveri | Haveri | Hirekerur | 173945 | 10.00 | Slab | 6.50 | routine |
| 2132 | BR:SH76:HNL3:197.263 | HNL3 | SH76 | Haveri | Haveri | Hangal | 197208 | 8.00 | Slab | 110.00 | repair |
| 2133 | BR:SH77:SRS91:11.93 | SRS91 | SH77 | Uttara Kannada | Sirsi | Sirsi | 11892 | 8.00 | Girder | 76.00 | routine |
| 2134 | BR:SH77:SRS91:24.01 | SRS91 | SH77 | Uttara Kannada | Sirsi | Sirsi | 23952 | 8.00 | Girder | 112.00 | repair |
| 2135 | BR:SH77:SGR87:58.895 | SGR87 | SH77 | Shimoga | Shimoga | Sagar | 58873 | 12.00 | Girder | 45.00 | repair |
| 2136 | BR:SH77:SGR87:66.775 | SGR87 | SH77 | Shimoga | Shimoga | Sagar | 66769 | 9.00 | Slab | 12.00 | repair |
| 2137 | BR:SH77:SGR87:69.335 | SGR87 | SH77 | Shimoga | Shimoga | Sagar | 69331 | 12.00 | Slab | 8.00 | repair |
| 2138 | BR:SH77:SGR87:71.5 | SGR87 | SH77 | Shimoga | Shimoga | Sagar | 71490 | 12.00 | Slab | 20.00 | routine |
| 2139 | BR:SH77:SGR87:84.933 | SGR87 | SH77 | Shimoga | Shimoga | Sagar | 84928 | 12.00 | Slab | 10.00 | routine |
| 2140 | BR:SH77:HSN203:94.563 | HSN203 | SH77 | Shimoga | Shimoga | Hosanagara | 94547 | 12.00 | Slab | 32.10 | routine |
| 2141 | BR:SH77:HSN203:102.00 | HSN203 | SH77 | Shimoga | Shimoga | Hosanagara | 101994 | 8.50 | Slab | 12.60 | routine |
| 2142 | BR:SH77:HSN203:102.05 | HSN203 | SH77 | Shimoga | Shimoga | Hosanagara | 102025 | 7.50 | Girder | 51.00 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number. | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2143 | BR:SH77:HSN203:107.2 | HSN203 | SH77 | Shimoga | Shimoga | Hosanagara | 107170 | 7.50 | Girder | 61.20 | repair |
| 2144 | BR:SH77:HSN203:114.7 | HSN203 | SH77 | Shimoga | Shimoga | Hosanagara | 114696 | 8.00 | Girder | 9.50 | repair |
| 2145 | BR:SH78:HUK207:28.15 | HUK207 | SH78 | Belgaum | Chikkodi | Hukkeri | 28147 | 10.00 | pipe | 6.50 | routine |
| 2146 | BR:SH78:HUK207:32.34 | HUK207 | SH78 | Belgaum | Chikkodi | Hukkeri | 32264 | 12.00 | Girder | 153.00 | routine |
| 2147 | BR:SH78:HUK207:36.855 | HUK207 | SH78 | Belgaum | Chikkodi | Hukkeri | 36845 | 8.00 | Slab | 20.00 | repair |
| 2148 | BR:SH78:CKD203:84.575 | CKD203 | SH78 | Belgaum | Chikkodi | Chikkodi | 84528 | 6.00 | Slab | 102.00 | routine |
| 2149 | BR:SH79:SPT3:6.62 | SPT3 | SH79 | Mandya | Mandya | Srirangapattana | 6612 | 12.00 | Slab | 16.00 | routine |
| 2150 | BR:SH79:SPT3:13.435 | SPT3 | SH79 | Mandya | Mandya | Srirangapattana | 13429 | 9.00 | Slab | 12.00 | routine |
| 2151 | BR:SH79:TNP205:17.16 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 17157 | 10.00 | Slab | 6.00 | repair |
| 2152 | BR:SH79:TNP205:28.395 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 28392 | 10.00 | Slab | 6.00 | repair |
| 2153 | BR:SH79:TNP205:29.015 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 29012 | 12.00 | Slab | 6.00 | repair |
| 2154 | BR:SH79:TNP205:39.025 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 38850 | 12.00 | Girder | 427.50 | routine |
| 2155 | BR:SH79:TNP205:42.145 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 42140 | 12.00 | Slab | 10.50 | routine |
| 2156 | BR:SH79:TNP205:49.43 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 49427 | 8.50 | Slab | 6.00 | repair |
| 2157 | BR:SH79:TNP205:52.855 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 52832 | 8.50 | pipe | 47.60 | routine |
| 2158 | BR:SH79:KLL301:60.815 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 60809 | 12.00 | Slab | 12.00 | routine |
| 2159 | BR:SH79:KLL301:61.335 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 61329 | 12.00 | Slab | 12.00 | routine |
| 2160 | BR:SH79:KLL301:63.49 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 63463 | 8.50 | pipe | 55.00 | repair |
| 2161 | BR:SH79:KLL301:75.768 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 75758 | 8.50 | pipe | 21.70 | routine |
| 2162 | BR:SH79:KLL301:77.048 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 77043 | 8.50 | Slab | 10.80 | routine |
| 2163 | BR:SH79:KLL301:80.273 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 80268 | 8.50 | Slab | 10.00 | repair |
| 2164 | BR:SH79:KLL301:90.172 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 90162 | 12.00 | Slab | 20.80 | routine |
| 2165 | BR:SH79:KLL301:119.112 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 119109 | 11.40 | Slab | 6.40 | repair |
| 2166 | BR:SH79:KLL301:120.392 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 120389 | 9.00 | Slab | 6.00 | repair |
| 2167 | BR:SH79:KLL301:121.137 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 121134 | 10.00 | Slab | 6.75 | repair |
| 2168 | BR:SH79:KLL301:121.782 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 121777 | 8.50 | Slab | 10.00 | repair |
| 2169 | BR:SH79:KLL301:128.482 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 128478 | 8.50 | Slab | 9.00 | repair |
| 2170 | BR:SH79:KLL301:159.407 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 159397 | 8.50 | Slab | 20.00 | repair |
| 2171 | BR:SH8:CRP2:21.325 | CRP2 | SH8 | Hassan | Hassan | Channarayapattana | 21317 | 8.50 | Slab | 17.00 | repair |
| 2172 | BR:SH8:CRP2:26.365 | CRP2 | SH8 | Hassan | Hassan | Channarayapattana | 26343 | 11.00 | Slab | 45.00 | routine |
| 2173 | BR:SH8:CRP2:27.38 | CRP2 | SH8 | Hassan | Hassan | Channarayapattana | 27330 | 10.00 | Slab | 100.00 | routine |
| 2174 | BR:SH8:CRP2:40.46 | CRP2 | SH8 | Hassan | Hassan | Channarayapattana | 40455 | 12.00 | Slab | 11.20 | routine |
| 2175 | BR:SH8:CRP2:40.995 | CRP2 | SH8 | Hassan | Hassan | Channarayapattana | 40877 | 12.00 | Girder | 236.50 | routine |
| 2176 | BR:SH8:HNP247:49.795 | HNP247 | SH8 | Hassan | Hassan | Holenarsipur | 49788 | 12.00 | Slab | 14.00 | routine |
| 2177 | BR:SH8:HNP247:52.495 | HNP247 | SH8 | Hassan | Hassan | Holenarsipur | 52484 | 8.50 | Girder | 23.00 | routine |
| 2178 | BR:SH8:ARK2:70.552 | ARK2 | SH8 | Hassan | Hassan_Special | Arkalgud | 70549 | 12.00 | Slab | 6.50 | routine |
| 2179 | BR:SH8:ARK2:74.422 | ARK2 | SH8 | Hassan | Hassan_Special | Arkalgud | 74418 | 12.00 | Slab | 8.00 | routine |
| 2180 | BR:SH8:ARK2:80.958 | ARK2 | SH8 | Hassan | Hassan_Special | Arkalgud | 80951 | 8.50 | Slab | 14.40 | repair |
| 2181 | BR:SH8:SVP78_A:98.203 | SVP78_A | SH8 | Kodagu | Kodagu | Somvarpet | 98199 | 12.00 | Slab | 8.00 | repair |

Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl..No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2182 | BR:SH8:SVP78_A:98.728 | SVP78_A | SH8 | Kodagu | Kodagu | Somvarpet | 98718 | 9.00 | Slab | 21.00 | repair |
| 2183 | BR:SH8:SVP78_A:102.173 | SVP78_A | SH8 | Kodagu | Kodagu | Somvarpet | 102153 | 8.50 | Girder | 40.00 | repair |
| 2184 | BR:SH8:SLP235:124.372 | SLP235 | SH8 | Hassan | Hassan_Special | Sakleshpur | 124364 | 6.00 | pipe | 17.50 | repair |
| 2185 | BR:SH8:SVP78_B:138.762 | SVP78_B | SH8 | Kodagu | Kodagu | Somvarpet | 138750 | 6.00 | Slab | 24.00 | repair |
| 2186 | BR:SH8:SVP78_B:160.464 | SVP78_B | SH8 | Kodagu | Kodagu | Somvarpet | 160408 | 8.50 | Girder | 112.00 | repair |
| 2187 | BR:SH8:SVP78_B:174.724 | SVP78_B | SH8 | Kodagu | Kodagu | Somvarpet | 174714 | 8.50 | Slab | 20.00 | repair |
| 2188 | BR:SH81:CRN119:6.33 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 6315 | 8.50 | Slab | 30.00 | routine |
| 2189 | BR:SH81:CRN119:6.43 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 6418 | 8.50 | Girder | 24.00 | repair |
| 2190 | BR:SH81:CRN119:8.03 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 8027 | 11.80 | Slab | 6.30 | repair |
| 2191 | BR:SH81:CRN119:24.687 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 24684 | 8.50 | Slab | 6.00 | routine |
| 2192 | BR:SH81:CRN119:26.002 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 25998 | 8.50 | Slab | 9.00 | repair |
| 2193 | BR:SH81:CRN119:27.682 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 27678 | 8.50 | Slab | 9.60 | repair |
| 2194 | BR:SH81:CRN119:29.927 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 29921 | 10.20 | Slab | 12.00 | repair |
| 2195 | BR:SH81:CRN119:32.697 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 32694 | 9.00 | Slab | 6.00 | repair |
| 2196 | BR:SH81:CRN119:34.027 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 34024 | 9.00 | Slab | 6.00 | repair |
| 2197 | BR:SH81:CRN119:35.452 | CRN119 | SH81 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 35449 | 9.00 | Slab | 6.00 | repair |
| 2198 | BR:SH81:GNP202:43.062 | GNP202 | SH81 | Chamrajnagar | Chamrajnagar | Gundlupet | 43057 | 9.00 | Slab | 10.00 | repair |
| 2199 | BR:SH81:GNP202:45.267 | GNP202 | SH81 | Chamrajnagar | Chamrajnagar | Gundlupet | 45262 | 10.00 | Slab | 10.00 | repair |
| 2200 | BR:SH81:GNP202:46.342 | GNP202 | SH81 | Chamrajnagar | Chamrajnagar | Gundlupet | 46338 | 12.00 | Slab | 8.00 | routine |
| 2201 | BR:SH81:GNP202:47.922 | GNP202 | SH81 | Chamrajnagar | Chamrajnagar | Gundlupet | 47916 | 10.50 | Others | 12.00 | repair |
| 2202 | BR:SH81:GNP202:50.107 | GNP202 | SH81 | Chamrajnagar | Chamrajnagar | Gundlupet | 50101 | 12.00 | Others | 12.00 | repair |
| 2203 | BR:SH81:GNP202:52.087 | GNP202 | SH81 | Chamrajnagar | Chamrajnagar | Gundlupet | 52083 | 12.00 | Others | 8.40 | repair |
| 2204 | BR:SH81:GNP202:54.472 | GNP202 | SH81 | Chamrajnagar | Chamrajnagar | Gundlupet | 54448 | 8.50 | Slab | 48.00 | repair |
| 2205 | BR:SH82:HOS3:4.785 | HOS3 | SH82 | Bangalore Rural | Bangalore | Hoskote | 4782 | 12.00 | Slab | 6.00 | routine |
| 2206 | BR:SH82:HOS3:7.32 | HOS3 | SH82 | Bangalore Rural | Bangalore | Hoskote | 7314 | 12.00 | Slab | 13.00 | routine |
| 2207 | BR:SH82:HOS3:17.095 | HOS3 | SH82 | Bangalore Rural | Bangalore | Hoskote | 17091 | 12.00 | Slab | 9.00 | routine |
| 2208 | BR:SH82:HOS3:19.85 | HOS3 | SH82 | Bangalore Rural | Bangalore | Hoskote | 19843 | 12.00 | Slab | 15.20 | routine |
| 2209 | BR:SH82:HOS3:21.665 | HOS3 | SH82 | Bangalore Rural | Bangalore | Hoskote | 21659 | 12.00 | Slab | 13.20 | routine |
| 2210 | BR:SH82:HOS3:22.295 | HOS3 | SH82 | Bangalore Rural | Bangalore | Hoskote | 22292 | 12.00 | Slab | 7.00 | routine |
| 2211 | BR:SH82:CMI1:25.374 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 25367 | 12.00 | Slab | 15.40 | routine |
| 2212 | BR:SH82:CMI1:25.819 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 25816 | 12.00 | Slab | 7.00 | routine |
| 2213 | BR:SH82:CMI1:26.854 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 26845 | 12.00 | Slab | 18.20 | routine |
| 2214 | BR:SH82:CMI1:28.379 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 28364 | 12.10 | Slab | 30.80 | routine |
| 2215 | BR:SH82:CMI1:31.274 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 31265 | 12.00 | Slab | 18.00 | routine |
| 2216 | BR:SH82:CMI1:32.269 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 32261 | 12.40 | Slab | 16.50 | routine |
| 2217 | BR:SH82:CMI1:33.474 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 33467 | 15.00 | Slab | 14.40 | routine |
| 2218 | BR:SH82:CMI1:34.284 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 34277 | 12.00 | Slab | 15.40 | routine |
| 2219 | BR:SH82:CMI1:40.484 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 40477 | 12.00 | Slab | 14.40 | routine |
| 2220 | BR:SH82:CMI1:43.284 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 43281 | 12.50 | pipe | 6.60 | routine |

Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl.No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2221 | BR:SH82:CMI1:50.064 | CMI1 | SH82 | Chikballapur | Chikballapur | Chintamani | 50052 | 8.50 | Slab | 24.00 | routine |
| 2222 | BR:SH82:SRI1:59.299 | SRI1 | SH82 | Kolar | Kolar | Srinivasapur | 59292 | 12.50 | pipe | 14.50 | routine |
| 2223 | BR:SH82:SRI1:63.629 | SRI1 | SH82 | Kolar | Kolar | Srinivasapur | 63624 | 8.50 | Slab | 11.80 | repair |
| 2224 | BR:SH82:SRI1:68.039 | SRI1 | SH82 | Kolar | Kolar | Srinivasapur | 68035 | 8.10 | Slab | 9.00 | repair |
| 2225 | BR:SH82:SRI1:70.609 | SRI1 | SH82 | Kolar | Kolar | Srinivasapur | 70606 | 11.90 | Slab | 6.80 | repair |
| 2226 | BR:SH82:SRI1:77.979 | SRI1 | SH82 | Kolar | Kolar | Srinivasapur | 77975 | 12.00 | Slab | 8.30 | repair |
| 2227 | BR:SH83:SAU210:6.295 | SAU210 | SH83 | Belgaum | Belgaum | Saundatti | 6281 | 8.00 | pipe | 29.50 | routine |
| 2228 | BR:SH83:RMG202:13.34 | RMG202 | SH83 | Belgaum | Belgaum | Ramdurg | 13335 | 8.00 | Slab | 10.00 | routine |
| 2229 | BR:SH83:RMG202:24.34 | RMG202 | SH83 | Belgaum | Belgaum | Ramdurg | 24324 | 8.00 | pipe | 32.00 | routine |
| 2230 | BR:SH83:RMG202:29.185 | RMG202 | SH83 | Belgaum | Belgaum | Ramdurg | 29176 | 8.00 | pipe | 19.50 | routine |
| 2231 | BR:SH83:RMG202:52.63 | RMG202 | SH83 | Belgaum | Belgaum | Ramdurg | 52621 | 8.00 | Slab | 18.00 | repair |
| 2232 | BR:SH83:RMG202:57.12 | RMG202 | SH83 | Belgaum | Belgaum | Ramdurg | 57117 | 12.00 | Slab | 7.00 | routine |
| 2233 | BR:SH83:RMG202:60.865 | RMG202 | SH83 | Belgaum | Belgaum | Ramdurg | 60862 | 10.00 | pipe | 6.50 | routine |
| 2234 | BR:SH83:NGD202:64.68 | NGD202 | SH83 | Gadag | Gadag | Nargund | 64660 | 12.00 | Slab | 40.00 | routine |
| 2235 | BR:SH83:NGD202:69.765 | NGD202 | SH83 | Gadag | Gadag | Nargund | 69755 | 12.00 | Slab | 20.00 | routine |
| 2236 | BR:SH83:NGD202:71.625 | NGD202 | SH83 | Gadag | Gadag | Nargund | 71615 | 12.00 | Slab | 20.00 | routine |
| 2237 | BR:SH83:RON77:80.605 | RON77 | SH83 | Gadag | Gadag | Ron | 80559 | 8.50 | Girder | 84.70 | repair |
| 2238 | BR:SH83:RON77:81 | RON77 | SH83 | Gadag | Gadag | Ron | 80989 | 7.50 | Pipe | 23.50 | repair |
| 2239 | BR:SH83:RON77:95.42 | RON77 | SH83 | Gadag | Gadag | Ron | 95381 | 8.50 | Slab | 98.00 | repair |
| 2240 | BR:SH83:RON77:108.485 | RON77 | SH83 | Gadag | Gadag | Ron | 108476 | 8.50 | Slab | 18.00 | repair |
| 2241 | BR:SH83:RON77:115.81 | RON77 | SH83 | Gadag | Gadag | Ron | 115806 | 10.00 | Pipe | 9.30 | repair |
| 2242 | BR:SH83:RON77:116.04 | RON77 | SH83 | Gadag | Gadag | Ron | 116035 | 10.00 | Pipe | 11.50 | repair |
| 2243 | BR:SH83:RON77:117.44 | RON77 | SH83 | Gadag | Gadag | Ron | 117430 | 10.00 | Pipe | 21.90 | repair |
| 2244 | BR:SH83:RON77:120.465 | RON77 | SH83 | Gadag | Gadag | Ron | 120461 | 8.50 | Slab | 8.00 | repair |
| 2245 | BR:SH83:RON77:123.425 | RON77 | SH83 | Gadag | Gadag | Ron | 123420 | 10.00 | Pipe | 10.00 | repair |
| 2246 | BR:SH84:SRA8:12.41 | SRA8 | SH84 | Tumkur | Madhugiri | Sira | 12388 | 12.00 | Slab | 45.00 | routine |
| 2247 | BR:SH84:SRA8:13.775 | SRA8 | SH84 | Tumkur | Madhugiri | Sira | 13755 | 8.50 | Girder | 40.00 | routine |
| 2248 | BR:SH84:GBB203:19.73 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 19724 | 12.00 | Slab | 12.00 | routine |
| 2249 | BR:SH84:GBB203:27.26 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 27255 | 12.00 | Slab | 10.00 | routine |
| 2250 | BR:SH84:GBB203:28.763 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 28755 | 8.00 | Slab | 16.00 | repair |
| 2251 | BR:SH84:GBB203:31.413 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 31409 | 8.00 | Slab | 8.00 | repair |
| 2252 | BR:SH84:GBB203:34.168 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 34165 | 10.00 | Slab | 6.00 | repair |
| 2253 | BR:SH84:GBB203:40.268 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 40265 | 10.00 | Slab | 6.00 | routine |
| 2254 | BR:SH84:GBB203:46.613 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 46532 | 8.00 | Pipe | 143.40 | repair |
| 2255 | BR:SH84:GBB203:61.077 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 61074 | 10.00 | pipe | 6.30 | routine |
| 2256 | BR:SH84:GBB203:76.182 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 76163 | 8.00 | pipe | 39.10 | routine |
| 2257 | BR:SH84:GBB203:77.757 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 77709 | 8.00 | pipe | 97.00 | routine |
| 2258 | BR:SH84:GBB203:78.144 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 78132 | 7.50 | pipe | 25.00 | routine |
| 2259 | BR:SH84:GBB203:81.339 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 81318 | 6.00 | Slab | 43.20 | routine |

## Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2260 | BR:SH84:KNL10:95.749 | KNL10 | SH84 | Tumkur | Tumkur | Kunigal | 95745 | 7.50 | pipe | 9.70 | routine |
| 2261 | BR:SH84:KNL10:103.679 | KNL10 | SH84 | Tumkur | Tumkur | Kunigal | 103672 | 12.00 | Girder | 15.00 | routine |
| 2262 | BR:SH84:KNL10:110.604 | KNL10 | SH84 | Tumkur | Tumkur | Kunigal | 110601 | 6.50 | Slab | 6.00 | routine |
| 2263 | BR:SH84:KNL10:110.889 | KNL10 | SH84 | Tumkur | Tumkur | Kunigal | 110845 | 8.50 | Girder | 83.60 | repair |
| 2264 | BR:SH84:KNL10:111.099 | KNL10 | SH84 | Tumkur | Tumkur | Kunigal | 111096 | 7.80 | Slab | 7.50 | routine |
| 2265 | BR:SH84:KNL10:115.859 | KNL10 | SH84 | Tumkur | Tumkur | Kunigal | 115852 | 8.00 | Slab | 14.00 | routine |
| 2266 | BR:SH84:KNL10:120.934 | KNL10 | SH84 | Tumkur | Tumkur | Kunigal | 120929 | 7.00 | Slab | 10.50 | routine |
| 2267 | BR:SH84:MDR29:130.163 | MDR29 | SH84 | Mandya | Mandya | Maddur | 130079 | 12.00 | Girder | 170.80 | routine |
| 2268 | BR:SH84:MDR29:130.478 | MDR29 | SH84 | Mandya | Mandya | Maddur | 130451 | 12.00 | Girder | 61.00 | routine |
| 2269 | BR:SH84:MND7:142.058 | MND7 | SH84 | Mandya | Mandya | Mandya | 142055 | 12.00 | Slab | 6.00 | routine |
| 2270 | BR:SH84:MND7:144.033 | MND7 | SH84 | Mandya | Mandya | Mandya | 144023 | 8.50 | Slab | 20.00 | routine |
| 2271 | BR:SH84:MND7:146.543 | MND7 | SH84 | Mandya | Mandya | Mandya | 146534 | 7.00 | Slab | 18.00 | routine |
| 2272 | BR:SH84:MND7:156.225 | MND7 | SH84 | Mandya | Mandya | Mandya | 156221 | 7.50 | Others | 8.00 | routine |
| 2273 | BR:SH84:MND7:158.22 | MND7 | SH84 | Mandya | Mandya | Mandya | 158217 | 12.00 | Others | 6.00 | routine |
| 2274 | BR:SH84:MND7:159.13 | MND7 | SH84 | Mandya | Mandya | Mandya | 159127 | 8.00 | Slab | 6.50 | routine |
| 2275 | BR:SH84:MND7:160.93 | MND7 | SH84 | Mandya | Mandya | Mandya | 160926 | 7.50 | Slab | 9.00 | routine |
| 2276 | BR:SH84:MND7:161.775 | MND7 | SH84 | Mandya | Mandya | Mandya | 161768 | 7.00 | Girder | 14.00 | routine |
| 2277 | BR:SH84:MND7:163.245 | MND7 | SH84 | Mandya | Mandya | Mandya | 163233 | 12.00 | Slab | 24.00 | routine |
| 2278 | BR:SH84:MND7:167.9 | MND7 | SH84 | Mandya | Mandya | Mandya | 167892 | 8.50 | pipe | 17.50 | repair |
| 2279 | BR:SH84:MND7:172.345 | MND7 | SH84 | Mandya | Mandya | Mandya | 172342 | 8.00 | Slab | 6.10 | routine |
| 2280 | BR:SH84:MND7:172.37 | MND7 | SH84 | Mandya | Mandya | Mandya | 172367 | 8.50 | Slab | 6.00 | routine |
| 2281 | BR:SH84:MND7:175.385 | MND7 | SH84 | Mandya | Mandya | Mandya | 175381 | 13.00 | Slab | 9.70 | routine |
| 2282 | BR:SH84:MLV202:185.18 | MLV202 | SH84 | Mandya | Mandya | Malavalli | 185173 | 7.00 | Others | 14.00 | repair |
| 2283 | BR:SH84:MLV202:190.265 | MLV202 | SH84 | Mandya | Mandya | Malavalli | 190261 | 8.80 | Slab | 8.00 | repair |
| 2284 | BR:SH84:TNP206:202.91 | TNP206 | SH84 | Mysore | Mysore | Tnarsipur | 202901 | 12.00 | Slab | 18.80 | routine |
| 2285 | BR:SH84:NJG63:215.618 | NJG63 | SH84 | Mysore | Mysore | Nanjangud | 215606 | 8.50 | Slab | 25.65 | routine |
| 2286 | BR:SH84:NJG63:220.528 | NJG63 | SH84 | Mysore | Mysore | Nanjangud | 220522 | 12.50 | pipe | 12.10 | routine |
| 2287 | BR:SH84:NJG63:223.422 | NJG63 | SH84 | Mysore | Mysore | Nanjangud | 223418 | 8.50 | Slab | 8.40 | routine |
| 2288 | BR:SH84:NJG63:227.092 | NJG63 | SH84 | Mysore | Mysore | Nanjangud | 227088 | 8.50 | Slab | 9.20 | routine |
| 2289 | BR:SH85:BNS4:24.76 | BNS4 | SH85 | Bangalore Urban | Bangalore | Bangalore South | 24757 | 9.00 | Slab | 6.00 | routine |
| 2290 | BR:SH85:BNS4:29.505 | BNS4 | SH85 | Bangalore Urban | Bangalore | Bangalore South | 29501 | 12.00 | Slab | 8.00 | routine |
| 2291 | BR:SH85:BNS4:31.4 | BNS4 | SH85 | Bangalore Urban | Bangalore | Bangalore South | 31395 | 12.00 | Slab | 11.00 | routine |
| 2292 | BR:SH85:BNS4:31.91 | BNS4 | SH85 | Bangalore Urban | Bangalore | Bangalore South | 31907 | 12.00 | Slab | 6.00 | routine |
| 2293 | BR:SH85:MGD202:34.375 | MGD202 | SH85 | Ramanagara | Ramanagara | Magadi | 34339 | 12.00 | Slab | 72.00 | routine |
| 2294 | BR:SH85:MGD202:41.54 | MGD202 | SH85 | Ramanagara | Ramanagara | Magadi | 41532 | 12.00 | Slab | 16.00 | routine |
| 2295 | BR:SH85:MGD202:43.27 | MGD202 | SH85 | Ramanagara | Ramanagara | Magadi | 43254 | 8.50 | Girder | 32.00 | routine |
| 2296 | BR:SH85:MGD202:45.405 | MGD202 | SH85 | Ramanagara | Ramanagara | Magadi | 45402 | 12.00 | Slab | 6.00 | routine |
| 2297 | BR:SH85:MGD202:57.49 | MGD202 | SH85 | Ramanagara | Ramanagara | Magadi | 57482 | 10.00 | pipe | 16.50 | routine |
| 2298 | BR:SH85:KNL3:71.205 | KNL3 | SH85 | Tumkur | Tumkur | Kunigal | 71194 | 8.00 | pipe | 23.50 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2299 | BR:SH85:KNL3:72.39 | KNL3 | SH85 | Tumkur | Tumkur | Kunigal | 72378 | 12.00 | Girder | 24.00 | routine |
| 2300 | BR:SH85:KNL3:73.225 | KNL3 | SH85 | Tumkur | Tumkur | Kunigal | 73221 | 8.50 | Slab | 9.50 | routine |
| 2301 | BR:SH85:KNL3:83.375 | KNL3 | SH85 | Tumkur | Tumkur | Kunigal | 83354 | 10.00 | Slab | 42.00 | routine |
| 2302 | BR:SH85:NGM209:127.215 | NGM209 | SH85 | Mandya | Mandya | Nagamangala | 127188 | 8.50 | Slab | 55.00 | routine |
| 2303 | BR:SH85:KRP251:144.645 | KRP251 | SH85 | Mandya | Mandya | Krishnarajpet | 144624 | 8.50 | Slab | 42.00 | routine |
| 2304 | BR:SH85:KRP251:145.89 | KRP251 | SH85 | Mandya | Mandya | Krishnarajpet | 145886 | 8.50 | Slab | 8.50 | routine |
| 2305 | BR:SH85:KRP251:153.78 | KRP251 | SH85 | Mandya | Mandya | Krishnarajpet | 153757 | 8.50 | Slab | 46.40 | repair |
| 2306 | BR:SH85:KRP251:157.485 | KRP251 | SH85 | Mandya | Mandya | Krishnarajpet | 157461 | 16.00 | Slab | 48.00 | routine |
| 2307 | BR:SH85:KRP251:165.285 | KRP251 | SH85 | Mandya | Mandya | Krishnarajpet | 165282 | 12.00 | Slab | 17.50 | routine |
| 2308 | BR:SH85:KRP251:166.245 | KRP251 | SH85 | Mandya | Mandya | Krishnarajpet | 166242 | 12.00 | Slab | 7.50 | routine |
| 2309 | BR:SH85:KRP251:166.74 | KRP251 | SH85 | Mandya | Mandya | Krishnarajpet | 166629 | 6.50 | Arch | 231.00 | repair |
| 2310 | BR:SH85:KRP251:168.93 | KRP251 | SH85 | Mandya | Mandya | Krishnarajpet | 168924 | 8.50 | Slab | 12.00 | routine |
| 2311 | BR:SH85:KRN224:175.89 | KRN224 | SH85 | Mysore | Hunsur | Krishnarajanagar | 175886 | 12.00 | Slab | 9.00 | repair |
| 2312 | BR:SH85:KRN224:180.945 | KRN224 | SH85 | Mysore | Hunsur | Krishnarajanagar | 180940 | 8.50 | Slab | 10.00 | routine |
| 2313 | BR:SH85:KRN224:186.685 | KRN224 | SH85 | Mysore | Hunsur | Krishnarajanagar | 186674 | 8.50 | Slab | 23.00 | routine |
| 2314 | BR:SH85:KRN224:195.055 | KRN224 | SH85 | Mysore | Hunsur | Krishnarajanagar | 195052 | 8.50 | Slab | 7.00 | repair |
| 2315 | BR:SH85:ARK201:197.14 | ARK201 | SH85 | Hassan | Hassan_Special | Arkalgud | 197126 | 12.00 | Slab | 28.50 | routine |
| 2316 | BR:SH85:ARK201:198.625 | ARK201 | SH85 | Hassan | Hassan_Special | Arkalgud | 198620 | 12.00 | Slab | 10.00 | repair |
| 2317 | BR:SH85:ARK201:205.165 | ARK201 | SH85 | Hassan | Hassan_Special | Arkalgud | 205159 | 12.00 | Slab | 12.00 | routine |
| 2318 | BR:SH85:ARK201:209.305 | ARK201 | SH85 | Hassan | Hassan_Special | Arkalgud | 209301 | 10.00 | Slab | 8.00 | routine |
| 2319 | BR:SH85:ARK201:212.905 | ARK201 | SH85 | Hassan | Hassan_Special | Arkalgud | 212897 | 8.50 | Slab | 16.00 | repair |
| 2320 | BR:SH85:ARK201:215.95 | ARK201 | SH85 | Hassan | Hassan_Special | Arkalgud | 215937 | 12.00 | Slab | 27.00 | routine |
| 2321 | BR:SH85:SVP80:234.265 | SVP80 | SH85 | Kodagu | Kodagu | Somvarpet | 234259 | 8.50 | Slab | 12.00 | routine |
| 2322 | BR:SH85:SVP80:236.68 | SVP80 | SH85 | Kodagu | Kodagu | Somvarpet | 236674 | 8.50 | Slab | 12.00 | routine |
| 2323 | BR:SH85:SLP236:277.73 | SLP236 | SH85 | Hassan | Hassan_Special | Sakleshpur | 277727 | 9.00 | Slab | 7.00 | repair |
| 2324 | BR:SH85:SLP236:290.225 | SLP236 | SH85 | Hassan | Hassan_Special | Sakleshpur | 290221 | 8.50 | Slab | 9.50 | repair |
| 2325 | BR:SH85:SLP236:290.33 | SLP236 | SH85 | Hassan | Hassan_Special | Sakleshpur | 290312 | 8.50 | Girder | 36.00 | repair |
| 2326 | BR:SH85:SLY201:305.56 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 305535 | 8.00 | Girder | 50.00 | repair |
| 2327 | BR:SH85:SLY201:310.21 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 310173 | 8.00 | Girder | 75.00 | repair |
| 2328 | BR:SH85:SLY201:314.23 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 314221 | 8.00 | Slab | 18.00 | repair |
| 2329 | BR:SH85:SLY201:319.15 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 319135 | 8.00 | Girder | 30.00 | repair |
| 2330 | BR:SH85:SLY201:320.32 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 320317 | 8.00 | Slab | 6.00 | repair |
| 2331 | BR:SH85:SLY201:320.92 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 320912 | 8.00 | Girder | 16.00 | repair |
| 2332 | BR:SH85:SLY201:321.16 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 321156 | 8.00 | Slab | 9.00 | repair |
| 2333 | BR:SH85:SLY201:326.53 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 326523 | 8.00 | Girder | 15.00 | repair |
| 2334 | BR:SH85:SLY201:329.89 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 329885 | 8.00 | Slab | 11.00 | repair |
| 2335 | BR:SH85:SLY201:332.875 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 332860 | 8.00 | Girder | 30.00 | repair |
| 2336 | BR:SH85:SLY201:334.99 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 334987 | 12.00 | Slab | 6.00 | routine |
| 2337 | BR:SH85:SLY201:338.17 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 338166 | 12.00 | Slab | 8.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sr. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len. (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2338 | BR:SH85:SLY201:342.235 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 342232 | 8.00 | Slab | 7.50 | repair |
| 2339 | BR:SH85:SLY201:343.285 | SLY201 | SH85 | Dakshina Kannada | Mangalore | Sulya | 343278 | 8.00 | Girder | 15.00 | repair |
| 2340 | BR:SH86:KRN225:11.06 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 11056 | 8.50 | Slab | 8.40 | routine |
| 2341 | BR:SH86:KRN225:12.135 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 12125 | 12.00 | Slab | 20.00 | routine |
| 2342 | BR:SH86:KRN225:12.77 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 12764 | 8.50 | Slab | 12.00 | routine |
| 2343 | BR:SH86:KRN225:17.39 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 17383 | 8.50 | Slab | 15.00 | repair |
| 2344 | BR:SH86:KRN225:23.506 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 23503 | 8.50 | Slab | 6.10 | routine |
| 2345 | BR:SH86:KRN225:25.370 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 25364 | 8.70 | Slab | 12.60 | routine |
| 2346 | BR:SH86:KRN225:31.021 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 31015 | 8.00 | Slab | 12.60 | routine |
| 2347 | BR:SH86:KRN225:33.426 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 33423 | 12.50 | pipe | 7.90 | repair |
| 2348 | BR:SH86:KRN225:35.381 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 35377 | 8.50 | Slab | 8.00 | routine |
| 2349 | BR:SH86:KRN225:35.826 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 35822 | 8.50 | Slab | 8.00 | routine |
| 2350 | BR:SH86:KRN225:36.061 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 36055 | 12.50 | pipe | 13.50 | routine |
| 2351 | BR:SH86:HNS234:43.931 | HNS234 | SH86 | Mysore | Hunsur | Hunsur | 43923 | 12.50 | pipe | 16.30 | routine |
| 2352 | BR:SH86:HNS234:58.47 | HNS234 | SH86 | Mysore | Hunsur | Hunsur | 58462 | 8.90 | Slab | 16.80 | repair |
| 2353 | BR:SH86:HNS234:62.66 | HNS234 | SH86 | Mysore | Hunsur | Hunsur | 62656 | 13.00 | Slab | 8.00 | routine |
| 2354 | BR:SH86:HDK203:72.865 | HDK203 | SH86 | Mysore | Hunsur | Heggadadevanakote | 72862 | 8.50 | Slab | 6.50 | repair |
| 2355 | BR:SH86:HDK203:73.555 | HDK203 | SH86 | Mysore | Hunsur | Heggadadevanakote | 73548 | 12.00 | Slab | 15.00 | routine |
| 2356 | BR:SH86:HDK203:80.76 | HDK203 | SH86 | Mysore | Hunsur | Heggadadevanakote | 80751 | 12.00 | Slab | 18.60 | routine |
| 2357 | BR:SH86:HDK203:90.269 | HDK203 | SH86 | Mysore | Hunsur | Heggadadevanakote | 90185 | 6.50 | Girder | 168.00 | repair |
| 2358 | BR:SH86:HDK203:93.779 | HDK203 | SH86 | Mysore | Hunsur | Heggadadevanakote | 93772 | 9.00 | Girder | 15.00 | repair |
| 2359 | BR:SH86:HDK203:100.944 | HDK203 | SH86 | Mysore | Hunsur | Heggadadevanakote | 100914 | 6.00 | Girder | 52.50 | repair |
| 2360 | BR:SH86:NJG62:108.194 | NJG62 | SH86 | Mysore | Mysore | Nanjangud | 108182 | 9.00 | Slab | 24.00 | routine |
| 2361 | BR:SH86:NJG62:116.45 | NJG62 | SH86 | Mysore | Mysore | Nanjangud | 116442 | 12.00 | Slab | 16.50 | routine |
| 2362 | BR:SH86:GNP201:120.19 | GNP201 | SH86 | Chamrajnagar | Chamrajnagar | Gundlupet | 120182 | 13.00 | Slab | 17.60 | routine |
| 2363 | BR:SH86:GNP201:124.995 | GNP201 | SH86 | Chamrajnagar | Chamrajnagar | Gundlupet | 124992 | 12.00 | Slab | 6.00 | routine |
| 2364 | BR:SH86:GNP201:143.955 | GNP201 | SH86 | Chamrajnagar | Chamrajnagar | Gundlupet | 143950 | 10.00 | Others | 11.00 | repair |
| 2365 | BR:SH86:GNP201:146.47 | GNP201 | SH86 | Chamrajnagar | Chamrajnagar | Gundlupet | 146460 | 12.00 | Slab | 20.00 | routine |
| 2366 | BR:SH87:ANK2:25.16 | ANK2 | SH87 | Bangalore Urban | Bangalore | Anekal | 25157 | 12.30 | Slab | 6.50 | routine |
| 2367 | BR:SH87:ANK2:35.75 | ANK2 | SH87 | Bangalore Urban | Bangalore | Anekal | 35744 | 12.50 | pipe | 13.50 | repair |
| 2368 | BR:SH89:SVP82:24.87 | SVP82 | SH89 | Kodagu | Kodagu | Somvarpet | 24815 | 10.00 | Steel Structure | 110.00 | routine |
| 2369 | BR:SH89:VJP72:50.703 | VJP72 | SH89 | Kodagu | Kodagu | Virajpet | 50692 | 8.50 | Girder | 22.60 | routine |
| 2370 | BR:SH89:VJP72:57.893 | VJP72 | SH89 | Kodagu | Kodagu | Virajpet | 57889 | 8.00 | Slab | 9.50 | repair |
| 2371 | BR:SH89:VJP72:68.228 | VJP72 | SH89 | Kodagu | Kodagu | Virajpet | 68223 | 10.00 | Slab | 10.00 | repair |
| 2372 | BR:SH89:VJP72:73.303 | VJP72 | SH89 | Kodagu | Kodagu | Virajpet | 73295 | 9.00 | Slab | 16.50 | routine |
| 2373 | BR:SH89:VJP72:77.578 | VJP72 | SH89 | Kodagu | Kodagu | Virajpet | 77563 | 12.00 | Girder | 30.00 | routine |
| 2374 | BR:SH89:VJP72:84.058 | VJP72 | SH89 | Kodagu | Kodagu | Virajpet | 84055 | 8.50 | pipe | 7.50 | repair |
| 2375 | BR:SH9:BNG3:4.195 | BNG3 | SH9 | Bangalore Urban | Bangalore | Bangalore-North | 4188 | 23.30 | Slab | 14.00 | routine |
| 2376 | BR:SH9:BNG3:12.41 | BNG3 | SH9 | Bangalore Urban | Bangalore | Bangalore-North | 12407 | 12.00 | pipe | 6.50 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposition |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2377 | BR:SH9:BNG3:16.52 | BNG3 | SH9 | Bangalore Urban | Bangalore | Bangalore-North | 16514 | 11.50 | Slab | 12.40 | routine |
| 2378 | BR:SH9:BNG3:16.695 | BNG3 | SH9 | Bangalore Urban | Bangalore | Bangalore-North | 16687 | 12.00 | pipe | 16.50 | repair |
| 2379 | BR:SH9:DOD2:24.72 | DOD2 | SH9 | Bangalore Rural | Bangalore. | Dod Ballapura | 24717 | 11.50 | Slab | 6.00 | repair |
| 2380 | BR:SH9:DOD2:29.203 | DOD2 | SH9 | Bangalore Rural | Bangalore | Dod Ballapura | 29197 | 8.50 | pipe | 13.50 | repair |
| 2381 | BR:SH9:GBR1:46.018 | GBR1 | SH9 | Chikballapur | Chikballapur | Gauribidanur | 46014 | 10.00 | pipe | 9.70 | repair |
| 2382 | BR:SH9:GBR1:48.638 | GBR1 | SH9 | Chikballapur | Chikballapur | Gauribidanur | 48634 | 11.50 | pipe | 8.00 | repair |
| 2383 | BR:SH9:GBR1:50.593 | GBR1 | SH9 | Chikballapur | Chikballapur | Gauribidanur | 50590 | 9.10 | Slab | 6.00 | repair |
| 2384 | BR:SH9:GBR1:53.935 | GBR1 | SH9 | Chikballapur | Chikballapur | Gauribidanur | 53932 | 10.00 | pipe | 6.70 | repair |
| 2385 | BR:SH9:GBR1:65.035 | GBR1 | SH9 | Chikballapur | Chikballapur | Gauribidanur | 64976 | 8.50 | Girder | 119.70 | repair |
| 2386 | BR:SH9:GBR1:66.98 | GBR1 | SH9 | Chikballapur | Chikballapur | Gauribidanur | 66961 | 8.00 | Girder | 39.90 | repair |
| 2387 | BR:SH9:GBR1:72.92 | GBR1 | SH9 | Chikballapur | Chikballapur | Gauribidanur | 72911 | 10.00 | pipe | 19.90 | repair |
| 2388 | BR:SH9:GBR1:75.345 | GBR1 | SH9 | Chikballapur | Chikballapur | Gauribidanur | 75339 | 10.00 | Slab | 12.00 | repair |
| 2389 | BR:SH90:HNS2:7.625 | HNS2 | SH90 | Mysore | Hunsur | Hunsur | 7611 | 12.00 | Slab | 28.50 | routine |
| 2390 | BR:SH90:PRP201:18.45 | PRP201 | SH90 | Mysore | Hunsur | Piriyapatna | 18446 | 8.50 | Slab | 8.90 | repair |
| 2391 | BR:SH90:VJP73:22.55 | VJP73 | SH90 | Kodagu | Kodagu | Virajpet | 22541 | 12.00 | Slab | 18.00 | routine |
| 2392 | BR:SH90:VJP73:25.626 | VJP73 | SH90 | Kodagu | Kodagu | Virajpet | 25622 | 8.50 | Slab | 9.40 | repair |
| 2393 | BR:SH90:VJP73:31.171 | VJP73 | SH90 | Kodagu | Kodagu | Virajpet | 31167 | 8.50 | Slab | 9.80 | repair |
| 2394 | BR:SH90:VJP73:36.916 | VJP73 | SH90 | Kodagu | Kodagu | Virajpet | 36907 | 12.00 | Slab | 18.40 | routine |
| 2395 | BR:SH90:VJP73:44.096 | VJP73 | SH90 | Kodagu | Kodagu | Virajpet | 44083 | 8.50 | Slab | 26.10 | repair |
| 2396 | BR:SH90:VJP73:50.061 | VJP73 | SH90 | Kodagu | Kodagu | Virajpet | 50056 | 8.50 | Slab | 10.90 | repair |
| 2397 | BR:SH90:VJP73:50.226 | VJP73 | SH90 | Kodagu | Kodagu | Virajpet | 50223 | 8.50 | Slab | 6.50 | repair |
| 2398 | BR:SH90:MDK201:67.043 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 67040 | 8.00 | Slab | 7.00 | repair |
| 2399 | BR:SH90:MDK201:69.413 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 69401 | 8.50 | Slab | 24.00 | repair |
| 2400 | BR:SH90:MDK201:76.183 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 76180 | 8.00 | Slab | 6.50 | repair |
| 2401 | BR:SH90:MDK201:78.148 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 78144 | 8.00 | Slab | 8.00 | repair |
| 2402 | BR:SH90:MDK201:79.558 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 79552 | 8.50 | Slab | 12.00 | repair |
| 2403 | BR:SH90:MDK201:80.303 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 80287 | 8.50 | Slab | 32.00 | repair |
| 2404 | BR:SH90:MDK201:86.722 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 86717 | 8.00 | Slab | 10.00 | repair |
| 2405 | BR:SH90:MDK201:96.457 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 96452 | 8.50 | Slab | 10.80 | routine |
| 2406 | BR:SH90:MDK201:99.192 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 99187 | 12.00 | Slab | 10.50 | routine |
| 2407 | BR:SH90:MDK201:104.922 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 104917 | 8.00 | Slab | 10.80 | repair |
| 2408 | BR:SH90:MDK201:112.682 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 112677 | 8.50 | Slab | 10.80 | routine |
| 2409 | BR:SH91:ARK202:2.565 | ARK202 | SH91 | Hassan | Hassan_Special | Arkalgud | 2562 | 12.00 | Slab | 7.00 | routine |
| 2410 | BR:SH91:ARK202:4.86 | ARK202 | SH91 | Hassan | Hassan_Special | Arkalgud | 4844 | 12.00 | Slab | 33.00 | routine |
| 2411 | BR:SH91:SVP83:12.3 | SVP83 | SH91 | Kodagu | Kodagu | Somvarpet | 12296 | 12.00 | Slab | 9.00 | routine |
| 2412 | BR:SH91:SVP83:14.93 | SVP83 | SH91 | Kodagu | Kodagu | Somvarpet | 14926 | 12.00 | Slab | 8.00 | routine |
| 2413 | BR:SH91:SVP83:16.82 | SVP83 | SH91 | Kodagu | Kodagu | Somvarpet | 16775 | 8.50 | Girder | 90.00 | routine |
| 2414 | BR:SH91:SVP83:31.41 | SVP83 | SH91 | Kodagu | Kodagu | Somvarpet | 31405 | 9.00 | Slab | 10.00 | repair |
| 2415 | BR:SH91:SVP83:33.5 | SVP83 | SH91 | Kodagu | Kodagu | Somvarpet | 33493 | 8.00 | Girder | 15.40 | repair |

Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2416 | BR:SH91:SVP83:38.73 | SVP83 | SH91 | Kodagu | Kodagu | Somvarpet | 38725 | 8.50 | pipe | 11.50 | repair |
| 2417 | BR:SH91:VJP74:63.929 | VJP74 | SH91 | Kodagu | Kodagu | Virajpet | 63924 | 10.00 | Slab | 11.00 | routine |
| 2418 | BR:SH91:VJP74:72.905 | VJP74 | SH91 | Kodagu | Kodagu | Virajpet | 72902 | 8.50 | Slab | 6.50 | routine |
| 2419 | BR:SH91:VJP74:84.355 | VJP74 | SH91 | Kodagu | Kodagu | Virajpet | 84352 | 8.50 | Slab | 6.50 | routine |
| 2420 | BR:SH91:VJP74:85.45 | VJP74 | SH91 | Kodagu | Kodagu | Virajpet | 85446 | 9.00 | Slab | 9.00 | routine |
| 2421 | BR:SH91:VJP74:86.055 | VJP74 | SH91 | Kodagu | Kodagu | Virajpet | 86051 | 8.00 | Slab | 8.00 | repair |
| 2422 | BR:SH91:VJP74:89.825 | VJP74 | SH91 | Kodagu | Kodagu | Virajpet | 89813 | 9.00 | Slab | 24.00 | repair |
| 2423 | BR:SH91:VJP74:90.59 | VJP74 | SH91 | Kodagu | Kodagu | Virajpet | 90585 | 9.00 | Slab | 11.00 | repair |
| 2424 | BR:SH92:KNK3:3.075 | KNK3 | SH92 | Ramanagara | Ramanagara | Kanakapura | 3065 | 8.00 | pipe | 21.10 | repair |
| 2425 | BR:SH92:KNK3:12.795 | KNK3 | SH92 | Ramanagara | Ramanagara | Kanakapura | 12790 | 8.00 | Slab | 10.50 | repair |
| 2426 | BR:SH92:KNK3:22.865 | KNK3 | SH92 | Ramanagara | Ramanagara | Kanakapura | 22852 | 8.15 | Slab | 27.20 | repair |
| 2427 | BR:SH93:KNP2:18.451 | KNP2 | SH93 | Belgaum | Belgaum | Khanapur | 18436 | 12.00 | Girder | 31.00 | routine |
| 2428 | BR:SH93:KNP2:23.926 | KNP2 | SH93 | Belgaum | Belgaum | Khanapur | 23919 | 12.00 | Girder | 15.00 | routine |
| 2429 | BR:SH93:KNP2:26.542 | KNP2 | SH93 | Belgaum | Belgaum | Khanapur | 26530 | 12.00 | Girder | 24.50 | routine |
| 2430 | BR:SH93:DRD4:38.592 | DRD4 | SH93 | Dharwad | Dharwad | Dharwad | 38577 | 8.00 | Arch | 31.50 | repair |
| 2431 | BR:SH93:HLY1:42.737 | HLY1 | SH93 | Uttara Kannada | Sirsi | Haliyal | 42715 | 8.50 | Girder | 45.00 | routine |
| 2432 | BR:SH93:HLY1:43.862 | HLY1 | SH93 | Uttara Kannada | Sirsi | Haliyal | 43859 | 12.00 | Slab | 6.50 | routine |
| 2433 | BR:SH93:HLY1:46.207 | HLY1 | SH93 | Uttara Kannada | Sirsi | Haliyal | 46201 | 12.00 | Girder | 12.00 | routine |
| 2434 | BR:SH93:HLY1:58.037 | HLY1 | SH93 | Uttara Kannada | Sirsi | Haliyal | 58033 | 8.50 | Slab | 8.00 | routine |
| 2435 | BR:SH93:HLY1:68.777 | HLY1 | SH93 | Uttara Kannada | Sirsi | Haliyal | 68768 | 8.50 | Girder | 18.00 | routine |
| 2436 | BR:SH93:HLY1:81.692 | HLY1 | SH93 | Uttara Kannada | Sirsi | Haliyal | 81661 | 7.00 | Girder | 62.50 | repair |
| 2437 | BR:SH93:YLP2:102.914 | YLP2 | SH93 | Uttara Kannada | Sirsi | Yellapur | 102909 | 8.50 | Slab | 11.00 | routine |
| 2438 | BR:SH93:YLP2:123.034 | YLP2 | SH93 | Uttara Kannada | Sirsi | Yellapur | 123024 | 8.00 | Slab | 21.00 | repair |
| 2439 | BR:SH93:YLP2:126.409 | YLP2 | SH93 | Uttara Kannada | Sirsi | Yellapur | 126404 | 8.50 | Slab | 11.00 | repair |
| 2440 | BR:SH93:YLP2:130.769 | YLP2 | SH93 | Uttara Kannada | Sirsi | Yellapur | 130742 | 7.00 | Girder | 55.00 | repair |
| 2441 | BR:SH93:SRS1:141.193 | SRS1 | SH93 | Uttara Kannada | Sirsi | Sirsi | 141188 | 8.00 | Girder | 11.00 | repair |
| 2442 | BR:SH93:SDP2:162.143 | SDP2 | SH93 | Uttara Kannada | Sirsi | Siddapur | 162139 | 8.00 | Slab | 8.00 | repair |
| 2443 | BR:SH93:SDP2:165.558 | SDP2 | SH93 | Uttara Kannada | Sirsi | Siddapur | 165542 | 8.00 | Slab | 32.00 | repair |
| 2444 | BR:SH93:SDP2:170.263 | SDP2 | SH93 | Uttara Kannada | Sirsi | Siddapur | 170256 | 8.50 | Slab | 14.00 | repair |
| 2445 | BR:SH93:SDP2:172.777 | SDP2 | SH93 | Uttara Kannada | Sirsi | Siddapur | 172764 | 8.00 | Slab | 27.00 | repair |
| 2446 | BR:SH93:SDP2:182.157 | SDP2 | SH93 | Uttara Kannada | Sirsi | Siddapur | 182152 | 8.00 | Slab | 11.00 | repair |
| 2447 | BR:SH93:SDP2:192.647 | SDP2 | SH93 | Uttara Kannada | Sirsi | Siddapur | 192638 | 8.50 | Girder | 19.00 | routine |
| 2448 | BR:SH93:SDP2:193.377 | SDP2 | SH93 | Uttara Kannada | Sirsi | Siddapur | 193361 | 8.50 | Girder | 32.00 | repair |
| 2449 | BR:SH94:GBR201:22.696 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 22677 | 8.50 | pipe | 39.50 | routine |
| 2450 | BR:SH94:GBR201:25.346 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 25340 | 8.50 | pipe | 13.10 | repair |
| 2451 | BR:SH94:GBR201:29.561 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 29549 | 8.50 | pipe | 25.00 | routine |
| 2452 | BR:SH94:GBR201:30.231 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 30225 | 9.80 | Slab | 13.80 | repair |
| 2453 | BR:SH94:GBR201:31.966 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 31962 | 12.00 | Slab | 9.20 | routine |
| 2454 | BR:SH94:GBR201:43.136 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 43122 | 7.50 | pipe | 29.50 | repair |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2455 | BR:SH94:GBR201:46.721 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 46718 | 8.30 | Slab | 7.00 | repair |
| 2456 | BR:SH94:GBR201:54.697 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 54652 | 12.00 | Girder | 90.00 | routine |
| 2457 | BR:SH94:GBR201:56.972 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 56933 | 8.00 | Pipe | 83.40 | repair |
| 2458 | BR:SH94:GBR201:58.577 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 58574 | 9.50 | pipe | 7.90 | repair |
| 2459 | BR:SH94:GBR201:65.612 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 65609 | 10.00 | pipe | 6.60 | repair |
| 2460 | BR:SH94:GBR201:71.517 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 71495 | 8.00 | pipe | 45.00 | repair |
| 2461 | BR:SH94:GBR201:72.272 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 72259 | 10.00 | pipe | 26.70 | repair |
| 2462 | BR:SH94:TMK202:108.415 | TMK202 | SH94 | Tumkur | Tumkur | Tumkur | 108412 | 12.00 | Slab | 7.00 | routine |
| 2463 | BR:SH94:TMK202:109.765 | TMK202 | SH94 | Tumkur | Tumkur | Tumkur | 109759 | 9.00 | Slab | 12.00 | repair |
| 2464 | BR:SH94:TMK202:123.95 | TMK202 | SH94 | Tumkur | Tumkur | Tumkur | 123946 | 10.00 | pipe | 8.50 | repair |
| 2465 | BR:SH94:TMK202:140.21 | TMK202 | SH94 | Tumkur | Tumkur | Tumkur | 140206 | 12.00 | Slab | 8.00 | routine |
| 2466 | BR:SH94:TMK202:141.56 | TMK202 | SH94 | Tumkur | Tumkur | Tumkur | 141557 | 8.00 | Slab | 6.00 | repair |
| 2467 | BR:SH94:MGD201:148.165 | MGD201 | SH94 | Ramanagara | Ramanagara | Magadi | 148160 | 8.00 | Slab | 10.00 | routine |
| 2468 | BR:SH94:MGD201:154.055 | MGD201 | SH94 | Ramanagara | Ramanagara | Magadi | 154051 | 7.50 | Slab | 8.00 | repair |
| 2469 | BR:SH94:MGD201:163.925 | MGD201 | SH94 | Ramanagara | Ramanagara | Magadi | 163921 | 12.50 | pipe | 9.70 | repair |
| 2470 | BR:SH94:MGD201:180.615 | MGD201 | SH94 | Ramanagara | Ramanagara | Magadi | 180611 | 12.00 | Slab | 8.00 | repair |
| 2471 | BR:SH94:RMN8:202.594 | RMN8 | SH94 | Ramanagara | Ramanagara | Ramnagaram | 202576 | 8.00 | Slab | 36.00 | repair |
| 2472 | BR:SH94:MLV8:241.94 | MLV8 | SH94 | Mandya | Mandya | Malavalli | 241925 | 8.00 | Slab | 30.00 | repair |
| 2473 | BR:SH94:MLV8:242.215 | MLV8 | SH94 | Mandya | Mandya | Malavalli | 242209 | 8.00 | Slab | 12.00 | repair |
| 2474 | BR:SH94:MLV8:245.545 | MLV8 | SH94 | Mandya | Mandya | Malavalli | 245541 | 8.00 | Slab | 8.00 | repair |
| 2475 | BR:SH95:HOS5:7.125 | HOS5 | SH95 | Bangalore Rural | Bangalore | Hoskote | 7118 | 14.00 | Slab | 14.00 | routine |
| 2476 | BR:SH95:MLR201:16.175 | MLR201 | SH95 | Kolar | Kolar | Malur | 16171 | 10.00 | Pipe | 9.70 | routine |
| 2477 | BR:SH95:MLR201:24.385 | MLR201 | SH95 | Kolar | Kolar | Malur | 24380 | 8.50 | Slab | 11.20 | routine |
| 2478 | BR:SH95:BGT200:48.255 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 48239 | 12.00 | Slab | 33.60 | routine |
| 2479 | BR:SH95:BGT200:53.087 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 53084 | 9.20 | Slab | 6.40 | repair |
| 2480 | BR:SH95:BGT200:60.607 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 60603 | 15.00 | Slab | 9.60 | repair |
| 2481 | BR:SH95:BGT200:63.087 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 63082 | 8.50 | Slab | 11.00 | routine |
| 2482 | BR:SH95:BGT200:65.122 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 65119 | 8.50 | Slab | 7.00 | routine |
| 2483 | BR:SH95:BGT200:66.897 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 66867 | 8.50 | Girder | 60.00 | routine |
| 2484 | BR:SH95:BGT200:74.682 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 74679 | 12.10 | Slab | 6.80 | routine |
| 2485 | BR:SH95:BGT200:74.792 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 74789 | 8.50 | Pipe | 6.60 | routine |
| 2486 | BR:SH96:DVN4:2.665 | DVN4 | SH96 | Bangalore Rural | Bangalore | Devanahalli | 2660 | 10.00 | Slab | 11.50 | repair |
| 2487 | BR:SH96:SGA1:13.51 | SGA1 | SH96 | Chikballapur | Chikballapur | Sidlaghatta | 13497 | 8.30 | Slab | 27.60 | repair |
| 2488 | BR:SH96:SGA1:18.025 | SGA1 | SH96 | Chikballapur | Chikballapur | Sidlaghatta | 18018 | 12.00 | Slab | 15.40 | routine |
| 2489 | BR:SH96:KOL201:31.544 | KOL201 | SH96 | Kolar | Kolar | Kolar | 31540 | 12.00 | Slab | 8.00 | routine |
| 2490 | BR:SH96:KOL201:31.794 | KOL201 | SH96 | Kolar | Kolar | Kolar | 31788 | 12.00 | Slab | 12.60 | routine |
| 2491 | BR:SH96:KOL201:38.014 | KOL201 | SH96 | Kolar | Kolar | Kolar | 38010 | 12.00 | Slab | 8.80 | routine |
| 2492 | BR:SH96:KOL201:41.394 | KOL201 | SH96 | Kolar | Kolar | Kolar | 41391 | 8.20 | Slab | 6.40 | routine |
| 2493 | BR:SH96:KOL201:45.644 | KOL201 | SH96 | Kolar | Kolar | Kolar | 45635 | 12.00 | Slab | 18.00 | routine |

**Details of Bridges Proposed for Repairs /Rehabilitation on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super.Str | Bridge Len (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 2494 | BR:SH96:KOL201:47.834 | KOL201 | SH96 | Kolar | Kolar | Kolar | 47831 | 12.00 | Slab | 7.20 | routine |
| 2495 | BR:SH96:KOL201:51.995 | KOL201 | SH96 | Kolar | Kolar | Kolar | 51977 | 12.00 | Slab | 36.00 | routine |
| 2496 | BR:SH96:KOL201:57.33 | KOL201 | SH96 | Kolar | Kolar | Kolar | 57327 | 12.00 | Slab | 7.50 | routine |
| 2497 | BR:SH96:KOL201:68.555 | KOL201 | SH96 | Kolar | Kolar | Kolar | 68552 | 8.00 | Slab | 7.00 | repair |
| 2498 | BR:SH96:BGT201:81.656 | BGT201 | SH96 | Kolar | Kolar | Bangarpet | 81653 | 12.00 | Slab | 7.60 | routine |
| 2499 | BR:SH96:BGT201:81.991 | BGT201 | SH96 | Kolar | Kolar | Bangarpet | 81988 | 12.00 | Slab | 6.80 | routine |
| 2500 | BR:SH96:BGT201:89.191 | BGT201 | SH96 | Kolar | Kolar | Bangarpet | 89188 | 12.00 | Slab | 7.00 | routine |
| 2501 | BR:SH96:BGT201:89.726 | BGT201 | SH96 | Kolar | Kolar | Bangarpet | 89723 | 11.80 | Slab | 7.50 | routine |
| 2502 | BR:SH98:CKD205:7.03 | CKD205 | SH98 | Belgaum | Chikkodi | Chikkodi | 7026 | 10.00 | Slab | 9.00 | repair |
| 2503 | BR:SH98:CKD205:22.78 | CKD205 | SH98 | Belgaum | Chikkodi | Chikkodi | 22735 | 12.00 | Girder | 90.00 | routine |
| 2504 | BR:SH98:CKD205:34.16 | CKD205 | SH98 | Belgaum | Chikkodi | Chikkodi | 34157 | 12.00 | Slab | 6.50 | repair |
| 2505 | BR:SH99:SRI201:3.755 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 3751 | 8.00 | Pipe | 8.80 | repair |
| 2506 | BR:SH99:SRI201:5.995 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 5992 | 10.00 | Pipe | 6.50 | repair |
| 2507 | BR:SH99:SRI201:7.46 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 7451 | 8.00 | Pipe | 19.20 | repair |
| 2508 | BR:SH99:SRI201:31.941 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 31938 | 8.50 | Slab | 7.60 | routine |
| 2509 | BR:SH99:SRI201:36.476 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 36456 | 10.00 | Pipe | 41.20 | repair |
| 2510 | BR:SH99:KOL202:52.831 | KOL202 | SH99 | Kolar | Kolar | Kolar | 52828 | 12.00 | Slab | 6.40 | routine |
| 2511 | BR:SH99:KOL202:60.547 | KOL202 | SH99 | Kolar | Kolar | Kolar | 60536 | 8.00 | Pipe | 22.00 | repair |
| 2512 | BR:SH99:KOL202:62.497 | KOL202 | SH99 | Kolar | Kolar | Kolar | 62493 | 10.00 | Slab | 9.60 | routine |
| 2513 | BR:SH99:MLR202:81.007 | MLR202 | SH99 | Kolar | Kolar | Malur | 81004 | 12.00 | Slab | 6.60 | routine |
| 2514 | BR:SH99:MLR202:86.867 | MLR202 | SH99 | Kolar | Kolar | Malur | 86864 | 12.10 | Slab | 6.60 | routine |
| 2515 | BR:SH99:MLR202:88.512 | MLR202 | SH99 | Kolar | Kolar | Malur | 88509 | 12.30 | Slab | 6.60 | routine |
| 2516 | BR:SH99:MLR202:89.207 | MLR202 | SH99 | Kolar | Kolar | Malur | 89204 | 12.20 | Slab | 7.40 | routine |
| 2517 | BR:SH99:MLR202:95.717 | MLR202 | SH99 | Kolar | Kolar | Malur | 95714 | 8.50 | Slab | 6.80 | routine |

Engineer in Chief,
Planning Road Asset & Management Center
4th Floor, PWD Annex Building, K.R.Circle,
Bangalore – 560 001.

# Details of Bridges Proposed for Widening on CRN Network

## Details of Bridges Proposed for Widening on CRN Network

| Sl No | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | BR:MDR_AFZ2:AFZ2:11.264 | AFZ2 | MDR_AFZ2 | Gulbarga | Gulbarga | Afzalpur | 11258 | 7.50 | pipe | 13.50 | Repair + Widen |
| 2 | BR:MDR_AFZ31:AFZ31:17.899 | AFZ31 | MDR_AFZ31 | Gulbarga | Gulbarga | Afzalpur | 17895 | 7.50 | pipe | 9.30 | Repair + Widen |
| 3 | BR:MDR_ALD8:ALD8:0.977 | ALD8 | MDR_ALD8 | Gulbarga | Gulbarga | Aland | 968 | 7.50 | pipe | 19.00 | Repair + Widen |
| 4 | BR:MDR_ALD8:ALD8:18.01 | ALD8 | MDR_ALD8 | Gulbarga | Gulbarga | Aland | 18006 | 7.50 | pipe | 9.40 | Repair + Widen |
| 5 | BR:MDR_BGM14:BGM14:12.029 | BGM14 | MDR_BGM14 | Belgaum | Belgaum | Belgaum | 12021 | 7.50 | pipe | 17.10 | Repair + Widen |
| 6 | BR:MDR_BID5:BID5:3.047 | BID5 | MDR_BID5 | Bidar | Bidar | Bidar | 3043 | 7.50 | pipe | 8.50 | Repair + Widen |
| 7 | BR:MDR_BID5:BID5:4.495 | BID5 | MDR_BID5 | Bidar | Bidar | Bidar | 4485 | 7.50 | pipe | 20.50 | Repair + Widen |
| 8 | BR:MDR_BID8:BID8:2.187 | BID8 | MDR_BID8 | Bidar | Bidar | Bidar | 2183 | 7.50 | pipe | 8.50 | Repair + Widen |
| 9 | BR:MDR_BID8:BID8:4.805 | BID8 | MDR_BID8 | Bidar | Bidar | Bidar | 4797 | 7.50 | pipe | 16.30 | Repair + Widen |
| 10 | BR:MDR_BID8:BID8:6.073 | BID8 | MDR_BID8 | Bidar | Bidar | Bidar | 6069 | 7.50 | pipe | 9.70 | Repair + Widen |
| 11 | BR:MDR_BJP9:BJP9:4.087 | BJP9 | MDR_BJP9 | Bijapur | Bijapur | Bijapur | 4082 | 7.50 | pipe | 11.40 | Repair + Widen |
| 12 | BR:MDR_CKD17:CKD17:10.78 | CKD17 | MDR_CKD17 | Belgaum | Chikkodi | Chikkodi | 10756 | 5.50 | Slab | 48.00 | Repair + Widen |
| 13 | BR:MDR_CNH10:CNH10:15.967 | CNH10 | MDR_CNH10 | Tumkur | Tumkur | Chiknayakanahalli | 15964 | 7.50 | pipe | 6.30 | Repair + Widen |
| 14 | BR:MDR_GUL13:GUL13:11.551 | GUL13 | MDR_GUL13 | Gulbarga | Gulbarga | Gulbarga | 11545 | 7.50 | pipe | 13.50 | Repair + Widen |
| 15 | BR:MDR_GUL13:GUL13:13.309 | GUL13 | MDR_GUL13 | Gulbarga | Gulbarga | Gulbarga | 13304 | 7.50 | pipe | 10.70 | Repair + Widen |
| 16 | BR:MDR_HUM17:HUM17:2.734 | HUM17 | MDR_HUM17 | Bidar | Bidar | Homnabad | 2729 | 7.50 | pipe | 10.00 | Repair + Widen |
| 17 | BR:MDR_HUM17:HUM17:7.093 | HUM17 | MDR_HUM17 | Bidar | Bidar | Homnabad | 7078 | 7.50 | pipe | 30.30 | Repair + Widen |
| 18 | BR:MDR_HUM19:HUM19:1.068 | HUM19 | MDR_HUM19 | Bidar | Bidar | Homnabad | 1062 | 6.00 | pipe | 13.50 | Repair + Widen |
| 19 | BR:MDR_HUM19:HUM19:3.018 | HUM19 | MDR_HUM19 | Bidar | Bidar | Homnabad | 3014 | 7.50 | pipe | 9.30 | Repair + Widen |
| 20 | BR:MDR_HUM19:HUM19:3.846 | HUM19 | MDR_HUM19 | Bidar | Bidar | Homnabad | 3841 | 7.50 | pipe | 10.70 | Repair + Widen |
| 21 | BR:MDR_KOP206:KOP206:6.43 | KOP206 | MDR_KOP206 | Koppal | Koppal | Koppal | 6425 | 7.00 | Slab | 10.40 | Repair + Widen |
| 22 | BR:MDR_KOP8:KOP8:12.377 | KOP8 | MDR_KOP8 | Koppal | Koppal | Koppal | 12369 | 7.50 | pipe | 16.30 | Repair + Widen |
| 23 | BR:MDR_KOP8:KOP8:20.811 | KOP8 | MDR_KOP8 | Koppal | Koppal | Koppal | 20803 | 7.50 | pipe | 17.90 | Repair + Widen |
| 24 | BR:MDR_MDG101:MDG101:10.496 | MDG101 | MDR_MDG101 | Tumkur | Madhugiri | Madhugiri | 10492 | 7.50 | Slab | 9.00 | Repair + Widen |
| 25 | BR:MDR_MDR16:MDR16:11.785 | MDR16 | MDR_MDR16 | Mandya | Mandya | Maddur | 11781 | 7.00 | Slab | 9.00 | Repair + Widen |
| 26 | BR:MDR_MLV5:MLV5:28.665 | MLV5 | MDR_MLV5 | Mandya | Mandya | Malavalli | 28643 | 5.00 | Slab | 45.00 | Repair + Widen |
| 27 | BR:MDR_MND2:MND2:22.255 | MND2 | MDR_MND2 | Mandya | Mandya | Mandya | 22251 | 7.50 | pipe | 8.00 | Repair + Widen |
| 28 | BR:MDR_RAI6:RAI6:16.385 | RAI6 | MDR_RAI6 | Raichur | Raichur | Raichur | 16373 | 7.50 | pipe | 24.70 | Repair + Widen |
| 29 | BR:SH1:HSN201:161.072 | HSN201 | SH1 | Shimoga | Shimoga | Hosanagara | 161067 | 7.00 | Slab | 10.00 | Repair + Widen |
| 30 | BR:SH1:BAI201_A:420.438 | BAI201_A | SH1 | Belgaum | Belgaum | Bailhongal | 420434 | 7.50 | Slab | 8.00 | Repair + Widen |
| 31 | BR:SH1:SAU205:425.368 | SAU205 | SH1 | Belgaum | Belgaum | Saundatti | 425363 | 7.50 | pipe | 10.00 | Repair + Widen |
| 32 | BR:SH1:HUK204:491.871 | HUK204 | SH1 | Belgaum | Chikkodi | Hukkeri | 491868 | 7.50 | Slab | 6.50 | Repair + Widen |
| 33 | BR:SH1:HUK204:493.336 | HUK204 | SH1 | Belgaum | Chikkodi | Hukkeri | 493331 | 7.50 | pipe | 11.50 | Repair + Widen |
| 34 | BR:SH1:HUK204:496.916 | HUK204 | SH1 | Belgaum | Chikkodi | Hukkeri | 496913 | 7.50 | pipe | 6.50 | Repair + Widen |
| 35 | BR:SH102:ARS201:26.08 | ARS201 | SH102 | Hassan | Hassan | Arsikere | 26070 | 6.50 | Slab | 20.00 | Repair + Widen |
| 36 | BR:SH103:GOK15:2.815 | GOK15 | SH103 | Belgaum | Chikkodi | Gokak | 2809 | 7.50 | pipe | 13.50 | Repair + Widen |

**Details of Bridges Proposed for Widening on CRN Network**

| Sl. No | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 37 | BR:SH103:GOK15:11.01 | GOK15 | SH103 | Belgaum | Chikkodi | Gokak | 11000 | 7.50 | pipe | 21.10 | Repair + Widen |
| 38 | BR:SH103:SAU203:40.226 | SAU203 | SH103 | Belgaum | Belgaum | Saundatti | 40222 | 7.50 | Slab | 8.50 | Repair + Widen |
| 39 | BR:SH103:SAU203:75.559 | SAU203 | SH103 | Belgaum | Belgaum | Saundatti | 75547 | 7.50 | pipe | 24.70 | Repair + Widen |
| 40 | BR:SH11:BAK2_B:46.89 | BAK2_B | SH11 | Bidar | Bidar | Basavakalyan | 46887 | 7.50 | pipe | 7.90 | Repair + Widen |
| 41 | BR:SH11:BAK2_B:52.175 | BAK2_B | SH11 | Bidar | Bidar | Basavakalyan | 52170 | 7.50 | pipe | 11.50 | Repair + Widen |
| 42 | BR:SH11:BAK2_B:55.245 | BAK2_B | SH11 | Bidar | Bidar | Basavakalyan | 55240 | 7.50 | pipe | 11.50 | Repair + Widen |
| 43 | BR:SH115:BRV64:15.645 | BRV64 | SH115 | Shimoga | Shimoga_special | Bhadravathi | 15638 | 6.50 | Girder | 14.00 | Repair + Widen |
| 44 | BR:SH115:HNN14:21.745 | HNN14 | SH115 | Davanagere | Davanagere | Honnali | 21741 | 7.00 | Slab | 9.00 | Repair + Widen |
| 45 | BR:SH115:HNN14:23.11 | HNN14 | SH115 | Davanagere | Davanagere | Honnali | 23106 | 7.00 | Slab | 9.00 | Repair + Widen |
| 46 | BR:SH12:ATN2:67.715 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 67707 | 7.50 | pipe | 17.50 | Repair + Widen |
| 47 | BR:SH12:ATN2:92.11 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 92105 | 7.50 | Slab | 10.00 | Repair + Widen |
| 48 | BR:SH12:ATN2:93.905 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 93900 | 7.50 | pipe | 11.20 | Repair + Widen |
| 49 | BR:SH12:ATN2:117.772 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 117768 | 7.50 | pipe | 9.90 | Repair + Widen |
| 50 | BR:SH122:AUR20:22.075 | AUR20 | SH122 | Bidar | Bidar | Aurad | 22071 | 7.50 | pipe | 8.50 | Repair + Widen |
| 51 | BR:SH122:AUR20:24.055 | AUR20 | SH122 | Bidar | Bidar | Aurad | 24051 | 7.50 | pipe | 8.50 | Repair + Widen |
| 52 | BR:SH122:BID51:63.26 | BID51 | SH122 | Bidar | Bidar | Bidar | 63253 | 7.50 | pipe | 14.50 | Repair + Widen |
| 53 | BR:SH122:BID51:81.165 | BID51 | SH122 | Bidar | Bidar | Bidar | 81161 | 7.50 | pipe | 8.00 | Repair + Widen |
| 54 | BR:SH122:BID51:82.135 | BID51 | SH122 | Bidar | Bidar | Bidar | 82130 | 7.50 | pipe | 10.00 | Repair + Widen |
| 55 | BR:SH122:BID51:96.605 | BID51 | SH122 | Bidar | Bidar | Bidar | 96597 | 7.50 | pipe | 16.00 | Repair + Widen |
| 56 | BR:SH122:HUM203:110.26 | HUM203 | SH122 | Bidar | Bidar | Homnabad | 110251 | 7.50 | pipe | 19.10 | Repair + Widen |
| 57 | BR:SH122:HUM203:116.205 | HUM203 | SH122 | Bidar | Bidar | Homnabad | 116197 | 7.50 | pipe | 17.70 | Repair + Widen |
| 58 | BR:SH124:ALD201_A:44.492 | ALD201_A | SH124 | Gulbarga | Gulbarga | Aland | 44487 | 7.50 | pipe | 11.50 | Repair + Widen |
| 59 | BR:SH124:ALD201_A:58.832 | ALD201_A | SH124 | Gulbarga | Gulbarga | Aland | 58826 | 7.50 | pipe | 13.50 | Repair + Widen |
| 60 | BR:SH124:ALD201_A:65.487 | ALD201_A | SH124 | Gulbarga | Gulbarga | Aland | 65482 | 7.50 | pipe | 10.00 | Repair + Widen |
| 61 | BR:SH124:ALD201_A:65.947 | ALD201_A | SH124 | Gulbarga | Gulbarga | Aland | 65942 | 7.50 | pipe | 11.50 | Repair + Widen |
| 62 | BR:SH124:BBV8:272.46 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 272457 | 7.50 | pipe | 7.90 | Repair + Widen |
| 63 | BR:SH124:BBV8:280.02 | BBV8 | SH124 | Bijapur | Bijapur | Basavanabagevadi | 280017 | 7.50 | pipe | 7.90 | Repair + Widen |
| 64 | BR:SH124:BLG204:312.081 | BLG204 | SH124 | Bagalkot | Bagalkot | Bilgi | 312071 | 7.50 | Slab | 20.00 | Repair + Widen |
| 65 | BR:SH125:GUL201:0.505 | GUL201 | SH125 | Gulbarga | Gulbarga | Gulbarga | 502 | 7.50 | Slab | 7.50 | Repair + Widen |
| 66 | BR:SH125:CTR75:51.89 | CTR75 | SH125 | Gulbarga | Sedam | Chitapur | 51880 | 7.50 | pipe | 21.60 | Repair + Widen |
| 67 | BR:SH125:CTR75:53.82 | CTR75 | SH125 | Gulbarga | Sedam | Chitapur | 53814 | 7.50 | Slab | 12.00 | Repair + Widen |
| 68 | BR:SH125:CTR75:56.93 | CTR75 | SH125 | Gulbarga | Sedam | Chitapur | 56920 | 7.50 | Slab | 21.00 | Repair + Widen |
| 69 | BR:SH125:CNL202:83.625 | CNL202 | SH125 | Gulbarga | Sedam | Chincholi | 83620 | 7.50 | pipe | 10.70 | Repair + Widen |
| 70 | BR:SH125:CNL202:85.635 | CNL202 | SH125 | Gulbarga | Sedam | Chincholi | 85630 | 7.50 | pipe | 10.70 | Repair + Widen |
| 71 | BR:SH125:CNL202:86.595 | CNL202 | SH125 | Gulbarga | Sedam | Chincholi | 86588 | 7.50 | pipe | 14.90 | Repair + Widen |
| 72 | BR:SH125:GUL202:97.545 | GUL202 | SH125 | Gulbarga | Gulbarga | Gulbarga | 97539 | 7.50 | pipe | 12.50 | Repair + Widen |

Details of Bridges Proposed for Widening on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluka | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 73 | BR:SH127:SED202:2.265 | SED202 | SH127 | Gulbarga | Sedam | Sedam | 2257 | 7.50 | pipe | 16.30 | Repair + Widen |
| 74 | BR:SH127:SED202:3.025 | SED202 | SH127 | Gulbarga | Sedam | Sedam | 3015 | 7.50 | pipe | 20.50 | Repair + Widen |
| 75 | BR:SH127:YDG204:66.591 | YDG204 | SH127 | Yadgir | Yadgir | Yadgir | 66582 | 7.00 | Slab | 18.00 | Repair + Widen |
| 76 | BR:SH127:DEV203:135.117 | DEV203 | SH127 | Raichur | Raichur | Devadurga | 135110 | 7.00 | Girder | 14.00 | Repair + Widen |
| 77 | BR:SH127:DEV203:141.757 | DEV203 | SH127 | Raichur | Raichur | Devadurga | 141747 | 7.50 | pipe | 20.50 | Repair + Widen |
| 78 | BR:SH128:BER10:220.87 | BER10 | SH128 | Bellary | Bellary | Bellary | 220867 | 7.50 | Slab | 6.50 | Repair + Widen |
| 79 | BR:SH129:KOP13:150.04 | KOP13 | SH129 | Koppal | Koppal | Koppal | 150013 | 7.50 | pipe | 55.50 | Repair + Widen |
| 80 | BR:SH129:KOP13:159.72 | KOP13 | SH129 | Koppal | Koppal | Koppal | 159707 | 7.50 | pipe | 27.50 | Repair + Widen |
| 81 | BR:SH129:MUI210:186.09 | MUI210 | SH129 | Gadag | Gadag | Mundargi | 186084 | 7.50 | Pipe | 13.50 | Repair + Widen |
| 82 | BR:SH130:GAN95:56.235 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 56227 | 5.00 | pipe | 16.50 | Repair + Widen |
| 83 | BR:SH130:KOP9:108.905 | KOP9 | SH130 | Koppal | Koppal | Koppal | 108888 | 7.00 | Girder | 34.00 | Repair + Widen |
| 84 | BR:SH131:HSP202:1.185 | HSP202 | SH131 | Bellary | Bellary | Hospet | 1181 | 7.50 | Slab | 9.00 | Repair + Widen |
| 85 | BR:SH131:HSP202:1.455 | HSP202 | SH131 | Bellary | Bellary | Hospet | 1452 | 7.00 | Slab | 6.60 | Repair + Widen |
| 86 | BR:SH131:SNR35:48.415 | SNR35 | SH131 | Bellary | Bellary | Sandur | 48412 | 7.50 | Pipe | 7.00 | Repair + Widen |
| 87 | BR:SH131:SNR35:50.11 | SNR35 | SH131 | Bellary | Bellary | Sandur | 50107 | 7.50 | Pipe | 7.00 | Repair + Widen |
| 88 | BR:SH131:SNR35:61.84 | SNR35 | SH131 | Bellary | Bellary | Sandur | 61837 | 7.50 | Pipe | 6.30 | Repair + Widen |
| 89 | BR:SH131:MOL201:95.21 | MOL201 | SH131 | Chitradurga | Chitradurga | Molakalmuru | 95202 | 7.50 | Pipe | 16.50 | Repair + Widen |
| 90 | BR:SH131:MOL201:95.71 | MOL201 | SH131 | Chitradurga | Chitradurga | Molakalmuru | 95701 | 7.50 | Pipe | 18.20 | Repair + Widen |
| 91 | BR:SH131:KDL44:98.05 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 98043 | 7.50 | Pipe | 14.50 | Repair + Widen |
| 92 | BR:SH131:KDL44:102.525 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 102522 | 7.50 | Pipe | 7.00 | Repair + Widen |
| 93 | BR:SH131:KDL44:123.18 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 123170 | 7.50 | Pipe | 21.90 | Repair + Widen |
| 94 | BR:SH131:KDL44:128.365 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 128356 | 7.50 | Pipe | 19.90 | Repair + Widen |
| 95 | BR:SH131:KDL44:146.08 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 146077 | 7.50 | Pipe | 7.00 | Repair + Widen |
| 96 | BR:SH131:KDL44:152.52 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 152516 | 7.50 | Pipe | 8.50 | Repair + Widen |
| 97 | BR:SH131:KDL44:152.97 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 152967 | 7.50 | Pipe | 7.00 | Repair + Widen |
| 98 | BR:SH131:KDL44:159.4 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 159386 | 7.50 | Pipe | 29.50 | Repair + Widen |
| 99 | BR:SH131:KDL44:163.89 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 163886 | 7.50 | Pipe | 8.50 | Repair + Widen |
| 100 | BR:SH131:KDL44:178.765 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 178751 | 7.50 | Pipe | 29.50 | Repair + Widen |
| 101 | BR:SH131:HGB61:188.95 | HGB61 | SH131 | Bellary | Hadagalli | Hagaribommanahalli | 188947 | 7.50 | Pipe | 6.70 | Repair + Widen |
| 102 | BR:SH133:BDM206:8.425 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 8422 | 7.50 | pipe | 7.90 | Repair + Widen |
| 103 | BR:SH133:BDM206:10.91 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 10907 | 7.50 | pipe | 7.90 | Repair + Widen |
| 104 | BR:SH133:BDM206:13.98 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 13974 | 7.50 | pipe | 12.50 | Repair + Widen |
| 105 | BR:SH133:BDM206:15.835 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 15830 | 7.50 | pipe | 10.00 | Repair + Widen |
| 106 | BR:SH133:BDM206:62.279 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 62262 | 7.50 | pipe | 34.50 | Repair + Widen |
| 107 | BR:SH133:HUD209:68.608 | HUD209 | SH133 | Bagalkot | Bagalkot | Hungund | 68600 | 7.50 | pipe | 17.00 | Repair + Widen |
| 108 | BR:SH133:HUD209:91.298 | HUD209 | SH133 | Bagalkot | Bagalkot | Hungund | 91294 | 7.50 | pipe | 9.50 | Repair + Widen |

**Details of Bridges Proposed for Widening on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 109 | BR:SH133:HUD209:92.473 | HUD209 | SH133 | Bagalkot | Bagalkot | Hungund | 92468 | 7.50 | pipe | 10.70 | Repair + Widen |
| 110 | BR:SH133:HUD209:93.383 | HUD209 | SH133 | Bagalkot | Bagalkot | Hungund | 93379 | 7.50 | pipe | 9.30 | Repair + Widen |
| 111 | BR:SH133:HUD209:94.983 | HUD209 | SH133 | Bagalkot | Bagalkot | Hungund | 94974 | 7.50 | pipe | 19.50 | Repair + Widen |
| 112 | BR:SH134:BDM203:25.79 | BDM203 | SH134 | Bagalkot | Bagalkot | Badami | 25786 | 7.00 | Slab | 8.00 | Repair + Widen |
| 113 | BR:SH134:BDM203:26.435 | BDM203 | SH134 | Bagalkot | Bagalkot | Badami | 26431 | 7.00 | Slab | 9.00 | Repair + Widen |
| 114 | BR:SH134:RMG205:27.765 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 27750 | 7.00 | Slab | 30.00 | Repair + Widen |
| 115 | BR:SH134:RMG205:29.715 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 29712 | 7.00 | Slab | 7.00 | Repair + Widen |
| 116 | BR:SH134:RMG205:30.535 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 30528 | 7.00 | Slab | 14.00 | Repair + Widen |
| 117 | BR:SH134:RMG205:31.84 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 31832 | 7.00 | Slab | 16.00 | Repair + Widen |
| 118 | BR:SH134:RMG205:34.749 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 34741 | 7.50 | pipe | 16.30 | Repair + Widen |
| 119 | BR:SH134:RMG205:37.961 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 37957 | 7.50 | pipe | 9.50 | Repair + Widen |
| 120 | BR:SH134:RMG205:50.028 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 50020 | 7.50 | pipe | 17.50 | Repair + Widen |
| 121 | BR:SH134:RMG205:52.978 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 52972 | 7.50 | pipe | 13.50 | Repair + Widen |
| 122 | BR:SH134:RMG205:59.398 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 59393 | 7.50 | pipe | 10.00 | Repair + Widen |
| 123 | BR:SH134:RMG205:62.933 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 62924 | 7.50 | pipe | 19.90 | Repair + Widen |
| 124 | BR:SH134:RMG205:69.024 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 69018 | 7.50 | Slab | 12.00 | Repair + Widen |
| 125 | BR:SH134:RMG205:71.389 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 71383 | 7.00 | Slab | 12.00 | Repair + Widen |
| 126 | BR:SH134:RMG205:76.539 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 76532 | 7.50 | pipe | 14.90 | Repair + Widen |
| 127 | BR:SH134:GOK17:88.974 | GOK17 | SH134 | Belgaum | Chikkodi | Gokak | 88964 | 12.50 | pipe | 21.90 | Repair + Widen |
| 128 | BR:SH134:GOK17:92.769 | GOK17 | SH134 | Belgaum | Chikkodi | Gokak | 92765 | 7.50 | pipe | 8.60 | Repair + Widen |
| 129 | BR:SH134:GOK17:108.979 | GOK17 | SH134 | Belgaum | Chikkodi | Gokak | 108969 | 7.50 | pipe | 20.50 | Repair + Widen |
| 130 | BR:SH135:BGL201:36.187 | BGL201 | SH135 | Bagalkot | Bagalkot | Bagalkot | 36184 | 7.50 | pipe | 7.00 | Repair + Widen |
| 131 | BR:SH135:BGL201:65.479 | BGL201 | SH135 | Bagalkot | Bagalkot | Bagalkot | 65473 | 7.50 | Slab | 12.00 | Repair + Widen |
| 132 | BR:SH136:RON78:1.015 | RON78 | SH136 | Gadag | Gadag | Ron | 1009 | 7.50 | Pipe | 13.00 | Repair + Widen |
| 133 | BR:SH136:GDG203:79.514 | GDG203 | SH136 | Gadag | Gadag | Gadag | 79508 | 6.50 | Slab | 13.00 | Repair + Widen |
| 134 | BR:SH136:MUI211:162.361 | MUI211 | SH136 | Gadag | Gadag | Mundargi | 162356 | 7.50 | Pipe | 10.70 | Repair + Widen |
| 135 | BR:SH136:MUI211:168.074 | MUI211 | SH136 | Gadag | Gadag | Mundargi | 168069 | 7.50 | Pipe | 10.70 | Repair + Widen |
| 136 | BR:SH136:HVR219:217.931 | HVR219 | SH136 | Haveri | Haveri | Haveri | 217928 | 7.50 | Slab | 7.00 | Repair + Widen |
| 137 | BR:SH137:SRS93:162.45 | SRS93 | SH137 | Uttara Kannada | Sirsi | Sirsi | 162443 | 7.50 | Slab | 15.00 | Repair + Widen |
| 138 | BR:SH139:SAU212:2.885 | SAU212 | SH139 | Belgaum | Belgaum | Saundatti | 2877 | 7.50 | pipe | 17.70 | Repair + Widen |
| 139 | BR:SH139:SAU212:3.575 | SAU212 | SH139 | Belgaum | Belgaum | Saundatti | 3572 | 7.50 | pipe | 6.50 | Repair + Widen |
| 140 | BR:SH139:RMG204:42.12 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 42117 | 7.50 | pipe | 7.90 | Repair + Widen |
| 141 | BR:SH139:RMG204:44.335 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 44331 | 7.50 | pipe | 9.30 | Repair + Widen |
| 142 | BR:SH139:RMG204:45.63 | RMG204 | SH139 | Belgaum | Belgaum | Ramdurg | 45624 | 7.50 | pipe | 12.10 | Repair + Widen |
| 143 | BR:SH139:MDL203:67.18 | MDL203 | SH139 | Bagalkot | Bagalkot | Mudhol | 67177 | 7.50 | pipe | 6.50 | Repair + Widen |
| 144 | BR:SH14:RMG3:0.54 | RMG3 | SH14 | Belgaum | Belgaum | Ramdurg | 532 | 6.50 | Slab | 16.00 | Repair + Widen |

## Details of Bridges Proposed for Widening on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 145 | BR:SH14:HUD3_A:73.952 | HUD3_A | SH14 | Bagalkot | Bagalkot | Hungund | 73949 | 7.50 | pipe | 7.00 | Repair + Widen |
| 146 | BR:SH14:HUD3_B:91.192 | HUD3_B | SH14 | Bagalkot | Bagalkot | Hungund | 91187 | 7.50 | pipe | 10.70 | Repair + Widen |
| 147 | BR:SH14:HUD3_B:92.972 | HUD3_B | SH14 | Bagalkot | Bagalkot | Hungund | 92965 | 7.50 | pipe | 14.50 | Repair + Widen |
| 148 | BR:SH14:MAN201:239.409 | MAN201 | SH14 | Raichur | Raichur | Manvi | 239399 | 7.50 | pipe | 20.50 | Repair + Widen |
| 149 | BR:SH149:CTR202_A:67.77 | CTR202_A | SH149 | Gulbarga | Sedam | Chitapur | 67765 | 5.00 | pipe | 10.70 | Repair + Widen |
| 150 | BR:SH149:GUL30:89.785 | GUL30 | SH149 | Gulbarga | Gulbarga | Gulbarga | 89778 | 7.00 | pipe | 15.60 | Repair + Widen |
| 151 | BR:SH149:CNL3:201.1 | CNL3 | SH149 | Gulbarga | Sedam | Chincholi | 201095 | 7.50 | pipe | 10.00 | Repair + Widen |
| 152 | BR:SH15:CNL1:106.914 | CNL1 | SH15 | Gulbarga | Sedam | Chincholi | 106895 | 7.50 | Slab | 39.00 | Repair + Widen |
| 153 | BR:SH15:SED2:146.283 | SED2 | SH15 | Gulbarga | Sedam | Sedam | 146273 | 7.50 | pipe | 20.50 | Repair + Widen |
| 154 | BR:SH16:SND2:14.48 | SND2 | SH16 | Bijapur | Bijapur | Sindgi | 14466 | 7.50 | pipe | 29.50 | Repair + Widen |
| 155 | BR:SH18:GOK202:37.325 | GOK202 | SH18 | Belgaum | Chikkodi | Gokak | 37319 | 6.50 | Arch | 12.00 | Repair + Widen |
| 156 | BR:SH18:GOK202:37.47 | GOK202 | SH18 | Belgaum | Chikkodi | Gokak | 37452 | 6.50 | Arch | 36.00 | Repair + Widen |
| 157 | BR:SH2:HVR2:65.53 | HVR2 | SH2 | Haveri | Haveri | Haveri | 65523 | 6.50 | Slab | 15.00 | Repair + Widen |
| 158 | BR:SH2:HVR2:74.08 | HVR2 | SH2 | Haveri | Haveri | Haveri | 74076 | 7.50 | Slab | 8.00 | Repair + Widen |
| 159 | BR:SH20:HUD2:133.162 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 133150 | 7.50 | Slab | 24.00 | Repair + Widen |
| 160 | BR:SH20:HUD2:136.752 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 136740 | 7.50 | Slab | 24.00 | Repair + Widen |
| 161 | BR:SH20:HUD2:137.372 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 137351 | 7.50 | Slab | 42.00 | Repair + Widen |
| 162 | BR:SH20:HUD2:143.377 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 143370 | 7.50 | Slab | 14.00 | Repair + Widen |
| 163 | BR:SH20:HUD2:146.641 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 146629 | 7.50 | Slab | 24.00 | Repair + Widen |
| 164 | BR:SH20:HUD2:149.981 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 149974 | 7.50 | Slab | 15.60 | Repair + Widen |
| 165 | BR:SH20:HUD2:150.291 | HUD2 | SH20 | Bagalkot | Bagalkot | Hungund | 150281 | 7.50 | Slab | 21.00 | Repair + Widen |
| 166 | BR:SH21:BLR4:10.485 | BLR4 | SH21 | Hassan | Hassan | Belur | 10480 | 7.00 | Slab | 11.20 | Repair + Widen |
| 167 | BR:SH23:MUI208:210.178 | MUI208 | SH23 | Gadag | Gadag | Mundargi | 210150 | 7.50 | Slab | 56.00 | Repair + Widen |
| 168 | BR:SH23:SRT202:240.903 | SRT202 | SH23 | Gadag | Gadag | Shirahatti | 240900 | 7.50 | Pipe | 7.50 | Repair + Widen |
| 169 | BR:SH23:SRT202:251.798 | SRT202 | SH23 | Gadag | Gadag | Shirahatti | 251782 | 7.50 | Slab | 32.00 | Repair + Widen |
| 170 | BR:SH24:HRY3:112.108 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 112103 | 6.00 | Slab | 10.50 | Repair + Widen |
| 171 | BR:SH24:HRY3:127.523 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 127518 | 6.00 | Slab | 10.40 | Repair + Widen |
| 172 | BR:SH25:HRR3:107.229 | HRR3 | SH25 | Davanagere | Davanagere | Harihar | 107198 | 6.50 | Girder | 63.00 | Repair + Widen |
| 173 | BR:SH25:HNN1:167.501 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 167497 | 7.50 | Girder | 9.00 | Repair + Widen |
| 174 | BR:SH25:HNN1:168.456 | HNN1 | SH25 | Davanagere | Davanagere | Honnali | 168451 | 7.50 | Girder | 10.00 | Repair + Widen |
| 175 | BR:SH27:CHK202:215.345 | CHK202 | SH27 | Chikmagalur | Chikmagalur | Chikmagalur | 215342 | 7.50 | pipe | 7.00 | Repair + Widen |
| 176 | BR:SH27:KDP206:371.525 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 371520 | 6.60 | Slab | 11.50 | Repair + Widen |
| 177 | BR:SH27:KDP206:371.625 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 371598 | 6.50 | Steel Structure | 54.00 | Repair + Widen |
| 178 | BR:SH27:KDP206:387.25 | KDP206 | SH27 | Udupi | Udupi | Kundapura | 387235 | 6.50 | Steel Structure | 30.00 | Repair + Widen |
| 179 | BR:SH28:DRD5:72.73 | DRD5 | SH28 | Dharwad | Dharwad | Dharwad | 72727 | 7.00 | Slab | 7.50 | Repair + Widen |
| 180 | BR:SH28:HBL4_A:93.63 | HBL4_A | SH28 | Dharwad | Dharwad | Hubli | 93626 | 7.50 | Pipe | 9.30 | Repair + Widen |

**Details of Bridges Proposed for Widening on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width in | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 181 | BR:SH28:HBL4_A:94.055 | HBL4_A | SH28 | Dharwad | Dharwad | Hubli | 94050 | 7.50 | Pipe | 10.70 | Repair + Widen |
| 182 | BR:SH28:HBL4_A:98.69 | HBL4_A | SH28 | Dharwad | Dharwad | Hubli | 98683 | 7.50 | Pipe | 14.90 | Repair + Widen |
| 183 | BR:SH29:HSP5:87.106 | HSP5 | SH29 | Bellary | Bellary | Hospet | 87096 | 6.00 | Steel Structure | 20.00 | Repair + Widen |
| 184 | BR:SH29:BER4:110.85 | BER4 | SH29 | Bellary | Bellary | Bellary | 110836 | 7.00 | Girder | 28.00 | Repair + Widen |
| 185 | BR:SH30:RON69_B:139.754 | RON69_B | SH30 | Gadag | Gadag | Ron | 139746 | 7.50 | Pipe | 17.50 | Repair + Widen |
| 186 | BR:SH30:SAU202:185.291 | SAU202 | SH30 | Belgaum | Belgaum | Saundatti | 185287 | 7.50 | pipe | 8.50 | Repair + Widen |
| 187 | BR:SH30:SAU202:189.341 | SAU202 | SH30 | Belgaum | Belgaum | Saundatti | 189338 | 7.50 | pipe | 7.30 | Repair + Widen |
| 188 | BR:SH30:SAU202:216.342 | SAU202 | SH30 | Belgaum | Belgaum | Saundatti | 216339 | 7.50 | pipe | 7.90 | Repair + Widen |
| 189 | BR:SH30:SAU202:216.547 | SAU202 | SH30 | Belgaum | Belgaum | Saundatti | 216542 | 7.50 | pipe | 10.70 | Repair + Widen |
| 190 | BR:SH30:BAI202:233.137 | BAI202 | SH30 | Belgaum | Belgaum | Bailhongal | 233134 | 7.50 | pipe | 6.50 | Repair + Widen |
| 191 | BR:SH30:BAI202:234.367 | BAI202 | SH30 | Belgaum | Belgaum | Bailhongal | 234360 | 6.00 | Slab | 15.00 | Repair + Widen |
| 192 | BR:SH30:KNP204:291.923 | KNP204 | SH30 | Belgaum | Belgaum | Khanapur | 291911 | 6.00 | Girder | 24.00 | Repair + Widen |
| 193 | BR:SH30:KNP204:298.938 | KNP204 | SH30 | Belgaum | Belgaum | Khanapur | 298933 | 7.00 | Slab | 10.00 | Repair + Widen |
| 194 | BR:SH31:ATN3:7.875 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 7871 | 7.50 | pipe | 9.30 | Repair + Widen |
| 195 | BR:SH31:ATN3:12.337 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 12331 | 7.00 | Slab | 12.00 | Repair + Widen |
| 196 | BR:SH31:ATN3:13.087 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 13084 | 7.50 | pipe | 7.30 | Repair + Widen |
| 197 | BR:SH31:ATN3:19.062 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 19049 | 7.00 | Slab | 27.00 | Repair + Widen |
| 198 | BR:SH31:ATN3:21.237 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 21229 | 7.00 | Slab | 16.50 | Repair + Widen |
| 199 | BR:SH31:ATN3:21.992 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 21986 | 7.00 | Slab | 12.00 | Repair + Widen |
| 200 | BR:SH31:ATN3:26.332 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 26320 | 7.00 | Slab | 24.00 | Repair + Widen |
| 201 | BR:SH31:ATN3:30.147 | ATN3 | SH31 | Belgaum | Chikkodi | Athni | 30135 | 7.00 | Girder | 24.00 | Repair + Widen |
| 202 | BR:SH31:RBG2:51.553 | RBG2 | SH31 | Belgaum | Chikkodi | Raibag | 51549 | 7.50 | pipe | 8.60 | Repair + Widen |
| 203 | BR:SH31:RBG2:62.968 | RBG2 | SH31 | Belgaum | Chikkodi | Raibag | 62960 | 7.50 | pipe | 16.30 | Repair + Widen |
| 204 | BR:SH31:GOK1:92.057 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 92033 | 7.00 | Slab | 48.00 | Repair + Widen |
| 205 | BR:SH31:GOK1:111.234 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 111221 | 7.00 | Slab | 26.00 | Repair + Widen |
| 206 | BR:SH31:BAI3:165.662 | BAI3 | SH31 | Belgaum | Belgaum | Bailhongal | 165656 | 7.50 | pipe | 13.10 | Repair + Widen |
| 207 | BR:SH31:BAI3:166.107 | BAI3 | SH31 | Belgaum | Belgaum | Bailhongal | 166092 | 6.50 | Arch | 30.00 | Repair + Widen |
| 208 | BR:SH31:BGM4:174.917 | BGM4 | SH31 | Belgaum | Belgaum | Belgaum | 174911 | 6.50 | Slab | 12.00 | Repair + Widen |
| 209 | BR:SH31:KNP4:191.745 | KNP4 | SH31 | Belgaum | Belgaum | Khanapur | 191741 | 7.50 | pipe | 8.50 | Repair + Widen |
| 210 | BR:SH32:ALD3:43.221 | ALD3 | SH32 | Gulbarga | Gulbarga | Aland | 43218 | 7.50 | pipe | 6.50 | Repair + Widen |
| 211 | BR:SH32:ALD3:48.521 | ALD3 | SH32 | Gulbarga | Gulbarga | Aland | 48516 | 7.50 | pipe | 11.50 | Repair + Widen |
| 212 | BR:SH32:GUL4:71.981 | GUL4 | SH32 | Gulbarga | Gulbarga | Gulbarga | 71975 | 7.00 | Slab | 12.00 | Repair + Widen |
| 213 | BR:SH32:GUL4:76.276 | GUL4 | SH32 | Gulbarga | Gulbarga | Gulbarga | 76273 | 7.00 | Slab | 7.00 | Repair + Widen |
| 214 | BR:SH32:GUL4:76.346 | GUL4 | SH32 | Gulbarga | Gulbarga | Gulbarga | 76343 | 7.00 | Slab | 7.00 | Repair + Widen |
| 215 | BR:SH33:TNP204:163.651 | TNP204 | SH33 | Mysore | Mysore | Tnarsipur | 163640 | 6.50 | Slab | 23.70 | Repair + Widen |
| 216 | BR:SH33:MYS232:169.791 | MYS232 | SH33 | Mysore | Mysore | Mysore | 169787 | 6.50 | Slab | 8.40 | Repair + Widen |

**Details of Bridges Proposed for Widening on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 217 | BR:SH34:BHA201:58.16 | BHA201 | SH34 | Bidar | Bidar | Bhalki | 58156 | 7.50 | pipe | 8.50 | Repair + Widen |
| 218 | BR:SH34:BAK204_A:79.955 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 79952 | 7.50 | pipe | 7.00 | Repair + Widen |
| 219 | BR:SH34:BAK204_A:83.48 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 83469 | 7.50 | pipe | 23.50 | Repair + Widen |
| 220 | BR:SH34:BAK204_A:86.265 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 86257 | 7.50 | pipe | 17.50 | Repair + Widen |
| 221 | BR:SH34:BAK204_A:116.32 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 116315 | 7.50 | pipe | 11.40 | Repair + Widen |
| 222 | BR:SH34:BAK204_A:141.18 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 141174 | 7.50 | pipe | 12.70 | Repair + Widen |
| 223 | BR:SH34:ALD202_I:143.925 | ALD202_I | SH34 | Gulbarga | Gulbarga | Aland | 143890 | 5.50 | Slab | 70.00 | Repair + Widen |
| 224 | BR:SH34:ALD202_A:149.81 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 149804 | 7.50 | pipe | 13.50 | Repair + Widen |
| 225 | BR:SH34:ALD202_A:158.005 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 158000 | 7.50 | pipe | 11.50 | Repair + Widen |
| 226 | BR:SH34:ALD202_A:159.97 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 159965 | 7.50 | pipe | 10.00 | Repair + Widen |
| 227 | BR:SH34:ALD202_A:178.42 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 178415 | 7.50 | pipe | 10.50 | Repair + Widen |
| 228 | BR:SH34:ALD202_A:197.92 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 197916 | 7.50 | pipe | 8.50 | Repair + Widen |
| 229 | BR:SH34:ALD202_A:202.565 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 202560 | 7.50 | pipe | 10.70 | Repair + Widen |
| 230 | BR:SH34:SND201:237.465 | SND201 | SH34 | Bijapur | Bijapur | Sindgi | 237457 | 7.50 | pipe | 16.00 | Repair + Widen |
| 231 | BR:SH34:SND201:246.38 | SND201 | SH34 | Bijapur | Bijapur | Sindgi | 246370 | 7.50 | pipe | 20.50 | Repair + Widen |
| 232 | BR:SH34:SND201:253.04 | SND201 | SH34 | Bijapur | Bijapur | Sindgi | 253034 | 7.50 | pipe | 13.50 | Repair + Widen |
| 233 | BR:SH34:BJP201:314.34 | BJP201 | SH34 | Bijapur | Bijapur | Bijapur | 314304 | 8.20 | Slab | 68.00 | Repair + Widen |
| 234 | BR:SH35:SGA2:3.775 | SGA2 | SH35 | Chikballapur | Chikballapur | Sidlaghatta | 3772 | 7.70 | Slab | 6.00 | Repair + Widen |
| 235 | BR:SH37:PUT3:23.265 | PUT3 | SH37 | Dakshina Kannada | Mangalore | Puttur | 23257 | 6.00 | Girder | 16.00 | Repair + Widen |
| 236 | BR:SH38:KLL302:10.218 | KLL302 | SH38 | Chamrajnagar | Chamrajnagar | Kollegal | 10214 | 7.50 | pipe | 9.70 | Repair + Widen |
| 237 | BR:SH40:HDG201:28.195 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 28174 | 7.00 | Slab | 42.00 | Repair + Widen |
| 238 | BR:SH41:IND2:9.055 | IND2 | SH41 | Bijapur | Bijapur | Indi | 9044 | 7.50 | pipe | 22.00 | Repair + Widen |
| 239 | BR:SH41:IND2:60.418 | IND2 | SH41 | Bijapur | Bijapur | Indi | 60411 | 7.50 | pipe | 14.50 | Repair + Widen |
| 240 | BR:SH41:IND2:67.832 | IND2 | SH41 | Bijapur | Bijapur | Indi | 67827 | 7.50 | pipe | 11.50 | Repair + Widen |
| 241 | BR:SH41:SND3:74.538 | SND3 | SH41 | Bijapur | Bijapur | Sindgi | 74524 | 7.50 | pipe | 28.00 | Repair + Widen |
| 242 | BR:SH41:MDD1:139.333 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 139328 | 7.50 | pipe | 10.00 | Repair + Widen |
| 243 | BR:SH41:MDD1:153.848 | MDD1 | SH41 | Bijapur | Bijapur | Muddebihal | 153838 | 7.50 | Slab | 20.00 | Repair + Widen |
| 244 | BR:SH41:LIN5:182.161 | LIN5 | SH41 | Raichur | Raichur | Lingsugur | 182145 | 7.00 | Slab | 32.00 | Repair + Widen |
| 245 | BR:SH44:GOK6:60.459 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 60449 | 7.50 | pipe | 20.50 | Repair + Widen |
| 246 | BR:SH44:GOK6:63.049 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 63045 | 7.00 | Slab | 8.00 | Repair + Widen |
| 247 | BR:SH44:GOK6:64.549 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 64544 | 7.50 | pipe | 10.70 | Repair + Widen |
| 248 | BR:SH44:GOK6:73.229 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 73225 | 10.00 | pipe | 8.50 | Repair + Widen |
| 249 | BR:SH44:MDL202:88.854 | MDL202 | SH44 | Bagalkot | Bagalkot | Mudhol | 88850 | 7.50 | pipe | 9.50 | Repair + Widen |
| 250 | BR:SH44:BDM204:107.101 | BDM204 | SH44 | Bagalkot | Bagalkot | Badami | 107096 | 7.50 | pipe | 11.50 | Repair + Widen |
| 251 | BR:SH44:BDM204:114.154 | BDM204 | SH44 | Bagalkot | Bagalkot | Badami | 114151 | 7.50 | pipe | 7.00 | Repair + Widen |
| 252 | BR:SH44:BDM204:134.829 | BDM204 | SH44 | Bagalkot | Bagalkot | Badami | 134823 | 7.50 | pipe | 13.00 | Repair + Widen |

## Details of Bridges Proposed for Widening on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width in | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 253 | BR:SH44:HUD206:185.62 | HUD206 | SH44 | Bagalkot | Bagalkot | Hungund | 185615 | 7.50 | pipe | 10.00 | Repair + Widen |
| 254 | BR:SH44:HUD206:186.69 | HUD206 | SH44 | Bagalkot | Bagalkot | Hungund | 186687 | 7.50 | pipe | 7.90 | Repair + Widen |
| 255 | BR:SH45:SAU3:47.471 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 47465 | 7.00 | Slab | 12.00 | Repair + Widen |
| 256 | BR:SH45:NVG201:104.187 | NVG201 | SH45 | Dharwad | Dharwad | Navalgund | 104184 | 7.50 | Pipe | 7.00 | Repair + Widen |
| 257 | BR:SH46:MUD3:1.995 | MUD3 | SH46 | Uttara Kannada | Sirsi | Mundgod | 1988 | 7.00 | Slab | 14.00 | Repair + Widen |
| 258 | BR:SH46:HLY201:39.616 | HLY201 | SH46 | Uttara Kannada | Sirsi | Haliyal | 39612 | 7.00 | Slab | 8.00 | Repair + Widen |
| 259 | BR:SH46:HLY201:61.709 | HLY201 | SH46 | Uttara Kannada | Sirsi | Haliyal | 61681 | 6.00 | Slab | 62.50 | Repair + Widen |
| 260 | BR:SH46:JOD202:124.28 | JOD202 | SH46 | Uttara Kannada | Sirsi | Joida | 124277 | 7.50 | pipe | 7.90 | Repair + Widen |
| 261 | BR:SH46:JOD202:135 | JOD202 | SH46 | Uttara Kannada | Sirsi | Joida | 134984 | 6.00 | Slab | 33.00 | Repair + Widen |
| 262 | BR:SH47:MND6:1.61 | MND6 | SH47 | Mandya | Mandya | Mandya | 1600 | 7.00 | Slab | 21.60 | Repair + Widen |
| 263 | BR:SH47:TPT213:122.468 | TPT213 | SH47 | Tumkur | Tumkur | Tiptur | 122465 | 7.50 | Slab | 7.00 | Repair + Widen |
| 264 | BR:SH47:CNH201:173.887 | CNH201 | SH47 | Tumkur | Tumkur | Chiknayakanahalli | 173882 | 7.50 | pipe | 10.00 | Repair + Widen |
| 265 | BR:SH47:HLK203:230.517 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 230513 | 7.50 | Pipe | 9.30 | Repair + Widen |
| 266 | BR:SH47:HLK203:244.562 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 244558 | 7.50 | Pipe | 8.00 | Repair + Widen |
| 267 | BR:SH47:DVG47:267.325 | DVG47 | SH47 | Davanagere | Davanagere | Davanagere | 267319 | 7.50 | Pipe | 13.50 | Repair + Widen |
| 268 | BR:SH47:DVG47:267.885 | DVG47 | SH47 | Davanagere | Davanagere | Davanagere | 267881 | 7.50 | Pipe | 9.70 | Repair + Widen |
| 269 | BR:SH47:HRP201:319.101 | HRP201 | SH47 | Davanagere | Davanagere | Harapanahalli | 319098 | 7.00 | Slab | 7.00 | Repair + Widen |
| 270 | BR:SH47:HRP201:323.321 | HRP201 | SH47 | Davanagere | Davanagere | Harapanahalli | 323314 | 7.00 | Slab | 14.00 | Repair + Widen |
| 271 | BR:SH48:SDP3:49.095 | SDP3 | SH48 | Uttara Kannada | Sirsi | Siddapur | 49089 | 7.00 | Slab | 12.00 | Repair + Widen |
| 272 | BR:SH48:CNG3:190.825 | CNG3 | SH48 | Davanagere | Davanagere | Channagiri | 190820 | 7.00 | Slab | 10.00 | Repair + Widen |
| 273 | BR:SH48:CNG3:205.655 | CNG3 | SH48 | Davanagere | Davanagere | Channagiri | 205648 | 7.50 | Girder | 15.00 | Repair + Widen |
| 274 | BR:SH48:CNG3:207.92 | CNG3 | SH48 | Davanagere | Davanagere | Channagiri | 207914 | 7.50 | Girder | 13.00 | Repair + Widen |
| 275 | BR:SH48:PVG58:357.535 | PVG58 | SH48 | Tumkur | Madhugiri | Pavagada | 357530 | 7.30 | Slab | 11.40 | Repair + Widen |
| 276 | BR:SH49:HSP201:27.37 | HSP201 | SH49 | Bellary | Bellary | Hospet | 27356 | 7.00 | Slab | 28.00 | Repair + Widen |
| 277 | BR:SH49:HSP201:35.87 | HSP201 | SH49 | Bellary | Bellary | Hospet | 35860 | 7.00 | Steel Structure | 21.00 | Repair + Widen |
| 278 | BR:SH49:HSP201:44.38 | HSP201 | SH49 | Bellary | Bellary | Hospet | 44374 | 7.00 | Slab | 12.00 | Repair + Widen |
| 279 | BR:SH5:SGA4:78.128 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 78125 | 7.50 | Slab | 7.00 | Repair + Widen |
| 280 | BR:SH50:BAT45:24.04 | BAT45 | SH50 | Uttara Kannada | Karwar | Bhatkal | 24032 | 7.50 | Slab | 16.50 | Repair + Widen |
| 281 | BR:SH51:BAK205:23.44 | BAK205 | SH51 | Bidar | Bidar | Basavakalyan | 23432 | 7.50 | pipe | 16.00 | Repair + Widen |
| 282 | BR:SH51:BAK205:25.045 | BAK205 | SH51 | Bidar | Bidar | Basavakalyan | 25038 | 7.50 | pipe | 14.50 | Repair + Widen |
| 283 | BR:SH51:BAK205:30.385 | BAK205 | SH51 | Bidar | Bidar | Basavakalyan | 30382 | 7.50 | pipe | 7.00 | Repair + Widen |
| 284 | BR:SH51:BAK205:31.61 | BAK205 | SH51 | Bidar | Bidar | Basavakalyan | 31605 | 7.50 | pipe | 10.00 | Repair + Widen |
| 285 | BR:SH51:BAK205:32.8 | BAK205 | SH51 | Bidar | Bidar | Basavakalyan | 32796 | 7.50 | pipe | 8.50 | Repair + Widen |
| 286 | BR:SH51:BAK205:33.025 | BAK205 | SH51 | Bidar | Bidar | Basavakalyan | 33022 | 7.50 | pipe | 7.00 | Repair + Widen |
| 287 | BR:SH52:TRT5:14.465 | TRT5 | SH52 | Shimoga | Shimoga_special | Tirthahalli | 14455 | 7.50 | Girder | 21.00 | Repair + Widen |
| 288 | BR:SH52:TRT5:18.545 | TRT5 | SH52 | Shimoga | Shimoga_special | Tirthahalli | 18538 | 7.00 | pipe | 15.50 | Repair + Widen |

**Details of Bridges Proposed for Widening on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str. | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 289 | BR:SH52:TRT5:20.99 | TRT5 | SH52 | Shimoga | Shimoga_special | Tirthahalli | 20982 | 7.50 | pipe | 17.50 | Repair + Widen |
| 290 | BR:SH52:TRT5:21.56 | TRT5 | SH52 | Shimoga | Shimoga_special | Tirthahalli | 21557 | 7.00 | Slab | 6.30 | Repair + Widen |
| 291 | BR:SH52:TRT5:22.84 | TRT5 | SH52 | Shimoga | Shimoga_special | Tirthahalli | 22837 | 7.00 | Slab | 6.30 | Repair + Widen |
| 292 | BR:SH52:HSN202:23.49 | HSN202 | SH52 | Shimoga | Shimoga | Hosanagara | 23487 | 7.50 | pipe | 7.00 | Repair + Widen |
| 293 | BR:SH52:HSN202:25.62 | HSN202 | SH52 | Shimoga | Shimoga | Hosanagara | 25611 | 7.00 | pipe | 19.50 | Repair + Widen |
| 294 | BR:SH52:HSN202:29.71 | HSN202 | SH52 | Shimoga | Shimoga | Hosanagara | 29705 | 5.00 | pipe | 10.50 | Repair + Widen |
| 295 | BR:SH53:ATN5:7.58 | ATN5 | SH53 | Belgaum | Chikkodi | Athni | 7577 | 7.50 | pipe | 7.30 | Repair + Widen |
| 296 | BR:SH53:ATN5:15.155 | ATN5 | SH53 | Belgaum | Chikkodi | Athni | 15141 | 7.50 | pipe | 29.50 | Repair + Widen |
| 297 | BR:SH53:RBG8:33.03 | RBG8 | SH53 | Belgaum | Chikkodi | Raibag | 33024 | 7.50 | pipe | 13.10 | Repair + Widen |
| 298 | BR:SH53:RBG8:41.134 | RBG8 | SH53 | Belgaum | Chikkodi | Raibag | 41127 | 7.50 | pipe | 15.50 | Repair + Widen |
| 299 | BR:SH53:RBG8:43.849 | RBG8 | SH53 | Belgaum | Chikkodi | Raibag | 43842 | 7.00 | Slab | 14.00 | Repair + Widen |
| 300 | BR:SH53:JMK201:54.396 | JMK201 | SH53 | Bagalkot | Bagalkot | Jamkhandi | 54392 | 7.50 | pipe | 9.70 | Repair + Widen |
| 301 | BR:SH54:BGM207:49.522 | BGM207 | SH54 | Belgaum | Belgaum | Belgaum | 49514 | 7.50 | Slab | 17.50 | Repair + Widen |
| 302 | BR:SH54:GOK8:58.267 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 58255 | 7.00 | Slab | 24.00 | Repair + Widen |
| 303 | BR:SH54:GOK8:71.068 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 71063 | 7.50 | pipe | 10.70 | Repair + Widen |
| 304 | BR:SH54:GOK8:84.062 | GOK8 | SH54 | Belgaum | Chikkodi | Gokak | 84056 | 7.50 | pipe | 13.50 | Repair + Widen |
| 305 | BR:SH55:SAU7:0.565 | SAU7 | SH55 | Belgaum | Belgaum | Saundatti | 562 | 7.50 | pipe | 6.50 | Repair + Widen |
| 306 | BR:SH55:SAU7:13.745 | SAU7 | SH55 | Belgaum | Belgaum | Saundatti | 13740 | 7.50 | pipe | 10.70 | Repair + Widen |
| 307 | BR:SH55:RMG6:21.635 | RMG6 | SH55 | Belgaum | Belgaum | Ramdurg | 21630 | 7.00 | Slab | 10.00 | Repair + Widen |
| 308 | BR:SH55:RMG6:24.275 | RMG6 | SH55 | Belgaum | Belgaum | Ramdurg | 24266 | 7.50 | pipe | 19.50 | Repair + Widen |
| 309 | BR:SH56:BAI7:19.125 | BAI7 | SH56 | Belgaum | Belgaum | Bailhongal | 19109 | 7.50 | Pipe | 33.50 | Repair + Widen |
| 310 | BR:SH56:BAI7:19.43 | BAI7 | SH56 | Belgaum | Belgaum | Bailhongal | 19422 | 7.50 | Pipe | 16.50 | Repair + Widen |
| 311 | BR:SH56:DRD7:47.045 | DRD7 | SH56 | Dharwad | Dharwad | Dharwad | 47042 | 7.50 | Pipe | 6.30 | Repair + Widen |
| 312 | BR:SH57:BDM205:50.53 | BDM205 | SH57 | Bagalkot | Bagalkot | Badami | 50525 | 7.50 | Slab | 11.00 | Repair + Widen |
| 313 | BR:SH57:SRT201:159.391 | SRT201 | SH57 | Gadag | Gadag | Shirahatti | 159387 | 7.50 | Pipe | 9.50 | Repair + Widen |
| 314 | BR:SH57:RBN2:224.475 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 224469 | 7.50 | Slab | 12.00 | Repair + Widen |
| 315 | BR:SH57:RBN2:230.955 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 230935 | 7.50 | Slab | 40.00 | Repair + Widen |
| 316 | BR:SH57:RBN2:233.355 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 233343 | 7.50 | Slab | 24.00 | Repair + Widen |
| 317 | BR:SH57:RBN2:236.167 | RBN2 | SH57 | Haveri | Haveri | Ranebennur | 236155 | 7.50 | Slab | 24.00 | Repair + Widen |
| 318 | BR:SH57:HKR203:249.167 | HKR203 | SH57 | Haveri | Haveri | Hirekerur | 249151 | 7.50 | Slab | 32.00 | Repair + Widen |
| 319 | BR:SH57:HKR203:251.212 | HKR203 | SH57 | Haveri | Haveri | Hirekerur | 251208 | 7.50 | Slab | 8.00 | Repair + Widen |
| 320 | BR:SH57:TRK212:392.869 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 392866 | 7.00 | Slab | 6.50 | Repair + Widen |
| 321 | BR:SH59:KST204:0.98 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 973 | 7.50 | Slab | 15.00 | Repair + Widen |
| 322 | BR:SH59:KST204:15.065 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 15058 | 7.50 | Slab | 14.00 | Repair + Widen |
| 323 | BR:SH59:KST204:18.575 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 18568 | 7.50 | Slab | 14.00 | Repair + Widen |
| 324 | BR:SH59:KST204:39.955 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 39950 | 7.50 | pipe | 10.70 | Repair + Widen |

**Details of Bridges Proposed for Widening on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 325 | BR:SH6:MUD2:139.51 | MUD2 | SH6 | Uttara Kannada | Sirsi | Mundgod | 139507 | 5.50 | Slab | 7.00 | Repair + Widen |
| 326 | BR:SH6:SRT1:220.07 | SRT1 | SH6 | Gadag | Gadag | Shirahatti | 220066 | 7.50 | Pipe | 8.50 | Repair + Widen |
| 327 | BR:SH6:RON1_A:287.66 | RON1_A | SH6 | Gadag | Gadag | Ron | 287653 | 7.50 | Pipe | 14.80 | Repair + Widen |
| 328 | BR:SH6:KST205:317.995 | KST205 | SH6 | Koppal | Koppal | Kushtagi | 317991 | 7.50 | pipe | 8.50 | Repair + Widen |
| 329 | BR:SH6:KST205:320.48 | KST205 | SH6 | Koppal | Koppal | Kushtagi | 320475 | 7.50 | pipe | 10.70 | Repair + Widen |
| 330 | BR:SH6:KST205:325.03 | KST205 | SH6 | Koppal | Koppal | Kushtagi | 325022 | 7.50 | Slab | 17.50 | Repair + Widen |
| 331 | BR:SH6:HUD5:337.905 | HUD5 | SH6 | Bagalkot | Bagalkot | Hungund | 337887 | 7.50 | Slab | 36.00 | Repair + Widen |
| 332 | BR:SH6:HUD5:339.71 | HUD5 | SH6 | Bagalkot | Bagalkot | Hungund | 339704 | 7.50 | pipe | 13.50 | Repair + Widen |
| 333 | BR:SH61:SRP205:81.182 | SRP205 | SH61 | Yadgir | Yadgir | Shorapur | 81169 | 7.00 | Slab | 27.00 | Repair + Widen |
| 334 | BR:SH61:SRP205:82.502 | SRP205 | SH61 | Yadgir | Yadgir | Shorapur | 82496 | 7.00 | Slab | 12.00 | Repair + Widen |
| 335 | BR:SH61:SRP205:85.267 | SRP205 | SH61 | Yadgir | Yadgir | Shorapur | 85253 | 7.50 | Slab | 28.00 | Repair + Widen |
| 336 | BR:SH61:SRP205:94.682 | SRP205 | SH61 | Yadgir | Yadgir | Shorapur | 94673 | 7.00 | Arch | 18.00 | Repair + Widen |
| 337 | BR:SH61:DEV201:164.216 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 164209 | 7.50 | pipe | 14.50 | Repair + Widen |
| 338 | BR:SH61:DEV201:176.354 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 176332 | 7.50 | pipe | 44.50 | Repair + Widen |
| 339 | BR:SH61:DEV201:185.039 | DEV201 | SH61 | Raichur | Raichur | Devadurga | 185025 | 7.50 | pipe | 29.50 | Repair + Widen |
| 340 | BR:SH61:RAI201:246.326 | RAI201 | SH61 | Raichur | Raichur | Raichur | 246319 | 7.50 | pipe | 14.50 | Repair + Widen |
| 341 | BR:SH63:GAN94:64.782 | GAN94 | SH63 | Koppal | Koppal | Gangawati | 64776 | 7.00 | Girder | 12.00 | Repair + Widen |
| 342 | BR:SH63:GAN94:75.674 | GAN94 | SH63 | Koppal | Koppal | Gangawati | 75671 | 7.50 | pipe | 7.90 | Repair + Widen |
| 343 | BR:SH63:GAN94:77.789 | GAN94 | SH63 | Koppal | Koppal | Gangawati | 77786 | 7.50 | pipe | 7.90 | Repair + Widen |
| 344 | BR:SH63:GAN94:80.359 | GAN94 | SH63 | Koppal | Koppal | Gangawati | 80330 | 7.50 | pipe | 58.30 | Repair + Widen |
| 345 | BR:SH63:YEL114:118.054 | YEL114 | SH63 | Koppal | Koppal | Yelbarga | 118044 | 7.50 | pipe | 20.50 | Repair + Widen |
| 346 | BR:SH63:YEL114:122.559 | YEL114 | SH63 | Koppal | Koppal | Yelbarga | 122554 | 7.50 | pipe | 10.70 | Repair + Widen |
| 347 | BR:SH63:YEL114:123.369 | YEL114 | SH63 | Koppal | Koppal | Yelbarga | 123363 | 7.50 | pipe | 13.50 | Repair + Widen |
| 348 | BR:SH63:YEL114:124.699 | YEL114 | SH63 | Koppal | Koppal | Yelbarga | 124695 | 7.50 | pipe | 8.50 | Repair + Widen |
| 349 | BR:SH63:YEL114:130.699 | YEL114 | SH63 | Koppal | Koppal | Yelbarga | 130693 | 7.50 | pipe | 12.10 | Repair + Widen |
| 350 | BR:SH63:YEL114:135.084 | YEL114 | SH63 | Koppal | Koppal | Yelbarga | 135071 | 7.50 | pipe | 27.50 | Repair + Widen |
| 351 | BR:SH65:NRP202:120.677 | NRP202 | SH65 | Chikmagalur | Chikmagalur | Narasimharajapura | 120672 | 9.00 | Slab | 11.00 | Repair + Widen |
| 352 | BR:SH65:NRP202:124.362 | NRP202 | SH65 | Chikmagalur | Chikmagalur | Narasimharajapura | 124358 | 7.50 | Slab | 8.00 | Repair + Widen |
| 353 | BR:SH65:CNG202:187.961 | CNG202 | SH65 | Davanagere | Davanagere | Channagiri | 187951 | 7.50 | Girder | 20.00 | Repair + Widen |
| 354 | BR:SH65:CNG202:225.047 | CNG202 | SH65 | Davanagere | Davanagere | Channagiri | 225034 | 7.00 | Girder | 27.00 | Repair + Widen |
| 355 | BR:SH65:DVG48:235.267 | DVG48 | SH65 | Davanagere | Davanagere | Davanagere | 235227 | 6.50 | Girder | 80.00 | Repair + Widen |
| 356 | BR:SH65:JGL202:287.98 | JGL202 | SH65 | Davanagere | Davanagere | Jagalur | 287975 | 7.50 | Slab | 10.80 | Repair + Widen |
| 357 | BR:SH65:MOL202:356.665 | MOL202 | SH65 | Chitradurga | Chitradurga | Molakalmuru | 356653 | 7.50 | Pipe | 25.00 | Repair + Widen |
| 358 | BR:SH65:MOL202:359.03 | MOL202 | SH65 | Chitradurga | Chitradurga | Molakalmuru | 359018 | 7.50 | Pipe | 25.00 | Repair + Widen |
| 359 | BR:SH67:MNG6:33.37 | MNG6 | SH67 | Dakshina Kannada | Mangalore | Mangalore | 33364 | 6.00 | Girder | 12.00 | Repair + Widen |
| 360 | BR:SH67:UDP202:71.285 | UDP202 | SH67 | Udupi | Udupi | Udupi | 71275 | 6.00 | Slab | 20.00 | Repair + Widen |

## Details of Bridges Proposed for Widening on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m. | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 361 | BR:SH69:SRS90:31.17 | SRS90 | SH69 | Uttara Kannada | Sirsi | Sirsi | 31164 | 7.50 | Girder | 12.00 | Repair + Widen |
| 362 | BR:SH69:SRS90:42.27 | SRS90 | SH69 | Uttara Kannada | Sirsi | Sirsi | 42263 | 7.60 | Slab | 15.00 | Repair + Widen |
| 363 | BR:SH69:SRS90:47.245 | SRS90 | SH69 | Uttara Kannada | Sirsi | Sirsi | 47242 | 7.50 | Slab | 7.50 | Repair + Widen |
| 364 | BR:SH72:CKD201_A:4.51 | CKD201_A | SH72 | Belgaum | Chikkodi | Chikkodi | 4507 | 7.00 | Slab | 6.60 | Repair + Widen |
| 365 | BR:SH72:CKD201_A:13.036 | CKD201_A | SH72 | Belgaum | Chikkodi | Chikkodi | 13033 | 7.50 | pipe | 7.00 | Repair + Widen |
| 366 | BR:SH72:CKD201_A:35.161 | CKD201_A | SH72 | Belgaum | Chikkodi | Chikkodi | 35147 | 7.50 | pipe | 29.50 | Repair + Widen |
| 367 | BR:SH72:ATN20_B:91.337 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 91334 | 7.50 | pipe | 6.50 | Repair + Widen |
| 368 | BR:SH72:ATN20_B:96.187 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 96181 | 7.50 | pipe | 13.50 | Repair + Widen |
| 369 | BR:SH72:ATN20_B:120.303 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 120298 | 7.50 | pipe | 10.50 | Repair + Widen |
| 370 | BR:SH72:ATN20_B:123.928 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 123922 | 7.50 | pipe | 12.70 | Repair + Widen |
| 371 | BR:SH72:ATN20_B:129.618 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 129607 | 7.50 | pipe | 22.00 | Repair + Widen |
| 372 | BR:SH72:ATN20_B:130.838 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 130825 | 7.50 | pipe | 27.10 | Repair + Widen |
| 373 | BR:SH73:RBG201:29.865 | RBG201 | SH73 | Belgaum | Chikkodi | Raibag | 29840 | 7.50 | pipe | 50.00 | Repair + Widen |
| 374 | BR:SH73:RBG201:30.55 | RBG201 | SH73 | Belgaum | Chikkodi | Raibag | 30547 | 7.50 | pipe | 6.70 | Repair + Widen |
| 375 | BR:SH73:RBG201:36.85 | RBG201 | SH73 | Belgaum | Chikkodi | Raibag | 36847 | 7.50 | pipe | 7.00 | Repair + Widen |
| 376 | BR:SH73:RBG201:39.424 | RBG201 | SH73 | Belgaum | Chikkodi | Raibag | 39420 | 7.50 | Slab | 8.00 | Repair + Widen |
| 377 | BR:SH73:CKD202:60.669 | CKD202 | SH73 | Belgaum | Chikkodi | Chikkodi | 60666 | 7.00 | Slab | 6.50 | Repair + Widen |
| 378 | BR:SH73:CKD202:62.109 | CKD202 | SH73 | Belgaum | Chikkodi | Chikkodi | 62106 | 7.00 | Slab | 6.50 | Repair + Widen |
| 379 | BR:SH73:HUK206_A:63.784 | HUK206_A | SH73 | Belgaum | Chikkodi | Hukkeri | 63776 | 7.50 | pipe | 16.50 | Repair + Widen |
| 380 | BR:SH73:HUK206_A:64.394 | HUK206_A | SH73 | Belgaum | Chikkodi | Hukkeri | 64391 | 7.00 | Slab | 6.50 | Repair + Widen |
| 381 | BR:SH73:BAI203:151.607 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 151603 | 7.00 | Slab | 8.00 | Repair + Widen |
| 382 | BR:SH73:BAI203:164.002 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 163985 | 7.50 | Slab | 35.00 | Repair + Widen |
| 383 | BR:SH73:BAI203:168.487 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 168482 | 7.50 | pipe | 10.00 | Repair + Widen |
| 384 | BR:SH73:BAI203:174.482 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 174478 | 7.00 | Slab | 8.00 | Repair + Widen |
| 385 | BR:SH75:BHA203:5.6 | BHA203 | SH75 | Bidar | Bidar | Bhalki | 5595 | 7.50 | pipe | 10.00 | Repair + Widen |
| 386 | BR:SH77:HSN203:113.11 | HSN203 | SH77 | Shimoga | Shimoga | Hosanagara | 113107 | 7.80 | Slab | 7.20 | Repair + Widen |
| 387 | BR:SH78:HUK207_A:2.895 | HUK207_A | SH78 | Belgaum | Chikkodi | Hukkeri | 2891 | 7.50 | pipe | 9.30 | Repair + Widen |
| 388 | BR:SH78:HUK207_A:8.285 | HUK207_A | SH78 | Belgaum | Chikkodi | Hukkeri | 8273 | 7.00 | Slab | 25.00 | Repair + Widen |
| 389 | BR:SH78:HUK207:51.3 | HUK207 | SH78 | Belgaum | Chikkodi | Hukkeri | 51294 | 7.50 | pipe | 13.50 | Repair + Widen |
| 390 | BR:SH78:CKD203:54.72 | CKD203 | SH78 | Belgaum | Chikkodi | Chikkodi | 54715 | 7.50 | pipe | 11.50 | Repair + Widen |
| 391 | BR:SH78:CKD203:63.91 | CKD203 | SH78 | Belgaum | Chikkodi | Chikkodi | 63907 | 7.50 | pipe | 6.50 | Repair + Widen |
| 392 | BR:SH78:CKD203:74.45 | CKD203 | SH78 | Belgaum | Chikkodi | Chikkodi | 74447 | 7.50 | pipe | 7.90 | Repair + Widen |
| 393 | BR:SH79:TNP205:35.295 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 35288 | 6.50 | Slab | 14.00 | Repair + Widen |
| 394 | BR:SH79:KLL301:91.232 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 91221 | 7.80 | Slab | 22.50 | Repair + Widen |
| 395 | BR:SH79:KLL301:122.407 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 122398 | 7.00 | Slab | 18.00 | Repair + Widen |
| 396 | BR:SH8:ARK2:90.373 | ARK2 | SH8 | Hassan | Hassan_Special | Arkalgud | 90367 | 6.50 | Girder | 13.50 | Repair + Widen |

**Details of Bridges Proposed for Widening on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 397 | BR:SH80:YLN201:73.931 | YLN201 | SH80 | Chamrajnagar | Chamrajnagar | Yelandur | 73926 | 7.00 | Slab | 11.00 | Repair + Widen |
| 398 | BR:SH83:RMG202:11.3 | RMG202 | SH83 | Belgaum | Belgaum | Ramdurg | 11297 | 7.50 | pipe | 7.90 | Repair + Widen |
| 399 | BR:SH83:RMG202:35.435 | RMG202 | SH83 | Belgaum | Belgaum | Ramdurg | 35428 | 7.50 | Slab | 14.00 | Repair + Widen |
| 400 | BR:SH83:RMG202:62.9 | RMG202 | SH83 | Belgaum | Belgaum | Ramdurg | 62880 | 7.50 | Slab | 40.00 | Repair + Widen |
| 401 | BR:SH83:RON77:91.11 | RON77 | SH83 | Gadag | Gadag | Ron | 91107 | 7.50 | Pipe | 6.30 | Repair + Widen |
| 402 | BR:SH83:RON77:123.72 | RON77 | SH83 | Gadag | Gadag | Ron | 123716 | 7.50 | Pipe | 9.50 | Repair + Widen |
| 403 | BR:SH84:GBB203:37.413 | GBB203 | SH84 | Tumkur | Tumkur | Gubbi | 37402 | 7.50 | pipe | 23.30 | Repair + Widen |
| 404 | BR:SH84:NJG63:225.002 | NJG63 | SH84 | Mysore | Mysore | Nanjangud | 224983 | 6.50 | Girder | 38.00 | Repair + Widen |
| 405 | BR:SH85:KNL3:86.83 | KNL3 | SH85 | Tumkur | Tumkur | Kunigal | 86812 | 7.50 | Slab | 37.50 | Repair + Widen |
| 406 | BR:SH85:ARK201:223.51 | ARK201 | SH85 | Hassan | Hassan_Special | Arkalgud | 223501 | 6.50 | Girder | 18.00 | Repair + Widen |
| 407 | BR:SH85:SVP80:251.075 | SVP80 | SH85 | Kodagu | Kodagu | Somvarpet | 251071 | 6.50 | Girder | 9.00 | Repair + Widen |
| 408 | BR:SH85:SLP236:258.47 | SLP236 | SH85 | Hassan | Hassan_Special | Sakleshpur | 258457 | 6.50 | Girder | 26.00 | Repair + Widen |
| 409 | BR:SH85:SLP236:265.83 | SLP236 | SH85 | Hassan | Hassan_Special | Sakleshpur | 265818 | 6.50 | Girder | 25.00 | Repair + Widen |
| 410 | BR:SH86:KRN225:24.376 | KRN225 | SH86 | Mysore | Hunsur | Krishnarajanagar | 24373 | 7.50 | pipe | 7.90 | Repair + Widen |
| 411 | BR:SH86:HDK203:96.104 | HDK203 | SH86 | Mysore | Hunsur | Heggadadevanakote | 96099 | 7.50 | Slab | 10.00 | Repair + Widen |
| 412 | BR:SH86:HDK203:101.199 | HDK203 | SH86 | Mysore | Hunsur | Heggadadevanakote | 101190 | 7.00 | Slab | 18.00 | Repair + Widen |
| 413 | BR:SH86:NJG62:109.294 | NJG62 | SH86 | Mysore | Mysore | Nanjangud | 109287 | 7.00 | Slab | 14.00 | Repair + Widen |
| 414 | BR:SH9:GBR1:74.585 | GBR1 | SH9 | Chikballapur | Chikballapur | Gauribidanur | 74580 | 7.00 | Slab | 11.40 | Repair + Widen |
| 415 | BR:SH94:GBR201:61.062 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 61059 | 7.50 | Slab | 7.80 | Repair + Widen |
| 416 | BR:SH94:GBR201:79.297 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 79294 | 7.50 | Slab | 6.10 | Repair + Widen |
| 417 | BR:SH94:MGD201:150.035 | MGD201 | SH94 | Ramanagara | Ramanagara | Magadi | 150028 | 7.50 | pipe | 14.50 | Repair + Widen |
| 418 | BR:SH94:MGD201:151.25 | MGD201 | SH94 | Ramanagara | Ramanagara | Magadi | 151244 | 7.50 | pipe | 13.10 | Repair + Widen |
| 419 | BR:SH95:MLR201:32.305 | MLR201 | SH95 | Kolar | Kolar | Malur | 32296 | 7.50 | Slab | 18.30 | Repair + Widen |
| 420 | BR:SH96:KOL201:51.85 | KOL201 | SH96 | Kolar | Kolar | Kolar | 51845 | 7.50 | Slab | 11.10 | Repair + Widen |
| 421 | BR:SH96:KOL201:65.05 | KOL201 | SH96 | Kolar | Kolar | Kolar | 65042 | 5.00 | Slab | 16.00 | Repair + Widen |
| 422 | BR:SH96:BGT201:68.825 | BGT201 | SH96 | Kolar | Kolar | Bangarpet | 68821 | 6.00 | Slab | 9.00 | Repair + Widen |
| 423 | BR:SH96:BGT201:91.436 | BGT201 | SH96 | Kolar | Kolar | Bangarpet | 91433 | 7.00 | Slab | 7.00 | Repair + Widen |
| 424 | BR:SH99:SRI201:3.51 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 3507 | 6.00 | Slab | 7.00 | Repair + Widen |
| 425 | BR:SH99:MLR202:80.292 | MLR202 | SH99 | Kolar | Kolar | Malur | 80288 | 7.50 | Pipe | 8.70 | Repair + Widen |
| 426 | BR:SH99:MLR202:82.367 | MLR202 | SH99 | Kolar | Kolar | Malur | 82363 | 7.30 | Slab | 8.80 | Repair + Widen |
| 427 | BR:SH99:MLR202:85.692 | MLR202 | SH99 | Kolar | Kolar | Malur | 85679 | 7.00 | Girder | 27.60 | Repair + Widen |

Engineer in Chief,
Planning Road Asset & Management Center
4th Floor, PWD Annex Building, K.R.Circle.
Bangalore -- 560 001.

# Details of Bridges Proposed for Reconstruction on CRN Network

## Details of Bridges Proposed for Reconstruction on CRN Network

| Sl. No | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | BR:MDR_ALD8:ALD8:1.71 | ALD8 | MDR_ALD8 | Gulbarga | Gulbarga | Aland | 1705 | 7.50 | pipe | 10.70 | reconstruction |
| 2 | BR:MDR_BER6:BER6:6.421 | BER6 | MDR_BER6 | Bellary | Bellary | Bellary | 6404 | 5.00 | Arch | 34.50 | reconstruction |
| 3 | BR:MDR_BER6:BER6:9.772 | BER6 | MDR_BER6 | Bellary | Bellary | Bellary | 9760 | 7.50 | Girder | 24.00 | reconstruction |
| 4 | BR:MDR_CNH10:CNH10:28.508 | CNH10 | MDR_CNH10 | Tumkur | Tumkur | Chiknayakanahalli | 28505 | 7.50 | pipe | 6.50 | reconstruction |
| 5 | BR:MDR_GBB3:GBB3:50.335 | GBB3 | MDR_GBB3 | Tumkur | Tumkur | Tumkur | 50330 | 7.00 | Stone Slab | 10.00 | reconstruction |
| 6 | BR:MDR_HBL15:HBL15:2.601 | HBL15 | MDR_HBL15 | Dharwad | Dharwad | Hubli | 2590 | 8.50 | Pipe | 23.50 | reconstruction |
| 7 | BR:MDR_HUM17:HUM17:11.36 | HUM17 | MDR_HUM17 | Bidar | Bidar | Homnabad | 11356 | 7.50 | pipe | 8.50 | reconstruction |
| 8 | BR:MDR_HUM19:HUM19:1.923 | HUM19 | MDR_HUM19 | Bidar | Bidar | Homnabad | 1919 | 7.50 | pipe | 9.30 | reconstruction |
| 9 | BR:MDR_HVR206:HVR206:6.823 | HVR206 | MDR_HVR206 | Haveri | Haveri | Haveri | 6815 | 8.50 | Pipe | 17.50 | reconstruction |
| 10 | BR:MDR_KOP8:KOP8:6.907 | KOP8 | MDR_KOP8 | Koppal | Koppal | Koppal | 6902 | 7.50 | pipe | 11.60 | reconstruction |
| 11 | BR:MDR_KTG5:KTG5:7.61 | KTG5 | MDR_KTG5 | Tumkur | Madhugiri | Koratagere | 7605 | 8.00 | Slab | 10.80 | reconstruction |
| 12 | BR:MDR_KTG5:KTG5:13.855 | KTG5 | MDR_KTG5 | Tumkur | Madhugiri | Koratagere | 13848 | 6.00 | Stone Slab | 14.40 | reconstruction |
| 13 | BR:MDR_MDL7:MDL7:28.812 | MDL7 | MDR_MDL7 | Bagalkot | Bagalkot | Mudhol | 28800 | 7.50 | Arch | 25.00 | reconstruction |
| 14 | BR:MDR_MDL7:MDL7:34.375 | MDL7 | MDR_MDL7 | Bagalkot | Bagalkot | Mudhol | 34366 | 7.50 | Arch | 18.00 | reconstruction |
| 15 | BR:MDR_MDR16:MDR16:5.028 | MDR16 | MDR_MDR16 | Mandya | Mandya | Maddur | 5025 | 5.00 | Slab | 6.00 | reconstruction |
| 16 | BR:MDR_MLR1:MLR1:21.574 | MLR1 | MDR_MLR1 | Kolar | Kolar | Malur | 21571 | 8.00 | Pipe | 7.00 | reconstruction |
| 17 | BR:MDR_MND2:MND2:9.28 | MND2 | MDR_MND2 | Mandya | Mandya | Mandya | 9273 | 8.00 | Slab | 15.00 | reconstruction |
| 18 | BR:MDR_MND2:MND2:14.491 | MND2 | MDR_MND2 | Mandya | Mandya | Mandya | 14488 | 6.50 | Stone Slab | 7.50 | reconstruction |
| 19 | BR:MDR_SNR20:SNR20:4.498 | SNR20 | MDR_SNR20 | Bellary | Bellary | Sandur | 4495 | 7.50 | Pipe | 7.00 | reconstruction |
| 20 | BR:MDR_SNR31:SNR31:5.231 | SNR31 | MDR_SNR31 | Bellary | Bellary | Sandur | 5223 | 7.00 | Slab | 16.00 | reconstruction |
| 21 | BR:MDR_SNR31:SNR31:11.479 | SNR31 | MDR_SNR31 | Bellary | Bellary | Sandur | 11476 | 8.00 | Pipe | 7.00 | reconstruction |
| 22 | BR:MDR_SRA10:SRA10:54.595 | SRA10 | MDR_SRA10 | Tumkur | Tumkur | Gubbi | 54590 | 9.00 | Slab | 11.00 | reconstruction |
| 23 | BR:MDR_TMK10:TMK10:9.442 | TMK10 | MDR_TMK10 | Tumkur | Tumkur | Tumkur | 9438 | 7.50 | pipe | 8.00 | reconstruction |
| 24 | BR:MDR_TMK5:TMK5:21.449 | TMK5 | MDR_TMK5 | Tumkur | Tumkur | Tumkur | 21444 | 8.00 | Slab | 10.00 | reconstruction |
| 25 | BR:MDR_TPT8:TPT8:42.991 | TPT8 | MDR_TPT8 | Tumkur | Tumkur | Tiptur | 42988 | 10.00 | Stone Slab | 6.40 | reconstruction |
| 26 | BR:SH1:SGR88:164.487 | SGR88 | SH1 | Shimoga | Shimoga | Sagar | 164474 | 6.50 | Arch | 27.00 | reconstruction |
| 27 | BR:SH1:SRB2:247.897 | SRB2 | SH1 | Shimoga | Shimoga | Sorab | 247892 | 7.00 | Slab | 10.00 | reconstruction |
| 28 | BR:SH1:DRD19:379.84 | DRD19 | SH1 | Dharwad | Dharwad | Dharwad | 379837 | 7.50 | Pipe | 6.50 | reconstruction |
| 29 | BR:SH1:BAI201_B:431.683 | BAI201_B | SH1 | Belgaum | Belgaum | Bailhongal | 431673 | 6.00 | Slab | 20.00 | reconstruction |
| 30 | BR:SH102:ARS201:70.06 | ARS201 | SH102 | Hassan | Hassan | Arsikere | 70055 | 7.00 | Slab | 11.00 | reconstruction |
| 31 | BR:SH102:HSS240:71.795 | HSS240 | SH102 | Hassan | Hassan | Hassan | 71789 | 10.00 | Slab | 12.00 | reconstruction |
| 32 | BR:SH104:DVN3:48.125 | DVN3 | SH104 | Bangalore Rural | Bangalore | Devanahalli | 48121 | 8.00 | Stone Slab | 8.10 | reconstruction |
| 33 | BR:SH110:BLR301:10.14 | BLR301 | SH110 | Hassan | Hassan | Belur | 10128 | 6.50 | Arch | 24.00 | reconstruction |
| 34 | BR:SH112:BLR302:4.115 | BLR302 | SH112 | Hassan | Hassan | Belur | 4110 | 6.50 | Arch | 10.40 | reconstruction |
| 35 | BR:SH115:HNN14:25.12 | HNN14 | SH115 | Davanagere | Davanagere | Honnali | 25114 | 7.50 | Slab | 12.00 | reconstruction |

**Details of Bridges Proposed for Reconstruction on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 36 | BR:SH12:BJP4:39.06 | BJP4 | SH12 | Bijapur | Bijapur | Bijapur | 39056 | 7.50 | pipe | 9.50 | reconstruction |
| 37 | BR:SH12:ATN2:110.992 | ATN2 | SH12 | Belgaum | Chikkodi | Athni | 110987 | 6.50 | Arch | 10.00 | reconstruction |
| 38 | BR:SH122:BID51:100.88 | BID51 | SH122 | Bidar | Bidar | Bidar | 100877 | 7.50 | pipe | 7.00 | reconstruction |
| 39 | BR:SH122:BID51:106.305 | BID51 | SH122 | Bidar | Bidar | Bidar | 106301 | 7.50 | pipe | 9.30 | reconstruction |
| 40 | BR:SH124:AFZ62:102.285 | AFZ62 | SH124 | Gulbarga | Gulbarga | Afzalpur | 102281 | 7.50 | pipe | 8.50 | reconstruction |
| 41 | BR:SH127:YDG204:56.426 | YDG204 | SH127 | Yadgir | Yadgir | Yadgir | 56422 | 6.50 | Stone Slab | 8.00 | reconstruction |
| 42 | BR:SH127:SHA203:98.855 | SHA203 | SH127 | Yadgir | Yadgir | Shahpur | 98851 | 7.50 | pipe | 9.30 | reconstruction |
| 43 | BR:SH127:DEV203:130.547 | DEV203 | SH127 | Raichur | Raichur | Devadurga | 130541 | 7.50 | pipe | 13.50 | reconstruction |
| 44 | BR:SH127:DEV203:139.532 | DEV203 | SH127 | Raichur | Raichur | Devadurga | 139526 | 7.50 | pipe | 13.50 | reconstruction |
| 45 | BR:SH127:MAN203:181.034 | MAN203 | SH127 | Raichur | Raichur | Manvi | 181026 | 7.50 | pipe | 16.30 | reconstruction |
| 46 | BR:SH128:BER10:213.27 | BER10 | SH128 | Bellary | Bellary | Bellary | 213267 | 10.00 | Slab | 7.50 | reconstruction |
| 47 | BR:SH128:BER10:214.03 | BER10 | SH128 | Bellary | Bellary | Bellary | 214018 | 7.50 | Pipe | 25.90 | reconstruction |
| 48 | BR:SH128:BER10:226.97 | BER10 | SH128 | Bellary | Bellary | Bellary | 226967 | 7.00 | Slab | 6.50 | reconstruction |
| 49 | BR:SH129:KST209:62.465 | KST209 | SH129 | Koppal | Koppal | Kushtagi | 62460 | 7.50 | pipe | 11.10 | reconstruction |
| 50 | BR:SH129:YEL202:106.86 | YEL202 | SH129 | Koppal | Koppal | Yelbarga | 106851 | 7.50 | pipe | 19.30 | reconstruction |
| 51 | BR:SH129:KOP13:143.095 | KOP13 | SH129 | Koppal | Koppal | Koppal | 143090 | 7.50 | pipe | 10.70 | reconstruction |
| 52 | BR:SH129:KOP13:147.08 | KOP13 | SH129 | Koppal | Koppal | Koppal | 147075 | 7.50 | pipe | 10.70 | reconstruction |
| 53 | BR:SH130:YEL203:21.462 | YEL203 | SH130 | Koppal | Koppal | Yelbarga | 21459 | 7.50 | pipe | 7.00 | reconstruction |
| 54 | BR:SH130:GAN95:68.345 | GAN95 | SH130 | Koppal | Koppal | Gangawati | 68342 | 6.00 | Slab | 6.40 | reconstruction |
| 55 | BR:SH130:KOP9:107.25 | KOP9 | SH130 | Koppal | Koppal | Koppal | 107235 | 6.00 | Stone Slab | 30.00 | reconstruction |
| 56 | BR:SH131:HSP202:0.905 | HSP202 | SH131 | Bellary | Bellary | Hospet | 901 | 6.00 | Arch | 8.00 | reconstruction |
| 57 | BR:SH131:SNR35:58.92 | SNR35 | SH131 | Bellary | Bellary | Sandur | 58916 | 7.50 | Pipe | 8.50 | reconstruction |
| 58 | BR:SH131:SNR35:64.415 | SNR35 | SH131 | Bellary | Bellary | Sandur | 64411 | 7.50 | Pipe | 8.50 | reconstruction |
| 59 | BR:SH131:MOL201:93.635 | MOL201 | SH131 | Chitradurga | Chitradurga | Molakalmuru | 93631 | 7.50 | Pipe | 8.00 | reconstruction |
| 60 | BR:SH131:KDL44:120 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 119990 | 7.50 | Stone Slab | 21.60 | reconstruction |
| 61 | BR:SH131:KDL44:154.04 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 154037 | 7.50 | Pipe | 7.00 | reconstruction |
| 62 | BR:SH131:KDL44:154.7 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 154697 | 7.50 | Pipe | 7.00 | reconstruction |
| 63 | BR:SH131:KDL44:165.82 | KDL44 | SH131 | Bellary | Hadagalli | Kudligi | 165800 | 7.50 | Pipe | 41.50 | reconstruction |
| 64 | BR:SH132:BER19:18.007 | BER19 | SH132 | Bellary | Bellary | Bellary | 18002 | 4.50 | Arch | 10.00 | reconstruction |
| 65 | BR:SH132:BER19:66.995 | BER19 | SH132 | Bellary | Bellary | Bellary | 66988 | 4.00 | Steel Structure | 14.00 | reconstruction |
| 66 | BR:SH133:BDM206:8.35 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 8347 | 7.50 | pipe | 6.50 | reconstruction |
| 67 | BR:SH133:BDM206:25.024 | BDM206 | SH133 | Bagalkot | Bagalkot | Badami | 25018 | 7.00 | pipe | 13.50 | reconstruction |
| 68 | BR:SH134:RMG205:53.938 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 53934 | 7.50 | pipe | 9.90 | reconstruction |
| 69 | BR:SH134:RMG205:54.638 | RMG205 | SH134 | Belgaum | Belgaum | Ramdurg | 54634 | 7.50 | pipe | 9.40 | reconstruction |
| 70 | BR:SH136:GDG203:99.504 | GDG203 | SH136 | Gadag | Gadag | Gadag | 99488 | 7.50 | Pipe | 32.50 | reconstruction |

## Details of Bridges Proposed for Reconstruction on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 71 | BR:SH136:MUI211:172.564 | MUI211 | SH136 | Gadag | Gadag | Mundargi | 172558 | 7.50 | Pipe | 12.10 | reconstruction |
| 72 | BR:SH136:HVR219:232.321 | HVR219 | SH136 | Haveri | Haveri | Haveri | 232316 | 7.50 | Slab | 11.00 | reconstruction |
| 73 | BR:SH136:BYD2:250.019 | BYD2 | SH136 | Haveri | Haveri | Byadagi | 250016 | 6.50 | Arch | 7.50 | reconstruction |
| 74 | BR:SH14:MAN201:238.144 | MAN201 | SH14 | Raichur | Raichur | Manvi | 238138 | 7.50 | pipe | 13.50 | reconstruction |
| 75 | BR:SH149:CTR202_A:66.565 | CTR202_A | SH149 | Gulbarga | Sedam | Chitapur | 66561 | 6.50 | Stone Slab | 9.00 | reconstruction |
| 76 | BR:SH15:YDG1:212.59 | YDG1 | SH15 | Yadgir | Yadgir | Yadgir | 212393 | 7.70 | Arch | 393.30 | reconstruction |
| 77 | BR:SH15:SHA206:239 | SHA206 | SH15 | Yadgir | Yadgir | Shahpur | 238982 | 6.50 | Arch | 36.00 | reconstruction |
| 78 | BR:SH154:SPT2:134.175 | SPT2 | SH154 | Mandya | Mandya | Srirangapattana | 134169 | 7.50 | Stone Slab | 12.00 | reconstruction |
| 79 | BR:SH154:SPT2:135.66 | SPT2 | SH154 | Mandya | Mandya | Srirangapattana | 135656 | 11.00 | Stone Slab | 8.40 | reconstruction |
| 80 | BR:SH154:SPT2:140.69 | SPT2 | SH154 | Mandya | Mandya | Srirangapattana | 140687 | 9.00 | Stone Slab | 7.20 | reconstruction |
| 81 | BR:SH16:SHA205_B:66.5 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 66488 | 7.00 | Slab | 24.00 | reconstruction |
| 82 | BR:SH16:SHA205_B:68.335 | SHA205_B | SH16 | Yadgir | Yadgir | Shahpur | 68326 | 6.50 | Arch | 18.00 | reconstruction |
| 83 | BR:SH2:HVR2:69.185 | HVR2 | SH2 | Haveri | Haveri | Haveri | 69171 | 6.50 | Arch | 28.00 | reconstruction |
| 84 | BR:SH2:HVR2:70.26 | HVR2 | SH2 | Haveri | Haveri | Haveri | 70254 | 6.50 | Arch | 12.00 | reconstruction |
| 85 | BR:SH2:HVR2:81.745 | HVR2 | SH2 | Haveri | Haveri | Haveri | 81742 | 7.00 | Arch | 7.50 | reconstruction |
| 86 | BR:SH2:HRP1:126.868 | HRP1 | SH2 | Davanagere | Davanagere | Harapanahalli | 126863 | 8.00 | Others | 10.00 | reconstruction |
| 87 | BR:SH2:KDL41:160.527 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 160518 | 12.00 | Others | 18.00 | reconstruction |
| 88 | BR:SH2:KDL41:191.71 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 191707 | 9.00 | Stone Slab | 6.60 | reconstruction |
| 89 | BR:SH2:KDL41:197.24 | KDL41 | SH2 | Bellary | Hadagalli | Kudligi | 197223 | 7.50 | Pipe | 34.50 | reconstruction |
| 90 | BR:SH20:LIN2:123.282 | LIN2 | SH20 | Raichur | Raichur | Lingsugur | 123270 | 7.00 | Arch | 24.00 | reconstruction |
| 91 | BR:SH21:HSS2:55.183 | HSS2 | SH21 | Hassan | Hassan | Hassan | 55122 | 6.50 | Arch | 123.50 | reconstruction |
| 92 | BR:SH21:ARK1:80.803 | ARK1 | SH21 | Hassan | Hassan_Special | Arkalgud | 80698 | 7.00 | Arch | 210.00 | reconstruction |
| 93 | BR:SH22:AFZ1:85.718 | AFZ1 | SH22 | Gulbarga | Gulbarga | Afzalpur | 85698 | 7.50 | pipe | 41.50 | reconstruction |
| 94 | BR:SH22:AFZ1:87.833 | AFZ1 | SH22 | Gulbarga | Gulbarga | Afzalpur | 87811 | 7.50 | pipe | 44.50 | reconstruction |
| 95 | BR:SH23:MUI208:220.493 | MUI208 | SH23 | Gadag | Gadag | Mundargi | 220490 | 7.50 | Slab | 7.00 | reconstruction |
| 96 | BR:SH23:MUI208:223.743 | MUI208 | SH23 | Gadag | Gadag | Mundargi | 223740 | 7.50 | Slab | 7.00 | reconstruction |
| 97 | BR:SH23:MUI208:224.268 | MUI208 | SH23 | Gadag | Gadag | Mundargi | 224265 | 7.00 | Arch | 7.00 | reconstruction |
| 98 | BR:SH23:SRT202:233.153 | SRT202 | SH23 | Gadag | Gadag | Shirahatti | 233135 | 7.00 | Arch | 36.00 | reconstruction |
| 99 | BR:SH24:TRK3:18.574 | TRK3 | SH24 | Chikmagalur | Chikmagalur | Tarikere | 18571 | 6.50 | Slab | 6.00 | reconstruction |
| 100 | BR:SH24:HRY3:86.543 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 86531 | 6.20 | Arch | 24.00 | reconstruction |
| 101 | BR:SH24:HRY3:92.443 | HRY3 | SH24 | Chitradurga | Chitradurga | Hiriyur | 92434 | 6.00 | Arch | 18.00 | reconstruction |
| 102 | BR:SH25:HRP2:67.903 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 67899 | 10.00 | Stone Slab | 9.00 | reconstruction |
| 103 | BR:SH25:HRP2:69.328 | HRP2 | SH25 | Davanagere | Davanagere | Harapanahalli | 69324 | 9.00 | Stone Slab | 8.00 | reconstruction |
| 104 | BR:SH26:RBN4:8.02 | RBN4 | SH26 | Haveri | Haveri | Ranebennur | 8016 | 7.50 | Pipe | 9.30 | reconstruction |
| 105 | BR:SH26:HSN2:110.459 | HSN2 | SH26 | Shimoga | Shimoga | Hosanagara | 110453 | 6.00 | Arch | 12.00 | reconstruction |

**Details of Bridges Proposed for Reconstruction on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 106 | BR:SH27:MDK3:11.635 | MDK3 | SH27 | Kodagu | Kodagu | Madikeri | 11587 | 7.50 | Arch | 96.00 | reconstruction |
| 107 | BR:SH27:SVP76:60.635 | SVP76 | SH27 | Kodagu | Kodagu | Somvarpet | 60625 | 4.50 | Steel Structure | 20.00 | reconstruction |
| 108 | BR:SH27:NRP201:230.315 | NRP201 | SH27 | Chikmagalur | Chikmagalur | Narasimharajapura | 230234 | 6.00 | Arch | 216.00 | reconstruction |
| 109 | BR:SH27:SNG203:275.7 | SNG203 | SH27 | Chikmagalur | Chikmagalur | Sringeri | 275697 | 7.50 | pipe | 6.30 | reconstruction |
| 110 | BR:SH3:KNK2:2.015 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 2005 | 8.50 | pipe | 21.60 | reconstruction |
| 111 | BR:SH3:KNK2:3.515 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 3506 | 7.50 | pipe | 19.90 | reconstruction |
| 112 | BR:SH3:KNK2:15.83 | KNK2 | SH3 | Ramanagara | Ramanagara | Kanakapura | 15827 | 8.00 | pipe | 6.40 | reconstruction |
| 113 | BR:SH31:RBG2:55.128 | RBG2 | SH31 | Belgaum | Chikkodi | Raibag | 55118 | 7.50 | pipe | 21.60 | reconstruction |
| 114 | BR:SH31:RBG2:62.143 | RBG2 | SH31 | Belgaum | Chikkodi | Raibag | 62140 | 7.50 | pipe | 6.50 | reconstruction |
| 115 | BR:SH31:GOK1:78.2 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 78197 | 7.00 | Slab | 7.00 | reconstruction |
| 116 | BR:SH31:GOK1:117.599 | GOK1 | SH31 | Belgaum | Chikkodi | Gokak | 117592 | 7.00 | Stone Slab | 15.00 | reconstruction |
| 117 | BR:SH34:AUR7:17.645 | AUR7 | SH34 | Bidar | Bidar | Aurad | 17640 | 7.50 | pipe | 10.70 | reconstruction |
| 118 | BR:SH34:BAK204_A:76.385 | BAK204_A | SH34 | Bidar | Bidar | Basavakalyan | 76382 | 6.00 | pipe | 7.00 | reconstruction |
| 119 | BR:SH34:ALD202_A:196.665 | ALD202_A | SH34 | Gulbarga | Gulbarga | Aland | 196662 | 7.50 | pipe | 7.90 | reconstruction |
| 120 | BR:SH34:JMK1:382.92 | JMK1 | SH34 | Bagalkot | Bagalkot | Jamkhandi | 382700 | 7.40 | Arch | 413.00 | reconstruction |
| 121 | BR:SH35:SGA2:4.38 | SGA2 | SH35 | Chikballapur | Chikballapur | Sidlaghatta | 4376 | 5.90 | Stone Slab | 8.80 | reconstruction |
| 122 | BR:SH35:SGA2:8.045 | SGA2 | SH35 | Chikballapur | Chikballapur | Sidlaghatta | 8038 | 5.50 | Stone Slab | 15.40 | reconstruction |
| 123 | BR:SH35:SGA2:10.7 | SGA2 | SH35 | Chikballapur | Chikballapur | Sidlaghatta | 10695 | 7.20 | Slab | 10.20 | reconstruction |
| 124 | BR:SH35:HOS4:35.315 | HOS4 | SH35 | Bangalore Rural | Bangalore | Hoskote | 35311 | 10.00 | pipe | 8.00 | reconstruction |
| 125 | BR:SH35:BNE7:52.743 | BNE7 | SH35 | Bangalore Urban | Bangalore | Bangalore-East | 52735 | 10.60 | Slab | 17.00 | reconstruction |
| 126 | BR:SH35:ANK3:64.643 | ANK3 | SH35 | Bangalore Urban | Bangalore | Anekal | 64639 | 12.70 | Slab | 9.00 | reconstruction |
| 127 | BR:SH35:ANK3:67.646 | ANK3 | SH35 | Bangalore Urban | Bangalore | Anekal | 67643 | 9.10 | Others | 6.00 | reconstruction |
| 128 | BR:SH35:ANK3:73.476 | ANK3 | SH35 | Bangalore Urban | Bangalore | Anekal | 73466 | 6.40 | Arch | 21.30 | reconstruction |
| 129 | BR:SH35:ANK3:74.151 | ANK3 | SH35 | Bangalore Urban | Bangalore | Anekal | 74135 | 6.50 | Arch | 33.00 | reconstruction |
| 130 | BR:SH35:ANK3:84.301 | ANK3 | SH35 | Bangalore Urban | Bangalore | Anekal | 84298 | 12.00 | Slab | 6.10 | reconstruction |
| 131 | BR:SH35:ANK3:85.651 | ANK3 | SH35 | Bangalore Urban | Bangalore | Anekal | 85648 | 9.80 | Slab | 7.00 | reconstruction |
| 132 | BR:SH38:KLL302:20.057 | KLL302 | SH38 | Chamrajnagar | Chamrajnagar | Kollegal | 20052 | 8.50 | Steel Structure | 10.40 | reconstruction |
| 133 | BR:SH38:KLL302:26.422 | KLL302 | SH38 | Chamrajnagar | Chamrajnagar | Kollegal | 26419 | 10.00 | pipe | 7.00 | reconstruction |
| 134 | BR:SH40:HDG201:29.315 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 29309 | 7.50 | Pipe | 13.10 | reconstruction |
| 135 | BR:SH40:HDG201:30.36 | HDG201 | SH40 | Bellary | Hadagalli | Hadagalli | 30357 | 7.50 | Pipe | 6.30 | reconstruction |
| 136 | BR:SH40:HGB59:56.76 | HGB59 | SH40 | Bellary | Hadagalli | Hagaribommanahalli | 56743 | 10.00 | Slab | 35.00 | reconstruction |
| 137 | BR:SH40:HGB59:59 | HGB59 | SH40 | Bellary | Hadagalli | Hagaribommanahalli | 58997 | 7.00 | Slab | 7.00 | reconstruction |
| 138 | BR:SH40:KDL3:109.045 | KDL3 | SH40 | Bellary | Hadagalli | Kudligi | 109035 | 7.50 | Pipe | 20.50 | reconstruction |
| 139 | BR:SH41:SND3:89.168 | SND3 | SH41 | Bijapur | Bijapur | Sindgi | 89150 | 6.50 | Arch | 36.00 | reconstruction |
| 140 | BR:SH41:LIN5:190.101 | LIN5 | SH41 | Raichur | Raichur | Lingsugur | 190096 | 7.50 | pipe | 11.50 | reconstruction |

## Details of Bridges Proposed for Reconstruction on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 141 | BR:SH44:GOK6:48.339 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 48332 | 7.50 | pipe | 14.00 | reconstruction |
| 142 | BR:SH44:GOK6:55.139 | GOK6 | SH44 | Belgaum | Chikkodi | Gokak | 55135 | 7.50 | pipe | 9.40 | reconstruction |
| 143 | BR:SH44:BDM204:145.829 | BDM204 | SH44 | Bagalkot | Bagalkot | Badami | 145824 | 6.00 | Arch | 11.00 | reconstruction |
| 144 | BR:SH44:HUD206:170.9 | HUD206 | SH44 | Bagalkot | Bagalkot | Hungund | 170888 | 8.00 | pipe | 24.50 | reconstruction |
| 145 | BR:SH45:SAU3:47.691 | SAU3 | SH45 | Belgaum | Belgaum | Saundatti | 47687 | 6.20 | Arch | 9.00 | reconstruction |
| 146 | BR:SH45:HDG202:196.813 | HDG202 | SH45 | Bellary | Hadagalli | Hadagalli | 196800 | 7.50 | Pipe | 26.10 | reconstruction |
| 147 | BR:SH47:MND6:0.945 | MND6 | SH47 | Mandya | Mandya | Mandya | 941 | 7.50 | pipe | 8.25 | reconstruction |
| 148 | BR:SH47:HLK203:262.157 | HLK203 | SH47 | Chitradurga | Chitradurga | Holalkere | 262151 | 6.00 | Arch | 12.60 | reconstruction |
| 149 | BR:SH47:HDG203:347.181 | HDG203 | SH47 | Bellary | Hadagalli | Hadagalli | 347178 | 9.00 | Stone Slab | 6.30 | reconstruction |
| 150 | BR:SH48:KMT3:38.44 | KMT3 | SH48 | Uttara Kannada | Karwar | Kumta | 38434 | 7.50 | Slab | 12.00 | reconstruction |
| 151 | BR:SH48:PVG58:356.325 | PVG58 | SH48 | Tumkur | Madhugiri | Pavagada | 356322 | 7.50 | Stone Slab | 6.00 | reconstruction |
| 152 | BR:SH49:SRG46:74.385 | SRG46 | SH49 | Bellary | Bellary | Siruguppa | 74382 | 7.50 | Pipe | 6.70 | reconstruction |
| 153 | BR:SH49:SRG46:98.01 | SRG46 | SH49 | Bellary | Bellary | Siruguppa | 98002 | 7.50 | Slab | 16.00 | reconstruction |
| 154 | BR:SH5:KOL2:15.37 | KOL2 | SH5 | Kolar | Kolar | Kolar | 15364 | 10.50 | Stone Slab | 13.20 | reconstruction |
| 155 | BR:SH5:CMI3:39.507 | CMI3 | SH5 | Chikballapur | Chikballapur | Chintamani | 39499 | 9.20 | Slab | 17.60 | reconstruction |
| 156 | BR:SH5:SGA4:64.58 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 64573 | 6.80 | Stone Slab | 15.40 | reconstruction |
| 157 | BR:SH5:SGA4:67.79 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 67786 | 10.30 | Slab | 8.40 | reconstruction |
| 158 | BR:SH5:SGA4:86.793 | SGA4 | SH5 | Chikballapur | Chikballapur | Sidlaghatta | 86790 | 9.00 | Stone Slab | 6.60 | reconstruction |
| 159 | BR:SH51:ALD203:52.84 | ALD203 | SH51 | Gulbarga | Gulbarga | Aland | 52823 | 7.50 | Pipe | 46.20 | reconstruction |
| 160 | BR:SH51:GUL5:62.33 | GUL5 | SH51 | Gulbarga | Gulbarga | Gulbarga | 62326 | 7.50 | pipe | 9.30 | reconstruction |
| 161 | BR:SH52:KDP2:85.539 | KDP2 | SH52 | Udupi | Udupi | Kundapura | 85529 | 8.00 | Pipe | 20.50 | reconstruction |
| 162 | BR:SH53:ATN5:21.7 | ATN5 | SH53 | Belgaum | Chikkodi | Athni | 21547 | 7.00 | Arch | 300.00 | reconstruction |
| 163 | BR:SH53:RBG8:31.425 | RBG8 | SH53 | Belgaum | Chikkodi | Raibag | 31417 | 7.50 | pipe | 16.50 | reconstruction |
| 164 | BR:SH54:KNP202:2.205 | KNP202 | SH54 | Belgaum | Belgaum | Khanapur | 2181 | 6.00 | Arch | 63.00 | reconstruction |
| 165 | BR:SH55:BJP21:89.599 | BJP21 | SH55 | Bijapur | Bijapur | Bijapur | 89591 | 7.50 | pipe | 17.70 | reconstruction |
| 166 | BR:SH56:NVG202:77.325 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 77315 | 7.50 | Pipe | 21.60 | reconstruction |
| 167 | BR:SH56:NVG202:79.525 | NVG202 | SH56 | Dharwad | Dharwad | Navalgund | 79514 | 7.50 | Pipe | 23.30 | reconstruction |
| 168 | BR:SH57:HVR221:193.92 | HVR221 | SH57 | Haveri | Haveri | Haveri | 193917 | 7.50 | Pipe | 7.30 | reconstruction |
| 169 | BR:SH57:TRK212:364.07 | TRK212 | SH57 | Chikmagalur | Chikmagalur | Tarikere | 364060 | 7.50 | Arch | 20.00 | reconstruction |
| 170 | BR:SH57:CHK201:444.069 | CHK201 | SH57 | Chikmagalur | Chikmagalur | Chikmagalur | 444060 | 6.50 | Arch | 18.00 | reconstruction |
| 171 | BR:SH57:BLR1:448.219 | BLR1 | SH57 | Hassan | Hassan | Belur | 448215 | 7.00 | Slab | 9.60 | reconstruction |
| 172 | BR:SH57:NJG60:672.804 | NJG60 | SH57 | Mysore | Mysore | Nanjangud | 672801 | 6.00 | Arch | 6.00 | reconstruction |
| 173 | BR:SH57:NJG60:673.286 | NJG60 | SH57 | Mysore | Mysore | Nanjangud | 673283 | 6.50 | Stone Slab | 6.00 | reconstruction |
| 174 | BR:SH57:CRN121:679.707 | CRN121 | SH57 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 679704 | 6.00 | Stone Slab | 7.20 | reconstruction |
| 175 | BR:SH59:KST204:3.89 | KST204 | SH59 | Koppal | Koppal | Kushtagi | 3863 | 7.50 | Slab | 55.00 | reconstruction |

**Details of Bridges Proposed for Reconstruction on CRN Network**

| Sl No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 176 | BR:SH6:MUD2:129.705 | MUD2 | SH6 | Uttara Kannada | Sirsi | Mundgod | 129700 | 6.00 | Arch | 11.00 | reconstruction |
| 177 | BR:SH6:MUD2:131.085 | MUD2 | SH6 | Uttara Kannada | Sirsi | Mundgod | 131082 | 6.50 | Arch | 6.00 | reconstruction |
| 178 | BR:SH6:SVN2:194.13 | SVN2 | SH6 | Haveri | Haveri | Savanur | 194124 | 6.50 | Arch | 12.00 | reconstruction |
| 179 | BR:SH61:MAN202:223.404 | MAN202 | SH61 | Raichur | Raichur | Manvi | 223364 | 7.00 | Arch | 116.10 | reconstruction |
| 180 | BR:SH61:MAN202:225.779 | MAN202 | SH61 | Raichur | Raichur | Manvi | 225774 | 7.50 | pipe | 10.70 | reconstruction |
| 181 | BR:SH61:MAN202:229.599 | MAN202 | SH61 | Raichur | Raichur | Manvi | 229595 | 7.50 | Arch | 9.00 | reconstruction |
| 182 | BR:SH61:MAN202:231.299 | MAN202 | SH61 | Raichur | Raichur | Manvi | 231290 | 7.50 | Arch | 18.00 | reconstruction |
| 183 | BR:SH61:MAN202:235.296 | MAN202 | SH61 | Raichur | Raichur | Manvi | 235287 | 7.00 | Arch | 18.00 | reconstruction |
| 184 | BR:SH61:MAN202:239.006 | MAN202 | SH61 | Raichur | Raichur | Manvi | 238997 | 7.00 | Arch | 18.00 | reconstruction |
| 185 | BR:SH61:RAI201:241.431 | RAI201 | SH61 | Raichur | Raichur | Raichur | 241428 | 7.50 | pipe | 7.00 | reconstruction |
| 186 | BR:SH62:BYD6:24.005 | BYD6 | SH62 | Haveri | Haveri | Byadagi | 23997 | 7.50 | Pipe | 16.40 | reconstruction |
| 187 | BR:SH62:HKR201:38.493 | HKR201 | SH62 | Haveri | Haveri | Hirekerur | 38489 | 7.00 | Slab | 9.00 | reconstruction |
| 188 | BR:SH63:SRG45:4.255 | SRG45 | SH63 | Bellary | Bellary | Siruguppa | 4252 | 6.00 | Slab | 7.00 | reconstruction |
| 189 | BR:SH63:SRG45:14.38 | SRG45 | SH63 | Bellary | Bellary | Siruguppa | 14371 | 7.50 | Pipe | 19.10 | reconstruction |
| 190 | BR:SH63:YEL114:127.039 | YEL114 | SH63 | Koppal | Koppal | Yelbarga | 127025 | 7.50 | pipe | 28.10 | reconstruction |
| 191 | BR:SH63:YEL114:129.314 | YEL114 | SH63 | Koppal | Koppal | Yelbarga | 129303 | 7.50 | pipe | 23.30 | reconstruction |
| 192 | BR:SH65:KPA8:77.658 | KPA8 | SH65 | Chikmagalur | Chikmagalur | Koppa | 77655 | 5.00 | Steel Structure | 6.00 | reconstruction |
| 193 | BR:SH65:KPA8:99.512 | KPA8 | SH65 | Chikmagalur | Chikmagalur | Koppa | 99494 | 6.00 | Steel Structure | 36.00 | reconstruction |
| 194 | BR:SH65:NRP202:101.112 | NRP202 | SH65 | Chikmagalur | Chikmagalur | Narasimharajapura | 101109 | 7.00 | Arch | 7.00 | reconstruction |
| 195 | BR:SH65:BRV67:161.736 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 161615 | 8.00 | Arch | 195.00 | reconstruction |
| 196 | BR:SH65:BRV67:164.771 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 164768 | 7.00 | Stone Slab | 7.50 | reconstruction |
| 197 | BR:SH65:BRV67:165.656 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 165653 | 7.00 | Stone Slab | 6.60 | reconstruction |
| 198 | BR:SH65:BRV67:166.096 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 166092 | 7.00 | Stone Slab | 9.00 | reconstruction |
| 199 | BR:SH65:BRV67:166.961 | BRV67 | SH65 | Shimoga | Shimoga_special | Bhadravathi | 166958 | 7.00 | Stone Slab | 6.60 | reconstruction |
| 200 | BR:SH65:DVG48:254.398 | DVG48 | SH65 | Davanagere | Davanagere | Davanagere | 254380 | 8.00 | Others | 36.00 | reconstruction |
| 201 | BR:SH65:DVG48:274.333 | DVG48 | SH65 | Davanagere | Davanagere | Davanagere | 274329 | 8.00 | Slab | 9.00 | reconstruction |
| 202 | BR:SH65:MOL202:370.865 | MOL202 | SH65 | Chitradurga | Chitradurga | Molakalmuru | 370861 | 9.50 | Slab | 8.40 | reconstruction |
| 203 | BR:SH67:MNG6:25.555 | MNG6 | SH67 | Dakshina Kannada | Mangalore | Mangalore | 25552 | 7.00 | pipe | 7.00 | reconstruction |
| 204 | BR:SH67:UDP202:79.79 | UDP202 | SH67 | Udupi | Udupi | Udupi | 79781 | 5.50 | Slab | 18.00 | reconstruction |
| 205 | BR:SH69:KMT2:22.01 | KMT2 | SH69 | Uttara Kannada | Karwar | Kumta | 22001 | 6.50 | Arch | 19.50 | reconstruction |
| 206 | BR:SH69:SRS90:51.065 | SRS90 | SH69 | Uttara Kannada | Sirsi | Sirsi | 51051 | 6.50 | Arch | 28.00 | reconstruction |
| 207 | BR:SH69:MUD1:128.176 | MUD1 | SH69 | Uttara Kannada | Sirsi | Mundgod | 128173 | 6.50 | Arch | 6.50 | reconstruction |
| 208 | BR:SH70:BEL3:14.455 | BEL3 | SH70 | Dakshina Kannada | Mangalore | Belthangady | 14452 | 7.00 | Steel Structure | 6.00 | reconstruction |
| 209 | BR:SH72:CKD201_A:45.781 | CKD201_A | SH72 | Belgaum | Chikkodi | Chikkodi | 45704 | 7.40 | Slab | 155.00 | reconstruction |
| 210 | BR:SH72:ATN20_B:97.847 | ATN20_B | SH72 | Belgaum | Chikkodi | Athni | 97843 | 7.50 | pipe | 9.90 | reconstruction |

Details of Bridges Proposed for Reconstruction on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 211 | BR:SH73:CKD202:59.834 | CKD202 | SH73 | Belgaum | Chikkodi | Chikkodi | 59831 | 7.50 | Slab | 7.00 | reconstruction |
| 212 | BR:SH73:GOK205_A:79.174 | GOK205_A | SH73 | Belgaum | Chikkodi | Gokak | 79170 | 6.50 | Arch | 9.00 | reconstruction |
| 213 | BR:SH73:HUK206_B:99.305 | HUK206_B | SH73 | Belgaum | Chikkodi | Hukkeri | 99287 | 7.00 | Slab | 36.00 | reconstruction |
| 214 | BR:SH73:BAI203:126.43 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 126427 | 7.50 | pipe | 7.90 | reconstruction |
| 215 | BR:SH73:BAI203:161.637 | BAI203 | SH73 | Belgaum | Belgaum | Bailhongal | 161633 | 6.50 | Arch | 9.00 | reconstruction |
| 216 | BR:SH74:NLM6:9.329 | NLM6 | SH74 | Bangalore Rural | Bangalore | Nelmangala | 9326 | 9.40 | Slab | 7.50 | reconstruction |
| 217 | BR:SH74:DOD3:41.119 | DOD3 | SH74 | Bangalore Rural | Bangalore | Dod Ballapura | 41116 | 7.20 | Stone Slab | 6.00 | reconstruction |
| 218 | BR:SH75:HUM202:39.437 | HUM202 | SH75 | Bidar | Bidar | Homnabad | 39433 | 7.00 | Arch | 9.00 | reconstruction |
| 219 | BR:SH75:HUM202:50.852 | HUM202 | SH75 | Bidar | Bidar | Homnabad | 50849 | 7.00 | Slab | 7.20 | reconstruction |
| 220 | BR:SH75:HUM202:53.557 | HUM202 | SH75 | Bidar | Bidar | Homnabad | 53554 | 10.00 | Slab | 6.40 | reconstruction |
| 221 | BR:SH76:HKR4_A:165.218 | HKR4_A | SH76 | Haveri | Haveri | Hirekerur | 165215 | 7.00 | Stone Slab | 6.60 | reconstruction |
| 222 | BR:SH79:SPT3:12.785 | SPT3 | SH79 | Mandya | Mandya | Srirangapattana | 12778 | 6.00 | Arch | 14.00 | reconstruction |
| 223 | BR:SH79:TNP205:16.05 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 16045 | 8.00 | Stone Slab | 10.00 | reconstruction |
| 224 | BR:SH79:TNP205:56.605 | TNP205 | SH79 | Mysore | Mysore | Tnarsipur | 56602 | 7.00 | pipe | 7.60 | reconstruction |
| 225 | BR:SH79:KLL301:79.993 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 79990 | 8.00 | Stone Slab | 7.50 | reconstruction |
| 226 | BR:SH79:KLL301:158.497 | KLL301 | SH79 | Chamrajnagar | Chamrajnagar | Kollegal | 158494 | 7.50 | pipe | 7.00 | reconstruction |
| 227 | BR:SH8:SLP235:112.188 | SLP235 | SH8 | Hassan | Hassan_Special | Sakleshpur | 112175 | 5.50 | Steel Structure | 26.00 | reconstruction |
| 228 | BR:SH8:SLP235:115.973 | SLP235 | SH8 | Hassan | Hassan_Special | Sakleshpur | 115960 | 5.50 | Steel Structure | 26.00 | reconstruction |
| 229 | BR:SH80:CRN118:53.886 | CRN118 | SH80 | Chamrajnagar | Chamrajnagar | Chamarajnagar | 53880 | 7.00 | Slab | 12.00 | reconstruction |
| 230 | BR:SH81:YLN202:1.555 | YLN202 | SH81 | Chamrajnagar | Chamrajnagar | Yelandur | 1552 | 8.30 | Slab | 6.00 | reconstruction |
| 231 | BR:SH82:SRI1:86.804 | SRI1 | SH82 | Kolar | Kolar | Srinivasapur | 86801 | 10.20 | Stone Slab | 6.30 | reconstruction |
| 232 | BR:SH83:RON77:82.985 | RON77 | SH83 | Gadag | Gadag | Ron | 82981 | 7.50 | Slab | 9.00 | reconstruction |
| 233 | BR:SH83:RON77:84.065 | RON77 | SH83 | Gadag | Gadag | Ron | 84061 | 7.50 | Slab | 9.00 | reconstruction |
| 234 | BR:SH84:SRA8:4.95 | SRA8 | SH84 | Tumkur | Madhugiri | Sira | 4944 | 9.00 | Stone Slab | 13.50 | reconstruction |
| 235 | BR:SH84:SRA8:9.34 | SRA8 | SH84 | Tumkur | Madhugiri | Sira | 9337 | 8.00 | Stone Slab | 6.00 | reconstruction |
| 236 | BR:SH84:SRA8:10.955 | SRA8 | SH84 | Tumkur | Madhugiri | Sira | 10951 | 8.00 | Stone Slab | 8.00 | reconstruction |
| 237 | BR:SH84:NJG63:223.647 | NJG63 | SH84 | Mysore | Mysore | Nanjangud | 223625 | 6.50 | Arch | 44.00 | reconstruction |
| 238 | BR:SH84:NJG63:226.272 | NJG63 | SH84 | Mysore | Mysore | Nanjangud | 226268 | 7.00 | Stone Slab | 8.00 | reconstruction |
| 239 | BR:SH85:KRN224:176.505 | KRN224 | SH85 | Mysore | Hunsur | Krishnarajanagar | 176498 | 8.00 | Stone Slab | 15.00 | reconstruction |
| 240 | BR:SH85:ARK201:200.995 | ARK201 | SH85 | Hassan | Hassan_Special | Arkalgud | 200989 | 6.00 | Slab | 12.00 | reconstruction |
| 241 | BR:SH86:HDK203:65.35 | HDK203 | SH86 | Mysore | Hunsur | Heggadadevanakote | 65343 | 7.20 | Stone Slab | 15.40 | reconstruction |
| 242 | BR:SH87:ANK2:29.38 | ANK2 | SH87 | Bangalore Urban | Bangalore | Anekal | 29375 | 11.50 | Slab | 11.80 | reconstruction |
| 243 | BR:SH87:ANK2:29.955 | ANK2 | SH87 | Bangalore Urban | Bangalore | Anekal | 29952 | 16.40 | Slab | 6.00 | reconstruction |
| 244 | BR:SH89:VJP72:83.573 | VJP72 | SH89 | Kodagu | Kodagu | Virajpet | 83559 | 4.25 | Steel Structure | 28.50 | reconstruction |
| 245 | BR:SH9:DOD2:41.568 | DOD2 | SH9 | Bangalore Rural | Bangalore | Dod Ballapura | 41562 | 8.30 | Others | 13.50 | reconstruction |

**Details of Bridges Proposed for Reconstruction on CRN Network**

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 246 | BR:SH9:DOD2:42.663 | DOD2 | SH9 | Bangalore Rural | Bangalore | Dod Ballapura | 42660 | 9.50 | Others | 6.30 | reconstruction |
| 247 | BR:SH90:VJP73:28.041 | VJP73 | SH90 | Kodagu | Kodagu | Virajpet | 28036 | 6.25 | Arch | 10.00 | reconstruction |
| 248 | BR:SH90:MDK201:100.827 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 100819 | 4.50 | Girder | 17.00 | reconstruction |
| 249 | BR:SH90:MDK201:106.622 | MDK201 | SH90 | Kodagu | Kodagu | Madikeri | 106616 | 4.50 | Slab | 13.00 | reconstruction |
| 250 | BR:SH93:YLP2:84.937 | YLP2 | SH93 | Uttara Kannada | Sirsi | Yellapur | 84932 | 6.50 | Arch | 11.00 | reconstruction |
| 251 | BR:SH93:YLP2:111.079 | YLP2 | SH93 | Uttara Kannada | Sirsi | Yellapur | 111023 | 4.50 | Girder | 112.50 | reconstruction |
| 252 | BR:SH94:GBR201:30.581 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 30578 | 7.10 | Slab | 6.20 | reconstruction |
| 253 | BR:SH94:GBR201:36.431 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 36424 | 7.80 | Stone Slab | 15.40 | reconstruction |
| 254 | BR:SH94:GBR201:38.721 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 38714 | 7.50 | Stone Slab | 14.30 | reconstruction |
| 255 | BR:SH94:GBR201:48.681 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 48678 | 10.00 | pipe | 6.60 | reconstruction |
| 256 | BR:SH94:GBR201:51.376 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 51372 | 7.50 | pipe | 9.40 | reconstruction |
| 257 | BR:SH94:GBR201:63.202 | GBR201 | SH94 | Chikballapur | Chikballapur | Gauribidanur | 63172 | 8.00 | Pipe | 65.40 | reconstruction |
| 258 | BR:SH94:KTG201:87.477 | KTG201 | SH94 | Tumkur | Madhugiri | Koratagere | 87473 | 6.90 | Slab | 8.00 | reconstruction |
| 259 | BR:SH94:TMK202:127.215 | TMK202 | SH94 | Tumkur | Tumkur | Tumkur | 127209 | 5.00 | Slab | 12.00 | reconstruction |
| 260 | BR:SH94:MGD201:158.705 | MGD201 | SH94 | Ramanagara | Ramanagara | Magadi | 158702 | 5.00 | Slab | 6.00 | reconstruction |
| 261 | BR:SH95:MLR201:24.795 | MLR201 | SH95 | Kolar | Kolar | Malur | 24790 | 8.20 | Stone Slab | 10.20 | reconstruction |
| 262 | BR:SH95:MLR201:33.59 | MLR201 | SH95 | Kolar | Kolar | Malur | 33585 | 7.80 | Stone Slab | 10.00 | reconstruction |
| 263 | BR:SH95:MLR201:41.69 | MLR201 | SH95 | Kolar | Kolar | Malur | 41685 | 7.20 | Stone Slab | 10.00 | reconstruction |
| 264 | BR:SH95:BGT200:50.822 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 50819 | 9.50 | Stone Slab | 6.40 | reconstruction |
| 265 | BR:SH95:BGT200:74.902 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 74898 | 7.50 | Stone Slab | 8.00 | reconstruction |
| 266 | BR:SH95:BGT200:75.027 | BGT200 | SH95 | Kolar | Kolar | Bangarpet | 75016 | 9.00 | Stone Slab | 22.00 | reconstruction |
| 267 | BR:SH96:DVN4:5.59 | DVN4 | SH96 | Bangalore Rural | Bangalore | Devanahalli | 5586 | 10.90 | Stone Slab | 8.00 | reconstruction |
| 268 | BR:SH96:SGA1:14.825 | SGA1 | SH96 | Chikballapur | Chikballapur | Sidlaghatta | 14803 | 6.50 | Arch | 45.00 | reconstruction |
| 269 | BR:SH96:SGA1:17.615 | SGA1 | SH96 | Chikballapur | Chikballapur | Sidlaghatta | 17611 | 6.50 | Arch | 9.00 | reconstruction |
| 270 | BR:SH96:SGA1:18.63 | SGA1 | SH96 | Chikballapur | Chikballapur | Sidlaghatta | 18627 | 12.00 | Stone Slab | 6.00 | reconstruction |
| 271 | BR:SH96:SGA1:20.535 | SGA1 | SH96 | Chikballapur | Chikballapur | Sidlaghatta | 20528 | 11.50 | Stone Slab | 14.00 | reconstruction |
| 272 | BR:SH96:HOS202:27.225 | HOS202 | SH96 | Bangalore Rural | Bangalore | Hoskote | 27222 | 10.00 | Stone Slab | 6.30 | reconstruction |
| 273 | BR:SH96:KOL201:30.894 | KOL201 | SH96 | Kolar | Kolar | Kolar | 30891 | 10.50 | Stone Slab | 7.20 | reconstruction |
| 274 | BR:SH96:KOL201:34.034 | KOL201 | SH96 | Kolar | Kolar | Kolar | 34031 | 8.50 | Stone Slab | 7.20 | reconstruction |
| 275 | BR:SH96:KOL201:34.629 | KOL201 | SH96 | Kolar | Kolar | Kolar | 34617 | 7.00 | Arch | 24.00 | reconstruction |
| 276 | BR:SH96:KOL201:39.224 | KOL201 | SH96 | Kolar | Kolar | Kolar | 39221 | 11.50 | Stone Slab | 6.30 | reconstruction |
| 277 | BR:SH96:KOL201:43.254 | KOL201 | SH96 | Kolar | Kolar | Kolar | 43251 | 10.30 | Stone Slab | 6.30 | reconstruction |
| 278 | BR:SH96:KOL201:46.884 | KOL201 | SH96 | Kolar | Kolar | Kolar | 46881 | 10.80 | Stone Slab | 6.60 | reconstruction |
| 279 | BR:SH96:KOL201:54.05 | KOL201 | SH96 | Kolar | Kolar | Kolar | 54042 | 8.10 | Arch | 16.50 | reconstruction |
| 280 | BR:SH96:KOL201:65.095 | KOL201 | SH96 | Kolar | Kolar | Kolar | 65092 | 6.50 | Slab | 6.90 | reconstruction |

## Details of Bridges Proposed for Reconstruction on CRN Network

| Sl. No. | Bridge Id | Link Id | SH/MDR Number | District | Division | Taluk | Bridge Chainage | Overall Width m | Type of Super Str | Bridge Length (m) | Tentative Improvement Proposal |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 281 | BR:SH96:BGT201:88.016 | BGT201 | SH96 | Kolar | Kolar | Bangarpet | 88012 | 6.50 | Stone Slab | 9.60 | reconstruction |
| 282 | BR:SH96:BGT201:88.261 | BGT201 | SH96 | Kolar | Kolar | Bangarpet | 88256 | 6.50 | Stone Slab | 10.00 | reconstruction |
| 283 | BR:SH96:BGT201:91.926 | BGT201 | SH96 | Kolar | Kolar | Bangarpet | 91921 | 7.00 | Pipe | 11.60 | reconstruction |
| 284 | BR:SH99:SRI201:28.021 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 28017 | 10.00 | Stone Slab | 8.50 | reconstruction |
| 285 | BR:SH99:SRI201:28.126 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 28122 | 11.20 | Stone Slab | 8.00 | reconstruction |
| 286 | BR:SH99:SRI201:37.741 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 37737 | 11.00 | Stone Slab | 8.00 | reconstruction |
| 287 | BR:SH99:SRI201:42.021 | SRI201 | SH99 | Kolar | Kolar | Srinivasapur | 42015 | 12.00 | Stone Slab | 12.00 | reconstruction |
| 288 | BR:SH99:MLR202:71.237 | MLR202 | SH99 | Kolar | Kolar | Malur | 71232 | 9.10 | Stone Slab | 10.80 | reconstruction |
| 289 | BR:SH99:MLR202:86.727 | MLR202 | SH99 | Kolar | Kolar | Malur | 86724 | 7.30 | Stone Slab | 6.90 | reconstruction |
| 290 | BR:SH99:MLR202:89.702 | MLR202 | SH99 | Kolar | Kolar | Malur | 89699 | 8.10 | Stone Slab | 6.60 | reconstruction |

Engineer in Chief,
Planning Road Asset & Management Center
4th Floor, PWD Annex Building, K.R.Circle.
Bangalore – 560 001.